

INS. CASE OWNER:

KORSAH

CC 4 / AIG1800

7824 / Khasz

LKK:

IDAC:

Surveyor:

Kenneth

DOI:

30/4/18

Date / Time:

21/4/18

Registered in Merimen:

21/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLN 5118X

Name of Insured:

Lim Hong Chye

Insured Tel No.:

HP:

93886648

Excess Sec II :SS

D.O.A.:

20/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Song Phixing Chan

Driver Tel No.:

93886648

(V/L: YES / NO)

Claim No.:

572020556296

Policy No.:

Make / Model:

Subaru Forester

Place of Accident:

TPE > SCS

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SLR 7101J



INSRS:

WSP:

Tel:

Liability:

RMKS:

Chay Hoo



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

27/6/18

M

SLR 7101J X; SLN 5118 X-X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

27/5/2018

Vic-ole #15

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

P/P

S\$ 23,057.57

12 days)

Reduction:

6

%

Email

Call

FINAL SETTLEMENT

Date/Time:

13/4/19

Confirm with:

JONG

Email

Call

Final Liability:

%

100

(Agreed / Assessed)

BOLA S/N No.:

28

If NO or B 28, Ass. Lia:

100%

Repair Cost: (w/loss)

S\$ 24,671.59

C7 Ver. C.C.; OIO Ver)

Loss of Rental (LOR) (w/loss)

S\$ 1,489.20

(16 days)

\$85

Loss of Use (LOU):

S\$

-

(\$ x days)

-

(\$ x days)

Loss of Income (LOI):

S\$

-

(\$ x days)

-

(\$ x days)

LOR only ☒ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

8.00

Medical:

S\$

-

Disbursement:

S\$

-

(e.g. Tow/ Independent)

Legal Cost

S\$

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$320.00

Total:

S\$ 26,134.59

Global Sum S\$:

-

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$ 26,134.59

Name 1:

CHONG HOE MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

-

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

-

ASS. REC. BY:

REF:

AIG/

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

12

days

Res.:

Yes or No

Lum Sum:

1-B.1 %

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

2/5

File pass to Catherine, car not ready

4/4

B 23,057.37 email

CRUD: A 1,556.00 (6%)

Veh No:

SLR 71017

Yr Regn:

08, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Ssang Yong Tivoli c.c

1397

Colour:

M. P. White

A/C:

Insured / Std / NI / NA

Sp. Reading

12001

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

KPT30B1VSHPI84227

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Nexen

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

2014/18

D.O.I.

30/4/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prell. Report

1)

Date/Time, File Return to?

☐

: Final Report

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC4/AIG18007824/Kha3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 27-04-2018		
		Code : AIG		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLN 5118X	Veh. Inspected	SLR 7101J	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	27/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	20/04/2018	Inspection Date	30/04/2018	
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLR 7101R
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1890485/YISHUN

Date: 30 Apr 2018

Policy No: C/NOTE : C0075076

Veh Reg No: SLR7101J

Make/Model: SSANGYONG TIVOLI
1.6G 6AT ABS 2WD E4

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 20/04/2018

TP Veh Reg No: SLN5118X

Chassis No: KPT30B1VSH164227

Engine No: 17391002090203

Reg. Date: 24/08/2017

Not Authorized

Repair B4 paint

8 23, 057.37

12 days

Estimate Repair Cost to Vehicle No :SLR7101J

PAGE:1/2

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price				
1 FRONT BUMPER	764.22	1 PC	764.22	✓
2 FRONT BUMPER REINFORCEMENT	461.10	1 PC	461.10	✓
3 FRONT BUMPER SPONGE	154.14	1 PC	154.14	✓
4 FRONT BUMPER CENTRE LOWER GRILLE	192.36	1 PC	192.36	✓
5 FRONT BUMPER INNER LOWER GARNISH	80.07	1 PC	80.07	✓
6 FRONT BUMPER SIDE LOWER SKIRT	127.24	2 PCS	254.48	✓
7 FRONT BUMPER FOG LAMPS	292.96	2 PCS	585.92	✓
8 FRONT BUMPER CLIPS	4.20	8 PCS	33.60	✓
9 FRONT GRILLE	240.45	1 PC	240.45	✓
10 FRONT GRILLE LOGO	89.10	1 PC	89.10	✓
11 FRONT GRILLE CLIPS	4.05	3 PCS	12.15	✓
12 HEADLAMPS	2,919.72	2 PCS	5,839.44	✓
13 AIR-CON CONDENSER	1,403.52	1 PC	1,403.52	✓
14 RADIATOR	1,184.56	1 PC	1,184.56	✓
15 FRT SUPPORT PANEL	1,711.50	1 PC	1,711.50	✓
16 FRONT SUPPORT PANEL LH INNER SPONGE	108.24	1 PC	108.24	✓
17 REAR BUMPER	770.92	1 PC	770.92	✓
18 REAR BUMPER REINFORCEMENT	570.98	1 PC	570.98	✓
19 REAR BUMPER REFLECTORS	49.59	2 PCS	99.18	✓
20 REAR REVERSE LAMP	193.10	1 PC	193.10	✓
21 REAR BUMPER CLIPS	4.20	6 PCS	25.20	✓
22 REAR TAILGATE	2,598.48	1 PC	2,598.48	✓
23 TAILGATE EMBLEM (SSANGYONG)	55.68	1 PC	55.68	✓
24 TAILGATE EMBLEM (TIVOLI)	57.21	1 PC	57.21	✓
25 TAILGATE LOGO	185.34	1 PC	185.34	✓
26 TAILGATE INNER LOCK	124.90	1 PC	124.90	✓
27 TAILGATE INNER RUBBER	277.15	1 PC	277.15	✓
28 REAR PANEL	599.24	1 PC	599.24	X
29 REAR PANEL INNER TOP GARNISH	89.29	1 PC	89.29	✓
30 REAR LH FENDER INNER GARNISH	536.35	1 PC	536.35	✓
31 REAR LH FENDER ARP GARNISH	153.12	1 PC	153.12	✓
32 REAR TOW COVER	40.75	1 PC	40.75	X
33 REAR SMART KEY ANTENNA	189.45	1 PC	189.45	X
34 BONNET	1,956.44	1 PC	1,956.44	✓
35 REAR NUMBER PLATE LAMPS	39.10	2 PCS	78.20	X
			21,715.83	
			Less 10%	2,171.58
				19,544.25

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120

TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 20/04/2018
 TP Veh Reg No: SLN5118X

Estimate No: ES1890485/YISHUN
Date: 30 Apr 2018
Policy No: C/NOTE : C0075076
Veh Reg No: SLR7101J
Make/Model: SSANGYONG TIVOLI
 1.6G 6AT ABS 2WD E4
Chassis No: KPT30B1VSHP164227
Engine No: 17391002090203
Reg. Date: 24/08/2017

Estimate Repair Cost to Vehicle No :SLR7101J

PAGE:2/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
Special Net				
36 REAR SPARE TYRE PANEL TOP COAT	80.00	1 PC	80.00	X
37 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
38 FRONT NUMBER PLATE	45.00	1 PC	45.00	✓
39 COOLANT (3 LTRS)	75.00	1 UNIT	75.00	✓
			240.00	240.00
Labour				
40 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
41 REMOVE & REFIX TAILGATE ASSY,REAR WIPER ASSY,REAR LOCK ASSY,TAILLAMPS,REAR BUMPER,BRACKETS,REAR NUMBER PLATE LAMP,CUT,WELD & RENEW REAR PANEL,STRAIGHTEN,KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT,TAILLAMP PANEL,REAR BOTH FENDERS & REALIGN THE SAME	1,200.00	1 LA	1,200.00	1000
42 REMOVE & REFIX REAR SEAT,CARPET,GARNISH,TOP ROOF LINING,ETC	120.00	1 LA	120.00	✓
43 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,REAR FENDERS,REAR BUMPER,REAR PANEL,TAILGATE & REAR AFFECTED AREAS	1,000.00	1 LA	1,000.00	900
44 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	60.00	1 LA	60.00	✓
45 REMOVE & REFIX REAR EXHAUST,STRAIGHTEN & CHECK SYSTEM	60.00	1 LA	60.00	✓
46 REMOVE & REFIX FRT BUMPER ASSY,REINFORCEMENT,FOG LAMPS,GRILLE, BONNET & ATTACHMENT,SUPPORT PANEL,FRT FENDERS,RADIATOR & MOTOR,BONNET & ATTACHMENT,KNOCK & REPAIR FRT RH FENDER,BONNET HINGES,FRT RH MAIN CHASSIS & REALIGN THE SAME	980.00	1 LA	980.00	800
47 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
48 PUTTY & RESPRAY ON BONNET,HINGES,FRT BUMP[ER TOP,LOWER,FRT FENDERS	980.00	1 LA	980.00	800
49 REMOVE & REFIX SMART KEY SENSOR & RESET SYSTEM	120.00	1 LA	120.00	✓
50 RUSTPROOFING	90.00	1 LA	90.00	✓
			4,830.00	4,830.00
			Total	S\$ 24,614.25
			Add GST @ 7%	1,723.00
			Total Amount Payable	S\$ 26,337.25

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

SLR 7101R

TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

Estimate No: ES1890485/YISHUN
 Date: 30 Apr 2018
 Policy No: C/NOTE : C0075076
 Veh Reg No: SLR7101J
 Make/Model: SSANGYONG TIVOLI
 1.6G 6AT ABS 2WD E4
 Chassis No: KPT30B1VSH164227
 Engine No: 17391002090203
 Reg. Date: 24/08/2017

WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 20/04/2018
 TP Veh Reg No: SLN5118X

Estimate Repair Cost to Vehicle No :SLR7101J

PAGE:1/2

Description	U/Price	Quantity	List Price	Amount
Net Price			SS	SS
1 FRONT BUMPER	764.22	1 PC	764.22	✓
2 FRONT BUMPER REINFORCEMENT	461.10	1 PC photo ✓	461.10	✓
3 FRONT BUMPER SPONGE	154.14	1 PC photo ✓	154.14	✓
4 FRONT BUMPER CENTRE LOWER GRILLE	192.36	1 PC	192.36	✓
5 FRONT BUMPER INNER LOWER GARNISH	80.07	1 PC	80.07	✓
6 FRONT BUMPER SIDE LOWER SKIRT	127.24	2 PCS	254.48	✓
7 FRONT BUMPER FOG LAMPS	292.96	2 PCS	585.92	✓
8 FRONT BUMPER CLIPS	4.20	8 PCS	33.60	✓
9 FRONT GRILLE	240.45	1 PC	240.45	✓
10 FRONT GRILLE LOGO	89.10	1 PC	89.10	✓
11 FRONT GRILLE CLIPS	4.05	3 PCS	12.15	✓
12 HEADLAMPS	2,919.72	2 PCS photo ✓	5,839.44	✓
13 AIR-CON CONDENSER	1,403.52	1 PC photo ✓	1,403.52	✓
14 RADIATOR	1,184.56	1 PC " ✓	1,184.56	✓
15 FRT SUPPORT PANEL	1,711.50	1 PC	1,711.50	✓
16 FRONT SUPPORT PANEL LH INNER SPONGE	108.24	1 PC photo ✓	108.24	✓
17 REAR BUMPER	770.92	1 PC	770.92	✓
18 REAR BUMPER REINFORCEMENT	570.98	1 PC	570.98	✓
19 REAR BUMPER REFLECTORS	49.59	2 PCS	99.18	✓
20 REAR REVERSE LAMP	193.10	1 PC	193.10	✓
21 REAR BUMPER CLIPS	4.20	6 PCS	25.20	✓
22 REAR TAILGATE	2,598.48	1 PC	2,598.48	✓
23 TAILGATE EMBLEM (SSANGYONG)	55.68	1 PC	55.68	✓
24 TAILGATE EMBLEM (TIVOLI)	57.21	1 PC	57.21	✓
25 TAILGATE LOGO	185.34	1 PC	185.34	✓
26 TAILGATE INNER LOCK	124.90	1 PC	124.90	✓
27 TAILGATE INNER RUBBER	277.15	1 PC	277.15	✓
28 REAR PANEL	599.24	1 PC	599.24	✗
29 REAR PANEL INNER TOP GARNISH	89.29	1 PC	89.29	✓
30 REAR LH FENDER INNER GARNISH	536.35	1 PC	536.35	✓
31 REAR LH FENDER ARP GARNISH	153.12	1 PC	153.12	✓
32 REAR TOW COVER	40.75	1 PC	40.75	✗
33 REAR SMART KEY ANTENNA	189.45	1 PC	189.45	✗
34 BONNET	1,956.44	1 PC	1,956.44	✓
35 REAR NUMBER PLATE LAMPS	39.10	2 PCS	78.20	✓
			21,715.83	
		Less 10%	2,171.58	19,544.25

Park 420886.39

2A, 614.25

20

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
 TEL: 64193000 FAX: 64153727
 ATTN: Motor Claim Department

WS Ref: TP/AIG/YS
 Claim Type: Third Party
 Accident Date: 20/04/2018
 TP Veh Reg No: SLN5118X

Estimate No: ES1890485/YISHUN
 Date: 30 Apr 2018
 Policy No: C/NOTE : C0075076
 Veh Reg No: SLR7101J
 Make/Model: SSANGYONG TIVOLI
 1.6G 6AT ABS 2WD E4
 Chassis No: KPT30B1VSHPI64227
 Engine No: 17391002090203
 Reg. Date: 24/08/2017

Estimate Repair Cost to Vehicle No :SLR7101J

PAGE:2/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
Special Net				
36 REAR SPARE TYRE PANEL TOP COAT	80.00	1 PC	80.00 ✓	
37 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00 ✓	
38 FRONT NUMBER PLATE	45.00	1 PC	45.00 ✓	
39 COOLANT (3 LTRS)	75.00	1 UNIT	75.00 ✓	
			240.00	240.00
Labour				
40 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00 ✓	
41 REMOVE & REFIX TAILGATE ASSY,REAR WIPER ASSY,REAR LOCK ASSY,TAILLAMPS,REAR BUMPER,BRACKETS,REAR NUMBER PLATE LAMP,CUT,WELD & RENEW REAR PANEL,STRAIGHTEN,KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT,TAILLAMP PANEL,REAR BOTH FENDERS & REALIGN THE SAME	1,200.00	1 LA	1,200.00 1000	
42 REMOVE & REFIX REAR SEAT,CARPET,GARNISH,TOP ROOF LINING,ETC	120.00	1 LA	120.00 ✓	
43 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,REAR FENDERS,REAR BUMPER,REAR PANEL,TAILGATE & REAR AFFECTED AREAS	1,000.00	1 LA	1,000.00 900	
44 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	60.00	1 LA	60.00 ✓	
45 REMOVE & REFIX REAR EXHAUST,STRAIGHTEN & CHECK SYSTEM	60.00	1 LA	60.00 ✓	
46 REMOVE & REFIX FRT BUMPER ASSY,REINFORCEMENT,FOG LAMPS,GRILLE, BONNET & ATTACHMENT,SUPPORT PANEL,FRT FENDERS,RADIATOR & MOTOR,BONNET & ATTACHMENT,KNOCK & REPAIR FRT RH FENDER,BONNET HINGES,FRT RH MAIN CHASSIS & REALIGN THE SAME	980.00	1 LA	980.00 800	
47 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00 ✓	
48 PUTTY & RESPRAY ON BONNET,HINGES,FRT BUMP[ER TOP,LOWER,FRT FENDERS	980.00	1 LA	980.00 800	
49 REMOVE & REFIX SMART KEY SENSOR & RESET SYSTEM	120.00	1 LA	120.00 ✓	
50 RUSTPROOFING	90.00	1 LA	90.00 ✓	
			4,830.00	4,830.00
			Total	S\$ 24,614.25
			Add GST @ 7%	1,723.00
			Total Amount Payable	S\$ 26,337.25

less 10%
 #20886.39
 2088.64
 #18797.76
 240 SN
 4120
 #23,207.76

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

Enquire Vehicle & Owner Information (Vehicle No. SLN5118X As At 20 Apr 2018 / 08:40:00)

Law Firm Search Details

Search Reason: Insurance claim in relation to traffic accident

Law Firm Case No.: CHM-SLR7101

Current Owner Details

Owner ID Type: Singapore NRIC

Owner ID: S8211474B

Owner Name: LIM CHONG CHEE (LIN ZHONGJI)

Registered Address Type: Private Residential (Condo Apt or House) / Shopping / Office Complexes

Registered Block/House No.:64

Registered Street Name: RIVERINA VIEW

Registered Unit No.: -

Registered Building Name: -

Registered Postal Code: 518413

Current Vehicle Details

Vehicle No.: SLN5118X

Make Description/Model: SUBARU / FORESTER 2.0I-L CVT AWD SR

Insurance Company Name: AIG ASIA PACIFIC INSURANCE PTE. LTD.

Mei Kwan (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Friday, 27 April, 2018 4:24 PM
To: 'Supramaniam, Darshene'; assignments; Admin A
Cc: 'Tan, Lily (AIG)'; 'Fong, Andy-SY'; 'Kaur, Baljit'; 'Lim, Sheng Yang'; 'Chan, Yoke Shi'; 'Chin, Lee-Ying'; 'Abu Kassim, Noor Mariesa'; 'Fan, Winnie-LW'; 'Md Ishak, Mohd Imran'
Subject: RE: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING MOTOR VEHICLES NO SLN5118X AND SLR7101J ON 20 APRIL 2018

Follow Up Flag: Follow up
Flag Status: Completed

Categories: HMK

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Supramaniam, Darshene [mailto:Darshene.Supramaniam@aig.com]
Sent: Friday, 27 April, 2018 4:12 PM
To: 'admin-a@lkkauto.com'; 'assignments@lkkauto.com'
Cc: Tan, Lily (AIG) <Lily.Tan@aig.com>; Fong, Andy-SY <Andy-SY.Fong@aig.com>; Kaur, Baljit <Baljit.Kaur@aig.com>; Lim, Sheng Yang <ShengYang.Lim@aig.com>; Chan, Yoke Shi <yokeshi.chan@aig.com>; Chin, Lee-Ying <Lee-Ying.Chin@aig.com>; Abu Kassim, Noor Mariesa <NoorMariesa.AbuKassim@aig.com>; Fan, Winnie-LW <Winnie-LW.Fan@aig.com>; Md Ishak, Mohd Imran <Imran.Ishak@aig.com>
Subject: FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING MOTOR VEHICLES NO SLN5118X AND SLR7101J ON 20 APRIL 2018

Hi,

Please refer to the enclosed request from **Cheng Hoe Motor Pte Ltd**

Kindly carry out Policy coverage verification first before conducting the pre-repair inspection within 48 hours

If you have any queries/concerns, please let us know.

Kindly assist to assign **Kenneth Kong** as Single Joint Expert as requested.

Thank you.

Best Regards,

Enquire PARF/COE Rebate for Registered VehicleSLR7101J
7P/AG**Vehicle Owner Particulars**

Owner ID Type: Business
Owner ID: 9034W

Vehicle Details

Vehicle No.: SLR7101J
Vehicle to be Exported: No
Intended De-registration Date: 20 Apr 2018
Vehicle Make: SSANGYONG
Vehicle Model: TIVOLI 1.6G 6AT ABS 2WD E4
Primary Colour: White
Manufacturing Year: 2017
Engine No.: 17391002090203
Chassis No.: KPT30B1VSHP164227
Maximum Power Output: 94.1 kW (126 bhp)
Open Market Value: \$17,380.00
Original Registration Date: 24 Aug 2017
First Registration Date: 24 Aug 2017
Transfer Count: 0
Actual ARF Paid: \$17,380.00

Intended PARF Rebate Details
PARF Eligibility: Yes
PARF Eligibility Expiry Date: 23 Aug 2027
PARF Rebate Amount: \$13,035.00

Intended COE Rebate Details
COE Expiry Date: 23 Aug 2027
COE Category: A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years): 10
QP Paid: \$42,900.00
COE Rebate Amount: \$40,074.00
Total Rebate Amount: \$53,109.00

The information contained herein is correct as at 20 Apr 2018

OK

Print Received Message

This mail is associated with :

***SLR7101J (5720205562SG)
[SLN5118X]**

TP

KMP LEASING

Apr 20 2018 8:00AM

[LIM CHONG CHEE]

Cheng Hoe Motor Pte Ltd

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 12/11/2019 08:16 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$26134.59) - SLR7101J - Claim Handler: MdNoor, Norsiah

Approved:26134.59.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	23 Apr 2018 Edit Reg		27 Apr 2018 00:00 Edit Adj Rpt	S\$23,057.37 Edit Estimates	S\$23,057.37 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	LIM CHONG CHEE, ID: S8211474B		
Main Claimant:	KMP LEASING, Co. Reg. No.: 53369034W		
Vehicle Reg. No.:	SLR7101J	Date of Loss:	20/04/2018 08:00 - :59 [7 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 5720205562SG	Policy/Cover Note No.:	1700003503 (Comprehensive) Coverage: 06/05/2017 - 05/05/2018
Vehicle Reg. No. (Insured):	SLN5118X	Policy No. (Claimant):	C0075076
		Excess:	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by MdNoor, Norsiah]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 09/05/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (12/11/2019): Alert - Adj Mandate Approved (S\$26134.59) - SLR7101J - Claim Handler: MdNoor, No...
- AIG_SG_EXPRESS (31/10/2019): Alert - Adj Mandate Maintained - SLR7101J - Claim Handler: MdNoor, Norsiah

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SLR7101J (5720205562SG)**
[SLN5118X]
TP
KMP LEASING
Apr 20 2018 8:00AM
[LIM CHONG CHEE]
Cheng Hoe Motor Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser ▼
------------------	---------------	--------------------	--------------	--------------	------	-------------------

Letters/Correspondences				1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit	

Assessment Reports				1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	02/05/18 14:25	Accident Statement From:OD - Reg. No: SLN5118X, Claimant: LIM CHONG CHEE		Load HTM	

Photos/Images				3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/05/18 16:09	Odometer Reading		Load JPG	☒
2	07/05/18 16:09	Chassis Number		Load JPG	☒
3	07/05/18 16:10	General View		Load JPG	☒
4	07/05/18 16:10	General View		Load JPG	☒
5	07/05/18 16:10	General View		Load JPG	☒
6	07/05/18 16:10	General View		Load JPG	☒
7	07/05/18 16:10	General View		Load JPG	☒
8	07/05/18 16:10	General View		Load JPG	☒
9	07/05/18 16:10	General View		Load JPG	☒
10	07/05/18 16:10	General View		Load JPG	☒
11	07/05/18 16:10	General View		Load JPG	☒
12	07/05/18 16:10	General View		Load JPG	☒
13	07/05/18 16:10	General View		Load JPG	☒
14	07/05/18 16:10	General View		Load JPG	☒
15	07/05/18 16:10	General View		Load JPG	☒
16	07/05/18 16:10	General View		Load JPG	☒
17	07/05/18 16:10	General View		Load JPG	☒
18	07/05/18 16:10	General View		Load JPG	☒
19	07/05/18 16:10	General View		Load JPG	☒
20	07/05/18 16:10	General View		Load JPG	☒
21	07/05/18 16:10	General View		Load JPG	☒
22	07/05/18 16:10	General View		Load JPG	☒
23	07/05/18 16:10	General View		Load JPG	☒
24	07/05/18 16:10	General View		Load JPG	☒
25	07/05/18 16:10	General View		Load JPG	☒
26	07/05/18 16:10	General View		Load JPG	☒
27	07/05/18 16:10	General View		Load JPG	☒
28	07/05/18 16:10	General View		Load JPG	☒
29	07/05/18 16:10	General View		Load JPG	☒
30	07/05/18 16:10	General View		Load JPG	☒
31	07/05/18 16:10	General View		Load JPG	☒
32	07/05/18 16:10	General View		Load JPG	☒
33	07/05/18 16:10	General View		Load JPG	☒

Letters/Correspondences

No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	1 per page	Thumbnail	Print
34	07/05/18 16:10	General View	1	Load JPG	✓
35	07/05/18 16:10	General View	1	Load JPG	✓
36	07/05/18 16:10	General View	1	Load JPG	✓
37	07/05/18 16:10	General View	1	Load JPG	✓
38	07/05/18 16:10	General View	1	Load JPG	✓
39	07/05/18 16:10	General View	1	Load JPG	✓
40	07/05/18 16:10	General View	1	Load JPG	✓
41	07/05/18 16:10	General View	1	Load JPG	✓
42	07/05/18 16:10	General View	1	Load JPG	✓
43	07/05/18 16:10	General View	1	Load JPG	✓
44	07/05/18 16:10	General View	1	Load JPG	✓
45	07/05/18 16:10	General View	1	Load JPG	✓
46	07/05/18 16:10	General View	1	Load JPG	✓
47	07/05/18 16:10	General View	1	Load JPG	✓
48	07/05/18 16:10	General View	1	Load JPG	✓
49	07/05/18 16:10	General View	1	Load JPG	✓
50	07/05/18 16:10	General View	1	Load JPG	✓
51	07/05/18 16:10	General View	1	Load JPG	✓
52	07/05/18 16:10	General View	1	Load JPG	✓
53	07/05/18 16:10	General View	1	Load JPG	✓
54	07/05/18 16:10	General View	1	Load JPG	✓
55	07/05/18 16:10	General View	1	Load JPG	✓
56	07/05/18 16:10	General View	1	Load JPG	✓
57	07/05/18 16:10	General View	1	Load JPG	✓
58	07/05/18 16:10	General View	1	Load JPG	✓
59	07/05/18 16:10	General View	1	Load JPG	✓
60	07/05/18 16:10	General View	1	Load JPG	✓
61	07/05/18 16:10	General View	1	Load JPG	✓
62	07/05/18 16:10	General View	1	Load JPG	✓
63	07/05/18 16:10	General View	1	Load JPG	✓
64	07/05/18 16:10	General View	1	Load JPG	✓
65	07/05/18 16:10	General View	1	Load JPG	✓
66	07/05/18 16:10	General View	1	Load JPG	✓
67	07/05/18 16:10	General View	1	Load JPG	✓
68	07/05/18 16:10	General View	1	Load JPG	✓
69	31/10/19 14:14	Reinspection Photo	1	Load JPG	✓
70	31/10/19 14:14	Reinspection Photo	1	Load JPG	✓
71	31/10/19 14:14	Reinspection Photo	1	Load JPG	✓
72	31/10/19 14:14	Reinspection Photo	1	Load JPG	✓
73	31/10/19 14:14	Reinspection Photo	1	Load JPG	✓
74	31/10/19 14:14	Reinspection Photo	1	Load JPG	✓
75	31/10/19 14:14	Reinspection Photo	1	Load JPG	✓
76	31/10/19 14:14	Reinspection Photo	1	Load JPG	✓
77	31/10/19 14:14	Reinspection Photo	1	Load JPG	✓
78	31/10/19 14:14	Reinspection Photo	1	Load JPG	✓
79	31/10/19 14:14	Reinspection Photo	1	Load JPG	✓

Documentation

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	1 per page	Thumbnail	Print
1	27/04/18 17:51	EMAIL PRS	1	Load PDF	
2	27/04/18 17:51	ACKNOWLEDGEMENT EMAIL TO AIG DD 27.04.2018	1	Load PDF	
3	27/04/18 17:51	TP GIA REPORT	1	Load PDF	
4	07/05/18 16:08	LETTER TO OI	1	Load PDF	
5	30/08/19 17:14	TP ESTIMATE - MARKED	1	Load PDF	
6	15/10/19 17:22	LOD	1	Load PDF	

Letters/Correspondences			1 per page ▼	☒
No.	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
7	15/10/19 17:22	RENTAL RECEIPT		Load PDF
8	15/10/19 17:22	LTA SEARCH		Load PDF
9	19/11/19 13:15	AUTHORISATION TO ACT		Load PDF
10	19/11/19 13:15	RELEASE VOUCHER		Load PDF
11	19/11/19 13:15	WORKSHOP INVOICE		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLN5118X (Insd veh)	Model:	SSANGYONG TIVOLI 1.6 G 6AT
	SLR7101J (TP veh)		ABS 2WD (A)
Date of Accident:	20/04/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		26,337.25
Final Repair Cost	:	\$		24,671.39
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		1,455.20
LTA / GIA Search Fee	:	\$		8.00
Others:	:	\$		
	:	\$		
Final Settlement Sum	:	\$		26,134.59

Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: 28

BOLA Liability: 100 (%) Assessed Liability (*): 100 (%)

** Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.*

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Cheng Hoe Motor Pte Ltd	:	\$ 26,134.59
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

19 Nov

2019

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG18007824/KHA3S2
Date: 19/11/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700003503
Claimant Vehicle No : SLR7101J **Insured Vehicle No :** SLN5118X
Date of Loss: 20/04/2018 Nature of Claim: TP Claim No: 5720205562SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLR7101J**
Make & Model: SSANGYONG TIVOLI, 1.6 G 6AT ABS 2WD (A) Engine No: 17391002090203
Reg. Date: 24/08/2017 (Man. Year: 2017) Chassis No: KPT30B1VSHP164227
Colour: Metallic Pearl White Odometer: 12001 km
Engine Capacity: 1597 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16
Front Left Side: Nexen 9 mm Rear Left Side: Nexen 9 mm
Front Right Side: Nexen 9 mm Rear Right Side: Nexen 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	19,784.25	18,887.37	896.88	4.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,830.00	4,170.00	660.00	13.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	24,614.25	23,057.37	1,556.88	6.33
+ GST 7.00/7.00% (S\$)	1,723.00	1,614.02	108.98	6.33
Nett Amount (S\$)	26,337.25	24,671.39	1,665.86	6.33
+ Car Rental (16.0 x S\$85.00/day + 7.00% GST) (S\$)		1,455.20		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		26,134.59		

INSPECTION

Date of Assignment: 27/04/2018
Date Inspected: 30/04/2018 Inspected At: Cheng Hoe Motor Pte Ltd (Yishun)
Estimated Period of Repair: 12.0 days Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Adjuster: KENNETH KONG

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	764.22 FN	*764.22 FN
2	1		*FRONT BUMPER REINFORCEMENT	Bent	461.10 FN	*461.10 FN
3	1		*FRONT BUMPER SPONGE	Cracked	154.14 FN	*154.14 FN
4	1		*FRONT BUMPER CENTRE LOWER GRILLE	Missing	192.36 FN	*192.36 FN
5	1		*FRONT BUMPER INNER LOWER GARNISH	Distorted	80.07 FN	*80.07 FN
6	2		*FRONT BUMPER SIDE LOWER SKIRT	Buckled	254.48 FN	*254.48 FN
7	2		*FRONT BUMPER FOG LAMPS	Mtg Cracked	585.92 FN	*585.92 FN
8	8		*FRONT BUMPER CLIPS	Necessary	33.60 FN	*33.60 FN
9	1		*FRONT GRILLE	Mtg Cracked	240.45 FN	*240.45 FN
10	1		*FRONT GRILLE LOGO	Necessary	89.10 FN	*89.10 FN
11	3		*FRONT GRILLE CLIPS	Necessary	12.15 FN	*12.15 FN
12	2		*HEADLAMPS	Mtg Cracked	5,839.44 FN	*5,839.44 FN
13	1		*AIR-CON CONDENSER	Buckled	1,403.52 FN	*1,403.52 FN
14	1		*RADIATOR	Punctured	1,184.56 FN	*1,184.56 FN
15	1		*FRT SUPPORT PANEL	Buckled	1,711.50 FN	*1,711.50 FN
16	1		*FRONT SUPPORT PANEL LH INNER SPONGE	Cracked	108.24 FN	*108.24 FN
17	1		*REAR BUMPER	Buckled	770.92 FN	*770.92 FN
18	1		*REAR BUMPER REINFORCEMENT	Bent	570.98 FN	*570.98 FN
19	2		*REAR BUMPER REFLECTORS	Mtg Cracked	99.18 FN	*99.18 FN
20	1		*REAR REVERSE LAMP	Cracked	193.10 FN	*193.10 FN
21	6		*REAR BUMPER CLIPS	Necessary	25.20 FN	*25.20 FN
22	1		*REAR TAILGATE	Bent	2,598.48 FN	*2,598.48 FN
23	1		*TAILGATE EMBLEM (SSANGYONG)	Necessary	55.68 FN	*55.68 FN
24	1		*TAILGATE EMBLEM (TIVOLI)	Necessary	57.21 FN	*57.21 FN
25	1		*TAILGATE LOGO	Necessary	185.34 FN	*185.34 FN
26	1		*TAILGATE INNER LOCK	Dented	124.90 FN	*124.90 FN
27	1		*TAILGATE INNER RUBBER	Distorted / Dented	277.15 FN	*277.15 FN
28	1		*REAR PANEL	Repair	599.24 FN	*- FN
29	1		*REAR PANEL INNER TOP GARNISH	Dented	89.29 FN	*89.29 FN
30	1		*REAR LH FENDER INNER GARNISH	Cracked	536.35 FN	*536.35 FN
31	1		*REAR LH FENDER ARP GARNISH	Cracked	153.12 FN	*153.12 FN
32	1		*REAR TOW COVER	Serviceable	40.75 FN	*- FN
33	1		*REAR SMART KEY ANTENNA	Serviceable	189.45 FN	*- FN
34	1		*BONNET	Buckled	1,956.44 FN	*1,956.44 FN
35	2		*REAR NUMBER PLATE LAMPS	Serviceable	78.20 FN	*- FN
36	1		*REAR SPARE TYRE PANEL TOP COAT	Not Necessary	80.00 FS	*- FS
37	1		*REAR WINDSCREEN GLASS GUM	Necessary	40.00 FS	*40.00 FS
38	1		*FRONT NUMBER PLATE	Dented	45.00 FS	*45.00 FS
39	1		*UNIT COOLANT (3 LTRS)	Necessary	75.00 FS	*75.00 FS

F=Franchise part, S=SpcNett, N=NettItemDisc.

Sub Total (\$\$)	21,955.83	20,968.19
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	2,171.58	2,080.82

Total Parts (\$\$)	19,784.25	18,887.37
--------------------	-----------	-----------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE AND REFIX REAR WINDSCREEN GLASS.	New	120.00	120.00
2	REMOVE & REFIX TAILGATE ASSY, REAR WIPER ASSY, REAR LOCK ASSY, TAILLAMPS, REAR BUMPER, BRACKETS, REAR NUMBER PLATE LAMP, CUT, WELD & RENEW REAR PANEL, STRAIGHTEN, KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT, TAILLAMP PANEL, REAR BOTH FENDERS & REALIGN THE SAME.	New	1,200.00	1,000.00
3	REMOVE & REFIX REAR SEAT, CARPET, GARNISH, TOP ROOF LINING, ETC.	New	120.00	120.00
4	PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR FENDERS, REAR BUMPER, REAR PANEL, TAILGATE & REAR AFFECTED AREAS.	New	1,000.00	900.00
5	REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM.	New	60.00	60.00
6	REMOVE & REFIX REAR EXHAUST, STRAIGHTEN & CHECK SYSTEM.	New	60.00	60.00
7	REMOVE & REFIX FRT BUMPER ASSY, REINFORCEMENT, FOG LAMPS, GRILLE, BONNET & ATTACHMENT, SUPPORT PANEL, FRT FENDERS, RADIATOR & MOTOR, BONNET & ATTACHMENT, KNOCK & REPAIR FRT RH FENDER, BONNET HINGES, FRT RH MAIN CHASSIS & REALIGN THE SAME.	New	980.00	800.00
8	REMOVE AND REFIX AIRCON, CHECK VACUUM & REFILL GAS.	New	100.00	100.00
9	PUTTY & RESPRAY ON BONNET, HINGES, FRT BUMPER TOP, LOWER, FRT FENDERS.	New	980.00	800.00
10	REMOVE & REFIX SMART KEY SENSOR & RESET SYSTEM.	New	120.00	120.00
11	RUSTPROOFING.	New	90.00	90.00
Gross Labour Cost (\$\$)			4,830.00	4,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >