

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SLR 7101R
TP/AIG

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY
#07-16 AIG BUILDING
SINGAPORE 079120

TEL: 64193000

FAX: 64153727

ATTN: Motor Claim Department

Estimate No: ES1890485/YISHUN

Date: 30 Apr 2018

Policy No: C/NOTE : C0075076

Veh Reg No: SLR7101J

Make/Model: SSANGYONG TIVOLI
1.6G 6AT ABS 2WD E4

Chassis No: KPT30B1VSHP164227

Engine No: 17391002090203

Reg. Date: 24/08/2017

WS Ref: TP/AIG/YS

Claim Type: Third Party

Accident Date: 20/04/2018

TP Veh Reg No: SLN5118X

Not Authorized

Repair B4 paint

8 23, 057.37

12 days

Estimate Repair Cost to Vehicle No :SLR7101J

PAGE:1/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
Net Price				
1 FRONT BUMPER	764.22	1 PC	764.22	✓
2 FRONT BUMPER REINFORCEMENT	461.10	1 PC	461.10	7✓
3 FRONT BUMPER SPONGE	154.14	1 PC	154.14	7✓
4 FRONT BUMPER CENTRE LOWER GRILLE	192.36	1 PC	192.36	✓
5 FRONT BUMPER INNER LOWER GARNISH	80.07	1 PC	80.07	✓
6 FRONT BUMPER SIDE LOWER SKIRT	127.24	2 PCS	254.48	✓
7 FRONT BUMPER FOG LAMPS	292.96	2 PCS	585.92	✓
8 FRONT BUMPER CLIPS	4.20	8 PCS	33.60	✓
9 FRONT GRILLE	240.45	1 PC	240.45	✓
10 FRONT GRILLE LOGO	89.10	1 PC	89.10	✓
11 FRONT GRILLE CLIPS	4.05	3 PCS	12.15	✓
12 HEADLAMPS	2,919.72	2 PCS	5,839.44	✓
13 AIR-CON CONDENSER	1,403.52	1 PC	1,403.52	✓
14 RADIATOR	1,184.56	1 PC	1,184.56	✓
15 FRT SUPPORT PANEL	1,711.50	1 PC	1,711.50	✓
16 FRONT SUPPORT PANEL LH INNER SPONGE	108.24	1 PC	108.24	✓
17 REAR BUMPER	770.92	1 PC	770.92	✓
18 REAR BUMPER REINFORCEMENT	570.98	1 PC	570.98	✓
19 REAR BUMPER REFLECTORS	49.59	2 PCS	99.18	✓
20 REAR REVERSE LAMP	193.10	1 PC	193.10	✓
21 REAR BUMPER CLIPS	4.20	6 PCS	25.20	✓
22 REAR TAILGATE	2,598.48	1 PC	2,598.48	✓
23 TAILGATE EMBLEM (SSANGYONG)	55.68	1 PC	55.68	✓
24 TAILGATE EMBLEM (TIVOLI)	57.21	1 PC	57.21	✓
25 TAILGATE LOGO	185.34	1 PC	185.34	✓
26 TAILGATE INNER LOCK	124.90	1 PC	124.90	✓
27 TAILGATE INNER RUBBER	277.15	1 PC	277.15	✓
28 REAR PANEL	599.24	1 PC	599.24	X
29 REAR PANEL INNER TOP GARNISH	89.29	1 PC	89.29	✓
30 REAR LH FENDER INNER GARNISH	536.35	1 PC	536.35	✓
31 REAR LH FENDER ARP GARNISH	153.12	1 PC	153.12	✓
32 REAR TOW COVER	40.75	1 PC	40.75	X
33 REAR SMART KEY ANTENNA	189.45	1 PC	189.45	X
34 BONNET	1,956.44	1 PC	1,956.44	✓
35 REAR NUMBER PLATE LAMPS	39.10	2 PCS	78.20	X
			21,715.83	
			Less 10%	2,171.58
				19,544.25

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S : AIG ASIA PACIFIC INSURANCE PTE LTD
 78 SHENTON WAY
 #07-16 AIG BUILDING
 SINGAPORE 079120
TEL: 64193000 **FAX:** 64153727
ATTN: Motor Claim Department

WS Ref: TP/AIG/YS
Claim Type: Third Party
Accident Date: 20/04/2018
TP Veh Reg No: SLN5118X

Estimate No: ES1890485/YISHUN
Date: 30 Apr 2018
Policy No: C/NOTE : C0075076
Veh Reg No: SLR7101J
Make/Model: SSANGYONG TIVOLI
 1.6G 6AT ABS 2WD E4
Chassis No: KPT30B1VSHP164227
Engine No: 17391002090203
Reg. Date: 24/08/2017

Estimate Repair Cost to Vehicle No :SLR7101J

PAGE:2/2

Description	U/Price	Quantity	List Price S\$	Amount S\$
Special Net				
36 REAR SPARE TYRE PANEL TOP COAT	80.00	1 PC	80.00	X
37 REAR WINDSCREEN GLASS GUM	40.00	1 PC	40.00	✓
38 FRONT NUMBER PLATE	45.00	1 PC	45.00	✓
39 COOLANT (3 LTRS)	75.00	1 UNIT	75.00	✓
			240.00	240.00
Labour				
40 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
41 REMOVE & REFIX TAILGATE ASSY,REAR WIPER ASSY,REAR LOCK ASSY,TAILLAMPS,REAR BUMPER,BRACKETS,REAR NUMBER PLATE LAMP,CUT,WELD & RENEW REAR PANEL,STRAIGHTEN,KNOCK & REPAIR REAR SPARE TYRE COMPARTMENT,TAILLAMP PANEL,REAR BOTH FENDERS & REALIGN THE SAME	1,200.00	1 LA	1,200.00	1000
42 REMOVE & REFIX REAR SEAT,CARPET,GARNISH,TOP ROOF LINING,ETC	120.00	1 LA	120.00	✓
43 PUTTY & RESPRAY ON REAR SPARE TYRE COMPARTMENT,REAR FENDERS,REAR BUMPER,REAR PANEL,TAILGATE & REAR AFFECTED AREAS	1,000.00	1 LA	1,000.00	900
44 REMOVE & REFIX REVERSE CAMERA & RESET SYSTEM	60.00	1 LA	60.00	✓
45 REMOVE & REFIX REAR EXHAUST,STRAIGHTEN & CHECK SYSTEM	60.00	1 LA	60.00	✓
46 REMOVE & REFIX FRT BUMPER ASSY,REINFORCEMENT,FOG LAMPS,GRILLE, BONNET & ATTACHMENT,SUPPORT PANEL,FRT FENDERS,RADIATOR & MOTOR,BONNET & ATTACHMENT,KNOCK & REPAIR FRT RH FENDER,BONNET HINGES,FRT RH MAIN CHASSIS & REALIGN THE SAME	980.00	1 LA	980.00	800
47 REMOVE AND REFIX AIRCON,CHECK,VACUUM & REFILL GAS	100.00	1 LA	100.00	✓
48 PUTTY & RESPRAY ON BONNET,HINGES,FRT BUMP[ER TOP,LOWER,FRT FENDERS	980.00	1 LA	980.00	800
49 REMOVE & REFIX SMART KEY SENSOR & RESET SYSTEM	120.00	1 LA	120.00	✓
50 RUSTPROOFING	90.00	1 LA	90.00	✓
			4,830.00	4,830.00
			Total	S\$ 24,614.25
			Add GST @ 7%	1,723.00
			Total Amount Payable	S\$ 26,337.25

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE