



HUA HONG PRIVATE LIMITED

25D Sungei Kadut Street 1 Singapore 729332
Tel: (65) 6661 9688 Fax: (65) 6661 9699 Email: info@huahong.com.sg

Estimate Repair List

7 June 2018

HHTPClaims18-38

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#09-16 AIG Building
Singapore 079120

ACCIDENT INVOLVING SLW 4422 B & SLN 8891 B ON 22/04/2018 ALONG FULLERTON ROAD AT ABOUT 1505 HOURS

Insured : HUA HONG PTE LTD
Vehicle Registration No : SLW 4422 B
Vehicle Make : TOYOTA
Vehicle Model : C-HR HYBRID 1.8S CVT
Vehicle Chassis No : ZYX102078427
Policy No : 5087272209-01
Date of Accident : 22/04/2018

Type of Claim: Third Party

S/N	Quantity	Description	Unit Price S\$	Amount S\$
1	1	Rear Bumper		\$ 950.00 <i>repair</i>
2	1	Rear Bumper Lower Garnish		\$ 650.00 <i>cut</i>
3	10	Rear Bumper Clip		\$ 30.00 <i>new</i>
4	2	Rear Bumper Retainer (LH/RH)		\$ 130.00 <i>new</i>
5	1	Rear Reinforcement		\$ 520.00 <i>1.6t</i>
				\$ 2,280.00
			Less 20% <i>25%</i>	\$ (456.00)
				\$ 1,824.00
6	1	Rear Reverse Sensor		\$ 200.00 <i>? new</i>
		To dismantle & change rear bumper, rear bumper lower garnish, rear reinforcement, knocking & pull straight rear panel		\$ 800.00 <i>300</i>
		To perform wire checking		\$ 20.00
		To dismantle & refit rear bumper sensor		\$ 60.00 <i>40</i>
		To spray rear bumper, rear reinforcement & rear panel		\$ 800.00 <i>250</i>
				\$ 3,704.00
			7% GST	\$ 259.28
			Total	\$ 3,963.28

Authorised by Claims Dept
Mrs Tan @ 9639 9195



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No work done until payment is received
- Shop is to be used for the purpose of repair only
- Subject to the terms and conditions of the contract

Acknowledged by Repairer
Signature:
Date: