



EUROKARS HABITAT PTE LTD
NO:12 SUNGEI KADUT, SINGAPORE 729648
ESTIMATE COST OF REPAIRS



India International Insurance #04-05 Iob Building, 64 Cecil St, 049711		NAME : Ms LMA Lau ADDRESS : 59 Pasir Ris Drive 1 #05-14 Singapore 519532 TEL :		WIP : 18382 EXCESS : DATE: 28.04.2018	
ATTN. : MOTOR CLAIMS FAX :					
VEH NO :	SDR225B	DATE IN :		CONTACT PERSON :	JOB THOMAS 6360 2446
CHASSIS NO :	WMWXM720902A77303	MILEAGE :		TYPE OF CLAIM :	TP
MODEL :	F56 MINI Cooper S	DATE REG.:	15.01.2016	POLICY NO. :	

NATURE OF WORKS

S/NO	Parts Description				
	QTY			REVISED	PRICES
1	BONNET F56 COOPER S ✓ DT	1	M41.00.7.374.520		\$ 1,481.94
2	BONNET ADJUSTER ✓ NEC	1	B51.76.7.183.752		\$ 7.69
3	BONNET TWIST PROTECTION ✓ NEC	2	M51.23.7.300.579		\$ 17.50
4	BONNET AIR SCOOP ✓ NEC	1	M51.13.7.376.052		\$ 134.00
5	HEADLAMP TRIM RING LH ✓ NEC	1	M51.13.7.300.631		\$ 68.94
6	HEADLAMP TRIM RING RH ✓ NEC	1	M51.13.7.300.632		\$ 68.94
7	HEADLAMP TRIM RING CLIPS ✓ NEC	12	M51.13.2.752.145		\$ 44.28
8	FRONT BUMPER R	1	M51.77.7.382.164		\$ 884.44
9	FRONT BUMPER SUPPORT LH ?	1	M51.11.7.360.741		\$ 70.44
10	FRONT BUMPER GASKET ✓ NEC	4	M51.11.7.380.443		\$ 94.00
11	FRONT BUMPER TRIM CHROME ?	1	M51.13.7.300.589		\$ 126.38
12	FRONT BUMPER RAIDIATOR GRILLE BLACK X	1	M51.13.7.335.528		\$ 210.56
13	FRONT BUMPER CENTER COVER GLOSSY BLACK X	1	M51.11.7.337.791		\$ 119.19
14	FRONT BUMPER AIR INLET LH X	1	M51.11.7.355.239		\$ 47.13
15	FRONT BUMPER SIDE SPOILER LH ✓ cut	1	M51.11.7.360.743		\$ 86.19
16	FRONT WHEEL ARCH COVER LH ✓ cut	1	M51.77.7.300.819		\$ 169.63
17	MINI LOGO ✓ NEC	1	M51.14.7.316.703		\$ 73.88
18	FRONT FENDER INNER SHIELD LH ?	1	M51.71.7.319.759		\$ 143.75
19	FRONT FENDER INNER SHIELD EXPANDING RIVETS R ✓ NEC	2	B07.14.7.136.172		\$ 1.88
20	FRONT FENDER INNER SHIELD EXPANDING NUT R ✓ NEC	8	B07.14.7.201.307		\$ 13.52
21	FRONT FENDER LH ✓ DT	1	M41.00.7.374.521		\$ 492.63
22	HEADLAMP BRACKET LH ✓ NEC	1	M51.64.7.301.599		\$ 70.44
23	HEADLAMP LH ✓ CRK	1	M63.11.7.383.211		\$ 2,329.81
24	HEADLAMP RH X	1	M63.11.7.383.212		\$ 2,329.81
25	FOGLAMP LH ?	1	M63.17.7.329.171		\$ 483.19
26	HEADLAMP LOCKING NUT ✓ NEC	6	M07.14.9.310.339		\$ 69.78
27	COOLANT LABEL ✓ NEC	1	M71.23.6.992.810		\$ 29.75
	TOTAL PARTS				\$ 9,669.69
					\$ -
	TOTAL PARTS COST				\$ 9,669.69
	Labour Description				
1	TO REPLACE BONNET, FRONT BUMPER, LH FRONT FENDER. TO REPAIR ALL				\$ 2,940.00
	AREAS AFFECTED BY THE ACCIDENT. 840/day				1680

	800 / pc, ne		2400
2	TO RESPRAY BONNET, FRONT BUMPER, LH FRONT FENDER.		\$ 2,600.00
			150
3	TO CARRY-OUT BODY CAVITY PRESERVATION.		\$ 250.00
4	TO REPAIR & RESPRAY 1 PC SPORT RIM	NETT	\$ 800.00 ✓
5	TO CHECK STEERING GEOMETRY & CONDUCT FULL WHEEL ALIGNMENT.	NETT	\$ 560.00 ✓
6	TO INSTALL THE FRONT BONNET STICKER.	NETT	\$ 350.00 ✓
			180
7	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 250.00
			280
8	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.		\$ 350.00
			50
9	SUNDRIES.	NETT	\$ 100.00
		TOTAL LABOUR	\$ - \$ 8,200.00
		TOTAL PARTS	\$ - \$ 9,669.69
		TOTAL	\$ - \$ 17,869.69
		LESS EXCESS	\$ - \$ -
		TOTAL AFTER EXCESS	\$ -
		GST 7%	\$ - \$ -
		GRAND TOTAL	\$ - \$ -

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

6 - 7 days.

Sebastian.

2/5/18.

- Part by part repair.
 - Question Mark Item Photo.
 - Photo Before Paint
- 90036121

sebastianyang@lkkauto.com.

LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:
--