

1st Autoworks Pte Ltd
23 Kaki Bukit Ave 4, #04-01 (South Wing) Singapore 415933

Repair Estimate

Date : 30/4/2018

Reference: SLP8433E
CHEVROLET
ORLANDO
Make: 1.4AT TURBO

TPALG.

VIC

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SLP8433E
CHASSIS NO.: KL1YA7589HK616032
ENGINE NO.: A14NET170200734

Name of insured : Tan Kheng Kee
Date of accident : 22/04/2018

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts

No.	Qty	Part Description	Price (SGD)
1	1	Front Bumper Emblem <i>new</i>	\$ 181.00
2	1	Front Bumper Upper <i>Rehd</i>	\$ 1,750.00
3	1	Front Radiator Grille <i>new</i>	\$ 355.00
4	1	Front License Plate Bracket <i>new</i>	\$ 40.00
5	1	Front Bumper Lower <i>2</i>	\$ 508.00
6	1	Front Bumper Sill Plate <i>M</i>	\$ 381.00
7	1	Front Bumper Lower Grille <i>n</i>	\$ 201.00
8	1	LHF Foglamp Cover	\$ 55.00
9	1	LHF Foglamp	\$ 377.00
10	1	Front Bumper Absorber	\$ 150.00
11	1	Front Bumper Reinforcement Bar <i>2 new</i>	\$ 1,060.00
12	1	LHF Bumper Bracket - Guide <i>new</i>	\$ 65.00
13	1	RHF Bumper Bracket - Guide	\$ 65.00
14	1	LHF Bumper Bracket - Support	\$ 65.00
15	1	RHF Bumper Bracket - Support	\$ 65.00

1931

1737.90

Parts Total: \$ 5,318.00
Less 10%: \$ 531.80
Total : \$ 4,786.20

Labour

Labour Description

No.

Price (SGD)

Front portion

1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts. (\$550 per day)	\$ 1,650.00
2	Carry out spray painting on accident affected area (\$450 per panel)	\$ 1,350.00
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	\$ 30.00

580
450
✓

1030

Labour Total : \$ 3,030.00

Others

Other Description

No. Qty

Price (SGD)

Front portion

1	1	Number plate with casement	\$ 45.00
2	10	Front bumper clip	\$ 65.00

✓
30

75

Other Total: \$ 110.00

GRAND TOTAL: \$ 7,926.20

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully



Suhaimi Ong

Service Executive
Suhaimi Ong
HP : 8298 8933 Fax: 6844 5185

Adrian Lim,
P/p 30/04/18
02 days.
total: 2842.90

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: