

BMW Dealer

Performance Motors LimitedA member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)*array to 7/6/2018
meeting owner
5/6/2018
summary*

GST REG. NO : M2 - 0020081 - X

30 APR 2018

E S T I M A T E

Estimate No. : b1 46770	Page No. : 1 of 1
Date Estimated : 30/04/2018	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Wong Cher Meng Kevin Gerard 50 Bedok Terrace Singapore 469209	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO. SLG3310G	CHASSIS NO. 5B45398	REGN. DATE 28/09/2016	MODEL 216d G TOURER	MILEAGE 0
-----------------------	------------------------	--------------------------	------------------------	--------------

DESCRIPTION	VALUE		
Replace rear bumper and remove attachment etc include knock on accident dent	850 1,275.00		
Spray painting rear bumper	934 1,038.00		
To check electrical wiring systems and rear section for proper function.	150 177.00		
Sundries.	✓ 40.00		
Total Labour 1: 2,530.00			
UK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
DESCRIPTION	QTY	PRIC	VALUE
RR BUMPER LH SIDE GUIDE	1	60.00	? 60.00
RR BUMPER RH SIDE GUIDE	1	60.00	? 60.00
REAR BUMPER CARRIER	1	423.80	? 423.80
SUPPORT CENTER REAR BUMPER	1	59.25	? 59.25
REAR BUMPER TRIM STRIP (CHROM)	1	105.65	at 105.65
LEFT PROTECT	1	2.10	? 2.10
RIGHT PROTECT FOIL	1	2.10	? 2.10
REAR BUMPER PANEL PRIMED (LINES PDC	1	966.25	de 966.25
Total Parts :			1,679.15

Claims OD / 3rd Party / Uninsured losses / Direct Settlement			
Regn No.	Claim No.		
Date&Time 7/5/18 @ 11am	Excess S\$		
Surveyor's Name Tanjune	Sign		
Surveyor's Tel 97455744	Authorised Yes / No		
Authorised Date WP	Time		
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No			
Surveyor's E-mail tanjune@ukauto.com			
		Labour 1 :	2,530.00
		Parts :	1,679.15
		Labour 2 :	0.00
		Excess :	0.00
		Total GST @ 7% :	294.64
		Grand Total :	4,503.79

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **