

INS. CASE OWNER:

Priya

CC 3/III1800

7867, T1 w63

LKK:

IDAC:

Surveyor:

Yabefikh

DOI:

ASSIGNMENT

6/6/18

Date / Time:

30/4/18

Registered in Merimen:

30/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 3295K

Name of Insured:

UTP

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A:

Vetetur

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: puny 58 mui

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

MIT18040849

Policy No.:

m1800015

Make / Model:

Perumnah

Place of Accident:

Semburan EST RD

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SUR 8508m



INSRS:

WSP:

Tel:

Liability:

RMKS:

Performance



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

2/5/18
union

SHC 3295K - X

SHC 3295K - Y

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

☐☐

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 29/8/18

Confirm with: Corrin

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 27

If NO or B 28, Ass. Lia:

Repair Cost:

SS 2112.18

Loss of Rental (LOR):

SS

-

(

days)

Loss of Use (LOU):

SS 150.00

(\$50 x 3 days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only ☐ LOU only ☐☐LOR + LOU ☐☐LOR + LOI ☐☐

(Tick only one)

GIA/LTA Search

SS

-

Medical:

SS

-

Disbursement:

SS

-

Legal Cost

SS

-

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

SS 2262.18

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS 2262.18

Name 1:

Performance Motors Ltd.

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
20/8/18

RECEIVED 30 AUG 2018



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC3/III18007867/wb3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 30-04-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3295K	Veh. Inspected	SLR 8508M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	30/04/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	28/04/2018	Inspection Date		
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190160 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63448773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190538 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

30 APR 2018

Estimate No. : b1 46771 Page No. : 1 of 1
Date Estimated : 30/04/2018
Prepared By : Kevin Leong Wai Kit

- ESTIMATE REPAIR FOR -

Wang Kaifei
115 Compassvale Bow
#13-12

Singapore 544815

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLR8508M	5E91248	29/08/2017	216i G TOURER	0

DESCRIPTION

To repair on rear bumper assembly & replace all attachments cause by accident

Painting on rear bumper assembly

To check electrical wiring systems at the rear section for proper function.

Sundries.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:

Signature:

Date:

VALUE

850 1,700.00 ✓

934 1,038.00 ✓

150 177.00 ✓

? 40.00 ✓

Total Labour 1: 2,955.00

DESCRIPTION

REAR BUMPER CARRIER

SUPPORT

REAR BUMPER PANEL PRIMED (PDC)

SET MOUNTS PDC SENSOR REAR

DECOUPING RING PDC TORQUE CONVERTER

QTY PRIC

1 423.80

1 59.25

1 966.25

1 62.95

4 5.05

VALUE

RM x 423.80

RM x 59.25

RM x 966.25

RM x 62.95

RM x 20.20

Total Parts : 1,532.45

Labour 1 : 2,955.00

Parts : 1,532.45

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 314.12

Grand Total : 4,801.57

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. MU-002081-X



FINAL REPORT

Estimate No. : b1 46771
Date Estimated : 30/04/2018
Prepared By : Kevin Leong Wai Kit

Page No. :

REPAIR FOR -
Wang Kaifei
115 Compassvale Bow
#13-12

- ACCOUNT - 219
India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Singapore 544815

REGN NO	CHASSI S NO	REGN DATE	MODEL	MILEAGE		
SLR8508M	5E91248	29/08/2017	216i G TOURER	0		
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT	
To make good the rear bumper include removing attachments to facilitate repairs and knocking out dents caused by the accident.			850.00		850.00	
To spray paint rear bumper			934.00		934.00	
To check electrical wiring systems at the rear section for proper function.			150.00		150.00	
Sundries.			40.00		40.00	
DESCRIPTION			UNIT PRICE	QTY	DISC. %	NETT

SUPPLEMENTARY ITEMS

Total Labour :	1,974.00
Total Parts :	
Total Labour & Parts :	1,974.00
Deduction for Excess :	
Total Repair Costs less Excess:	1,974.00
GST @7%:	138.18
Grand Total :	2,112.18

View Received Message

This mail is associated with :

***SLR8508M (MCT18040849)**
[SHC3295K]

TP

WANG KAIFEI

Apr 28 2018 10:00AM

[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

[Reply](#) [Reply All](#) [Mark as Unread](#) [Print Message](#) [Delete Message](#) [Forward](#)

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 29/08/2018 15:16 PM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$2262.18) - SLR8508M - Claim Handler: Priya

Approved:2262.18.

DOCUMENTS SUMMARY

There are no documents.



(V V V)

India Int'l Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711
Attention: Motor Claims

"Without Prejudice"

Your Ref:

Our Ref:

Date:

Subject:

27 July 2018

ACCIDENT INVOLVING VEHICLES SLR8508M & SHC3295K ON 28.04.2018

Dear Sirs

We refer to the above matter.

The accident was caused solely by the negligence on the part of your insured. As a result of the said accident, our client has suffered losses which are set out hereunder as follows:-

Cost of repair	:	S\$	2112.18
Loss of use	:	S\$	150.00 (S\$ 50.00 x 3 days)
Total	:	S\$	2262.18

A copy of each of the following supporting documents is enclosed:

1. Copy of Accident Report
2. Copy of Final Repair bill
3. Copy of Identification Card & Driving License
4. Copy of Letter of Authorisation

Performance Motors
Limited
1800-Call-BMW
(1800-2255-269)

www.pml.com.sg

303 Alexandra Road
Sime Darby
Performance Centre
Singapore 159941
Tel Sales 6319 0100
Tel AfterSales:
6319 0111
Fax 6474 7770

315 Alexandra Road
#01-01
Sime Darby
Business Centre
Singapore 159944
Tel Sales 6319 0511
Tel AfterSales:
6319 0527
Fax 6479 6624

260
Kampong Arang Rd
East Coast Centre
Singapore 438180
Tel AfterSales:
6319 0688
Fax 6344 1332

Registered Office
305 Alexandra Road
#02-01
Vantage
Automotive Centre
Singapore 159942

Co. Reg. No.
197401559W

Please note that you or your insured should send us an acknowledgement of receipt of this letter within fourteen (14) days from the date of this letter, failing which our client will have no alternative but to commence legal proceedings against you without any further notice to you or your insured.

Should you have a counterclaim against our client arising out of the accident, you are also required to send a letter giving full particulars of the counterclaim together with all relevant supporting documents within eight (8) weeks of your receipt of this letter.

For any correspondence, please contact Ms Caroline Tan at 6319-0174 / Fax. 6479-4601 or email to pml-pbsp@sime-darby.com.sg.

Yours sincerely

Teng Wai Khan
Customer Service Manager, Body & Paint

Performance Motors Limited

A member of the Sime Darby Group



LETTER OF AUTHORISATION

ACCIDENT INVOLVING SLR 8508 M & SHC 3295K ON 28/4/18.

I, Wang Kai Fei owner of Vehicle Registration No. SLR 8508 M hereby authorise **Performance Motors Limited** to submit, correspond, negotiate and settle my claim for cost of repair and/or uninsured losses arising from the above accident.

I further authorise **Performance Motors Limited** to execute, sign, seal and deliver all documents whatsoever in relation to this matter and to accept and receive any payment due to me in respect of my claim above.

I hereby declare that all acts and documents done by virtue of this Letter of Authorisation on my behalf shall be good valid and effectual to all intents and purposes whatsoever as if the same had been done or executed by me in person.

I further confirm that the acceptance by **Performance Motors Limited** of the settlement amount in respect of such claim shall constitute the full discharge of my claim in respect of such loss and damage.

Signed by:

Name: _____ (Date)

NRIC No.:

In the presence of:

Name: Kevin Leong (Date)

NRIC No.:



In service since 1987

INTERNATIONAL INSURANCE PTE LTD

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III - Direct Settlement (PODS)

India Ref: MCI180404811
Claimant Ref: SLR 8508M

We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 2112.18 (repair cost), S\$ 150.00 (loss of use/rental), S\$ NIL (search fee), vehicle no. SLR 8508M that was damaged pursuant to the accident which occurred on 28/4/18 (date) at Song Kang East Rd (location) involving vehicle no. SHC 3295K (insured vehicle). This is pursuant to the inspection conducted on 6/6/18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Wang Kai Fei ("the third party claimant") of vehicle no. SLR 8508M to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SLR 8508M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 2262.18 to Performance Motors Limited

Dated this 29 day of 8 2018

CLAIMANT:

Signature:

Signed by "the workshop"
(with chop)

Name:

Address:

WITNESS:

Signature:

MTH
Signed by appointed Surveyor

Name:

LKK Auto Consultants Pte Ltd

Address:

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 |
S(408933)



INDIA INTERNATIONAL INSURANCE PTE LTD

CO. REG. NO.: 198703792K

64 CECIL STREET #04/#05/#06-02 IOB BUILDING SINGAPORE 049711 TEL: 6347 6100 FAX: 6224 4174 • 6225 7743 WEB: www.iii.com.sg

POSTAL ADDRESS: ROBINSON ROAD P.O. BOX NO. 738 SINGAPORE 901438

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1273582

Date IN : 07/06/2018

Cust. Svc. Advisor: Kevin Leong Wai Kit

Page No. : 1 of 1

Invoice Number : 1988879 / WSB

Invoice Date : 20/07/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Wang Kaifei
115 Compassvale Bow
#13-12

Singapore 544815

- INVOICE TO - 219

India Int'L Insurance Pte Ltd
64 Cecil Street
#04-05 IOB Building
Singapore 049711

REGN. NO.
SLR8508M

CHASSIS NO.
5E91248

REGN. DATE
29/08/2017

MODEL
216I G TOURER

MILEAGE
10626

- - - - LABOUR 1 - - - -

To make good the rear bumper including to remove and
install body parts in order to carry out painting job.

To respray rear bumper.

To check electrical wiring systems at the rear section
for proper function.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 28.4.2018. 3RD PARTY CAR : SHC3295K.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO
CONSULTANTS PTE LTD ON 6.6.2018 AT 3.50 PM. AUTHORISED
REPAIR BY MS VIVIAN LAU FROM LKK ON 4.5.2018 VIA E-MAIL.
PROPOSE LOSS OF USE = \$50X3. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

Total Labour 1: 1,974.00

- - - - LABOUR 2 - - - -

-

NETT
0.00
Total Labour 2: 0.00

Labour Charges : 1,934.00
Parts Charges : 0.00
Lubricant/Misc : 40.00

Total Labour & Parts Charges : S\$ 1,974.00
Less Insurance Excess : S\$ 0.00
Invoice Total Amount Exclude GST : S\$ 1,974.00
GST @ 7% : S\$ 138.18
Invoice Total Amount Include GST : S\$ 2,112.18

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 2,112.18

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.



...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018 Edit Reg		06 Jun 2018 00:00 Edit Adj Rpt	S\$1,974.00 Edit Estimates	S\$1,974.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS [Created by adjuster]

Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: -		
Main Claimant:	WANG KAIFEI , ID: S7980328F		
Vehicle Reg. No.:	SLR8508M	Date of Loss:	28/04/2018 10:00 - :59 [7 Months and 30 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / MCT18040849	Policy/Cover Note No.:	MCOM0015
Vehicle Reg. No. (Insured):	SHC3295K	Policy No. (Claimant):	
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Priya]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/05/2018]		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)



























- III_SG (29/08/2018): Alert - Adj Mandate Approved (S\$2262.18) - SLR8508M - Claim Handler: Priya
- III_SG (04/05/2018): Alert - Adj Mandate Approved (S\$0.00) - SLR8508M - Claim Handler: Priya

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLR8508M (MCT18040849)
[SHC3295K]
TP
WANG KAIFEI
Apr 28 2018 10:00AM
[COMFORT TRANSPORTATION PTE LTD]
Performance Motors Limited

Upload Documents			Upload Photos			Compose New Letter			View View in Browser		
Photos/Images									3 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
2	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
3	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
4	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
5	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
6	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
7	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
8	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
9	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
10	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
11	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
12	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
13	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
14	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
15	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
16	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
17	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
18	28/08/18 18:18	General View		 Load JPG	<input checked="" type="checkbox"/>						
Documentation									1 per page		<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print						
1	30/04/18 12:37	TP ESTIMATE		 Load TIF							
2	30/04/18 12:37	TP GIA REPORT		 Load PDF							
3	07/06/18 19:18	TP ESTIMATE- MARKED		 Load PDF							
4	08/08/18 17:08	WORKSHOP INVOICE		 Load PDF							
5	08/08/18 17:08	LOD		 Load PDF							
6	04/09/18 10:53	DISCHARGE VOUCHER		 Load PDF							
7	04/09/18 10:53	AUTHORISATION TO ACT FORM		 Load PDF							
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print						
1	02/05/18 08:40	Singapore Accident Statement		 Load PDF							

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling InsurerNote: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III18007867/T1WB3Q2

Date: 04/09/2018

REFERENCE

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SLR8508M	Insured Vehicle No :	SHC3295K
Date of Loss:	28/04/2018	Nature of Claim:	TP
		Claim No:	MCT18040849

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLR8508M	Engine No:	39685029B38A15A
Make & Model:	BMW 216D, 1.5 D Active Tourer (F45) (A)	Chassis No:	WBA2D920905E91248
Reg. Date:	29/08/2017 (Man. Year: 2017)	Odometer:	10626 km
Colour:	Black		
Engine Capacity:	1499 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60 R16	Rear Tyre Size:	205/60 R16
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,572.45	40.00	1,532.45	97.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,915.00	1,934.00	981.00	33.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,487.45	1,974.00	2,513.45	56.01
+ GST 7.00/7.00% (S\$)	314.12	138.18	175.94	56.01
Nett Amount (S\$)	4,801.57	2,112.18	2,689.39	56.01
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
	Nett Liability (S\$)	2,262.18		

INSPECTION

Date of Assignment:	06/06/2018	
Date Inspected:	06/06/2018 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	3.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 08 Aug 2018)
Parts: M1-MPV	BMW 216D 1.5 D Active Tourer (F45) (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLR8508M)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	40.00 FS	*40.00 FS
2	1		*REAR BUMPER CARRIER	Not Necessary	423.80 FS	*- FS
3	1		*SUPPORT	Not Necessary	59.25 FS	*- FS
4	1		*REAR BUMPER PANEL PRIMED (PDC)	Repair	966.25 FS	*- FS
5	1		*SET MOUNTS PDC SENSOR REAR	Not Necessary	62.95 FS	*- FS
6	4		*DECOUPING RING PDC TORQUE CONVERTER	Not Necessary	20.20 FS	*- FS
Total Parts (\$\$)					1,572.45	40.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPAIR ON REAR BUMPER ASSEMBLY & REPLACE ALL ATTACHMENTS CAUSE BY ACCIDENT	New	1,700.00	850.00
2	PAINTING ON REAR BUMPER ASSEMBLY	New	1,038.00	934.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
Gross Labour Cost (\$\$)			2,915.00	1,934.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >