

INS. CASE OWNER:

Bimaad.

CC3 / AIG1800

7869, T1g63/4

LKK:

IDAC:

Surveyor:

Tampin

DOI:

ASSIGNMENT

28/5/18

Date / Time:

20/4/18

Registered in Merimen:

20/4/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SBN 9766E

Name of Insured:

Mg Enk HUNT

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

26/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Mg Yong Quan MYN

Driver Tel No.:

(V/L: YES / NO)

Claim No.:

024178941056

Policy No.:

200426241

Make / Model:

LEXUS

Place of Accident:

Kluang road 1 km from

MVE ship RO

OI GIA REPORT: YES / NO

TP GIA REPORT: YES / NO

Insured Liability:

Final? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:

Pekeran



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/Time

3/5/18
77M

3/5/18 @ 2:00

spoke to OJD. he confirmed the accident details. Informed TP claim and he agree to settle.

11/11/18

Freepuse to Juma k

RECEIVED 02 OCT 2018

RECEIVED 12 DEC 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

THIN > Juma

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

Trametic

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

11/11/18

Confirm with:

Car

Email

Call

Final Liability:

SS

100

(

Agreed / Admitted)

BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

SS

12360.11

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

500.00 (\$ 100 x 5 days)

Loss of Income (LOI):

SS

(\$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

2.00

Medical:

SS

-

Disbursement:

SS

-

(e.g. Tow/ Independent)

Legal Cost

SS

-

Total:

SS

12862.11

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

12362.11

Name 1:

Performance Motors Ltd

Payee 2: (Strike if N.A.)

SS

500.00

Name 2:

Brotin Muhuri

Payee 3: (Strike if N.A.)

SS

-

Name 3:

-

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

220

Gymer

Tampah

REF:

AIG

N

ASSIGNMENT

From: Date: 28/5/18

Estimated Cost:

OD TP WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLP 2224G
at Workshop m/s Performance
of 303 Alexandra Road

Insured

Policy No

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh.

9am - 12pm
Inthiran

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS lwp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLP 2224G Yr Regn: 2017 May
Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW X3 c.c. 1997

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 7723 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WBAWY920400 X0125

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/50R18

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU (PIR) SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 0 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A.

D.O.I. 28/5/18 & 11/10

Survey held at: PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

PIP \$ 11551.50 (Red \$ 262.27 (19%))

Date/Time: File Pass to?

☐

: Preli. Report

If

☐

: Final Report

Date/Time: File Return to?

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

1. S + RS \$

2. Photos

3. Others

TOTAL

Report Format :

Lump Sum / I.B.I. : \$

Add Fee: ☐ Site Insp : \$☐ Interview : \$☐ Tech. Invs : \$☐ Weekend : \$



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC3/AIG18007869/ub3	
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 30-04-2018	
		Code : AIG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBU 9766E	Veh. Inspected	SLP 2224G
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	30/04/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	28/04/2018	Inspection Date	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

Survey only

29.05 @ 9.10pm



BMW Dealer

Performance Motors Limited

A member of the BMW Group
Co. Reg. No. 1974015598 GST Reg. No. M2-0020081-X

103, Alexandra Road
BMW Group Performance Centre
Singapore 119941
Tel: 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax: 64747770

290, Kengong Arang Road
East Coast Centre
Singapore 438180
Tel: 61180888 (AfterSales)
Fax: 61449771

310, Alexandra Road
BMW Group Business Centre
Singapore 119944
Tel: 63190528 (AfterSales)
63190533/545 (Motorcycle)
Fax: 64796661 (AfterSales)
64796624 (Motorcycle)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

30 APR 2018

Estimate No. : b1 46776

Page No. : 1 of 2

Date Estimated : 30/04/2018

Prepared By : Merina Chia San San

- ESTIMATE REPAIR FOR -

Brotin Muhuri
11 Tanjong Rhu Road
#19-04

Singapore 436896

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2224G	0X01125	29/05/2017	X3 sDrive20	0

10-17, 14

DESCRIPTION

To replace rear bumper, bootlid including attachments
etc and to knock out dented area caused by accident

VALUE

2500 3,400.00

To paint rear bumper, bootlid and tail end panel

2774 2,749.00

To check electrical wiring systems and lightings at the
rear section for proper function

150 177.00

To remove and install boot compartment carpet and garnish
to facilitate repairs

230 271.00

To carry out body cavity preservation.
(Per panel)

100 118.00

To conduct water leak tests.

75.00

Sundries

150.00

Total Labour 1: 6,940.00

DESCRIPTION

BOOTLID
LEFT TRUNK L
RIGHT TRUNK
REAR BUMPER SET MOUNTING PARTS (VAL
RR BUMPER CARRIER ECE
FLAP TOWING EYE REAR
RR RH BUMPER MIDDLE MOUNTING
RR BUMPER RH MOUNT
COVER MIDDLE BOTTOM
CLADDING BUMPER REAR (PDC/SCHWARZ)
REAR BUMPER PANEL PRIMED (PDC)
EMBLEM GROMMET
TRUNK LID BADGE
MODEL LETTERING X3

QTY	PRIC
1	1,807.20
1	74.60
1	74.60
1	38.55
1	738.05
1	35.95
1	142.55
1	198.30
1	68.70
1	197.35
1	1,409.45
2	0.80
1	59.00
1	62.55

VALUE
1,807.20
74.60
74.60
38.55
738.05
35.95
142.55
198.30
68.70
197.35
1,409.45
1.60
59.00
62.55

69.50

Performance Motors Limited

A member of the Lion Garby Group
Co. Reg. No. 197401059W GST Reg. No. M2-0020081-X



303, Alexandra Road
Lion Garby Performance Centre
Singapore 159941
Tel: 67190100 (Sales & Admin)
67190111 (AfterSales)
Fax: 64747770

390, Raffles Avenue Road
East Coast Centre
Singapore 478162
Tel: 67190880 (AfterSales)
Fax: 67449770

11F, Kleanette Road
Lion Garby Business Centre
Singapore 159944
Tel: 67190529 (AfterSales)
67190533/333 (Motorcard)
Fax: 64794402 (AfterSales)
64794424 (Motorcard)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46776 Page No. : 2 of 2
Date Estimated : 30/04/2018
Prepared By : Merina Chia San San

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2224G	0X01125	29/05/2017	X3 sDrive20	0

DESCRIPTION	QTY	PRIC	VALUE
SPINDLE DRIVE LH	1	414.30	AN X 414.30
SPINDLE DRIVE RH	1	414.30	AN X 414.30
BOOTLID GASKET	1	128.90	AN X 128.90
REAR RH LIGHT IN THE SIDE PANEL	1	440.85	AN X 440.85
THIRD STOPLAMP	1	233.60	AN X 233.60
RH REFLECTOR	1	35.20	AN X 35.20
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	AN X 20.20
BUMPER PDC SENSOR (SCHWARZ)	1	236.85	AN X 236.85
Total Parts :			7,069.50

Claim CO : 001018 / Uninsured Assets / Damage

Regn No: _____ Claim No: _____

Date/Time: 28/5/18 @ 11am Excess \$: _____

Surveyor's Name: Tan Kah Seng Sign: _____

Surveyor's Tel: 92443329 Authored: _____

Approved By: _____ Time: _____

REMARKS: BY SURVEYOR 6/18/18

Surveyor's Email: tan.kah.seng@liongarby.com

No. of Working Days Recommended: 6-7 days

Liability Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Work being done is on a "time and materials" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,940.00
Parts	:	7,069.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	980.67
Grand Total	:	14,990.17

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **



FINAL REPORT

Estimate No. : b1 46776
Date Estimated : 30/04/2018
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
Brotin Muhuri
11 Tanjong Rhu Road
#19-04

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 436896

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLP2224G	0X01125	29/05/2017	X3 sDrive20	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace rear bumper and attachments, boot lid and attachments, rear RH light in side panel, third stoplamp include making good the tail end panel and knocking out dents caused by the accident	2550.00		2,550.00
To spray paint rear bumper, boot lid and tail end panel	2474.00		2,474.00
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00
To remove and install boot compartment carpet and garnish to facilitate repairs	230.00		230.00
To carry out body cavity preservation. (Per panel).	100.00		100.00
To conduct water leak tests.	75.00		75.00
Sundries	150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,807.20	1.00		1,807.20
RR BUMPER CARRIER ECE	738.05	1.00		738.05
RR RH BUMPER MIDDLE MOUNTING	142.55	1.00		142.55
RR BUMPER RH MOUNT	198.30	1.00		198.30
CLADDING BUMPER REAR (PDC/SCHWARZ)	197.35	1.00		197.35
REAR BUMPER PANEL PRIMED (PDC)	1,409.45	1.00		1,409.45 *
EMBLEM GROMMET	0.80	2.00		1.60 *
MODEL LETTERING X3	62.55	1.00		62.55 *
TRUNK LID BADGE	69.50	1.00		69.50 *
# BUMP STOP *	3.25	10.00		32.50 <i>NEW</i> ✓
# EXPANDING RIVET *	1.35	10.00		13.50 <i>NEW</i> ✓
REAR RH LIGHT IN THE SIDE PANEL	440.85	1.00		440.85
THIRD STOPLAMP	233.60	1.00		233.60
RH REFLECTOR	35.20	1.00		35.20
DECOUPLING RING PDC TORQUE CONVERTE	5.05	4.00		20.20
BUMPER PDC SENSOR (SCHWARZ)	236.85	1.00		236.85



FINAL REPORT

# (DG) CLEANER R1 (100ML) *	23.85	1.00	23.85 <i>all</i>
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	1.00	131.55 <i>all</i>
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00	27.85 <i>all</i>

SUPPLEMENTARY ITEMS

Total Labour :	5,729.00
Total Parts :	5,822.50
Total Labour & Parts :	11,551.50
Deduction for Excess :	0.00
Total Repair Costs less Excess:	11,551.50
GST @7%:	808.61
Grand Total :	12,360.11

Email \$11,551.50, 6 days

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559M, GST Reg. No. M2-0020081-8



SUPPLEMENTARY

Estimate No. : b1 46776
Date Estimated : 30/04/2018
Prepared By : Merina Chia San San

Page No. :

REPAIR FOR -
Brotin Muhuri
11 Tanjong Rhu Road
#19-04

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 436896

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SLP2224G	0X01125	29/05/2017	X3 sDrive20	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BUMP STOP *	3.25	10.00		32.50
# EXPANDING RIVET *	1.35	10.00		13.50
# (DG) CLEANER R1 (100ML) *	23.85	1.00		23.85
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	1.00		131.55
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00		27.85

Total Labour :	
Total Parts :	229.25
Total Labour & Parts :	229.25

14238-75

Survey only
29.05 @ 9.12pm

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

380, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/534 (Motorrad)
Fax. 64786601 (AfterSales)
64796524 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

30 APR 2018

Estimate No. : b1 46776
Date Estimated : 30/04/2018
Prepared By : Merina Chia San San

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Brotin Muhuri
11 Tanjong Rhu Road
#19-04

Singapore 436896

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2224G	0X01125	29/05/2017	X3 sDrive20	0

DESCRIPTION

To replace rear bumper, bootlid including attachments etc and to knock out dented area caused by accident

2550 3,400.00

To paint rear bumper, bootlid and tail end panel

2774 2,749.00

To check electrical wiring systems and lightings at the rear section for proper function.

150 177.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

230 271.00

To carry out body cavity preservation.
(Per panel).

100 118.00

To conduct water leak tests.

✓ 75.00

Sundries.

? 150.00

Total Labour 1: 6,940.00

DESCRIPTION

BOOTLID
LEFT TRUNK L
RIGHT TRUNK
REAR BUMPER SET MOUNTING PARTS (VAL
RR BUMPER CARRIER ECE
FLAP TOWING EYE REAR
RR RH BUMPER MIDDLE MOUNTING
RR BUMPER RH MOUNT
COVER MIDDLE BOTTOM
CLADDING BUMPER REAR (PDC/SCHWARZ)
REAR BUMPER PANEL PRIMED (PDC)
EMBLEM GROMMET
TRUNK LID BADGE
MODEL LETTERING X3

QTY	PRIC
1	1,807.20
1	74.60
1	74.60
1	38.55
1	738.05
1	35.95
1	142.55
1	198.30
1	68.70
1	197.35
1	1,409.45
2	0.80
1	59.00
1	62.55

VALUE
67 1,807.20
? 74.60
? 74.60
? 38.55
? 738.05
x 35.95
? 142.55
? 198.30
? 68.70
? 197.35
del 1,409.45
u/c 1.60
u/c 59.00
u/c 62.55



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159943
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Tampong Arang Road
East Coast Centre
Singapore 438160
Tel. 63190886 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/538 (Motocrad)
Fax. 64796601 (AfterSales)
64796624 (Motocrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 46776
Date Estimated : 30/04/2018
Prepared By : Merina Chia San San

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLP2224G	0X01125	29/05/2017	X3 sDrive20	0

DESCRIPTION	QTY	PRIC	VALUE
SPINDLE DRIVE LH	1	414.30	X 414.30
SPINDLE DRIVE RH	1	414.30	? 414.30
BOOTLID GASKET	1	128.90	128.90
REAR RH LIGHT IN THE SIDE PANEL	1	440.85	? 440.85
THIRD STOPLAMP	1	233.60	? 233.60
RH REFLECTOR	1	35.20	35.20
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
BUMPER PDC SENSOR (SCHWARZ)	2	236.85	? 473.70

Total Parts : 7,069.50

Claims CD / Sub / Uninsured losses / Direct Sublimation

Regn No. _____ Claim No. _____

Quoted Time 28/5/18 @ 11am Excess \$0

Surveyor's Name Tanpin Sign _____

Surveyor's Tel 92443269 Authored _____

Authorized By _____ Time _____

RESURVEYED BY SUPERVISOR / No. _____

Surveyor's Name Tanpin & Puanbom.

No. of Working Days Recommended 6-7 days

Link Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party claims are on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,940.00
Parts	:	7,069.50
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	980.67
Grand Total	:	14,990.17

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Print Received Message

This mail is associated with :

***SLP2224G (0341789410SG)**
[SBU9766E]
TP
BROTIN MUHURI
Apr 28 2018 7:00PM
[NG ENG HUAT]
Performance Motors Limited

From AIG Asia Pacific Insurance Pte. Ltd. (Express) (AIG_SG_EXPRESS), sent on 16/11/2018 10:21 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$12862.11) - SLP2224G - Claim Handler: Ler, Bernard-JQ

Approved:12862.11:Hi, mandate has been given as follows: Cost of Repair : \$12,360.11 As per surveyor
finalization Loss of Use : \$500.00 5 days @ S\$ 100/day LTA/ GIA Search Fee : \$2.00 Total : \$12,862.11

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

**AIG THIRD PARTY EXPRESS SETTLEMENT
FOR ACCIDENTS ON OR AFTER 1ST JUNE 2008
(PAYMENT BREAKDOWN)**

Vehicle No:	SIP 22246	Model:	
Date of Accident:	28-4-2018		

Global Sum Settlement	<input type="checkbox"/> Yes	<input type="checkbox"/> No	
Repair Estimate	\$	14990.17	
Final Repair Cost	\$	12360.11	
Loss of Use	\$	5000	5 days at \$ 1000 per day
Rental (if any)	\$		days
LTA / GIA Search Fee	\$	200	
Others:	\$		
	\$		
Final Settlement Sum	\$	12862.11	
Is Third Party Workshop GIA Registered? <input type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below)			
A)	For Non GIA Registered Workshop:	Agreed Liability	_____(%)
B)	For GIA Registered Workshop:	BOLA Applicable: Yes/No	
		BOLA Scenario No:	
	BOLA Liability: _____(%)	Assessed Liability (*): _____(%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks			

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Ltd	\$	12360.11
2)	Performance Motors Ltd	\$	200
3)	Brotin Muhuri	\$	5000

Signed by appointed surveyor _____

Date _____

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act;
Survey Report; Medical Report/ Bill (if any))

Hsiao Tong (LKKAUTO)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Friday, 16 November 2018 10:22 AM
To: Thin Thin (LKKAUTO)
Cc: Hsiao Tong (LKKAUTO); Admin A
Subject: RE: <MANDATE> Your Ref: 0341789410SG; Our Ref: CC3/AIG18007869/T1ub3 [ACCIDENT ON 28/04/2018 INVOLVING VEHICLES SBU 9766E AND SLP 2224G]

Dear Thin Thin,

Mandate has been given as follows:

Cost of Repair	:	\$	12,360.11	As per surveyor finalization
Loss of Use	:	\$	500.00	5 days @ S\$ 100/day
LTA/ GIA Search Fee	:	\$	2.00	
Total	:	\$	12,862.11	

For your necessary handling please.

Thanks.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946 | Fax +(65) 6835 7416

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Thin Thin (LKKAUTO) [mailto:thinthin@lkkauto.com]
Sent: 7 November 2018 12:10 PM
To: Ler, Bernard-JQ
Cc: Hsiao Tong (LKKAUTO); Admin A
Subject: <MANDATE> Your Ref: 0341789410SG; Our Ref: CC3/AIG18007869/T1ub3 [ACCIDENT ON 28/04/2018 INVOLVING VEHICLES SBU 9766E AND SLP 2224G]

Your Ref: 0341789410SG
Our Ref: CC3/AIG18007869/T1ub3

"Without Prejudice"

Dear Sir / Madam,

ACCIDENT ON 28/04/2018 INVOLVING VEHICLES SBU 9766E AND SLP 2224G

We refer to the above matter.

OI collided to rear portion of TP vehicle.

According to GIA Barometer of Liability, our insured's liability is down. We did clarify with OI the nature of the accident. We had informed OI about the NCD issue.

We seek your approval to offer to TP repairer, **Performance Motors Limited** is as follows: -

	Claimed Amount	Revised Amount
Cost of Repair (W/GST)	\$ 15,246.70	\$ 12,360.11
Loss of Use (5 days x \$ 100)	\$ 500.00	\$ 500.00
LTA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 15,748.70	\$ 12,862.11

Total amount of claim (Liability 100%)

\$ 12,862.11

For your approval in Merimen please.

Relevant documents are uploaded in Merimen.

Best Regards,

Thin Thin Hlaing | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: thinthin@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Our Ref: CC3/AIG18007869/ub3

24 MAY 2018

NG ENG HUAT
2E HONG SAN WALK
#05-01
SINGAPORE 689051

Dear Sir/Madam,

ACCIDENT INVOLVING SBU 9766E & SLP 2224G ON 28/04/2018

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you and/or your authorized driver under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 10 days from the date of this letter.

Please note that your No-Claim Discount (NCD) (if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Yours faithfully,

THIN THIN HLAING
Case Handler
DID: 6841 2360
FAX: 6741 4108
Email: thinthin@lkkauto.com

c.c. *AIG Asia Pacific Insurance Pte Ltd*
(Motor Claims Dept)

AUTHORISATION TO ACT
(AIG Express Third Party Claim)

I, BROTHU MUHURI (the third party claimant) of 11 Tanjong Ahy
Road #19-04 (436896) (address), owner of SIP 22246 (vehicle no.)
hereby authorize Performance Motors Ltd ("the workshop") to act for me
with respect to my claim for repair costs and/or rental and/or loss of use ("claim") for my vehicle
no. SIP 22246 that was damaged pursuant to the accident which occurred on 28.4.2018
(date) along RIVER VINEY / LAMMING WAY (location) involving vehicle no/s
SBUA766E ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit
and the workshop is further authorized to receive payment further to settlement of my claim with
payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without
prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other
vehicle/s is concerned.

Dated this 08 (day) of 06 (month) 2018 (year)

Brothu Muhuri

Signed by "the third party claimant"
(with chop if applicable)

A

Signed by "the workshop"
(with chop)

RELEASE VOUCHER
(AIG Express Third Party Claim)

"We/I, Performance Motors Ltd ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$12360.11 (Repair Cost), S\$500 (Loss of ~~rental~~/use), S\$2 (Disbursement), for vehicle no. SLP2224G that was damaged pursuant to the accident which occurred on 28.4.18 (date) along River Valley Rd to Canning Lane (location) involving vehicle no/s 58491665. This is pursuant to the inspection conducted on 28.5.18 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner Protin Muhuri ("the third party claimant") of vehicle no. SLP2224G make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SLP2224G (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 11th (day) of Dec (month) 2018 (year)



MMH

Signed by appointed surveyor

A

Signed by "the workshop" (with chop)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64767770280, Kampong Arang Road
East Coast Centre
Singapore 436180
Tel. 63190888 (AfterSales)
Fax. 63449773315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190828 (AfterSales)
63190833/536 (Motorrad)
Fax. 64796801 (AfterSales)
64796824 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1272248

Date IN : 04/06/2018

Cust. Svc. Advisor: Gary Poh Chai Hoon

Page No. : 1 of 2

Invoice Number : 2007532 / WSB

Invoice Date : 12/09/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

- CUSTOMER INFORMATION -

Mr Brotin Muhuri
11 Tanjong Rhu Road
#19-04

Singapore 436896

- INVOICE TO - 121

AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120REGN. NO.
SLP2224GCHASSIS NO.
0X01125REGN. DATE
29/05/2017MODEL
X3 SDRIVE20MILEAGE
7986

- - - - LABOUR 1 - - - -

To replace rear bumper and attachments, right tail lamp,
rear boot lid and attachments etc including to make good the
tail end panel and knock outdented area caused by the accident. To remove and install body
parts in order to carry out painting job.To respray rear bumper, rear boot lid and tail end panel
etc.To check electrical wiring systems and lightings at the
rear section for proper function.To remove and install boot compartment carpet and garnish
to facilitate repairs.

To carry out body cavity preservation.

To conduct water leak tests.

Sundries.

INS CLAIMS : ACCIDENT REPAIR. DIRECT SETTLEMENT.

DATE OF ACCIDENT : 28.4.2018. 3RD PARTY CAR : SBU9766E.

YOUR REF NO : NIL.

VEHICLE WAS SURVEYED BY MR TAUFIKH FROM LKK AUTO
CONSULTANTS PTE LTD ON 28.5.2018 AT 11.00 AM.
AUTHORISED REPAIR BY MS THIN THIN HLAING FROM LKK ON
3.5.2018 VIA E-MAIL.PROPOSE LOSS OF USE = \$100X5. THE AMOUNT IS SUBJECTED
TO INSURANCE COMPANY CONFIRMATION.

GIA SEARCH FEE = \$2.00.

NETT

2,550.00

2,474.00

150.00

230.00

100.00

75.00

150.00

0.00

0.00

0.00

Total Labour 1:

5,729.00

- - - - PARTS - - - -

BOOTLID
CLADDING BUMPER REAR (PDC/SCHWARZ)
REAR BUMPER PANEL PRIMED (PDC)
REAR RH LIGHT IN THE SIDE PANEL
RH REFLECTOR
TRUNK LID BADGE
EMBLEM GROMMETQty Retail
Price1 1,807.20
1 197.35
1 1,409.45
1 440.85
1 35.20
1 69.50
2 0.80

NETT

1,807.20
197.35
1,409.45
440.85
35.20
69.50
1.60

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020881-x



309, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190886 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64726601 (AfterSales)
64796624 (Motorrad)

SERVICE TAX INVOICE

Repair Order No. : B1 1272248

Date IN : 04/06/2018

Cust. Svc. Advisor: Gary Poh Chai Hoon

Page No. : 2 of 2

Invoice Number : 2007532 / WSB

Invoice Date : 12/09/2018

Payment Terms : 30 Days From Invoice

Invoice By : Sharon Heng

MODEL LETTERING X3	1	62.55	62.55
DECOUPLING RING PDC TORQUE CONVERTE	4	5.05	20.20
RR BUMPER CARRIER ECE	1	738.05	738.05
THIRD STOPLAMP	1	233.60	233.60
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	1	131.55	131.55
(DG) CLEANER R1 (100ML)	1	23.85	23.85
(DG/SL) GLASS PRIMER 30ML (VP206)	1	27.85	27.85
BUMP STOP	10	3.25	32.50
BUMPER PDC SENSOR (SCHWARZ)	1	236.85	236.85
RR BUMPER RH MOUNT	1	198.30	198.30
RR RH BUMPER MIDDLE MOUNTING	1	142.55	142.55
EXPANDING RIVET	10	1.35	13.50
Total Parts :			5,822.50

Labour Charges : 5,579.00
Parts Charges : 5,822.50
Lubricant/Misc : 150.00

Total Labour & Parts Charges : S\$ 11,551.50
Less Insurance Excess : S\$ 0.00
Invoice Total Amount Exclude GST : S\$ 11,551.50
GST @ 7% : S\$ 808.61
Invoice Total Amount Include GST : S\$ 12,360.11

Computer generated invoice. No signature is required.

Amount Payable Include GST : S\$ 12,360.11

All amounts are in Singapore Dollars.

Work was carried out subject to the Company's Terms and Conditions of Service.

No complaints will be entertained unless reported within seven (7) days of the date of this invoice.

For credit purchases, interest @1% per month will be debited on overdue amounts.





RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-064696

Date of Request: 30/04/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 30/04/2018

Enquiry By Vivi

TP Vehicle No. SBU9766E

Accident Date 28/04/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
SBU9766E	AIG Asia Pacific Insurance Pte. Ltd.	16/09/2017-15/09/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.



RECORDS MANAGEMENT CENTRE

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-064696

Date of Request: 30/04/2018

Your Ref No: Online Purchase

Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 159941

Dear Sir/Madam,

Enquiry Date 30/04/2018

Enquiry By Vivi

TP Vehicle No. SBU9766E

Accident Date 28/04/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licensee's Number: **S7261093H**

Name: **BROTIN MUHURI**

Birth Date: **15 Sep 1972**
Issue Date: **04 Sep 2007**

001526813C

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7261093H



Name

BROTIN MUHURI

Race

INDIAN

Date of birth

15-09-1972

Sex

M

Country/Place of birth

INDIA

S7261093H

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

PASS DATE

Class 3 Motor Cars ≤ 2000kg with ≤ 7 passengers, exclusive of the driver; and other motor vehicles ≤ 2500kg 04 Sep 2007



9339633



MRC No. S7261093H



Nationality

INDIAN

Date of issue

06-08-2014

Address

**11 TANJONG RHU ROAD
#19-04
SINGAPORE 438896**

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING











Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 Apr 2018 Edit Reg		28 May 2018 00:00 Edit Adj Rpt	S\$11,551.50 Edit Estimates	S\$11,551.50 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	NG ENG HUAT , ID: S1441228Z								
Main Claimant:	BROTIN MUHURI , ID: 57261093H								
Vehicle Reg. No.:	SLP2224G	Date of Loss:	28/04/2018 19:00 - 159 [10 Months and 30 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 0341789410SG	Policy/Cover Note No.:	2100428291 (Comprehensive)						
Vehicle Reg. No. (Insured):	SBU9766E	Policy No. (Claimant):	C0072105						
		Excess:							
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com								
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: (65) 6221 8611								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 10/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (16/11/2018): Alert - Adj Mandate Approved (S\$12862.11) - SLP2224G - Claim Handler: Ler, Berna...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLP2224G (0341789410SG)
[SBU9766E]
TP
BROTIN MUHURI
Apr 28 2018 7:00PM
[NG ENG HUAT]
Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page <input type="checkbox"/>	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	Edit	
Assessment Reports			1 per page <input type="checkbox"/>	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	02/05/18 12:02	Accident Statement Addm. #1 <small>From: CO - Reg. No: SBU9766E, Claimant: NG ENG HUAT</small>	Load HTML	
Photos/Images			3 per page <input type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
2	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
3	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
4	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
5	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
6	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
7	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
8	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
9	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
10	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
11	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
12	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
13	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
14	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
15	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
16	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
17	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
18	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
19	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
20	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
21	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
22	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
23	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
24	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
25	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
26	07/11/18 12:10	General View	Load JPG	<input checked="" type="checkbox"/>
27	07/11/18 12:10	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
28	07/11/18 12:10	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
29	07/11/18 12:10	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
30	07/11/18 12:10	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	07/11/18 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
32	07/11/18 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
33	07/11/18 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
34	07/11/18 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
35	07/11/18 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	07/11/18 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	07/11/18 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	07/11/18 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	07/11/18 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	07/11/18 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	07/11/18 12:10	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	30/04/18 12:44	TP ESTIMATE	 Load TIF	
2	30/04/18 12:44	TP GIA REPORT	 Load PDF	
3	31/05/18 20:15	TP ESTIMATE- MARKED	 Load PDF	
4	29/10/18 11:15	LETTER TO OI	 Load PDF	
5	29/10/18 11:15	GIA SEARCH	 Load PDF	
6	17/12/18 08:13	WORKSHOP INVOICE	 Load PDF	
7	17/12/18 08:13	AUTHORISATION TO ACT FORM	 Load PDF	
8	17/12/18 08:13	AUTHORISATION TO ACT FORM	 Load PDF	
9	17/12/18 08:13	Release Voucher	 Load PDF	
10	17/12/18 08:13	TP IC	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SBU9766E (Insd veh)	Model:	BMW X3 2.0 (A)
	SLP2224G (TP veh)		
Date of Accident:	28/04/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	15,246.70
Final Repair Cost	:	\$	12,360.11
Loss of Use	:	\$	500.00
Rental (if any)	:	\$	0.00
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	12,862.11

5.00 days at \$100.00 per day
days

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ ~~No~~ BOLA Scenario No: _____
 27
 BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)
 * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 12,362.11
2)	Brotin Muhuri	:	\$ 500.00
3)		:	\$

JOANNE LEE KHANG MIN

17 Dec
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
 (Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd

(Co Reg No:199607198R)
51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18007869/T1UB3Q2
Date: 17/12/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100428291
Claimant Vehicle No: SLP2224G Insured Vehicle No: SBU9766E
Date of Loss: 28/04/2018 Nature of Claim: TP Claim No: 0341789410SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLP2224G
Make & Model: BMW X3, 2.0 (A) Engine No: A6621619N20B20A
Reg. Date: 29/05/2017 (Man. Year: 2017) Chassis No: WBAWY920400X01125
Colour: Black Odometer: 7723 km
Engine Capacity: 1997 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/50 R18 Rear Tyre Size: 245/50 R18
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,459.25	5,972.50	1,486.75	19.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,790.00	5,579.00	1,211.00	17.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	14,249.25	11,551.50	2,697.75	18.93
+ GST 7.00/7.00% (S\$)	997.45	808.61	188.84	18.93
Nett Amount (S\$)	15,246.70	12,360.11	2,886.59	18.93
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,862.11		

INSPECTION

Date of Assignment: 28/05/2018
Date Inspected: 28/05/2018 Inspected At: Performance Motors Limited (Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941
Estimated Period of Repair: 6.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** THIN THIN HLAING

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*BOOTLID	Bent	1,807.20 FS	*1,807.20 FS
3	1		*LEFT TRUNK L	Not Necessary	74.60 FS	*- FS
4	1		*RIGHT TRUNK	Not Necessary	74.60 FS	*- FS
5	1		*REAR BUMPER SET MOUNTING PARTS (VAL)	Not Necessary	38.55 FS	*- FS
6	1		*RR BUMPER CARRIER ECE	Bent	738.05 FS	*738.05 FS
7	1		*FLAP TOWING EYE REAR	Not Necessary	35.95 FS	*- FS
8	1		*RR RH BUMPER MIFFLE MOUNTING	Deformed	142.55 FS	*142.55 FS
9	1		*RR BUMPER RH MOUNT	Deformed	198.30 FS	*198.30 FS
10	1		*COVER MIDDLE BOTTOM	Not Necessary	68.70 FS	*- FS
11	1		*CLADDING BUMPER REAR (PDC/SCHWARZ)	Deformed	197.35 FS	*197.35 FS
12	1		*REAR BUMPER PANEL PRIMED (PDC)	Deformed	1,409.45 FS	*1,409.45 FS
13	2		*EMBLEM GROMMET	Necessary	1.60 FS	*1.60 FS
14	1		*TRUNK LID BADGE	Necessary	69.50 FS	*69.50 FS
15	1		*MODEL LETTERING X3	Necessary	62.55 FS	*62.55 FS
16	1		*SPINDLE DRIVE LH	Not Necessary	414.30 FS	*- FS
17	1		*SPINDLE DRIVE RH	Not Necessary	414.30 FS	*- FS
18	1		*BOOTLID GASKET	Not Necessary	128.90 FS	*- FS
19	1		*REAR RH LIGHT IN THE SIDE PANEL	Cracked	440.85 FS	*440.85 FS
20	1		*THIRD STOPLAMP	Necessary	233.60 FS	*233.60 FS
21	1		*RH REFLECTOR	Missing	35.20 FS	*35.20 FS
22	4		*DECOUPLING RING PDC TORQUE CONVERTE	Necessary	20.20 FS	*20.20 FS
23	1		*BUMPER PDC SENSOR (SCHWARZ) (2 PCSBMU)	Not Working (1 PCS ONLY)	473.70 FS	*236.85 FS
24	10		*BUMP STOP	Necessary	32.50 FS	*32.50 FS
25	10		*EXPANDING RIVET	Necessary	13.50 FS	*13.50 FS
26	1		*(DG) CLEANER R1 (100ML)	Necessary	23.85 FS	*23.85 FS
27	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	131.55 FS	*131.55 FS
28	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 7,459.25 5,972.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER ,BOOTLID INCLUDING ATTACHMENTS ETC AND TO KNOCK OUT DENTED AREA CAUSED BY ACCIDENT	New	3,400.00	2,550.00
2	TO PAINT REAR BUMPER ,BOOTLID AND TAIL END PANEL	New	2,749.00	2,474.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	230.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
6	TO CONDUCT WATER LEAK TESTS	New	75.00	75.00
Gross Labour Cost (S\$)			6,790.00	5,579.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >