

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 04 May 2018

Preliminary Advice

Vehicle No	: SKA118J	Accident Date	: 22/04/2018
Make	: BMW 730LI	Policy No.	: DMPCSN3097041700
Assignment Date	: 30/04/2018	Excess	: S\$3,600.00
Date of Inspection	: 03/05/2018	Est. Duration of Repair	: 0.00
Inspection At	: CHAI MOTOR WORKSHOP SDN BHD (HQ) NO 3, JALAN BERTAM 8, TAMAN DAYA, 81100 JOHOR BAHRU, JOHOR DARUL TAKZIM		

Point of Impact / General Description of Damages

The vehicle caught fire.

Repairer's Estimate (Gross)	:S\$	TOTAL LOSS
Revised Amount	:S\$	TOTAL LOSS
Check Items (Estimated)	:S\$	0.00
Total	:S\$	0.00

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	85,000.00
COE / PARF Rebate	:S\$	70,109.00
Salvage Value	:S\$	
Margin for Repair	:S\$	14,891.00

Brake System	: In Order
Steering System	: In Order
Tyre Condition (Front)	: 5/5 mm
Tyre Condition (Rear)	: 5/5 mm

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (x) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :