

REF: msh

ASSIGNMENT

From: Date: 03/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJN 3333C

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

5 days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No.

SJN 3333C Yr Regn: 09/10

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

M 2250 Cgi 1796

Colour

M. Gold A/C: Insured / Std / NI / NA

Sp. Reading

113551

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

W00 2120472A 220345

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

245/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

3 mm

R/Bal.

3 mm

L/Bal.

3 mm

L/Bal.

3 mm

D.O.A.

26/4/18

D.O.I.

21/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Acc body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

3/5 File pass to Catherine, est normal

L/S \$ 4,300/-

14/05/18 \$ 8000.50 - \$ 4,300/- (Reduc - 46.3%)

14/05/18 Confirmed L/S \$ 4,300/- with repainer (Gaine) @ 14:15pm. via email

14/05/18 @ 14:09 p.m. revised to Chia Nyuk Pui via message.

RECEIVED 14 MAY 2018

Date/Time. File Pass to?

14/05/18

1)

Typist

Date/Time. File Return to?

2)

Report Format:

Lump Sum / I.B.L. (\$

4,300/-

: Preli. Report

: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 0

Survey Fee:

Transportation:

) ... \$ + ... \$

) Photos

) Other

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Insp (\$

☐

Weekend (\$

150

10

160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	26 Apr 2018		30 Apr 2018 10:57 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	CNC GENERAL CONTRACTORS (PTE) LTD, Co. Reg. No.: 200917807R								
Main Claimant:	LIM KIM LAI, ID: S0523902H								
Vehicle Reg. No.:	SJN3333C	Date of Loss:	26/04/2018 07:00 - :59 [91 Months and 10 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 556941	Policy/Cover Note No.:	A28813365MCY (Comprehensive) Coverage: 24/09/2017 - 23/09/2018						
Vehicle Reg. No. (Insured):	SJJ7195D	Policy No. (Claimant):							
		Excess:							
Repairer:	Serve You Motor Service (HQ) BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265, 569536 Ang Mo Kio - Tel: 64815652								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhla Nyuk Pul - 6594 2521]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/05/2018]								
Driver/Custodian (Insured):	CHUA YUEH SHAIN (CAI YUXUAN) (), NRIC: S7522852Z, Tel: +6597536365								
Adj Asg. Remarks:	Pls assign case to Mr Kenneth Kong.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail 									
There are no mail for this case.									
<input type="checkbox"/> ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete 									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Monday, 14 May 2018 2:15 PM
To: 'Elaine Chia'; 'Kenneth Kong (LKKAuto)'
Cc: 'Admin-D (LKKAuto)'; 'SUR'
Subject: RE: Confirm repair cost for SJN 3333 C Acc/date: 26/4/2018

Dear Elaine,

Confirmed repair cost at Lump Sum \$4300/= for SJN 3333 C. (5 days)

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Elaine Chia [mailto:elainesyms@gmail.com]
Sent: Friday, 11 May 2018 10:25 AM
To: Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>
Subject: Re: Confirm repair cost for SJN 3333 C Acc/date: 26/4/2018

Hi Kenneth,

We accept and confirm repair cost at Lump Sum \$4300/= for SJN 3333 C. (5 days)

Thank you.

Elaine Chia

Serve You Motor Service

Blk 5033 Ang Mo Kio Ind Park 2

#01-265 (S) 569536

H/P: 9239 3188 Tel: 6481 0555 / 6481 5652

Fax: 6483 1654

On Fri, May 11, 2018 at 9:59 AM, Kenneth Kong (LKKAuto) <KennethKong@lkkauto.com> wrote:

: Attach finalised for SJN 3333C. Kenneth

From: Elaine Chia [mailto:elainesyms@gmail.com]
Sent: Monday, 7 May, 2018 2:00 PM
To: Kenneth Kong (LKKAuto); Admin A
Subject: Re: After repair photos for SJN 3333 C Acc/date: 26/4/2018

Hi Kenneth

Re: After repair photos for SJN 3333 C Acc/date: 26/4/2018

Hereby attach the after repair photos for SJN 3333 C.

Thank you.

Elaine Chia

Serve You Motor Service

Blk 5033 Ang Mo Kio Ind Park 2

#01-265 (S) 569536

H/P: 9239 3188 Tel: 6481 0555 / 6481 5652

Fax: 6483 1654

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 14 May 2018

Preliminary Advice

Insured Vehicle No	: SJJ7195D		
TP Vehicle No	: SJN3333C	Accident Date	: 26/04/2018
Make	: MERCEDES-BENZ E250	Assignment Date	: 30/04/2018
Date of Inspection	: 02/05/2018	Est. Duration of Repair	: 5 days
Inspection At	: Serve You Motor Service (HQ) BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265 Singapore 569536		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s rear body portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	8,000.50
Revised Amount	:S\$	5,438.70
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,438.70

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	26/04/2018 10:46
Date Of Accident	26/04/2018 07:15
Exact Location Of Accident	BUKIT BATOK WEST AVE 8
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJN3333C
Insured/Policyholder	
Name Of Registered Owner	LIM KIM LAI
NRIC No	S0523902H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97553333
Alternative Phone No	OFFICE-97553333

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E250-1.8 (A)

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5067415584-03 (CLASSIC)
Cover Note Number	

Driver

Name of Driver	LIM KIM LAI
NRIC No	S0523902H
Date Of Birth	05/10/1943
Occupation	OUTDOOR
Date Of Driving Pass	09/01/1963
Driving Experience	55 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-97553333
Fax Number	
Contact Number	OFFICE-97553333
Email Address	NOEMAIL

Address	4 HIGHGATE WALK
Postcode	S598755
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information on the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I WAS TRAVELLING ALONG BUKIT BATOK WEST AVE 8 (INFRONT OF BT BATOK SEC SCHOOL) AFTER ALIGHTNING MY GRANDCHILDREN TO SCHOOL. ALL OF A SUDDEN, A VEHICLE WHICH WAS PARK ON THE LEFT SIDE OF THE LANE MOVE OUT WITHOUT CHECKING. AS A RESULT, THE SAID VEHICLE HIT ONTO THE REAR LEFT PASSENGER DOOR OF MY VEHICLE. ATTENDED BY : SUSAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJJ7195D
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHUA YUEH SHIAN
NRIC/Passport Number	S7522852Z
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.


IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659645
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DECLARATION

I/We declare the foregoing particulars are true in every respect. 2016



Policyholder's Signature _____
Date & Time: _____


Driver's Signature
(If driver is not the policyholder)
Date & Time:

IDAC BUKIT BATOK (VAC)
511 Bukit Batok Street 23
Singapore 659545
Tel: 6560 3312 Fax: 6569 0722
Email: vacbb@singnet.com.sg

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

26/4/18

7.15AM BUKIT BATOK WAST AVE-8



26 APR 2018

SERVE YOU MOTOR SERVICE

BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2

#01-265, SINGAPORE 569536

TEL. NO: 64810555 / FAX NO. 64831654

E-MAIL: elainesyms@gmail.com

INS: MSIG INSURANCE (SINGAPORE) PTE LTD

OWNER: LIM KIM LAI

Registration no. : SJN 3333 C/ MERCEDES BENZ E250 CGI

Date : 30-Apr-18

Quotation No. : 18430-1

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

- | | | | |
|---|---|------------------------------|---------|
| 1 | 1 | Rear bumper | 1462.00 |
| 2 | 1 | Rear LH bumper side retainer | |
| 3 | 1 | Rear LH door | |
| 4 | 1 | Rear LH fender | |

Sub-total: \$4,845.00
Less 10 % \$484.50
\$4,360.50

SPECIAL NETT ITEMS

- | | | | |
|---|-------|---|---------|
| 1 | 1 set | Rear bumper chrome moulding (corner, 3 pcs) | C 92.00 |
| 2 | 1 | Rear LH door chrome moulding | 93.00 |
| 3 | 1 | Rear LH rim | |
| 4 | 1 | Rear LH tyre | |

Sub-total: \$320.00
Less 10 % \$32.00
\$288.00

LABOUR CHARGE

- | | | |
|---|--|------------|
| 1 | To dismantle / renew the rear accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts. | \$1,100.00 |
| 2 | Supply spray paint material and necessary items to respray on rear damaged area. | \$1,000.00 |
| 3 | To remove and refix Rear LH door compartment assembly (Power window / glass / lock assembly...) | \$180.00 |
| 4 | To reset vehicle programme | \$120.00 |


Sub-total: \$2,400.00
Grand Total: \$8,000.50

LKK Auto Consultants hereby certify that the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SERVE YOU MOTOR SERVICE
 BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2
 #01-265, SINGAPORE 569536
 TEL. NO: 64810555 / FAX NO. 64831654
 E-MAIL: elainesyms@gmail.com



INS: MSIG INSURANCE (SINGAPORE) PTE LTD

OWNER: LIM KIM LAI

Registration no. : SJN 3333 C/ MERCEDES BENZ E250 CGI

Date : 30-Apr-18

Quotation No. : 18430-1

Not with the LK 2430d Penny After Pain 5 day

S/N	Qty	Item	Amount
-----	-----	------	--------

LIST ITEMS

- | | | |
|---|---|------------------------------|
| 1 | 1 | Rear bumper <i>1482-n</i> |
| 2 | 1 | Rear LH bumper side retainer |
| 3 | 1 | Rear LH door |
| 4 | 1 | Rear LH fender |

Sub-total:	\$1,745.00
Less 10 %	\$129.00
	\$1,983.00
	\$988.00 X
	\$4,845.00
	\$484.50
	\$4,360.50

*BT/LH \$1,745.00 ✓
 RM \$129.00 ✓
 RM \$1,983.00 ✓
 R \$988.00 X*

SPECIAL NETT ITEMS

- | | | |
|---|-------|--|
| 1 | 1 set | Rear bumper chrome moulding (corner, 3 pcs) <i>C P2-co</i> |
| 2 | 1 | Rear LH door chrome moulding <i>P3-co</i> |
| 3 | 1 | Rear LH rim |
| 4 | 1 | Rear LH tyre |

RM	\$320.00
RM	\$220.00
After	\$450.00
RM	\$250.00
	\$1,240.00

106

LABOUR CHARGE

- | | |
|---|--|
| 1 | To dismantle / renew the rear accident damaged portion. To panel beating, reshape, straighten, orientate and align repair / replacement parts. |
| 2 | Supply spray paint material and necessary items to respray on rear damaged area. |
| 3 | To remove and refix Rear LH door compartment assembly (Power window / glass / lock assembly...) |
| 4 | To reset vehicle programme |

\$1,100.00

\$1,000.00

\$180.00

\$120.00

LKK Auto Consultants
 The Reparer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer
 Signature:
 Date:

700
6601
809
700
 Subtotal \$2,400.00
 Grand Total: \$8,000.50

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	26 Apr 2018		30 Apr 2018 10:57 Edit Adj Rpt	S\$4,300.00 Edit Estimates	S\$4,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	-----------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CNC GENERAL CONTRACTORS (PTE) LTD, Co. Reg. No.: 200917807R		
Main Claimant:	LIM KIM LAI, ID: S0523902H		
Vehicle Reg. No.:	SJN3333C	Date of Loss:	26/04/2018 07:00 - :59 [91 Months and 10 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 556941	Policy/Cover Note No.:	A28813365MCY (Comprehensive) Coverage: 24/09/2017 - 23/09/2018
Vehicle Reg. No. (Insured):	SJJ7195D	Policy No. (Claimant):	
		Excess:	
Repairer:	Serve You Motor Service (HQ) BLOCK 5033 ANG MO KIO INDUSTRIAL PARK 2 #01-265, 569536 Ang Mo Kio - Tel: 64815652		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by KENNETH KONG] ... [Final Rpt due 30/05/2018]		
Driver/Custodian (Insured):	CHUA YUEH SHAIN (CAI YUXUAN) (), NRIC: S7522852Z, Tel: +6597536365		
Adj Asg. Remarks:	Pls assign case to Mr Kenneth Kong.		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SJN3333C (556941)**
[SJJ7195D]
TP
LIM KIM LAI
Apr 26 2018 7:00AM
[CNC GENERAL CONTRACTORS (PTE) LTD]
Serve You Motor Service

[Upload Documents](#) |
 [Upload Photos](#) |
 [Compose New Letter](#)

View View in Browser

Assessment Reports				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	30/04/18 09:31	Accident Statement From: SC - Reg. No: SJJ7195D, Claimant: CNC GENERAL CONTRACTORS (PTE) LTD		Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/05/18 14:09	Adjuster Immediate Advice		Load HTM	

Photos/Images				3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
2	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
3	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
4	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
5	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
6	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
7	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
8	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
9	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
10	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
11	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
12	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>
13	14/05/18 14:01	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>
14	14/05/18 14:01	Chassis Number		Load JPG	<input checked="" type="checkbox"/>
15	14/05/18 14:01	General View		Load JPG	<input checked="" type="checkbox"/>

Documentation				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print
1	30/04/18 09:31	SJN3333C GIA Rpt From: SC - Reg. No: SJJ7195D, Claimant: CNC GENERAL CONTRACTORS (PTE) LTD		Load PDF	
2	30/04/18 09:37	PRI		Load PDF	
3	30/04/18 10:57	Email frm TP - Agreed to appoint LKK, Mr Kenneth Kong as SJE		Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			

Show Remarks To: ☐ Handling Insurer
Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18007882/KS3BE2

Date: 18/05/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: A28813365MCY
 Claimant Vehicle No: SJN3333C Insured Vehicle No: SJJ7195D
 Date of Loss: 26/04/2018 Nature of Claim: TP Claim No: 556941

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJN3333C**
 Make & Model: MERCEDES-BENZ E250, 1.8 CGI (A) Engine No: 27186030064797
 Reg. Date: 16/09/2010 (Man. Year: 2010) Chassis No: WDD2120472A220345
 Colour: Metallic Gold Odometer: 113551 km
 Engine Capacity: 1796 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 245/45 R17 Rear Tyre Size: 245/45 R17
 Front Left Side: Pirelli 3 mm Rear Left Side: Pirelli 3 mm
 Front Right Side: Pirelli 3 mm Rear Right Side: Pirelli 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,600.50	3,998.70	1,601.80	28.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	1,440.00	960.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,000.50	5,438.70	2,561.80	32.02
Approved Total (Overridden) (S\$)		4,300.00		
Nett Amount (S\$)	8,000.50	4,300.00	3,700.50	46.25

INSPECTION

Date of Assignment: 30/04/2018
 Date Inspected: 02/05/2018 Inspected At: Serve You Motor Service (HQ)
 BLOCK 5033 ANG MO KIO INDUSTRIAL
 PARK 2 #01-265
 Singapore 569536

Estimated Period of Repair: 5.0 days

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG **Version:** 1.0 (Last Synchronised: 18 May 2018)
Parts: 143 **MERCEDES-BENZ E250 1.8 CGI (A) (Catalogue:Merimen Singapore 1.0)**
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SJN3333C)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent / Cut	1,745.00 FL	*1,462.00 FL
2	1		*REAR LH BUMPER SIDE RETAINER	Necessary	129.00 FL	*129.00 FL
3	1		*REAR LH DOOR	Bent	1,983.00 FL	*1,983.00 FL
4	1		*REAR LH FENDER	Repair	988.00 FL	*- FL
5	1		*SET REAR BUMPER CHROME MOULDING (CORNER, 3PCS)	Necessary	320.00 FS	*248.40 FS
6	1		*REAR LH DOOR CHROME MOULDING	Necessary	220.00 FS	*83.70 FS
7	1		*REAR LH RIM	Dented / Cut	450.00 FS	*450.00 FS
8	1		*REAR LH TYRE	Serviceable	250.00 FS	*- FS
					Sub Total (\$\$)	6,085.00 4,356.10
					- List Item Discount on L Items 10.00/10.00% (\$\$)	484.50 357.40
					Total Parts (\$\$)	5,600.50 3,998.70

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE / RENEW THE REAR ACCIDENT DAMAGED PORTION. TO PANEL BEATING, RESHAPE, STRAIGHTEN ORIENTATE AND ALIGN REPAIR / REPLACEMENT PARTS	New	1,100.00	700.00
2	SUPPLY SPRAY PAINT MATERIAL AND NECESSARY ITEMS TO RESPRAY ON REAR DAMAGED AREA	New	1,000.00	660.00
3	TO REMOVE AND REFIX REAR LH DOOR COMPARTMENT ASSEMBLY (POWER WINDOW / GLASS / LOCK / ASSEMBLY...)	New	180.00	80.00
4	TO RESET VEHICLE PROGRAMME	New	120.00	0.00
Gross Labour Cost (S\$)			2,400.00	1,440.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >