

DATE 27/4/2018 12:11

2018/04/27 12:11
L. K.

4 Sum
AIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Fender Mudflap (LH) ✓			\$ 15.50
	Rear Door (LH)			\$ 1,294.70
	Rear Door Protector(LH) ✓			\$ 54.50
	Front Door (LH) ✓			\$ 1,344.50
	Rocker Panel Outer Garnish (LH) x Rep.			\$ 463.40
	Rear Wheel Hup-Cap (LH) ✓			\$ 145.00
	SUB TOTAL			\$ 3,317.60
	LESS 20%			\$ 663.52
	DISCOUNTED TOTAL			\$ 2,654.08
	Rear Door Tel No. Sticker (LH) ✓			\$ 10.00
	Front Door Coloured Comfort Logo (LH) ✓			\$ 75.00
	Front Door Advertisement Logo (LH) x			\$ 100.00
				\$ 185.00
	Labour Charge			
	Panel Beating			\$ 1,000.00
	Spray Painting Charge			\$ 800.00
	Wiring Charge			\$ 50.00
	Tuff Kote			\$ 50.00
	Transfer of Door		\$ 120.00	\$ 240.00
	Rear Wheel Alignment			\$ 120.00
	TOTAL LABOUR			\$ 2,260.00
	ESTIMATE TOTAL			\$ 5,099.08
	1/Colin LKK 27/4/18 140hrs. 3 Rep. 4/5 After Repair photo			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from insurance company Acknowledged by Repairer Signature: _____ Date: _____			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.