



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLM4085T

Make & Model : INFINITI, Q30 1.5D DCT, SJKDAAH15U1019721

Year of : 2016

Manufacture

Estimation No. : E18040075

DOA : 27/04/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Front bumper / <i>re</i>	1400	1.00 2511	0.00 / 0.00
2	Front bumper clip / <i>re</i>	50	1.00 70	0.00 / 0.00
3	Front bumper retainer (LH) X <i>NN</i>	1.00	25.6	0.00 X 0.00
4	Front bumper retainer (RH) / <i>re</i>	1.00	35.6	0.00 / 0.00
5	Front bumper bracket (RH) X <i>NN</i>	1.00	250	0.00 X 0.00
6	Front bumper reinforcement X <i>NN</i>	1.00	1230	0.00 X 0.00
7	Front bumper sponge <i>CRA</i>	110	1.00 49.6	0.00 / 0.00
8	Front bumper fog lamp garnish (RH) / <i>scr</i>	180	1.00 290	0.00 / 0.00
9	Front bumper towing cap X <i>NN</i>	1.00	60	0.00 X 0.00
10	Front bumper lower grille X <i>NN</i>	1.00	420	0.00 X 0.00
11	Front grille assy X <i>CRA</i>	1100	1.00 1240	0.00 / 0.00
12	Front grille logo X <i>re</i>	1.00	119.2	0.00 / 0.00
13	Front grille clip X <i>re</i>	30	1.00 70	0.00 / 0.00
14	Front grille chrome piece X <i>NN</i>	1.00	212.3	0.00 X 0.00
15	Front panel X <i>NN</i>	1.00	1560	0.00 X 0.00
16	Front panel chrome piece X	1.00	389	0.00 X 0.00
17	Head lamp (RH) / <i>CRA</i>	4400	1.00 4670	0.00 / 0.00
18	Head lamp clip (RH) X	1.00	30	0.00 X 0.00
19	Front fender (RH) X <i>NN</i>	1.00	520	0.00 X 0.00
20	Front fender cowling (RH) X <i>NN</i>	1.00	25.4	0.00 X 0.00
21	Front fender cowling clip (RH) X <i>NN</i>	1.00	70	0.00 X 0.00
22	Front fender inner panel (RH) X <i>NN</i>	1.00	1284	0.00 X 0.00
23	Front fender arch garnish (RH) X <i>BR</i>	600	1.00 1200	0.00 / 0.00
24	Front fender arch garnish clip (RH) X <i>re</i>	30	1.00 70	0.00 / 0.00
25	Support panel X <i>NN</i>	1.00	872	0.00 X 0.00
26	Support panel top garnish X <i>NN</i>	1.00	495.3	0.00 X 0.00
27	Support panel side bracket (LH) X <i>NN</i>	1.00	91	0.00 X 0.00

8054.8

10%: 7249.32

Continue on next page...



Torque 5 Pte Ltd

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLM4085T
Make & Model : INFINITI, Q30 1.5D DCT, SJKDAAH15U1019721
Year of Manufacture : 2016
Estimation No. : E18040075
DOA : 27/04/2018

No	Description	Qty	U/P	Amt
28	Support panel side bracket (RH) X	1.00	91 0.00	0.00
29	Condenser X	1.00	1160 0.00	0.00
30	Radiator X	1.00	1783.70 0.00	0.00
31	Washer tank X	1.00	460 0.00	0.00
				Amt S\$ 0.00
				Discount (0.00%) S\$ 0.00
				Subtotal S\$ 0.00

Section: Labour Items

32	To R&R accident affected areas	1.00	1,000.00	1,000.00	200
33	To putty & respray accident affected areas	1.00	1,000.00	1,000.00	200
34	To rust proof accident affected areas	1.00	60.00	60.00	X
35	To R&R aircon condenser & refill gas	1.00	200.00	200.00	X SNN
36	To check wiring layout & head lamp focus	1.00	80.00	80.00	30
37	To check wheel alignment	1.00	180.00	180.00	X SNN
				Amt S\$ 2,520.00	
				Discount (0.00%) S\$ 0.00	
				Subtotal S\$ 2,520.00	430

3 Days.

lump sum repair.

After repair photos.

Gmo Qianp.

30/4/18.

2679.32

20/02 6100

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 0.00
Labour Items Subtotal S\$ 2,520.00
Total S\$ 2,520.00