

**Torque 5 Pte Ltd**

No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLM4085T
Make & Model : INFINITI, Q30 1.5D DCT, SJKDAAH15U1019721
Year of Manufacture : 2016

Estimation No. : E18040075
DOA : 27/04/2018

No	Description	Qty	U/P	Amt
Section: List Items				
1	Front bumper / <i>RL</i>	1.00	0.00	0.00
2	Front bumper clip / <i>RL</i>	1.00	0.00	0.00
3	Front bumper retainer (LH) X <i>NN</i>	1.00	0.00	0.00
4	Front bumper retainer (RH) / <i>RL</i>	1.00	0.00	0.00
5	Front bumper bracket (RH) ?	1.00	0.00	0.00
6	Front bumper reinforcement ?	1.00	0.00	0.00
7	Front bumper sponge ?	1.00	0.00	0.00
8	Front bumper fog lamp garnish (RH) / <i>scr</i>	1.00	0.00	0.00
9	Front bumper towing cap X	1.00	0.00	0.00
10	Front bumper lower grille X	1.00	0.00	0.00
11	Front grille assy X	1.00	0.00	0.00
12	Front grille logo X	1.00	0.00	0.00
13	Front grille clip X	1.00	0.00	0.00
14	Front grille chrome piece X	1.00	0.00	0.00
15	Front panel X	1.00	0.00	0.00
16	Front panel chrome piece X	1.00	0.00	0.00
17	Head lamp (RH) / <i>CRA</i>	1.00	0.00	0.00
18	Head lamp clip (RH) X	1.00	0.00	0.00
19	Front fender (RH) X	1.00	0.00	0.00
20	Front fender cowling (RH) X	1.00	0.00	0.00
21	Front fender cowling clip (RH) X	1.00	0.00	0.00
22	Front fender inner panel (RH) X	1.00	0.00	0.00
23	Front fender arch garnish (RH) ?	1.00	0.00	0.00
24	Front fender arch garnish clip (RH) ?	1.00	0.00	0.00
25	Support panel X	1.00	0.00	0.00
26	Support panel top garnish X	1.00	0.00	0.00
27	Support panel side bracket (LH) X	1.00	0.00	0.00

Continue on next page...



Torque 5 Pte Ltd
No.8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #01-50 Singapore 415875
Tel: +65 6452 4457 | Fax: +65 6452 4584 | Email: enquiry@torque5.com
Co. & GST Reg. No.: 201313221G

ESTIMATION REPORT

Vehicle No : SLM4085T
Make & Model : INFINITI, Q30 1.5D DCT, SJKDAAH15U1019721
Year of Manufacture : 2016
Estimation No. : E18040075
DOA : 27/04/2018

No	Description	Qty	U/P	Amt
28	Support panel side bracket (RH) X	1.00	0.00	0.00
29	Condenser X	1.00	0.00	0.00
30	Radiator X	1.00	0.00	0.00
31	Washer tank X	1.00	0.00	0.00

Amt S\$ 0.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 0.00

Section: Labour Items

32	To R&R accident affected areas	1.00	1,000.00	1,000.00	200
33	To putty & respray accident affected areas	1.00	1,000.00	1,000.00	200
34	To rust proof accident affected areas	1.00	60.00	60.00	X
35	To R&R aircon condenser & refill gas	1.00	200.00	200.00	X
36	To check wiring layout & head lamp focus	1.00	80.00	80.00	30
37	To check wheel alignment	1.00	180.00	180.00	X

Amt S\$ 2,520.00
Discount (0.00%) S\$ 0.00
Subtotal S\$ 2,520.00

3 Days.

lump sum repair.

After repair photos.

Guo Qiang.

30/4/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

List Items Subtotal S\$ 0.00
Labour Items Subtotal S\$ 2,520.00
Total S\$ 2,520.00