

Adrian Lkt. Longpac

PRIME MOTOR WORKS

BLOCK 1, KAKI BUKIT AVENUE 6, #01-43, SINGAPORE 417883

NEEDS CAR

TEL: 6747 9241 FAX: 6741 7276 HP: 9067 8767

30/04/2018**Blk 1 Kaki Bukit Ave 6**

EMAIL: primemotorworks@hotmail.sg

RCB No: 53177286A

01-43**Singapore 417883**

TP Longpac

Vivian

Nett: HK

Accident date: 28/04/2018**Estimated repair cost for vehicle no: SJU1898R NISSAN SYLPHY 1.5 '09****CHASSIS NUMER: JN1BAAG11Z0110428**

S/n	Qty	Nett Items	U/price	Amount	
1	2	Front Head Lamp <i>cracked</i>	\$558.00	\$1,116.00	✓
2	2	Front Head Lamp Lower Bracket <i>HP new</i>	\$38.10	\$76.20	X
3	1	Front Bumper <i>deformed</i>		\$566.20	✓
4	2	Front Bumper Side Retainer <i>new</i>	\$35.20	\$70.40	✓
5	10	Front Bumper Clips <i>new</i>	\$6.50	\$65.00	30 ✓
6	1	Front Bumper Inner Sponge <i>cracked</i>		\$207.10	✓
7	1	Front Bumper Reinforcement <i>Bent</i>		\$563.70	✓
8	2	Front Bumper Reinforcement Bracket <i>HP new</i>	\$155.40	\$310.80	X
9	1	Front Bumper Fog Lamp <i>cracked</i>		\$327.30	✓
10	1	Front Bumper Fog Lamp Cover <i>cracked</i>		\$130.10	✓
11	1	Front Bumper Number Plate <i>HP new</i>		\$50.00	X
12	2	Front Bumper Side Moulding <i>new</i>	\$48.80	\$97.60	✓
13	1	Front L/H Fender <i>Buckled</i>		\$573.50	✓
14	1	Front L/H Fender Cowling <i>3 HP new</i>		\$77.40	X
15	10	Front L/H Fender Cowling Clips <i>new</i>	\$6.50	\$65.00	X
16	1	Front Grille <i>cracked</i>		\$364.50	✓
17	1	Front Grille Emblem Logo <i>new</i>		\$66.40	✓
18	6	Front Grille Clips <i>new</i>	\$6.50	\$39.00	20 ✓
19	1	Front Support Panel <i>2 HP</i>		\$308.50	X
20	1	Front Support Panel Top Cover <i>new</i>		\$381.50	X
21	8	Front Support Panel Top Cover Clips <i>new</i>	\$6.50	\$52.00	X
22	1	Front Bonnet		\$1,023.80	X
23	1	Front Bonnet Chrome Moulding <i>HP</i>		\$127.50	X
24	1	Front Bonnet Lock <i>new</i>		\$62.10	X
25	1	Front Bonnet Insulator		\$147.00	X
26	8	Front Bonnet Insulator Clips	\$6.50	\$52.00	X
27	1	Rear Boot Lid <i>distorted</i>		\$796.70	✓
28	2	Rear Boot Lid Hinges <i>Bent</i>	\$41.00	\$82.00	✓
29	1	Rear Boot Lid Emblem Logo <i>new</i>		\$66.40	✓
30	1	Rear Boot Lid Sylphy Logo		\$88.10	✓
31	1	Rear Boot Lid Center Top Chrome Moulding <i>cracked</i>		\$270.60	✓
32	4	Rear Boot Lid Center Top Chrome Moulding Clips <i>new</i>	\$6.50	\$26.00	✓

33	1	Rear Boot Lid Center Lower Chrome Moulding	cracked	\$152.70	✓
34	4	Rear BootLid Center Lower Chrome Moulding Clips	new \$6.50	\$26.00	✓
35	1	Rear Boot Lid Number Plate	3x4	\$50.00	x
36	2	Rear Boot Lid Number Plate Lamp	new	\$66.50	\$133.00 x
37	2	Rear Boot Lid Side Reflector	cracked	\$220.10	\$440.20 ✓
38	1	Rear Boot Lid Inner Lock	damaged		\$102.50 ✓
39	1	Rear Boot Lid Inner Rubber	lt		\$106.30 ✓
40	1	Rear Boot Lid Inner Trim Board	3x4		\$497.00 x
41	8	Rear Boot Lid Inner Trim Board Clips	new	\$6.50	\$52.00 x
42	2	Rear Tail Lamp	cracked	\$241.80	\$483.60 ✓
43	2	Rear Tail Lamp Panel	LT Distorted	\$165.10	\$330.20 165.10
44	4	Rear Tail Lamp Clips	new	\$8.50	\$34.00 ✓
45	2	Rear Tail Lamp Lower Bracket	Damaged	\$35.20	\$70.40 ✓
46	1	Rear Bumper	Distorted		\$660.80 ✓
47	2	Rear Bumper Side Retainer	new	\$51.20	\$102.40 ✓
48	10	Rear Bumper Clips	new	\$6.50	\$65.00 30
49	1	Rear Bumper Center Moulding	new		\$162.80 ✓
50	2	Rear Bumper Mud Shield	3x4	\$51.10	\$102.20 x
51	8	Rear Bumper Mud Shield Clips	new	\$6.50	\$52.00 x
52	2	Rear Bumper Bracket	damaged	\$91.70	\$183.40 ✓
53	1	Rear Bumper Inner Sponge	defound		\$38.60 ✓
54	2	Rear Bumper Side Reflector	LT cracked	\$66.60	\$133.20 66.60
55	1	Rear End Panel	Distorted		\$438.70 ✓
56	1	Rear End Panel Top Garnish	defound		\$242.80 ✓
57	1	Rear End Panel Lock Sensor	Damaged	\$69.10	\$69.10 ✓
58	2	Rear Fender	LT Buckle, RH Repair	\$996.40	\$1,992.80 996.40
59	2	Rear Fender Inner Trim Board	3x4	\$231.70	\$463.40 x
60	16	Rear Fender Inner Trim Board Clips	new	\$6.50	\$104.00 x
61	2	Rear Fender Air-Duct	HP new	\$69.10	\$138.20 x
62	1	Rear Spare Tyre Panel	Repair		\$774.10 x
63	1	Rear Spare Tyre Panel Top Cover	defound		\$495.00 ✓
64	1	Rear Windscreen	new		\$1,364.00 x
65	1	Rear Windscreen Moulding	new		\$157.30 ✓
66	1	Rear Exhaust Aluminium Cover	HP new		\$144.70 x
67	2	Rear Exhaust Mounting	HP new	\$47.10	\$94.20 x

10687.30

9618.51

Subtotal : \$18,707.00

S/n	Qty	S/Nett	Items	U/price	Amount
1	1		Rear Bumper Reverse Sensor	Damaged	\$350.00 200
2	1		Rear Spare Tyre Panel & End Panel Sealant	HP new	\$450.00 x
3	1		Front Air-Con Condenser	HP new	\$453.80 x

4	1	Front Radiator	HPM	\$517.90	X
5	1	Rear Boot Lid Camera	Damaged	\$680.00	880
6	1	Rear Exhaust	Repair	\$504.00	X
7	1	Rear Center Exhaust	HPM	\$374.40	X
Subtotal :-				\$3,330.10	

580

Labour charges

To remove & refit cushion	\$280.00	80
To remove & refit reverse sensor	\$120.00	50
To remove & refit rear & center exhaust	\$380.00	80
To remove & refit rear camera	\$180.00	50
To remove & refit rear petrol tank	\$280.00	80
To remove & refit rear windscreen	\$120.00	✓
Gum	\$50.00	✓
To remove & refit front air-con condenser, radiator, fan motor & top up gas	\$380.00	X
To check wiring	\$100.00	60
Tuff kote	\$150.00	100
Panel beating	\$4,000.00	2000
Spray painting	\$3,000.00	1800

4470.

Subtotal :- \$9,040.00

Total:- \$31,077.10

Total 14668.57
2/50 11.5K (Nett Value)
14 Days
11.5K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: