

ASS. RES. BY

REF CS3/LPC17023837/M12/37

Total Instruction

Paper Survey

Surveyor

MA

ASSIGNMENT (Office)

From (Person)

Chg Hk

of LPC

Date/Time

30042018

Estimated Cost

Bill to

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.

Gx 7879B

Insured

SJL 4000S

at Workshop in/s

E M Solution

Tel

6456 0226

of

160 Sin Ming Drive # 03-18/19

Policy No.

Claim No.

17/17/17/VP05/020280

Sum Insured

Excess

Make of Veh

(Client's Record)

D.O.A

13/12/2017

CA / REV / REP. / REV 24 HRS

18/12/17

H.O.D. Endorsed

Date/Time

247pm @ 15/12/17

Person Contacted

Bernard

Vehicle IN/OUT

Date/Time	Action/Instruction
	(X) Estimate
	Gx 7879B - X
	SJL 4000S - CC4/LPC16004236/A063q2
	D.O.A: 12/10/2015
	Dismantle: 18/12/17
	After paint: 22/12/17 (G) 1yrs 7wks.

MV ~~10k~~ \$10.8k

28/5/18

L/S


4100/2

(Red 3000, 4090)

with

6 days

labour


28/5/2018

RECEIVED 30 MAY 2018

17/5/18

by email first
no bill
logged

REF:

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

Yr Regn:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt + Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

RECEIVED 27 DEC 2017

Date/Time: File Pass to?

☐

Preli. Report

☐

Final Report

Date/Time: File Return to?

2) 26/12 - typst

Report Format:

PRS

Lump Sum / I.B.I: (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

) \$ - RS \$

) Photos

) Others

TOTAL

Catherine Chong (LKK Auto)

From: ONG LI LI <llong@lonpac.com>
Sent: Monday, 30 April, 2018 3:37 PM
To: Nivitha (LKK Auto); assignments@lkkauto.com
Cc: MT_Claim_SG; 'SUR'
Subject: RE: Our client's vehicle no. GX7879B (EM Solution); Your insured's vehicle no. SJL4000S - PRI 17/17/17/VP05/020280
Attachments: 20280 TP SURVEY REPORT.pdf

Hi Nivitha

Attached is the TP survey report with photographs. Please let us have your surveyor's comment.

Regards,
Ong Li Li
Senior Claims Executive | Lonpac Insurance Bhd
300 Beach Road #17-04/07 The Concourse Singapore 199555
Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Friday, 15 December, 2017 2:49 PM
To: ONG LI LI; assignments@lkkauto.com
Cc: MT_Claim_SG; 'SUR'
Subject: RE: Our client's vehicle no. GX7879B (EM Solution); Your insured's vehicle no. SJL4000S - PRI 17/17/17/VP05/020280

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: ONG LI LI [mailto:llong@lonpac.com]
Sent: Friday, 15 December, 2017 2:38 PM
To: Hui Ting; assignments@lkkauto.com; Catherine Chong (LKK Auto)
Cc: MT_Claim_SG; Corene Chong
Subject: RE: Our client's vehicle no. GX7879B (EM Solution); Your insured's vehicle no. SJL4000S - PRI 17/17/17/VP05/020280

Without Prejudice
Save as to Costs

Dear Hui Ting

We are not agreeable to your list of Single Joint Experts and we shall appoint LKK Auto Consultants Pte Ltd for the pre-repair survey.

Dear LKK

Please refer to the attached and attend to the pre-repair survey.

Regards,

Ong Li Li

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road #17-04/07 The Concourse Singapore 199555

Tel : (65) 6250 7388 Ext. 254 Fax: (65) 6296 2706

From: Hui Ting [<mailto:huiting@crossbordersllc.com>]

Sent: Friday, 15 December, 2017 2:30 PM

To: GERALD POH WEE BIN

Cc: MT_Claim_SG; Corene Chong

Subject: RE: Our client's vehicle no. GX7879B (EM Solution); Your insured's vehicle no. SJL4000S - PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. We refer to your email dated 14 December 2017.
2. Our client objects appointing your surveyor as single joint expert.
3. We propose one of the motor surveyors named in the list below to conduct the joint pre-repair survey as a single joint expert:-

1)	Dennis Yap	Pal's Appriaser Pte Ltd
2)	Micheal Yap	Mc-coy Appriaser Pte Ltd
3)	Andy Yap	LCW Appriaser Pte Ltd
4)	B J Loi	Par Automotive Consultancy
5)	Sebastian Lim	Constant Appraiser Services
6)	Lee Yew Hok	Constant Appraiser Services
7)	Alan Cheong	CL Appraiser Pte Ltd
8)	Jason Lek	JP Knights
9)	Tay Beng Hee	Autoprobe Consultants
10)	Samuel Phun	Autoprobe Consultants
4. Please let us know within two (2) working days whether you are agreeable to the appointment of any of the above motor surveyors as a single joint expert.

Thank You.

Regards

Huiting

TEL: 6812 6873

CrossBorders LLC

133 New Bridge Road

#23-03/04/05 Chinatown Point

Singapore 059413

Tel: (65) 6438 1323

Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

From: GERALD POH WEE BIN [<mailto:geraldpoh@lonpac.com>]

Sent: Thursday, December 14, 2017 12:16 PM

To: Hui Ting <huiting@crossbordersllc.com>

Cc: MT_Claim_SG <mt_claim@lonpac.com>

Subject: RE: Our client's vehicle no. GX7879B (EM Solution); Your insured's vehicle no. SJL4000S - PRI

WITHOUT PREJUDICE

Our Ref : 17/17/17/VP05/020280

Dear Hui Ting,

Please see attached and revert to us.

Best Regards

Gerald Poh

Senior Claims Executive | Lonpac Insurance Bhd

300 Beach Road, #17-04/07 The Concourse, Singapore 199555

Tel: (65) 6250 7388 Ext.255 | Fax: (65) 6296 2706

From: Hui Ting [<mailto:huiting@crossbordersllc.com>]

Sent: Thursday, 14 December, 2017 11:30 AM

To: MT_Claim_SG

Cc: Corene Chong

Subject: Our client's vehicle no. GX7879B (EM Solution); Your insured's vehicle no. SJL4000S - PRI

Your attention is drawn to the CONFIDENTIALITY NOTICE below.

WITHOUT PREJUDICE

Dear Sirs

1. Please find attached our PRI notice dated 14 December 2017 for your kind attention.
2. Please reply email to corene@crossbordersllc.com & huiting@crossbordersllc.com

Thank You.

Regards

Huiting

TEL: 6812 6873

CrossBorders LLC

133 New Bridge Road

#23-03/04/05 Chinatown Point
Singapore 059413
Tel: (65) 6438 1323
Fax: (65) 6438 2313

CONFIDENTIALITY NOTICE

This e-mail from CrossBorders LLC (including any attachment(s) to it) is confidential and may also be privileged and exempt from disclosure under applicable law. Accordingly, if you are not the intended recipient please notify us immediately, delete this e-mail (including any attachment to it) from your computer system and do not disclose or distribute it to any other person or continue to read this e-mail. Thank you.

CrossBorders LLC DOES NOT ACCEPT SERVICE OF COURT DOCUMENTS OR NOTICE OF ANY PROCEEDINGS BY FACSIMILE OR EMAIL

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
----------------	---------

Owner ID:	0899Z
-----------	-------

Vehicle Details

Vehicle No.:	GX7879B
--------------	---------

Vehicle to be Exported:	No
-------------------------	----

Intended De-registration Date:	26 Dec 2017
--------------------------------	-------------

Vehicle Make:	NISSAN
---------------	--------

Vehicle Model:	URVAN
----------------	-------

Primary Colour:	Silver
-----------------	--------

Manufacturing Year:	2004
---------------------	------

Engine No.:	ZD30043578
-------------	------------

Chassis No.:	JN1MG4E25Z0711737
--------------	-------------------

Maximum Power Output:	-
-----------------------	---

Open Market Value:	\$22,223.00
--------------------	-------------

Original Registration Date:	17 Sep 2004
-----------------------------	-------------

First Registration Date:	17 Sep 2004
--------------------------	-------------

Transfer Count:	5
-----------------	---

Actual ARF Paid:	\$1,112.00
------------------	------------

Intended PARF Rebate Details

PARF Eligibility:	No
-------------------	----

PARF Eligibility Expiry Date:	-
-------------------------------	---

PARF Rebate Amount:	\$0.00
---------------------	--------

Intended COE Rebate Details

PARF/COE Rebate Enquiry

COE Expiry Date:	31 Jul 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$20,383.00
COE Rebate Amount:	\$6,509.00
Total Rebate Amount:	\$6,509.00
Message	
Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.	

The information contained herein is correct as at 26 Dec 2017

OK

> **Back to OneMotoring**

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	0899Z

Vehicle Details

Vehicle No.:	GX7879B
Vehicle to be Exported:	No
Intended De-registration Date:	30 May 2018
Vehicle Make:	NISSAN
Vehicle Model:	URVAN
Primary Colour:	Silver
Manufacturing Year:	2004
Engine No.:	ZD30043578
Chassis No.:	JN1MG4E25Z0711737
Maximum Power Output:	-
Open Market Value:	\$22,223.00
Original Registration Date:	17 Sep 2004
First Registration Date:	17 Sep 2004
Transfer Count:	5
Actual ARF Paid:	\$1,112.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	31 Jul 2019
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	5
PQP Paid:	\$20,383.00
COE Rebate Amount:	\$4,766.00
Total Rebate Amount:	\$4,766.00

Message

Please note that all future COE renewals for this vehicle can only be for a 5-year period, subject to the statutory lifespan (if applicable) of the vehicle.

The information contained herein is correct as at 30 May 2018

OK

PAR Automotive Consultancy

Regn. No: 52986974L

Thomson Rd Post Office PO Box 029 Singapore 915701. Tel : 64531173, Fax : 64536131.

Consultants: Vehicle appraisal & inspection, accident investigation, expert witness

Report No: 0041-18-EMAm

30 March 2018

ACCIDENT VEHICLE SURVEY REPORT

DK Engineering Technology Pte Ltd
160 Sin Ming Drive #03-19 Sin Ming Autocity
Singapore 575722

VEHICLE INFORMATION:

Vehicle Reg No.:	GX7879B	Odometer:	439036km
Make & Model:	Nissan Urvan	Colour:	Silver
Chassis number:	JN1MG4E25Z0711737	Date of accident:	13/12/2017
Year of Regn.:	17/09/2004	Date inspected:	16/12/2017
Repairer at:	EM Solution Pte Ltd	Date inspected (After Repair):	-
	160 Sin Ming Drive #03-19 Sin Ming Autocity		
	Singapore 575722		

STATIC CHECKS, where applicable:

Steering :	serviceable
Footbrake :	serviceable
Handbrake :	serviceable
Paintwork :	Good
General condition :	Good

TIRE CONDITION:

	<u>LH / Make</u>	<u>RH / Make</u>	<u>Size</u>
Front:	5mm/Maxxis	5mm/Maxxis	195R15
Rear:	5mm/Maxxis	5mm/Maxxis	195R15

POINT OF IMPACT AND DAMAGE, where applicable:

Impact on the rear portion.
Please see details as described in the Annex for parts and labour.

REMARKS:

We have inspected the above-mentioned vehicle on a "Without Prejudice" basis.

Parts and Labour Assessment

Report No: 0041-18-EMAm Vehicle No: GX7879B

Description of part	Qty	Condition as inspected	Repairer's estimate	Our adjustment
Rear tailgate	1	buckled	2,101.40	2,101.40 <i>BUG ✓</i>
Rear tailgate outer garnish	1	fractured	371.00	371.00 <i>SVCX</i>
Rear tailgate outer garnish clip	2	necessary	13.00	13.00 <i>NN</i>
Rear tailgate inner trim board	1	deformed	120.10	120.10 <i>SVCX</i>
Rear tailgate inner trim board clip	16	necessary	24.00	24.00 <i>NNX</i>
Rear bumper	1	squashed	644.90	644.90 <i>DM ✓</i>
Rear bumper inner step panel	1	bent	153.40	153.40 <i>BT ✓</i>
Rear tail lamp inner panel RH/LH	2	bent	706.00	706.00 <i>SVCX</i>
Rear end panel (outer)	1	bent	435.50	435.50 <i>BT ✓</i>
Rear boot floor panel end finisher	1	bent	162.60	162.60 <i>BT ✓</i>
<i>Subtotal before discount</i>			4,731.90	4,731.90 <i>3497.80</i>
<i>Percentage discount</i>	<i>0%</i>	<i>and 30%</i>	0.00	1,419.57 <i>1049.34</i>
Sub-total 1			4,731.90	3,312.33 <i>2448.46</i>
Rear tailgate emblem "Nissan" logo	1	necessary	42.80	42.80 <i>NEC ✓</i>
Rear tailgate hinge RH/LH	2	bent	138.20	138.20 <i>SVCX</i>
Rear tailgate damper RH/LH	2	bent	328.80	328.80 <i>SVCX</i>
Rear tailgate lock	1	jammed	266.10	266.10 <i>Jm ✓</i>
Rear tailgate lock cover	1	deformed	26.20	26.20 <i>Dm ✓</i>
Rear tailgate lock striker	1	bent	26.60	26.60 <i>BT ✓</i>
Rear tailgate outer key lock	1	jammed	66.10	66.10 <i>X NN</i>
Rear tailgate central locking	1	shorted	129.60	129.60 <i>SC ✓</i>
Rear tailgate wiper motor	1	shorted	555.60	555.60 <i>SVCX</i>
Tailgate weatherstrip	1	deformed	122.60	122.60 <i>Dm ✓</i>
Rear tail lamp RH/LH	2	fractured	362.80	362.80 <i>CR ✓</i>
Rear tail lamp lower bracket RH/LH	2	bent	56.00	56.00 <i>BT ✓</i>
Rear exhaust pipe	1	bent	887.30	887.30 <i>SVCX</i>
Rear exhaust pipe rubber mounting	3	deformed	87.00	87.00 <i>Dm ✓</i>
<i>Subtotal before discount</i>			3,095.70	3,095.70 <i>1119.70</i>
<i>Percentage discount</i>	<i>0%</i>	<i>and 10%</i>	0.00	309.57 <i>111.97</i>
Sub-total 2			3,095.70	2,786.13 <i>1007.73</i>
Rear tailgate glass sealant	1	necessary	70.00	70.00 <i>40/-</i>
Rear tailgate sticker '70km/h'	1	necessary	10.00	10.00 <i>✓</i>
Rear tailgate sticker '8 pax'	1	necessary	10.00	10.00 <i>✓</i>
<i>Subtotal before discount</i>			90.00	90.00 <i>60/-</i>

Percentage discount 0% and 0%

	0.00	0.00
Sub-total 3	90.00	-90.00 60.00
Parts-total	7,917.60	6,188.46 3516.19
1. To straighten and panel beating rear RH/LH body panel, rear boot floor panel and rear frame members. To cut/weld rear outer end panel and rear RH/LH tail lamp inner panel. To remove and refit above parts.	1,400.00	+1,100.00 800/-
2. To putty, re-spray painting and polish affected areas.	1,500.00	+1,200.00 600/-
3. To check and rectify wiring system.	80.00	50.00 30
4. To rust proof affected areas.	90.00	60.00 40/-
5. To remove and refit rear tailgate glass.	150.00	120.00 ✓
6. To remove, transfer and refit rear tailgate components.	150.00	100.00 50
7. To remove and refit rear exhaust pipe.	150.00	120.00 50
Labour total	3,520.00	2,750.00 1690.00
Parts & Labour total	11,437.60	8,938.46 5206.19

Results of inspection of the accident vehicle are as shown above.

We have taken into consideration the age and condition of the vehicle in our recommendation.

Hence, the recommended cost of repairs based on LUMP SUM repairs is :

\$7,100.00

and the recommended number of working days for the repairs is :

8

B J Loi (I Eng. MIMI, AIRTE)
Automotive Appraiser

4/5 4100/2

5 days labour

17/5/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD			Ref : CS3/LPC17023837/Bvd3s2-1	
300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Date : 08-06-2018	
			Code : LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SJL 4000S	Veh. Inspected	GX 7879B	
Policy No.		Coverage (\$)	0.00	
Claim No.	17/17/17/VP05/020280	Excess (\$)	0.00	
Assign From	ONG LI LI	Assign Date	30/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN	c.c	2953	
Engine No.	HIDDEN	Year of Reg.	2004	
Chassis No.	JN1MG4E25Z0711737	Colour	SILVER	
Odometer	439036	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15	MAXXIS	7 mm	
L/H Front Tyre	195 R15	MAXXIS	7 mm	
R/H Rear Tyre	195 R15	MAXXIS	7 mm	
L/H Rear Tyre	195 R15	MAXXIS	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	13/12/2017	Inspection Date	18/12/2017	
Survey held at	EM SOLUTION PTE LTD 160 SIN MING DRIVE #03-18/19 SIN MING AUTOCITY SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GX 7879B

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR TAILGATE	BUCKLED	2,101.40	2,101.40
1	REAR TAILGATE OUTER GARNISH	SERVICEABLE	371.00	-
2	REAR TAILGATE OUTER GARNISH CLIP	NOT NECESSARY	13.00	-
1	REAR TAILGATE INNER TRIM BOARD	SERVICEABLE	120.10	-
16	REAR TAILGATE INNER TRIM BOARD	NOT NECESSARY	24.00	-
1	REAR BUMPER	DAMAGED	644.90	644.90
1	REAR BUMPER INNER STEP PANEL	BENT	153.40	153.40
2	REAR TAIL LAMP INNER PANEL RH/LH	SERVICEABLE	706.00	-
1	REAR END PANEL (OUTER)	BENT	435.50	435.50
1	REAR BOOT FLOOR PANEL END FINISHER	BENT	162.60	162.60
	LESS 30% DISCOUNT		-	-1,049.34
			4,731.90	2,448.46
NETT ITEMS				
1	REAR TAILGATE EMBLEM "NISSAN" LOGO (N)	NECESSARY	42.80	42.80
2	REAR TAILGATE HINGE RH/LH (N)	SERVICEABLE	138.20	-
2	REAR TAILGATE DAMPER RH/LH (N)	SERVICEABLE	328.80	-
1	REAR TAILGATE LOCK (N)	JAMMED	266.10	266.10
1	REAR TAILGATE LOCK COVER (N)	DAMAGED	26.20	26.20
1	REAR TAILGATE LOCK STRIKER (N)	BENT	26.60	26.60
1	REAR TAILGATE OUTER KEY LOCK (N)	NOT NECESSARY	66.10	-
1	REAR TAILGATE CENTRAL LOCKING (N)	SHORT CIRCUIT	129.60	129.60
1	REAR TAILGATE WIPER MOTOR (N)	SERVICEABLE	555.60	-
1	TAILGATE WEATHERSTRIP (N)	DAMAGED	122.60	122.60
2	REAR TAIL LAMP RH/LH (N)	CRACKED	362.80	362.80
2	REAR TAIL LAMP LOWER BRACKET RH/LH (N)	BENT	56.00	56.00
1	REAR EXHAUST PIPE (N)	SERVICEABLE	887.30	-
3	REAR EXHAUST PIPE RUBBER MOUNTING (N)	DAMAGED	87.00	87.00
	LESS 10% DISCOUNT		-	-111.97
			3,095.70	1,007.73
SPECIAL NETT ITEMS				
1	REAR TAILGATE GLASS SEALANT (SN)	NECESSARY	70.00	40.00
1	REAR TAILGATE STICKER '70KM/H' (SN)	NECESSARY	10.00	10.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR TAILGATE STICKER '8 PAX' (SN)	NECESSARY	10.00	10.00
			90.00	60.00
	LABOUR			
	TO STRAIGHTEN AND PANEL BEATING REAR RH/LH BODY PANEL, REAR BOOT FLOOR PANEL AND REAR FRAME MEMBERS. TO CUT / WELD REAR OUTER END PANEL AND REAR RH/LH TAIL LAMP INNER PANEL. TO REMOVE AND REFIT ABOVE PARTS.		1,400.00	800.00
	TO PUTTY, RE-SPRAY PAINTING AND POLISH AFFECTED AREAS.		1,500.00	600.00
	TO CHECK AND RECTIFY WIRING SYSTEM.		80.00	30.00
	TO RUST PROOF AFFECTED AREAS.		90.00	40.00
	TO REMOVE AND REFIT REAR TAILGATE GLASS.		150.00	120.00
	TO REMOVE, TRANSFER AND REFIT REAR TAILGATE COMPONENTS.		150.00	50.00
	TO REMOVE AND REFIT REAR EXHAUST PIPE.		150.00	50.00
			3,520.00	1,690.00
GRAND TOTAL			11,437.60	5,206.19
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,100.00

Report Ref No. CS3/LPC17023837/Bvd3s2-1

LIM TEOW GUAN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.