

Yew Tee Automobile Tech Pte Ltd (Co.Reg.No.200311009C)

Synergy@kb 25 Kaki Bukit Road 4 #01-60/61
Singapore 417800

Tel: 67023113 Fax: 67023773 Email: YTKB

INSURER : AXA INSURANCE SINGAPORE PTE LTD**PARTICULARS OF CLAIM**

Claim Type:	TP	Ref. No:	YTKB/TP/1804/021
Policy No:	B29070437MCX	Date of Loss:	20/05/2018
Vehicle Reg. No.:	SJN9420U	Driveable?	yes
Driver Age:	26/04/2018	Third Party Vehicle No.:	SKP9935D,SKM5160P,SGQ 4288M
Any Injuries?	yes	Contact No:	92371343
Insured/Claimant:	ADVANCE LIMO & RENTAL PTE LTD	Driver:	ADVANCE LIMO & RENTAL PTE LTD

Make/Model:	Honda, Freed - GB31	Vehicle Reg. Date:	05/03/2009
Vehicle Colour:	BLUE	Engine Number:	L15A2339036
Chassis No:	GB31038567	Odometer:	
Total Loss?	NO	Est. Duration of Repair(Day)	7

Description of Accident/loss CHAIN COLLISON
Remarks:
Present Location: Yew Tee Automobile Tech Pte Ltd (Kaki Bukit)-YTKB

COST OF CLAIMS

	Amount
Parts	3,706.38
Miscellaneous Items	200.00
Labour	910.00
Paintwork Labour	675.00
Towing	0.00

Gross Total(\$\$):	5,491.38
GST 7.00%(\$\$):	384.40
Nett Amount(\$\$):	5,875.78

This claim is handled by: Shaun Toh L M

*not about
LKK
n/s #31001
6/1
27/4/18
to be photo taken*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorised by Repairer
Signature:
Date:

REPAIR DETAILS**Estimates On Parts**

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	FRONT BUMPER <i>Dis</i>	562.00	562.00	-25.00	421.50 ✓
2	1	FRONT HEADLAMP LH <i>2 ne</i>	650.00	650.00	-25.00	487.50 ✓
3	1	FRONT BUMPER TOWING COVER <i>W.1</i>	18.00	18.00	-25.00	13.50 ✓
4	1	FRONT BUMPER REINFORCEMENT <i>DD</i>	348.50	348.50	-25.00	261.38 ✓
5	1	FRONT BUMPER SIDE RETAINER LH <i>set</i>	35.00	35.00	-25.00	26.25 ✓
6	1	FRONT BUMPER BRACKET LH <i>set</i>	17.00	17.00	-25.00	12.75 ✓
7	1	FRONT SUPPORT PANEL <i>DD/BWC</i>	555.00	555.00	-25.00	416.25 ✓
8	1	REAR BUMPER <i>m/w.1</i>	562.00	562.00	-25.00	421.50 ✓
9	1	REAR BUMPER SIDE RETAINER LH <i>ner</i>	35.00	35.00	-25.00	26.25 ✓
10	1	REAR END PANEL <i>Rx</i>	780.00	780.00	-25.00	585.00 ✗
11	1	REAR TAILGATE <i>re</i>	1,153.00	1,153.00	-25.00	864.75 ✗
12	1	REAR TAILGATE FREED EMBLEM <i>ner</i>	55.00	55.00	-25.00	41.25 ✓
13	1	REAR TAILGATE LOGO <i>ner</i>	60.00	60.00	-25.00	45.00 ✓
14	1	REAR BUMPER TOWING COVER <i>DD</i>	18.00	18.00	-25.00	13.50 ✓
15	1	FRONT BUMPER CLIP <i>ner</i>	35.00	35.00 <i>S.V</i>	0.00	35.00 ✓
16	1	REAR BUMPER CLIP <i>ner</i>	35.00	35.00 <i>S.V</i>	0.00	35.00 ✓

Total Parts (\$\$) 3,706.38

Estimates of Miscellaneous Items

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1 <i>set</i>	REAR REVERSE SENSOR <i>small 200</i>	200.00	200.00	0.00	200.00
Sub Total (\$\$)						<u>200.00</u>

Estimates On Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Remove and Replace the above Damaged Parts, Straighten, Knock out, Realign and Repair including Cut and Weld body panels. To Re-adjust to the Original position using power tools.	800.00	800.00	0.00	800.00 <i>720</i>
2	1	To Remove and Refit Rear Bumper Sensor.	80.00	80.00	0.00	80.00 <i>50</i>
3	1	To Disconnect and Reconnect, Check Electrical wiring Harness Wire, Sockets, Replace Damaged Parts.	30.00	30.00	0.00	30.00 ✓

Gross Labour Cost (\$\$) 910.00

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
1	1	To Carry-Out Body Cavity Preservation.	30.00	30.00	0.00	30.00 ✓
2	1	To Supply Spray Terostat Sealant On The Cutting Areas.	45.00	45.00	0.00 <i>11</i>	45.00 ✗
3	1	To Spray painting on the Replaced and Repair Parts, Prepare Spray Such as Masking Tape the unaffected areas with paper, Cleaning and Sanding of Surfaces, Final Polishing and Waxing are also available.	600.00	600.00	0.00	600.00 ✓

P-2915-5
257
2186.62
3886.62

Estimates On Paint Work Labour

No.	Qty	Particulars	Rate	Amount	%Disc	After Disc
Gross Labour Cost (\$\$)						675.00

< END OF ESTIMATES >