

**HONDA****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

Kindly Help to arrange
Surveyor to Survey this
Vehicle thanks

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

6748934 = Katherine 03 MAY 2018 @ 11:00am
Marcus Chua / Quo Qiang

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SLP3127Y
Chassis No : JHMRU1810GX202133
Model : HRV DX-SIN CVT YM 2016
Owner's Name : YU SIEW LAN
Ins Policy No. :
Date of Accident : 26/4/2018

Document No. : SQT18001753
Date : 27. Apr 2018
Customer No. : WZA006
Svc Advisor : LIM CHOU SIONG
Engine No : L15B4532133
Date | Time : 27. Apr 2018 6:21:39 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER: YU SIEW LAN						
	OWNER INSURER: TOKIO MARINE INSURANCE SINGAPORE L						
	ACC DATE: 26/4/2018						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER: AXA INSURANCE S'PORE PTE LTD						
	TP VEH: YN4224A						
BO-NUM-COMP-S	NUMBER PLATE WITH CASING-S(N) X NN	1	45.00		45.00	3.15	48.15
04711-T7A-N00ZZ	FACE,FR.BUMPER / CRA De - photo	1	466.20	35	303.03	21.21	324.24
71104-T7A-000ZE	COVERFR.TOWING HOOK X	1	14.20	35	9.23	0.65	9.88
71111-T7A-000	GUIDER.FR.BUMPER AIR X	1	27.90	35	18.13	1.27	19.40
71116-T7A-000	GUIDEL.FR.BUMPER AIR X	1	27.90	35	18.13	1.27	19.40
71130-T7A-010ZZ	BEAM COMP.FR.BUMPER ?	1	236.60	35	153.79	10.77	164.56
71140-T7A-000	BEAMR.FR.BUMPER UPPER ?	1	23.90	35	15.53	1.09	16.62
71161-T7A-000	GARNISHR.FR.BUMPER BEAM ?	1	7.50	35	4.87	0.34	5.21
71166-T7A-000	GARNISHL.FR.BUMPER BEAM ?	1	7.50	35	4.87	0.34	5.21
71190-T7A-000	BEAML.FR.BUMPER UPPER ?	1	23.90	35	15.53	1.09	16.62
71193-T7A-000	SPACERR.FR.BUMPER SIDE = 5 sec.	1	10.40	35	6.76	0.47	7.23
71198-T7A-000	SPACERL.FR.BUMPER SIDE =	1	10.40	35	6.76	0.47	7.23
91505-TM8-003	CLIPBUMPER / REC	22	2.00	35	28.60	2.00	30.60
71126-T7B-Z01	SET,FR.GRILLE ASSY / CRA	1	265.50	35	172.57	12.08	184.65
71122-T7A-901	MOLDINGFR.GRILLE UPPER / CRA	1	186.10	35	120.96	8.47	129.43
71123-T7A-901	MOLDINGFR.GRILLE / CRA	1	42.80	35	27.82	1.95	29.77
71150-T7A-000	BEAMR.FR.GRILLE SIDE UPPER ?	1	38.70	35	25.15	1.76	26.91
71151-T7A-000	BEAMR.FR.GRILLE SIDE UPPER ?	1	17.20	35	11.18	0.78	11.96
71152-T7A-000	BEAML.FR.GRILLE SIDE UPPER ?	1	4.50	35	2.92	0.20	3.12
75700-TA0-A00	EMBLEMFR. / REC	1	25.90	35	16.83	1.18	18.01

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SLP3127Y

Chassis No : JHMRU1810GX202133

Model : HRV DX-SIN CVT YM 2016

Owner's Name : YU SIEW LAN

Ins Policy No. :

Date of Accident : 26/4/2018

Document No. : SQT18001753

Date : 27. Apr 2018

Customer No. : WZA006

Svc Advisor : LIM CHOU SIONG

Engine No : L15B4532133

Date | Time : 27. Apr 2018 6:21:39 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
90301-ST0-003	NUTPUSH 3MM	2	1.90	35	2.47	0.17	2.64
33100-T7S-E11	HEADLIGHT ASSY,R.	1	1661.00	35	1079.65	75.58	1155.23
33150-T7S-E11	HEAD LIGHT ASSY,L.	1	1479.70	35	961.80	67.33	1029.13
60100-T7A-000ZZ	HOOD COMP ENGINE	1	785.20	35	510.38	35.73	546.11
60120-T7A-000ZZ	HINGE COMPR.HOOD	1	39.10	35	25.41	1.78	27.19
60170-T7A-000ZZ	HINGE COMPL.HOOD	1	39.10	35	25.41	1.78	27.19
74120-T7A-003	LOCK ASSYHOOD	1	87.70	35	57.00	3.99	60.99
80050-TG7-000	LABLE AIR CON	1	0.80	35	0.52	0.04	0.56
19043-PNB-A00	LABELCOOLANT INFORMATION	1	4.90	35	3.18	0.22	3.40
Sum Item					3673.48	257.16	3,930.64
BOSUN	SUNDRIES	1	30.00	10	30.00	2.10	32.10
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	80.00	/	80.00	5.60	85.60
BKBU01R	REPLACE FR BUMPER, FR GRILLE, BONNET, REPAIR	1	1400.00	1125	1400.00	98.00	1498.00
BP03R	SPRAY PAINTING ON FR BUMPER, BONNET & BULKHEAD	1	1200.00	1050	1200.00	84.00	1284.00
Sum Labor					2710.00	189.70	2,899.70

Survey By

Date & Time

Excess

Status

Signature

Total Amount 6,383.48 446.86 6,830.34

Total (Inclusive of GST) 6,830.34

5 Days
before paint photos.

Printed on 27/4/2018 6:54:09 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: