

15/5/2010

INS. CASE OWNER:

Jas

CC4 ASM 7912, M ub352

LKK:
IDAC:

Surveyor:

MNRMS

DOI:

ASSIGNMENT

15/5/18

Date / Time:

20/4/18

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

SEP 2200

Name of Insured:

FOM WEE ROCK

Insured Tel No.:

HP: 82222100

Excess Sec II :\$

D.O.A:

28/4/18

Is driver the owner?

(YES) / NO

Nature of Accident:

Claim No.:

SEM00FHX (4N468

Policy No.:

VPA/PIA4644

Make / Model:

TOYOTA

Place of Accident:

TRAFFIC LIGHT TMR BET BT.
BETWE 1 & WEST AVE

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES NO

TP GIA REPORT: YES NO

Insured Liability:

%

Final ? Yes / No

SGE 435U

INSRS:
WSP:
Tel:
Liability:
RMKS:Kah
motorINSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date / Time

15/5/18
7:11

SGE 435U

SEP 2200

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

THAN 3/5

3/5/18

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Manday/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

2/5/18

Spoke to OI, he confirmed the accident.

RECEIVED 21 AUG 2018

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

S\$

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

20/8/18

Confirm with

Emilin

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

27

If NO or B 28, Ass. Lia:

Repair Cost:

S\$

6786.41

Loss of Rental (LOR):

S\$

(

days)

Loss of Use (LOU):

S\$

900.00 (\$ 100 x 9 days)

Loss of Income (LOI):

S\$

(\$ x days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Total:

S\$

7686.41

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

7686.41

Name 1:

KAH MOTOR CO SDN BHD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

REF: ASM(LAXA)

U63

ASSIGNMENT

From: Date: 02UB2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHE 435U

at Workshop m/s Kah Motor

of 15 Ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: New

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 60k.

IDAC Accident Rpt: Consistent? : Yes or No

GLA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: PIP % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

7/3/2024

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHE 435U Yr Regn: 3 / 06

Type: Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey C.C. 2354

Colour: Gold A/C Insured / Std / NI / NA

Sp. Reading: 262756 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRB18505C202951

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R: 215 / 60 R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 28/4/18

D.O.A. 2/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction LTA 39965
Rep 7 Rev

\$ 342.44 (Red: \$ 3718.78 / 37%.)

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

\$ + RS. \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18007912/ub3

8 SHENTON WAY #24-01
AXA TOWERS SINGAPORE 068811

Date : 30-04-2018



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKP 2220D	Veh. Inspected	SGE 435U
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	30/04/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	28/04/2018	Inspection Date	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SGE435U
Chassis No : JHMRB18505C202951
Model : ODYSSEY 2.4 EXV AUTO
Owner's Name : SUWANDI NGATURI
Ins Policy No. :
Date of Accident : 28/4/2018

Document No. : SQT18001767
Date : 28. Apr 2018
Customer No. : WZA006
Svc Advisor : LIEW THYE WEI
Engine No : K24A62002952
Date | Time : 28. Apr 2018 2:45:38 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: SUWANDI NGATURI OWNER INSURER: NTUC ACC DATE: 28/4/18 SURVEYED BY: DATE: REF NO: TP INSURER: AXA INSURANCE TP VEH: SKP2220D						
BO-NUM-PLATE	NUMBER PLATE (N)	1	25.00		25.00	1.75	26.75 ✓
04715-SFE-000ZZ	FACERR BUMPER	1	815.40	35	530.01	37.10	567.11 ✓
71521-SFE-003	MOULDING R RR	1	59.30	35	38.54	2.70	41.24 ✓
71526-SFE-003	MOULDING L RR	1	59.30	35	38.54	2.70	41.24 ✓
71593-SFE-003	SPACER R RR BPR SIDE	1	17.60	35	11.44	0.80	12.24 ✓
71598-SFE-003	SPACERL RR BUMPER SIDE	1	17.60	35	11.44	0.80	12.24 ✓
91503-SZ3-003	CLIP ABUMPER	10	3.90	35	25.35	1.77	27.12 ✓
04663-SFE-Q00ZZ	STIFFENERRR.BPR FACE	1	445.70	35	289.70	20.28	309.98 ✓
74440-SFE-003	W/STRIPTAILGATE	1	131.10	35	85.21	5.96	91.17 ✓
68100-SFE-305ZZ	TAILGATE COMP	1	1356.20	35	881.53	61.71	943.24 ✓
74890-SFE-305ZN	GARNISH SETTAILGATE	1	498.90	35	324.28	22.70	346.98 ✓
75701-SFE-003	EMBLEMREAR CENTER	1	30.20	35	19.63	1.37	21.00 ✓
75722-SFE-003	EMBLEM RR (ODYSSEY)	1	35.10	35	22.81	1.60	24.41 ✓
84640-SFE-J11ZC	LINING RR PANEL	1	233.30	35	151.64	10.61	162.25 ✓
71530-SFE-000ZZ	BEAM RR BUMPER	1	101.70	35	66.10	4.63	70.73 ✓
RS-4P	BUMPER SENSOR 4PCS	1	180.00		180.00	12.60	192.60 ✓
Sum Item					2701.22	189.08	2,890.30
BOSUN	SUNDRIES	1	30.00		30.00	2.10	32.10 ✓
BOJSE	BODY JOINT SEALANT.	1	80.00		80.00	5.60	85.60 ✓
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	7.00	107.00 ✓

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATIONGST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

Registration No : SGE435U
Chassis No : JHMRB18505C202951
Model : ODYSSEY 2.4 EXV AUTO
Owner's Name : SUWANDI NGATURI
Ins Policy No. :
Date of Accident : 28/4/2018

Document No. : SQT18001767
Date : 28. Apr 2018
Customer No. : WZA006
Svc Advisor : LIEW THYE WEI
Engine No : K24A62002952
Date | Time : 28. Apr 2018 2:45:38 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	80.00		80.00	5.60	85.60
BA02R	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)	1	120.00		120.00	8.40	128.40
BMI02D	REMOVE & INSTALL SPEAKER BOARD RR SEATS TRUNK	1	350.00		350.00	24.50	374.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	300.00		300.00	21.00	321.00
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	1	450.00		450.00	31.50	481.50
BKRP02M	CUT OFF & RENEW RR PANEL. STRAIGHTEN	1	2800.00		2800.00	196.00	2996.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	2800.00		2800.00	196.00	2996.00
Sum Labor					7360.00	515.20	7,875.20

Survey By

Date & Time

Excess

Status

Signature

Total Amount 10,061.22 704.28 10,765.50

Total (Inclusive of GST) 10,765.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 30/4/2018 9:04:13 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



QUOTATION

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : AXA INSURANCE S'PORE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
Registration No : SGE435U
Chassis No : JHMRB18505C202951
Model : ODYSSEY 2.4 EXV AUTO
Owner's Name : SUWANDI NGATURI
Ins Policy No. :
Date of Accident : 28/4/2018

Document No. : SQT18002106 Page 1
Date : 23. May 2018
Customer No. : WZA006
Svc Advisor :
Engine No : K24A62002952
Date | Time : 23. May 2018 7:18:23 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount Incl GST
SUPPLEMENTARY LABOUR & PARTS							
04733-SFE-000	RUBBERRR.W/SHIELD	1	31.40	Cut 35 ✓	20.41	1.43	21.84
73227-SFE-000	MOLDINGRR.W/SHIELD	2	16.80	NEC 35 ✓	21.84	1.53	23.37
73228-SFE-000	MOULDINGR RR W/SHIELD	1	18.30	NEC 35 ✓	11.89	0.83	12.72
73278-SFE-000	MLDGL RR W/SHIELD	1	18.30	NEC 35 ✓	11.89	0.83	12.72
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00	NEC ✓	60.00	4.20	64.20
Sum Item					126.03	8.82	134.85

Survey By

Date & Time

Excess

Status

Signature

Total Amount 126.03 8.82 134.85

Total (Inclusive of GST) 134.85

Printed on 23/5/2018 7:22:06 PM

This is a computer generated invoice. No signature is required.

Pert prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

*8 days
Att: Marcus***SERVICE PRE-INVOICE**

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
 Chassis No: JHMRB18505C202951
 License No: SGE435U
 Mileage: 263115
 Engine No: K24A62002952

Document No: SVO18026460
 Printed By: TWLIEW
 Order Date: 8. May 2018
 Order Time: 3:05:17 PM
 Service Advisor: LIEW THYE WEI

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount incld	Amount	GST
	TP DIRECT SETTLEMENT (J/NO: 70451)							
	OWNER: SUWANDI NGATURI							
	OWNER INSURER: NTUC							
	ACC DATE: 28/4/18							
	SURVEYED BY: MARCUS							
	DATE: 2/5/18 @ 14.05PM							
	REF NO:							
	TP INSURER: AXA INSURANCE							
	TP VEH: SKP2220D							
BO-NUM	NUMBER PLATE (N)	✓	25.00		25.00	1.75	26.75	
04715-SFE-000ZZ	FACERR BUMPER	✓	815.40	35	530.01	37.10	567.11	
91503-SZ3-003	CLIP ABUMPER	10 ✓	3.90	35	25.35	1.77	27.12	
04663-SFE-Q00ZZ	STIFFENERRR.BPR FACE	✓	445.70	35	289.70	20.28	309.98	
68100-SFE-305ZZ	TAILGATE COMP	✓	1,356.20	35	881.53	61.71	943.24	
74890-SFE-305ZN	GARNISH SETTAILGATE	✓	498.90	35	324.28	22.70	346.98	
75701-SFE-003	EMBLEMREAR CENTER	✓	30.20	35	19.63	1.37	21.00	
75722-SFE-003	EMBLEM RR (ODYSSEY)	✓	35.10	35	22.81	1.60	24.41	
71530-SFE-000ZZ	BEAM RR BUMPER	✓	101.70	35	66.10	4.63	70.73	
RS-4P	BUMPER SENSOR 4PCS	✓	180.00		180.00	12.60	192.60	
04733-SFE-000	RUBBERRR.W/SHIELD (S)	1	31.40	35	20.41	1.43	21.84	
73227-SFE-000	MOLDINGRR.W/SHIELD (S)	2	16.80	35	21.84	1.53	23.37	
73228-SFE-000	MOULDINGRR RR W/SHIELD (S)	1	18.30	35	11.89	0.83	12.72	
73278-SFE-000	MLDGL RR W/SHIELD (S)	1	18.30	35	11.89	0.83	12.72	
BO-WS-SEALANT	WINDSCREEN SEALANT (N) (S)	1	60.00		60.00	4.20	64.20	
	SUM PARTS:				2,490.44	174.33	2,664.77	
BOSUN	0672	✓	10.00		10.00	0.70	10.70	
	SUNDRIES							
BOJSE	0672	✓	80.00		80.00	5.60	85.60	
	BODY JOINT SEALANT.							
BOBC		✓	100.00		100.00	7.00	107.00	
	BODY UNDERSIDE COATING (N)							
BP00R		✓	250.00		250.00	17.50	267.50	
	APPLY BODY UNDERSIDE COATING (N).							
BML02I	EXT-YJ	✓	80.00	20	64.00	4.48	68.48	
	INSPECT RR LIGHTING MECHANISMS.							
	PERFORM WATER							
	TEST.(N)							
BA02R	EXT-YJ	✓	80.00	20	64.00	4.48	68.48	
	REMOVE & RENEW REVERSE							
	SENSORS-4 PCS (N)							
BMI02D		✓	280.00	20	224.00	15.68	239.68	
	REMOVE & INSTALL SPEAKER BOARD							
	RR SEATS TRUNK							
	LININGS GARNISHES & ETC.(N)							
BG02D	EXT-YJ	✓	300.00	20	240.00	16.80	256.80	
	REMOVE & INSTALL RR. WINDSCREEN.							
	(N)							
BKTG02R	EXT-YJ	✓	350.00	20	280.00	19.60	299.60	
	REMOVE & TRANSFER ITEMS TO NEW							
	TAILGATE. ADJUST &							
	ALIGN TAILGATE.(N)							

**HONDA****SERVICE PRE-INVOICE****KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer: WZA006 / AXA INSURANCE
Chassis No: JHMRB18505C202951
License No: SGE435U
Mileage: 263115
Engine No: K24A62002952

Document No: SVO18026460
Printed By: TWLIEW
Order Date: 8. May 2018
Order Time: 3:05:17 PM
Service Advisor: LIEW THYE WEI

BKRP02M	EXT-YJ CUT OFF & RENEW RR PANEL. STRAIGHTEN ALIGN RR FLOOR PAN & RENEW DAMAGE PARTS.	✓ 1,575.00	20	1,260.00	88.20	1,348.20
BP05R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)	✓ 1,600.00	20	1,280.00	89.60	1,369.60
		SUM LABOUR:		3,852.00	269.64	4,121.64
		TOTAL SGD		6,342.44	443.97	6,786.41
Total Payable (SGD)						6,786.41

GST Amount is calculated from individual line(s)



Service Request Details

Claim

S8M00FHX

Reference

None 

Loss Date

April 28, 2018

Request Date

April 30, 2018

Due Date

May 8, 2018

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

30042018 @ 12.11pm
Kiew veh not in.

Actions

Next Step

Agree to perform service

Decline Work

Accept Work

Vehicle Information

Incident Vehicle Registration #

SGE435U

Make

Model

Primary Contact/Insured

KOH WEE HOCK
33 HUME AVENUE, #10-14, 598734, Singapore
68711240
WEEHOCK.KOH@MERCATUS.COM.SG

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions

[Messages](#)[Invoices](#)[History](#)[Documents](#)[Assessment](#)[Metrics](#)[Notes](#)[New Message](#)**TYPE****SENT**

4/30/18 10:54 AM

FROM

TAN Jas

SUBJECT

DS

BODY

hi, please proceed to DS and seek mandate for sett...



<< Service Request Details

Claim S8M00FHX

Reference CC4/ASM18007912/ub3

Loss Date 28 April 2018

Request Date 30 April 2018

Due Date 30 April 2019

Vendor Name LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss Third Party Vehicle Damage

Services Pending verification - Direct Settlement

Actions

Next Step Finish the work

Complete Work

More

Vehicle Information

Incident SGE435U

Vehicle

Registration #

Make

Model HONDA/ODYSSEY

Service Address

...

Primary Contact/Insured

KOH WEE HOCK
33 HUME AVENUE, #10-14, 598734,
Singapore
68711240
WEEHOCK.KOH@MERCATUS.COM.SG

Claim Handler

TAN Jas
6568804844
jas.tan@axa.com.sg

Additional Instructions

Messages Invoices History Documents Assessment Metrics Notes

New Message

TYPE	SENT	FROM	SUBJECT	BODY	
?	14/8/18 11:44 AM	TAN Jas	Re:Request for Mandate approval for S8M00FHX	hi, you may have our mandate to proceed as IA adv...	↩
?	14/8/18 11:22 AM	LKK AUTO CONSULTANTS PTE LTD (TP)	Request for Mandate approval for S8M00FHX	Dear Jas, OID rear-ended to TP vehicle. We did cla...	↩
?	8/5/18 7:35 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	IA uploaded	.	↩

TYPE	SENT	FROM	SUBJECT	BODY	
	30/4/18 12:12 PM	LKK AUTO CONSULTANTS PTE LTD (TP)	VNI	Please be informed that vehicle currently not in t...	
	30/4/18 10:54 AM	TAN Jas	DS	hi, please proceed to DS and seek mandate for sett...	



SERVICE REQUESTS

MESSAGES

CLAIMS



Re:Request for Mandate approval for S8M00FHX

Type

Question

Message

hi, you may have our mandate to proceed as IA advised.

Reply

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SKP 2220D (Insd veh)	Model:	HONDA
	SGE 435U (TP veh)		ODYSSEY 2.4A
Date of Accident:	28/04/2018		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	10,900.35
Final Repair Cost	:	\$	6,786.41
Loss of Use	:	\$	900.00
Rental (if any)	:	\$	9 days at \$100.00 per day
LTA / GIA Search Fee	:	\$	days

Others:	:	\$
---------	---	----

	:	\$
Final Settlement Sum	:	\$ 7,686.41

Is Third Party Workshop GIA Registered? ☒ YES ☐ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability _____(%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: _____

BOLA Liability: _____100_____(%) Assessed Liability (*): _____(%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	KAH MOTOR CO. SDN. BHD.	:	\$ 7,686.41

NUR SHAQILAH BTE ABDOL
WAHAB

03/09/2018
Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

Claim	SBM0JFHX
Reference	
CC4ASM18007912Uub3c2	Loss Date
April 28, 2018	Request Date
April 30, 2018	Due Date
April 30, 2019	Vendor Name
LKK AUTO CONSULTANTS PTE LTD (TP)	Type of Loss
Third Party Vehicle Damage	Services
Pending verification - Direct Settlement	
Additional Instructions	

Actions	Document Type
Next Step	Finish the work
Complete Work New	
Document SubType	
Upload Documents	
Vehicle Information	
Incident Vehicle Registration #	SGE435U
Make	Service Address
HONDA ODYSSEY	Model
KOH WEE HOCK 33 HUME AVENUE, #10-14, 598734, Singapore 68711240 WEEHOCK.KOH@MERCATUS.COM.SG	Primary Contact/Insured
Claim Handler	
TAN Jas 6568804844 jas.tan@axa.com.sg	

NAME	TYPE	SUB-TYPE	AUTHOR	MESSAGES	INVOICES	HISTORY	DOCUMENTS
				Assessment	Metrics	Notes	

DATE UPLOADED

Claim

S8M00FHx

Reference

CC4/ASM18007912/Uub3c2

Loss Date

April 28, 2018

Request Date

April 30, 2018

Due Date

April 30, 2019

Vendor Name

LKK AUTO CONSULTANTS PTE LTD (TP)

Type of Loss

Third Party Vehicle Damage

Services

Pending verification - Direct Settlement

Additional Instructions

Actions

Next Step

Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

SGE435U

Make

Service Address

HONDA/ODYSSEY

Model

Primary Contact/Insured

KOH WEE HOCK

33 HUME AVENUE, #10-14, 598734, Singapore

68711240

WEEHOCK.KOH@MERCATUS.COM.SG

Claim Handler

TAN Jas

6568804844

jas.tan@axa.com.sg

Created User

VISHNU BATHAM Shekhar

Version Date

4/30/18 10:21 AM

Estimated Amount

6342.44

Approved Amount

6342.44

Status

Open

Share

Clone

Messages

Invoices

History

Documents

Assessment

Metrics

Notes

SHARE

CLONE

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration#	SGE435U	Purchase Date	mm/dd/yyyy
Registration State	SINGAPORE	Registration Date *	08/03/2006
Mileage	262756	Age of Vehicle	11
Driver Details			
CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION	POST SURVEY INFORMATION
Manufacturing Year	2005	Driver Name	YONAS NGATURU
Make	HONDA	Date of Birth	mm/dd/yyyy
Model	HONDA/ODYSSEY	Age	21
Type		Occupation	Unknown
Type of Paint		Education Qualification	Other
Chassis No	JHMRB18505C202951	Driving Experience	0
Engine No	K24A62002952	Driver License #	
Engine Capacity	2354 cc	License Type	

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	05/02/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	0		Engine Modification	Yes No
Young/Inexperienced/Unlicensed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	215/60R16	Rear Tyre Size	215/60R16
Front left side	YOKOHAMA 6mm	Rear left side	YOKOHAMA 6mm
Front right side	YOKOHAMA 6mm	Rear right side	YOKOHAMA 6mm

SERVICE REQUESTS MESSAGES CLAIMS

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary Parts

Auto

Approve

Deny

Submit All

Labour

Auto

Approve

Deny

Submit All

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTR%	DISC COUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1				BODY UNDERSIDE COATING			100	0	0	0	Reviewing			
	2				APPLY BODY UNDERSIDE COATING			250	0	0	0	Reviewing			
	3				INSPECT RR LIGHTING MECHANISMS, PERFORM WATER			64	0	0	0	Reviewing			
	4				REMOVE & RENEW REVERSE SENSORS			64	0	0	0	Reviewing			
	5				REMOVE & INSTALL SPEAKER BOARD RR SEAT'S TRUNK			224	0	0	0	Reviewing			
	6				REMOVE & INSTALL RR WINDSCREEN			240	0	0	0	Reviewing			
	7				REMOVE & TRANSFER ITEMS TO NEW TAILGATE, ADJUST &			280	0	0	0	Reviewing			
	8				CUT OFF & RENEW RR PANEL STRAIGHTEN			1250	0	0	0	Reviewing			
	9				SPRAY PAINTING ON REPAIRED OR REPLACED AREAS			1260	0	0	0	Reviewing			

Assessment Details

General & Workshop DetailsVehicle & Driver DetailsVehicle ConditionTaxes & RatioParts & LabourMiscellaneousSummary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
	1	DAYS OF REPAIR	Reviewing	8		
	2	NUMBER PLATE	Reviewing	25	BENT	
	3	FACERR BUMPER	Reviewing	530.01	DENTED / DEFORMED	
	4	MOULDING R RR	Reviewing	0	NOT NECESSARY	
	5	MOULDING L RR	Reviewing	0	NOT NECESSARY	
	6	SPACER R RR BPR SIDE	Reviewing	0	NOT NECESSARY	
	7	SPACER RR BUMPER SIDE	Reviewing	0	NOT NECESSARY	
	8	CLIP ABUMPER	Reviewing	25.35	NECESSARY	
	9	STIFFENER BPR FACE	Reviewing	289.7	BENT	
	10	WSTRIP TAILGATE	Reviewing	0	NOT NECESSARY	
	11	TAILGATE COMP	Reviewing	681.53	BADLY DENTED	

SERVICE REQUESTS MESSAGES CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Rollo Parts & Labour Miscellaneous Summary

Claim Amount \$6,342.44

Claim Amount \$6,342.44

CATEGORY	ESTIMATE	REVISED AMOUNT
Labour	\$3,762.00	\$3,762.00
Miscellaneous	\$2,580.44	\$2,580.44

Submit for Review