

22/03/2002

S.S. REC. BY:

REF: CS / MS618007918 / Uth22

Special Instruction:

S. UVA 107
M. Uthman

M. Uthman

ASSIGNMENT (Office)

From (Person):

Elaire Ngu

of

MS61

Date/Time: 30/04/2018 3:58pm

Estimated Cost:

Bill to:

OD / ~~FD~~ / WS / TP RES / OD RES / EVA / INV / MY / CS

To Inspect Vehicle No:

ABC 4301R

Insured:

SLB 1790T

at Workshop m/s

Tan Lim Motor

Tel:

6858 5151

of

51 Defu Lane 10

Policy No:

A804450542mx

Claim No:

555422

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

09042018

CA / REV / REP. / REV 24 HRS wpi

02052018 @ after 10am

H.O.D. Endorsement:

Date/Time:

30/04/2018 4:18pm

Person Contacted:

Caymen

Vehicle: IN ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate	
	ABC 4301R - CS3 / AIG 15017557 / Yuass1-1	DOA: 23/01/15
	SLB 1790T - CVI / VAL 18007051 / UH	DOA: 07/04/18
3/5-	Report via menmen. prell advise.	



nesses, Come And View 10 delivered, Another Priced Car by U...

Orchard Credit Pte Ltd

Posted: 22-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A

\$26,800

\$10,300 /yr

19-Jun-2009

1,998 cc

-

Luxury

Available

Elegant Silver, Spacious Sedan, Low Maintenance Cost, Very Well Maintained, Drive Away With Minimum Down Payment, Flexible In-house Loan Packages Available.

Prime Motor & Leasing

Posted: 25-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

Car Buying

Car Selling


Car Aftermarket

Car Ownership

On The Move

Lifestyle

9 Day Trial Guarantee
24 Hours Special Offers, Best Forecast



Toyota Camry 2.0A

\$32,800

\$10,910 /yr

01-Dec-2009

1,998 cc

-

Luxury

Available

Accident Free! Very Good Condition! No Repairs Needed! All Trade In Welcome, Major Bank And In House Loan Available! Night And Door Step Viewing Available! Hurry Call Our Friendly Staff To View And Dis...

Posted: 13-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A

\$27,800

\$11,310 /yr

09-Jun-2009

1,998 cc

-

Luxury

Available

Well kept And Maintained By Previous Owner, Ideal For Short Term Usage, Most Popular Japanese Sedan With Comfortable Legroom, Trade In And Loan Available, Hurry Make An Appt To View This Unit Now.

Lay A Lap Pte Ltd

Posted: 21-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A

\$31,800

\$10,900 /yr

29-Oct-2009

1,998 cc

119,000 km

Luxury

Available

Low Mileage, Excellent Condition! View To Believe! Hurry! Trade In Welcome, Car Available In Showroom For Viewing Now. Contact For More Details.

Posted: 13-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota



Toyota Camry 2.0A

\$25,800

\$9,700 /yr

11-Jun-2009

1,998 cc

-

Luxury

Available

10% Downpayment. \$1,451/mth. Good Condition. Flexible Loan Package. Instant Approval. Ex Bankrupt Welcome. High Trade In.

Posted: 09-Feb-2018 Tags: 2009 Toyota Camry, Toyota Camry, Toyota, Camry, Used Toyota

REF: MBH

Bureau

M/min

ASSIGNMENT

From: Date: 02052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBC 4301R

at Workshop m/s

Tan Lim Motor

of

51 Dehu Lane 10

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

33k.

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

6

days

Res.: Yes or No

Lum Sum:

13.1

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

65284

Vehicle: IN / OUT

6/2022

Veh No:

GBC 4301R

Yr Regn:

6/12

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

(M)

Make:

Nissan cabstar

c.c

2953

Colour:

S-her

A/C

Insured / Std / NI / NA

Sp. Reading

127699

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JN1SC2F2420R0348

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195 R15

R:

165 R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6/6

mm

L/Bal.

6

mm

L/Bal.

6/6

mm

D.O.A.

9/4/18

D.O.I.

2/5/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

LTA 23691 dep. Pl. 4 yrs. net 9309
check cost price on high side10/5/18 @ 3820.90 conf. call with willian.
Red: 12861.97 : 77%

RECEIVED 14 MAY 2018

Date/Time, File Pass to?

☐

: Preli. Report

1) 14/5 Typst

☒

: Final Report

Date/Time, File Return to?

2)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

3820.90

Days Of Repair:

6

Resurvey No. of Trip:

1

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

TOTAL

200

200

JustEquity Law Corporation

ADVOCATES & SOLICITORS • COMMISSIONER FOR OATHS

171 Chin Swee Road, #02-06 CES Centre, Singapore 169077.
Telephone (65) 6536 9339, (65) 6253 1812, (65) 6397 2008, (65) 6533 2327
Fax : (65) 6253 0120 (Conveyancing), (65) 6536 5368 (Litigation)
Email : info@juseq.com.sg

Writer: David Slow
Secretary: Serene Ng

Our Ref: JEC/161003/1016/LHS/SN

12 April 2018

BY FAX 6256 4315 &
CERTIFICATE OF POSTING

LKK Auto Consultants Pte Ltd
51 Ubi Ave 1
#01-25 Pay Ubi Industrial Park
Singapore 408933
Attention: Mr. Adrian Ling

Dear Sirs,

MC SUIT NO. 14394 OF 2017
ACCIDENT INVOLVING XD 3374X & XD 7320A ON 25.10.16

We refer to the above matter.

We act for the Plaintiffs, the owner of motor vehicle No. XD 3374X and M/s. Linda Phua Law Practice acts for the 1st & 2nd Defendants, the owner/driver of XD 7320A.

You have been appointed the Single Joint Expert(SJE) in order to examine the Plaintiffs car no. XD 3374X and give your views and recommendations regarding the Plaintiffs claim for damage to his car.

Kindly carry out a physical inspection of the Plaintiffs vehicle no. XD 3374X and forward to parties your SJE report in relation to the alleged claim for cost of repairs to the Plaintiffs car. Kindly liaise with our staff, Mr. Frankie Chan @ 6536 5339 on a date and time when the physical inspection of the Plaintiffs vehicle can be carried out.

We enclose the following documents for your perusal:-
1. GIA report of the Plaintiffs car no. XD 3374X; and
2. Survey report by Chartered Auto Assessors.

We look forward to hearing from you.

Yours faithfully

Encl: By Post

cc: Linda Phua Law Practice
Ref: LP/NTUC/2017-0379

By fax 65348911 Only

CONFIDENTIALITY CAUTION

This message is intended only for the use of the individual or entity to whom it is addressed and contains information that is privileged and confidential. If you, the reader of this message, are not the intended recipient, you should not disseminate, distribute or copy this communication. If you have received this communication in error, please notify us immediately by telephone and return the original message to us at the above address at our expense. Thank you.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2018 16:19 Sendback Est	11 Apr 2018 13:04 S\$16,521.87	30 Apr 2018 15:58 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

Insured:	Catherine Yu Hsio Lam, ID: S7522661F		
Main Claimant:	EONS TECHNOLOGIES PTE LTD, Co. Reg. No.: 199306529H		
Vehicle Reg. No.:	GBC4301R	Date of Loss:	09/04/2018 12:00 - :59 [69 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 555422	Policy/Cover Note No.:	A80445054QMX (Comprehensive) Coverage: 16/10/2017 - 15/10/2018
Vehicle Reg. No. (Insured):	SLB1790T	Policy No. (Claimant):	5093647721
		Excess:	S\$500.00
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/05/2018]		
Adj Asg. Remarks:	ON WP. Survey appt on 02/05/18, Owner leave car at 10.00am. Please contact us ASAP if you cannot attend this assignment.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Elaine Ngu Siau Mei

Date: 03 May 2018

Preliminary Advice

Insured Vehicle No	: SLB1790T	Accident Date	: 09/04/2018
TP Vehicle No	: GBC4301R	Assignment Date	: 30/04/2018
Make	: NISSAN CABSTAR	Est. Duration of Repair	: 6.00
Date of Inspection	: 02/05/2018		
Inspection At	: TAN LIM MOTOR PTE LTD (DEFU) 51 DEFU LANE 10 SINGAPORE 539216		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear & front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	16,521.87
Revised Amount	:S\$	6,154.84
Check Items (Estimated)	:S\$	674.94
Total	:S\$	6,829.78

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

() The vehicle is economical/not economical for repair.

(x) The above survey was conducted on a 'without prejudice' basis.

Sharon Yee

From: Sharon Yee
Sent: Wednesday, 26 December, 2012 7:07 PM
To: 'Kandiah, Jayadas'
Subject: RE: 800591177 Accident involving SKA4772T and SJR1041L on 23rd July 2012 along Defu Lane 1
Attachments: claimant invoice.pdf; email from wksp.pdf
Importance: High

Dear Sir,

We refer to the email below.

TP repairer had agreed on the COR at \$ 3370.50 (w/gst) but not the LOU at \$180.00 p/day.

We have been trying hard to negotiate with TP repairer on the LOU. However, TP claimant still insisted \$300p/day after much negotiation from \$350 to \$300.

Enclosed is the invoice TP claimant used to charge customers for their LOU for your perusal.

TP informed that their client's have taken over the conduct of this matter.(please see attached)

Hope the above helps.

BEST WISHES & HAPPY NEW YEAR 2013

Thank you

Best regards,
Sharon Yee
LKK Auto Consultants Pte Ltd
DID : 6749 4274
Fax : 6741 4108
Email : sharonyee@lkkauto.com

From: Kandiah, Jayadas [<mailto:Jayadas.Kandiah@chartisinsurance.com>]
Sent: Wednesday, 26 December, 2012 3:35 PM
To: Sharon Yee
Subject: 800591177 Accident involving SKA4772T and SJR1041L on 23rd July 2012 along Defu Lane 1

Dear Sharon,

I have taken over this file. Can you advise me where matters stand currently?
I understand that your were in negotiation with 3P to settle LOU at \$180.

With Best Regards,
Jayadas Kandiah (Mr.)
Claims Department

CHARTIS 

CHARTIS SINGAPORE INSURANCE PTE LTD
CHARTIS Building,
78 Shenton Way, #08-16, Singapore 079120
DID: 6419-1960 / Fax: 6835-7416
Email: Jayadas.Kandiah@chartisinsurance.com

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	09/04/2018 18:35
Date Of Accident	09/04/2018 13:00
Exact Location Of Accident	AYE BEFORE EXIT TO CLEMENTI ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBC4301R
-----------------------------	----------

Insured/Policyholder

Name Of Registered Owner	EONS TECHNOLOGIES PTE LTD
Co Reg No	199306529H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97623967

Vehicle Particulars

Manufacturer	NISSAN
Model	CABSTAR-3.0 5M/T ABS 2DR 2WD EURO 5 (A)
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	5093647721
Cover Note Number	

Driver

Name of Driver	TAN LYE HUAT
NRIC No	S1573536H
Date Of Birth	03/10/1963
Occupation	INDOOR
Date Of Driving Pass	13/03/1984
Driving Experience	34 YEARS AND 0 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address	BLOCK 475D UPPER SERANGOON CRESCENT #05-569
Postcode	537475
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	PAID DRIVER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2
Passenger 1	NAME: : UNKNOWN GENDER: : MALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

On 09.04.2018 at about 1300hrs, I was driving my vehicle (A: GBC4301R) along the extreme right lane of the AYE before exit to Clementi Road. While vehicles ahead stopped, I followed suit with brake applied. Suddenly, I felt an impact from behind. A vehicle (B: SLB1790T) had hit onto rear portion of my vehicle causes my vehicle moved forward and hit onto rear portion of vehicle (C: SKZ7182U). Vehicle A (GBC4301R): 1 male passenger on board. Vehicle B (SLB1790T): No passenger on board. Vehicle C (SKZ7182U): No passenger on board.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLB1790T
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SKZ7182U
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time:


Reporting Centre/Personnel's Signature
Name:
NRIC/FIN No.:

9/4/2018
1800 hrs

anyun
G28196666.

Sketch Plan Pg. 2

SKETCH PLAN



A: GBC4301R

B: SLB1790T

C: SKZ71824

AYE before exit to Clementi Road

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Refer to GIP Report.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time:

9/4/2018 1800hrs



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

aymen
G589964CX

1000



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	6529H
Vehicle Details	
Vehicle No.:	GBC4301R
Vehicle to be Exported:	No
Intended De-registration Date:	02 May 2018
Vehicle Make:	NISSAN
Vehicle Model:	CABSTAR 3.0 5M/T ABS 2DR 2WD TURBO
Primary Colour:	Silver
Manufacturing Year:	2011
Engine No.:	ZD30298053K
Chassis No.:	JN1SC2F24Z0850348
Maximum Power Output:	-
Open Market Value:	\$34,386.00
Original Registration Date:	14 Jun 2012
First Registration Date:	14 Jun 2012
Transfer Count:	1
Actual ARF Paid:	\$1,720.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	13 Jun 2022
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$57,589.00
COE Rebate Amount:	\$23,691.00
Total Rebate Amount:	\$23,691.00

The information contained herein is correct as at 02 May 2018

OK

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Company
Owner ID: 6529H

Vehicle Details

Vehicle No.: GBC4301R
Vehicle to be Exported: Yes
Intended De-registration Date: 09 Apr 2018
Vehicle Make: NISSAN
Vehicle Model: CABSTAR 3.0 5M/T ABS 2DR 2WD TURBO
Primary Colour: Silver
Manufacturing Year: 2011

Engine No.: ZD30298053K
Chassis No.: JN1SC2F24Z0850348

Maximum Power Output:

Open Market Value: \$34,386.00

Original Registration Date: 14 Jun 2012

First Registration Date: 14 Jun 2012

Transfer Count: 1

Actual ARF Paid: \$1,720.00

Intended PARF Rebate Details

PARF Eligibility: No

PARF Eligibility Expiry Date: -

PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 13 Jun 2022

COE Category: C - Goods Vehicle & Bus

COE Period(Years): 10

QP Paid: \$57,589.00

COE Rebate Amount: \$24,059.00

Total Rebate Amount: \$24,059.00

The information contained herein is correct as at 09 Apr 2018

OK




Post an Advertisement

Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

2007 Suzuki Swift Mega Sports 1.6M.



One And Only Fully Rebuilt Unit
 On The Market.
 Direct Owner StarAd



Browse by Category ▼

Sort by

6 vehicles

Nissan Cabstar

Advanced

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mile
Search Selection	Nissan Cabstar		Any	Any	2012	Any	
	Nissan Cabstar		\$35,800	\$8,140 /yr	24-Sep-2012	2,953 cc	
Fuel Type: Diesel Barely Hard To Find Box With Partition! Partition Can Be Taken It Out Too! Its 5 Doors! Can Segregate Your Items For D House Loan Available! Faster Call Us Now For More De...							
ABWIN (1994) Pte Ltd							
Posted: 26-Apr-2018 Tags: 2012 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan							
	Nissan Cabstar		\$32,800	\$8,560 /yr	29-Feb-2012	2,953 cc	
Fuel Type: Diesel Super Low Depreciation, \$3000 Drive Away, Super Good Condition, No Need Repair, Price Negotiable, High Loan With Lo Trade In Welcome, Call Me Now!							
ABWIN Bus Pte Ltd							
Posted: 24-Apr-2018 Tags: 2012 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan							
	Nissan Cabstar		\$36,800	\$8,190 /yr	30-Oct-2012	2,953 cc	
Fuel Type: Diesel Affordable Price And Negotiable! Low Mileage & Good Condition. Well Interior Maintenance. Reliable And Easy Maintenar Call / Whatsapp Now For View.							
ABWIN Bus Pte Ltd							
Posted: 24-Apr-2018 Tags: 2012 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan							
	Nissan Cabstar		\$35,800	\$8,140 /yr	24-Sep-2012	2,953 cc	
Fuel Type: Diesel 10 Feet Lorry With Box, 2 Sliding Doors For Easy Loading And Unloading. Can Remove Box And Replace With Open Or C New Paintwork. In House Loan Available, High Trade In, Call...							
ABWIN (1994) Pte Ltd							
ad: 23-Apr-2018 Tags: 2012 Nissan Cabstar, Nissan Cabstar, Nissan, Cabstar, Used Nissan							

- | | | |
|---|---|--------------------------------|
| 9 | 1 | Turbo Logo |
| 8 | 1 | Rear end panel insulation seal |
| 7 | 1 | Reverse sensor(1 set) |

Grand 460.00 200
17 80.00 X
acc 30.00
 Other Total: 1240.00

Total: \$19,628.70
 Gst (7%): \$1,374.01
 GRAND TOTAL: \$21,002.71

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN. PARTS PRICES ARE SUBJECT TO CHANGES.

Yours faithfully



Service Adviser

Ronnie Tan

HP : 8298 8933 Fax:6844 5185



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

TP INSURER: MSIG Insurance (Singapore) Pte. Ltd. (HQ)

Catherine Yu Hsio Lam
Clementi Avenue 4 Block 301
Singapore 368088

Claimant Insurer: NTUC Income Insurance Co-operative Ltd

Marius
2/5/18 @ 100%

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	TP005042018
Policy No:		Date of Loss:	09/04/2018
Vehicle Reg. No.:	GBC4301R	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	TAN LYE HUAT		

Make/Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Vehicle Reg. Date:	14/06/2012
Vehicle Colour:	SILVER		
Engine No:	ZD30298053K	Chassis No:	JN1SC2F24Z0850348
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	6		

not allowed
to be repaired before early
6 day. 2/5/18

Description of Accident/Loss

ON 09.04.2018 AT ABOUT 1300HRS, I WAS DRIVING MY VEHICLE (A: GBC4301R) ALONG THE EXTREME RIGHT LANE OF THE AYE BEFORE EXIT TO CLEMENTI ROAD. WHILE VEHICLES AHEAD STOPPED, I FOLLOWED SUIT WITH BRAKE APPLIED. SUDDENLY, I FELT AN IMPACT FROM BEHIND. A VEHICLE (B: SLB1790T) HAD HIT ONTO REAR PORTION OF MY VEHICLE CAUSES MY VEHICLE MOVED FORWARD AND HIT ONTO REAR PORTION OF VEHICLE (C: SKZ7182U). VEHICLE A (GBC4301R): 1 MALE PASSENGER ON BOARD. VEHICLE B (SLB1790T): NO PASSENGER ON BOARD. VEHICLE C (SKZ7182U): NO PASSENGER ON BOARD.

Present Location: TAN LIM MOTOR PTE LTD (DEFU)

COST OF CLAIMS

	Amount
Parts	13,711.87
Miscellaneous Items	0.00
Labour	1,810.00
Paintwork Labour	1,000.00
Towing	0.00
Gross Total (S\$)	16,521.87
+ GST 7.00% (S\$)	1,156.53
Nett Amount (S\$)	17,678.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Part prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No final modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:

This claim is handled by: SAM LOW PUI MUN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

8

1937.12

1938.1

1938.2

1938.3

1938.4

1938.5

1938.6

1938.7

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 11 Apr 2018)

Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: Tan Lim Motor Pte Ltd/GBC4301R/11/04/2018 13:04

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*tailgate lid	0.00	0.00	*3,483.80 F X
2	1		*tailgate lid 70km/h stricker	0	0.00	*15.00 FS 10
3	1		*tailgate lid Nissan sticker 35-00	0.00	0.00✓	*25.50 F ✓
4	1		*reverse sensor	0	0.00	*260.00 FS 200
5	1		*rear cargo check end panel	0.00	0.00	*886.40 F X
6	2		*rear lamp 75x22=150	0.00	0.00✓	*497.20 F ✓
7	2		*rear lamp panel	0.00	0.00	*230.00 F X
8	1		*rear license plate	0	0.00	*80.00 FS 14
9	1		*rear license plate lamp	0.00	0.00	*71.30 F X
10	1		*spare tyre holder	0.00	0.00	*198.70 F X
11	1		*side gate lid lock handle	0.00	0.00	*163.40 F X
12	2		*side gate lid rubber stopper	0.00	0.00	*25.80 F X
13	1		*front body panel	0.00	0.00	*1,412.70 F X
14	1		*wiper panel	0.00	0.00	*494.60 F X
15	1		*front body panel cabstar badge 30	0.00	0.00✓	*30.00 F ✓
16	1		*front centre grille 280	0.00	0.00✓	*438.40 F ✓
17	1		*front centre grille emblem badge	0.00	0.00	*55.10 F X
18	1		*front bumper 465	0.00	0.00✓	*859.20 F ✓
19	1		*front license plate	0	0.00	*105.10 FS 14
20	1		*n/s wiper arm	0.00	0.00	*103.10 F X
21	1		*n/s wiper arm cover 8.00	0.00	0.00✓	*15.10 F ✓
22	1		*wiper motor	0.00	0.00	*512.80 F X
23	1		*wiper linkage	0.00	0.00	*73.00 F X
24	1		*front wing mirror assy	0.00	0.00	*171.80 F X
25	1		*front wing mirror garnish base 85	0.00	0.00✓	*111.30 F ✓
26	2		*headlamp 241 260	0.00	0.00✓	*787.20 F 120
27	2		*headlamp lower garnish 60	0.00	0.00✓	*150.00 F 120
28	1		*n/s front corner panel	0.00	0.00	*389.90 F X
29	1		*front windshield glass weatherstrip	0.00	0.00	*93.50 F X
30	1		*front windshield glass weatherstrip sealant	0	0.00	*180.00 FS X
31	1		*front windshield glass weatherstrip sponge	0	0.00	*100.00 FS X

F=Franchise part. S=SpcNett.

Sub Total (\$\$) 12,019.90
 + Margin on L,N Items 15.00% (\$\$) 1,691.97
 Total Parts (\$\$) 13,711.87

Tan Lim Motor Pte Ltd/GBC4301R/11/04/2018 13:04. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

P-1446
 1572
 1662.90
 S.N - 238
 labour - 1920
 3820.90

12

13

14

15

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Paintwork Labour			
1	Putty and spray painting of the affected portion.	New 800	1,000.00
Labour Items			
2	To check electrical lighting concerned.	New 30	120.00
3	To remove and refit front windscreen glass.	New 11 X	150.00
4	To rust-proofing of the affected areas.	New 50	120.00
5	To reinstall of rear bumper parking sensor.	New 40	100.00
6	To transfer of tailgate fittings, fixture and perform waterseepage test.	New 11 X	120.00
7	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same. <i>include rear chassis member</i>	New 1000	1,200.00
Gross Labour Cost (\$\$)			2,810.00

Tan Lim Motor Pte Ltd/GBC4301R/11/04/2018 13:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

1920

< END OF ESTIMATES >

51 Defu Lane 10 Singapore 539216
Tel : 6858 5151 (24 hours) Fax : 6858 0877
email@tlmotor.com.sg www.tlmotor.com.sg
Co. Reg. No.: 199503965M GST Reg. No. : M2-8922054-2

1000



REPAIR DETAILS

Reference

Part Source:

(Last Synchronised: 10 May 2018)

Parts:

N/A

NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)

Labour:

Repairer's

(Price-denominated Standard List)

Print Code:

Tan Lim Motor Pte Ltd/GBC4301R/10/05/2018 14:21

Validity:

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info:

Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*side mirror (round) <i>115</i>	0.00	0.00	<i>3.00</i> *55.00 F
2	1		*left finisher side garnish upper <i>(ADD)</i>	0.00	0.00	<i>4.50</i> *85.00 F
						<i>18</i>
Sub Total (S\$)						140.00
+ Margin on L,N Items 15.00% (S\$)						21.00
Total Parts (S\$)						161.00

Tan Lim Motor Pte Ltd/GBC4301R/10/05/2018 14:21. Not valid without Reference section.
Generated using Merimen e-Claims IEAS



日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
 TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
 48A SUNGEI KADUT AVE SINGAPORE 729672
 TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
 GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

TOYOTA GENUINE PARTS
Dept Direct: 6305 9610

LEXUS
Dept Direct: 6305 9611

DAIHATSU
Dept Direct: 6417 9792

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
 Forch (Made in Germany)
 Spark plug: Nippon Denso, NGK (Made in Japan)

IAN LIM MOTOR PTE LTD
 51 DEFU LANE 10

SINGAPORE 539216
 TEL : 68585151 FAX : 68580877
 ATTN : HUA : 93424525

TAX INVOICE : AR201805-00236
 DATE : 02/05/2018
 CUSTOMER ID : TAN004
 VEH REG. NO. : GBC4301R
 TERMS : 30 days
 PO NO. :
 PAGE NO. : Page 1 of 2
 CURR : SGD

TP 201804005

SQ STOCKID	DESCRIPTION	Stk Loc	QTY	UPPRICE	AMOUNT
1. N26540-T8700 F22 F23 U41	TAIL LAMP RH	PA PL3-E1-04A	1	✓ 75.00	75.00
2. N26545-T8700 F22 F23 U41	TAIL LAMP LH F24	PA PL3-D1-06A	1	✓ 75.00	75.00
3. N62010-MA010/MD80A F24	FRT BUMPER & REFORCEMENT	PA PL4-D1-F	1	465.00	465.00
4. N61877-MA160/B F24	FINISHER SIDE GARNISH UPPER LH (B)	PA PL3-A1-04A	1	85.00	85.00
5. N26075-MA000/A F24	H/LAMP UNIT LH	PA PL3-B1-02B	1	260.00	260.00
6. N96331-ST002 F24	SIDE MIRROR (ROUND)	PA PL3-D1-06A	1	55.00	55.00
7. N62320-MA000/MA02B F24	RAD GRILLE	PA PL3-B1-130	1	280.00	280.00

TP 201804005

CONTINUE NEXT PAGE

02/05/2018 10:57:55AM

Goods Sold are not refundable for Cash.
 Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 02/05/2018 10:29:48AM

ORIGINAL

p-1466

PL3-b

280

PA 01-06A

1

日美汽車私人有限公司

JAE AUTO PTE LTD


BIK 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg
GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939

Arrange By	Driver
------------	--------



Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made In Japan)

TAN LIM MOTOR PTE LTD
51 DEFU LANE 10

SINGAPORE 539216
TEL : 68585151 FAX : 68580877
ATTN : HUA : 93424525

(2)

TAX INVOICE : AR201805-002
DATE : 02/05/2018
CUSTOMER ID : TAN
VEH REG. NO. : GBC430
TERMS : 30 da
PO NO. :
PAGE NO. : Page 2 of 2
CURR : SGD

TP 201804005

8

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8. N75894-MB40B/MA00A	H/LAMP LOWER COVER GARNISH LH	PA	1	60.00	60.00
F24		PL3-D1-05A			

[Handwritten signature]

TP 201804005

	SUB-TOTAL :	1,355
	ADD GST 7.00 %	94
E. & O.E	TOTAL AMOUNT SGD :	1,449

[P] 02/05/2018 10:57:55AM
Goods Sold are not refundable for Cash.
Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

[E] 02/05/2018 10:29:48A

JAE Auto Pte. Ltd.

Sales Executive: JOE

This is computer generated document.
No signature is required.



Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

PAGE
CURR

PRICE AMOUNT

日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939



TOYOTA
GENUINE PARTS



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6

TAN LIM MOTOR PTE LTD
51 DEFU LANE 10
GATE NO.: M2-0119201-3 CO. REG. NO.: 199307741M

SINGAPORE 539216
TEL : 68585151 FAX : 68580877
ATTN : HUA : 93424525

Wiper blade: NWE Nippon Wiper blade, Silver (Made in Korea)

Spark plug: Denso NGK (Made in Japan)

TAX INVOICE AR201805-004

DATE 02/05/20

CUSTOMER ID : TAN0

VEH REG. NO. : GBC430

TERMS : 30 da

PO NO. :

PAGE NO. : Page 1 of

CURR. : SC

TP 201804005

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1	N65092-MB40A	CABSTAR EMBLEM WIPER PANEL	MO	1	30.00	30.00
F24			SUPPLIER			

SUB-TOTAL : 30
ADD GST 7.00 % 2

E. & O E TOTAL AMOUNT SGD : 32

[P] 02/05/2018 11:57:44AM

[E] 02/05/2018 11:57:32

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JOE



* A R 2 0 1 8 0 5 - 0 0 4 2 2 *

This is computer generated document.
No signature is required.

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

日美汽車私人有限公司

JAE AUTO PTE LTD

Bik 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

TAN LIM MOTOR PTE LTD
51 DEFU LANE 10

SINGAPORE 539216

TEL : 68585151 FAX : 68580877

ATTN : HUA : 93424525

TP 201804005

Wiper blade: NWB (Nippon Wiper blade), Slipper (Made in Korea)
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201805-002
DATE : 02/05/20
CUSTOMER ID : TAN0
VEH REG. NO. : GBC430
TERMS : 30 da
PO NO. :
PAGE NO. : Page 1 of
CURR : SC

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1.	N28882-MB400 F24	WIPER ARM COVER	CC CC9-D-01B2	1	8.00	8.00

[Handwritten signature]

TP 201804005

SUB-TOTAL : 8.00
ADD GST 7.00 % 0.50

E. & O E TOTAL AMOUNT SGD : 8.50

[P] 02/05/2018 12:31:40PM

[E] 02/05/2018 10:34:47AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: JOE

This is computer generated document.
No signature is required.



* A R 2 0 1 8 0 5 - 0 0 2 5 0 *

Goods Received in Good Order

Signature / Co Stamp / Date

ORIGINAL

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

TAN LIM MOTOR PTE LTD
51 DEFU LANE 10

SINGAPORE 539216

TEL : 68585151 FAX : 68580877

ATTN : HUA : 93424525

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9939TOYOTA
GENUINE PARTS

LEXUS



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: NWB (Nippon Wiper blade), Super (Made in Korea).

Spark plug: Bosch (Made in Germany)

Spark plug: Nippon Denso (Made in Japan)

TAX INVOICE AR201805-00245

DATE : 02/05/2018

CUSTOMER ID : TAN004

VEH REG. NO. : GBC4301R

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR. : SGD

TP 201804005

SQ STOCKID

DESCRIPTION

StkLoc

QTY

U/PRICE

AMOUNT

1. N99098-DA000/DA200

TAILGATE STICKER NISSAN
RED 99099-1T902

MO

1

35.00

35.00

F23 NEW F24

2. N61877-MA010

F24

SIDE GARNISH COVER LH (S)

2H26SD

MO

1

18.00

18.00

2P13

SUB-TOTAL : 53.00

ADD GST 7.00 % 3.71

E. & O.E

TOTAL AMOUNT SGD : 56.71

[P] 02/05/2018 10:36:39AM

[E] 02/05/2018 10:33:51AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : JOE



* A R 2 0 1 8 0 5 - 0 0 2 4 5 *

Goods Received in Good Order

This is computer generated document.

No signature is required.

Signature / Co Stamp / Date

ORIGINAL

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	10 Apr 2018 16:19	11 Apr 2018 13:04	30 Apr 2018 15:58	S\$3,820.90	S\$3,820.90		Pending for Survey Report
	Sendback Est	S\$16,521.87	Edit Adj Rpt	Edit Estimates	View Rpt		Cancel Case
Supp #1	10 May 2018 14:20	10 May 2018 14:21	10 May 2018 14:21			(Combined)	Combined with Main Uncombine Suppl.
		S\$161.00					

Main	Reference	Claim Details	Documents	Show All
-------------	------------------	----------------------	------------------	--------------------------

CLAIM SUBFOLDER DETAILS

Insured:	Catherine Yu Hsio Lam , ID: S7522661F		
Main Claimant:	EONS TECHNOLOGIES PTE LTD , Co. Reg. No.: 199306529H		
Vehicle Reg. No.:	GBC4301R	Date of Loss:	09/04/2018 12:00 - :59 [69 Months and 26 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 555422	Policy/Cover Note No.:	A80445054QMX (Comprehensive) Coverage: 16/10/2017 - 15/10/2018
Vehicle Reg. No. (Insured):	SLB1790T	Policy No. (Claimant):	5093647721
		Excess:	S\$500.00
Repairer:	Tan Lim Motor Pte Ltd (Defu) 51 Defu Lane 10, 539216 Defu Lane - Tel: 6858 5151		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Elaine Ngu Siau Mei - 6594 2540]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 30/05/2018]		
Adj Asg. Remarks:	ON WP. Survey appt on 02/05/18, Owner leave car at 10.00am. Please contact us ASAP if you cannot attend this assignment.		

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)
[Search Tasks](#)
[Create New Task](#)
[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

GBC4301R (555422)
[SLB1790T]
TP
EONS TECHNOLOGIES PTE LTD
Apr 9 2018 12:00PM
[Catherine Yu Hsio Lam]
Tan Lim Motor Pte Ltd

Upload Documents Upload Photos Compose New Letter			View View In Browser	
Assessment Reports			1 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	11/04/18 13:04	Repairer Estimates	 Load HTM	☐
2	10/05/18 14:21	Repairer Estimates Suppl. #1	 Load HTM	☐
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	03/05/18 16:04	Adjuster Immediate Advice	 Load HTM	☐
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/18 13:22	Chassis Number	 Load JPG	☒
2	02/05/18 13:22	Odometer Reading	 Load JPG	☒
3	02/05/18 13:22	General View	 Load JPG	☒
4	02/05/18 13:22	General View	 Load JPG	☒
5	02/05/18 13:22	General View	 Load JPG	☒
6	02/05/18 13:22	General View	 Load JPG	☒
7	02/05/18 13:22	General View	 Load JPG	☒
8	02/05/18 13:22	General View	 Load JPG	☒
9	02/05/18 13:22	General View	 Load JPG	☒
10	02/05/18 13:22	General View	 Load JPG	☒
11	02/05/18 13:22	General View	 Load JPG	☒
12	02/05/18 13:22	General View	 Load JPG	☒
13	02/05/18 13:22	General View	 Load JPG	☒
14	02/05/18 13:22	General View	 Load JPG	☒
15	02/05/18 13:22	General View	 Load JPG	☒
16	02/05/18 13:22	General View	 Load JPG	☒
17	02/05/18 13:22	General View	 Load JPG	☒
18	02/05/18 13:22	General View	 Load JPG	☒
19	02/05/18 13:22	General View	 Load JPG	☒
20	02/05/18 13:22	General View	 Load JPG	☒
21	02/05/18 13:22	General View	 Load JPG	☒
22	02/05/18 13:22	General View	 Load JPG	☒
23	02/05/18 13:22	General View	 Load JPG	☒
24	02/05/18 13:22	General View	 Load JPG	☒
25	02/05/18 13:22	General View	 Load JPG	☒
26	02/05/18 13:22	General View	 Load JPG	☒
27	02/05/18 13:22	General View	 Load JPG	☒
28	02/05/18 13:22	General View	 Load JPG	☒
29	02/05/18 13:22	General View	 Load JPG	☒
30	02/05/18 13:22	General View	 Load JPG	☒
31	02/05/18 13:22	General View	 Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
32	02/05/18 13:22	General View		☒
33	02/05/18 13:22	General View		☒
34	02/05/18 13:22	General View		☒
35	02/05/18 13:22	General View		☒
36	02/05/18 13:22	General View		☒
37	02/05/18 13:22	General View		☒
38	02/05/18 13:22	General View		☒
39	02/05/18 13:22	General View		☒
40	02/05/18 13:22	General View		☒
41	02/05/18 13:22	General View		☒
42	02/05/18 13:22	General View		☒
43	02/05/18 13:22	General View		☒
44	02/05/18 13:22	General View		☒
45	02/05/18 13:22	General View		☒
46	02/05/18 13:22	General View		☒
47	02/05/18 13:22	General View		☒
48	02/05/18 13:22	General View		☒
49	02/05/18 13:22	General View		☒
50	02/05/18 13:22	General View		☒
51	02/05/18 13:22	General View		☒
52	02/05/18 13:22	General View		☒
53	02/05/18 13:22	General View		☒
54	02/05/18 13:22	General View		☒
55	02/05/18 13:22	General View		☒
56	02/05/18 13:22	General View		☒
57	02/05/18 13:22	General View		☒
58	02/05/18 13:22	General View		☒
59	02/05/18 13:22	General View		☒
60	02/05/18 13:22	General View		☒
61	02/05/18 13:22	General View		☒
62	02/05/18 13:22	General View		☒
63	02/05/18 13:22	General View		☒
64	02/05/18 13:22	General View		☒
65	02/05/18 13:22	General View		☒
66	02/05/18 13:22	General View		☒
67	02/05/18 13:22	General View		☒
68	02/05/18 13:23	General View		☒
69	02/05/18 13:23	General View		☒
70	02/05/18 13:23	General View		☒
71	02/05/18 13:23	General View		☒
72	02/05/18 13:23	General View		☒
73	02/05/18 13:23	General View		☒
74	02/05/18 13:23	General View		☒
75	02/05/18 13:23	General View		☒
76	02/05/18 13:23	General View		☒
77	02/05/18 13:23	General View		☒
78	02/05/18 13:23	General View		☒
79	10/05/18 08:59	Reinspection Photo		☒
80	10/05/18 08:59	Reinspection Photo		☒
81	10/05/18 08:59	Reinspection Photo		☒

Assessment Reports			1 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
82	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
83	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
84	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
85	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
86	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
87	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
88	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
89	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
90	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
91	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
92	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
93	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
94	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
95	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
96	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
97	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
98	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
99	10/05/18 08:59	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	17/04/18 11:41	TP SKZ7182U GIA REPORT From:OD - Reg. No: SLB1790T, Claimant: CATHERINE YU HSIO LAM	 Load PDF	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (Internal Surveyor)	Thumbnail	Print
1	19/04/18 11:13	Email - Survey Appt	 Load PDF	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	18/05/18 14:30	Parts Invoice	 Load PDF	
2	18/05/18 14:45	Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	09/04/18 18:42	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	09/04/18 18:42	Accident Photo	 Load JPG	☒
2	09/04/18 18:42	Accident Photo	 Load JPG	☒
3	09/04/18 18:42	Accident Photo	 Load JPG	☒
4	09/04/18 18:42	Accident Photo	 Load JPG	☒
5	09/04/18 18:42	Accident Photo	 Load JPG	☒
6	09/04/18 18:42	Accident Photo	 Load JPG	☒
7	09/04/18 18:42	Accident Photo	 Load JPG	☒
8	09/04/18 18:42	Accident Photo	 Load JPG	☒
9	09/04/18 18:42	Accident Photo	 Load JPG	☒
10	09/04/18 18:42	Accident Photo	 Load JPG	☒
11	09/04/18 18:42	Accident Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	Tan Lim Motor Pte Ltd (Defu)	Thumbnail	Print
1	09/04/18 18:41	Sketch Plan	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Repairer ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG18007918/UTBE2**Date:** 18/05/2018**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A80445054QMX
Claimant Vehicle No :	GBC4301R	Insured Vehicle No :	SLB1790T
Date of Loss:	09/04/2018	Nature of Claim:	TP
		Claim No:	555422

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBC4301R		
Make & Model:	NISSAN CABSTAR, 3.0 5M/T ABS 2DR 2WD EURO 5 (A)	Engine No:	ZD30298053K
Reg. Date:	14/06/2012 (Man. Year: 2011)	Chassis No:	JN1SC2F24Z0850348
Colour:	Silver	Odometer:	127699 km
Engine Capacity:	2953 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15	Rear Tyre Size:	165 R13 (D)
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6/6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6/6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,872.87	1,900.90	11,971.97	86.30
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,810.00	1,120.00	690.00	38.12
Paintwork Labour	1,000.00	800.00	200.00	20.00
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,682.87	3,820.90	12,861.97	77.10
+ GST 7.00/7.00% (S\$)	1,167.80	267.46	900.34	77.10
Nett Amount (S\$)	17,850.67	4,088.36	13,762.31	77.10

INSPECTION

Date of Assignment:	30/04/2018	Present Location:	Tan Lim Motor Pte Ltd (Defu)
Date Inspected:	02/05/2018	Inspected At:	51 Defu Lane 10
			Singapore 539216
Estimated Period of Repair:	6.0 days		

Adjuster: MARCUS CHUA**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 18 May 2018)
Parts: N/A NISSAN CABSTAR 3.0 5M/T ABS 2DR 2WD EURO 5 (A) (Model not available in database)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for GBC4301R)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*tailgate lid (WCP)	Repair	3,483.80 F	*- F
2	1		*tailgate lid 70km/h stricker	Necessary	15.00 FS	*10.00 FS
3	1		*tailgate lid Nissan sticker (WCP)	Necessary	25.50 F	*35.00 F
4	1		*reverse sensor	Cracked	260.00 FS	*200.00 FS
5	1		*rear curgo check end panel (WCP)	Repair	886.40 F	*- F
6	2		*rear lamp (WCP)	Cracked	497.20 F	*150.00 F
7	2		*rear lamp panel (WCP)	Repair	230.00 F	*- F
8	1		*rear license plate	Bent	80.00 FS	*14.00 FS
9	1		*rear license plate lamp (WCP)	Not Necessary	71.30 F	*- F
10	1		*spare tyre holder (WCP)	Not Necessary	198.70 F	*- F
11	1		*side gate lid lock handle (WCP)	Not Necessary	163.40 F	*- F
12	2		*side gate lid rubber stopper (WCP)	Not Necessary	25.80 F	*- F
13	1		*front body panel (WCP)	Repair	1,412.70 F	*- F
14	1		*wiper panel (WCP)	Not Necessary	494.60 F	*- F
15	1		*front body panel cabstar badge (WCP)	Necessary	30.00 F	*30.00 F
16	1		*front centre grille (WCP)}	Cracked	438.40 F	*280.00 F
17	1		*front centre grille emblem badge (WCP)}		55.10 F	*- F
18	1		*front bumper (WCP)	Bent	859.20 F	*465.00 F
19	1		*front license plate	Bent	105.10 FS	*14.00 FS
20	1		*n/s wiper arm (WCP)	Not Necessary	103.10 F	*- F
21	1		*n/s wiper arm cover (WCP)	Missing	15.10 F	*8.00 F
22	1		*wiper motor (WCP)	Not Necessary	512.80 F	*- F
23	1		*wiper linkage (WCP)	Not Necessary	73.00 F	*- F
24	1		*front wing mirror assy (WCP)	Not Necessary	171.80 F	*- F
25	1		*front wing mirror garnish base (WCP)	Broken	111.30 F	*85.00 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*headlamp (WCP)	N/S Cracked	787.20 F	*260.00 F
27	1		*headlamp lower garnish (WCP)	N/S Cracked	150.00 F	*60.00 F
28	1		*n/s front corner panel (WCP)	Repair	389.90 F	*- F
29	1		*front windshield glass weatherstrip (WCP)	Not Necessary	93.50 F	*- F
30	1		*front windshield glass weatherstrip sealant	Not Necessary	180.00 FS	*- FS
31	1		*front windshield glass weatherstrip sponge	Not Necessary	100.00 FS	*- FS
Supplementary #1						
32	1		*side mirror (round) (WCP)	Broken	55.00 F	*55.00 F
33	1		*left finisher side garnish upper (WCP)	Missing	85.00 F	*18.00 F

F=Franchise part. S=SpcNett.

Sub Total (S\$)	12,159.90	1,684.00
+ Margin on L,N Items 15.00/15.00% (S\$)	1,712.97	216.90
Total Parts (S\$)	13,872.87	1,900.90

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Paintwork Labour</u>				
1	Putty and spray painting of the affected portion.	New	1,000.00	800.00
<u>Labour Items</u>				
2	To check electrical lighting concerned.	New	120.00	30.00
3	To remove and refit front windscreen glass.	New	150.00	0.00
4	To rust-proofing of the affected areas.	New	120.00	50.00
5	To reinstall of rear bumper parking sensor.	New	100.00	40.00
6	To transfer of tailgate fittings, fixture and perform waterseepage test.	New	120.00	0.00
7	Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	New	1,200.00	1,000.00
Gross Labour Cost (S\$)			2,810.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

