

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST1804-039

DATE : 30-Apr-2018

POLICY NO. : FWD PNPV2017-00009195

VEHICLE REG. NO. : SLJ6230T

VEHICLE MAKE : MAZDA2 5-DOOR HATCHBACK 1.5L SP

TO Motor Claim Department
EQ Insurance Company Limited
 22 Gemmill Lane, Singapore 069257
 Tel: 6223 9433
 Fax: 6224 3903

FOR SURVEYOR

--

ESTIMATE REPAIR COST

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Front Door LH	1	\$ 1,180.00	\$ 1,180.00
2	Front Door Out Weather Seal LH	1	\$ 100.00	\$ 100.00
3	Front Door Inner Seal LH	1	\$ 120.00	\$ 120.00
4	Front Door Rear Moulding (Black Sticker) LH	1	\$ 50.00	\$ 50.00
5	Rear Door LH	1	\$ 1,180.00	\$ 1,180.00
6	Rear Door LH Hinge Lower	1	\$ 60.00	\$ 60.00
7	Rear Door Window Regulator LH	1	\$ 220.00	\$ 220.00
8	Rear Door Out Weather Seal LH	1	\$ 120.00	\$ 120.00
9	Rear Door Inner Seal LH	1	\$ 120.00	\$ 120.00
10	Rear Door Front Moulding (Black Sticker) LH	1	\$ 50.00	\$ 50.00
Total Spare Parts				\$ 3,200.00
	<u>SPECIAL NETT</u>			
Total Special Nett				\$ -
	<u>LABOUR</u>			
11	Spray painting Rear Fender LH, Sill Panel LH and 2 Doors LH	1	\$ 1,000.00	\$ 1,000.00
12	Repair, Replace and Refill Affected Accident Area	1	\$ 1,000.00	\$ 1,000.00
13	Transfer Door Fittling and Window Mechanism to New Door	2	\$ 100.00	\$ 200.00
14	Reset SRS and Door lock Sensor/Remote	1	\$ 150.00	\$ 150.00
15	Repair Rear Rim LH	1	\$ 100.00	\$ 100.00
16	Wheels Computer Alignment / Wheel Balancing	1	\$ 80.00	\$ 80.00
17	Check and rectify electrical wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,560.00
Amount Before Excess				\$ 5,760.00
Add GST @ 7%				403.20
Total Amount Payable				\$ 6,163.20

Estimate prepared by: **Raymond Tan**

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.

Please arrange this vehicle to be surveyed soonest possible. Thank you.