

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422/ 6745 4422 Fax : 6747- 6720 REG NO 200501102H

CHINA TAIPING INSURANCE (SINGAPORE) PTE LTD

3 Anson Road #16-00
 Springleaf Tower
 Singapore 079909
 Tel : 6389 - 6111
 Fax : 6224 - 7478 / 7175

Quotation
 DATE : 30.04.2018
 VEH NO : SKU8652A
 MODEL : Honda Vezel
 D O A : 27.04.2018
 YR REF : GT2567E

Vivian

Attn : Motor Claim Dept

(Pls arrange vehicle survey & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SKU8652A (Honda Vezel)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>deformed</i>	1	880.00 ✓
2	Rear Bumper Clips <i>new</i>	1 set	30.00 ✓
3	Rear Bumper Side Holder - LH & RH <i>new</i>	2	70.40 ✓
4	Rear Bumper Reflector - LH & RH <i>RH cracked</i>	2	302.40 151.20 ✓
5	Rear Side Bumper - LH & RH <i>Repair</i>	2	390.00 X
6	Rear End Panel <i>dent</i>	1	585.00 ✓
7	Rear End Panel Top Garnish <i>deformed</i>	1	168.00 ✓
8	Rear End Panel Buzzer <i>Not New</i>	1	135.00 X
9	Taillamp - LH & RH <i>RH cut</i>	2	921.20 460.60 ✓
10	Tailgate <i>Distorted</i>	1	1,100.00 ✓
11	Tailgate Lock <i>damaged</i>	1	182.00 ✓
12	Tailgate Weatherstripe <i>cut</i>	1	145.00 ✓
13	Tailgate Inner Trim Board <i>deformed</i>	1	368.20 ✓
14	Tailgate Inner Trim Board Clips <i>new</i>	1 set	30.00 ✓
15	Tailgate Reflector - LH & RH <i>RH cut</i>	2	729.60 364.80 ✓
16	Tailgate Glass Moulding <i>new</i>	1	133.80 ✓
17	Spare Tyre Panel Top Cover <i>new</i>	1	235.00 X
18	Tool Box Sponge	1	260.90 X
19	Rear Exhaust Pipe <i>3 x 1 1/2"</i>	1	784.50 X
20	Rear Exhaust Mounting <i>new</i>	1	45.00 X

4669

3735.20

Less 20%

\$ 7,496.00
 (1,499.20)
 \$ 5,996.80

S/NETT ITEMS

1	Rear Number Plate <i>new</i>	1	30.00 X
2	Rear Number Plate Holder <i>new</i>	1	30.00 X
3	Reverse Sensor <i>damaged</i>	1 set	280.00 200 ✓

RE : ESTIMATE FOR ACCIDENT REPAIR SKU8652A (Honda Vezel)

4	Rear End Panel Sealant <i>Her</i>	1	60.00 ✓
5	Tailgate Glass Sealant <i>Her</i>	1	60.00 ✓
5	Rear Camera <i>Damaged</i>	1	480.00 400
			720
			\$ 940.00
Total parts			<u>\$ 6,936.80</u>

LABOUR CHARGE

1	To knocking out rear portion & renew above parts	\$ 1,200.00 <i>80</i>
2	To putty & spray up paint works	\$ 1,200.00 <i>80</i>
3	To check wiring system	\$ 50.00 <i>30</i>
4	To underseal	\$ 150.00 <i>50</i>
5	To remove reverse sensor	\$ 100.00 <i>50</i>
6	To remove rear camera	\$ 100.00 <i>50</i>
7	To remove upholstery	\$ 150.00 <i>80</i>
8	To remove exhaust pipes	\$ 150.00 <i>X</i>
9	To transfer tailgate fittings	\$ 150.00 <i>80</i>
10	To remove tailgate top spoiler	\$ 120.00 <i>60</i>
11	To remove tailgate glass	\$ 150.00 <i>120</i>
Total Labour		\$ 3,520.00
Grand Total		<u>\$ 10,456.80</u>

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total: 6575.20
L/s: 5250
06 Days