

ASS. REC. BY:

REF: CS/MS618007930 / Grbnz

Special Instruction:

Surveyor

AR

ASSIGNMENT (Office)

From (Person):

Angie Tiong

of

MS6

Date/Time:

30042018 1:54pm

Estimated Cost:

Bill to:

OD / TP / AWS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SL 4208L

Insured:

Public Liability

at Workshop m/s

Kah Motor

Tel:

8100 6306

of

15 ubi Rd 4

Policy No:

Claim No:

546701 PLY

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27/2007

(Client's Record)

CA / REV / REP / REV 24 HRS 'DS'

02052018 @ 10am

H.O.D. Endorsement:

Date/Time:

30042018 3:04pm

Person Contacted:

Ang

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SL 4208L - X

Public Liability - X

9/5/18

Email preli revised to Angie

29/6/18

@ 4:45pm Ang said vehicle will send for repair on 3/7/18

9/7/18

@ 8:43am Ang said no G/A report

Insurance  
Maiman

Hand.

REF: msth

ASSIGNMENT

From: \_\_\_\_\_ Date: 02 05 2018

Estimated Cost: \_\_\_\_\_

OD /  TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SL2 4208L

at Workshop m/s: Kah Motor

of: 1B Ubi Rd 4

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: Any

(Policy Condition) Exam

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'DS'

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLL4208L Yr Regn: 24 Feb 2017

Type:  M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or (497)

Make: Honda HRV cc 1.5

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 22689 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JHM RU 1810GX 201858

Gen. Cond:  Good / Fair / Poor / Burnt

Steering:  In order / Jammed / Leaked / Burnt or

Brake:  In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD /  RIM or

Tyre Size: F: 215/60 R16  
R: "

BS /  DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front	Rear
R/Bal. 6 mm	R/Bal. 6 mm
L/Bal. 6 mm	L/Bal. 6 mm

D.O.A. \_\_\_\_\_ D.O.I. 02-05-18

Survey held at: w/s 10:30 AM

Des. of Damages: Frt / Rear /  O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
9/7/18	Final fig \$ 2534.95 confirmed by email (Ref 671-38, 217)
RECEIVED 09 JUL 2018	

Date/Time. File Pass to?  : Prefi. Report

1)  : Final Report

Date/Time. File Return to? \_\_\_\_\_

2) 9/7 - typist

Report Format: TP

Lump Sum / I.B.I. (\$) 2534.95

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

150

Add Fee:  Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

TOTAL



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: 546701PLY  
Our ref: CS/MSG18007930/Gvb

Date: 9/5/2018

The Motor Claims Department  
M/s MSIG INSURANCE (SINGAPORE) PTE LTD

WITHOUT PREJUDICE

Dear Sir/Madam,

**PRELIMINARY ADVICE OF VEHICLE NO. SLL 4208L**


We thank you for your instruction on 30/4/2018

Please be informed that we had conducted the inspection of the above mentioned vehicle on 2/5/2018 at the premises of M/s KAH MOTOR and have the following to report-

Workshop Estimate Amount	: S\$3,206.33
Revised Estimate Amount	: S\$2,757.81
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the o/s portion



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

XING GUO QIANG (HP 8288 0282)

M.MATAI, AMSAE-A

Automobile Assessor

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Wednesday, 9 May 2018 8:06 AM  
**To:** 'Angie Tiong'  
**Cc:** SUR  
**Subject:** RE: New Assignment - Survey of Third party vehicle SLL4208L - MSIG Ref: 546701 PLY - Public Liability case  
**Attachments:** SLL 4208L PRELI REVISED.pdf

Dear Angie,

Enclosed preliminary revised of vehicle SLL 4208L  
Date of survey: 2/5/2018  
Number of days:4 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Monday, 30 April 2018 3:02 PM  
**To:** 'Angie Tiong' <angie\_tiong@sg.msig-asia.com>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>  
**Subject:** RE: New Assignment - Survey of Third party vehicle SLL4208L - MSIG Ref: 546701 PLY - Public Liability case

Dear Angie,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Angie Tiong [[mailto:angie\\_tiong@sg.msig-asia.com](mailto:angie_tiong@sg.msig-asia.com)]  
**Sent:** Monday, 30 April, 2018 1:54 PM  
**To:** [assignments@lkkauto.com](mailto:assignments@lkkauto.com)  
**Subject:** New Assignment - Survey of Third party vehicle SLL4208L - MSIG Ref: 546701 PLY - Public Liability case

Dear Veron

We refer to our telephone conversation this afternoon.

Please arrange to survey third party vehicle, SLL4208L at Kah Motor on 2/5/18 (Wednesday) at 10.00am.

We have agreed with Kah Motor to do a direct settlement. Attached is the repair quotation for vehicle SLL4208L for your attention.

Thanks & Regards

Angie Tiong  
Executive, Claims Services  
D: +65 6594 2526 | F: +65 66431 349 | [angie\\_tiong@sg.msig-asia.com](mailto:angie_tiong@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

**CONFIDENTIALITY NOTICE**

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

## Catherine Chong (LKK Auto)

---

**From:** Angie Tiong <angie\_tiong@sg.msig-asia.com>  
**Sent:** Monday, 30 April, 2018 1:54 PM  
**To:** assignments@lkkauto.com  
**Subject:** New Assignment - Survey of Third party vehicle SLL4208L - MSIG Ref: 546701 PLY - Public Liability case  
**Attachments:** Scan Data from FX-D59479 (112 KB)

Dear Veron

We refer to our telephone conversation this afternoon.

Please arrange to survey third party vehicle, SLL4208L at Kah Motor on 2/5/18 (Wednesday) at 10.00am.

We have agreed with Kah Motor to do a direct settlement. Attached is the repair quotation for vehicle SLL4208L for your attention.

Thanks & Regards

Angie Tiong  
Executive, Claims Services  
D: +65 6594 2526 | F: +65 66431 349 | [angie\\_tiong@sg.msig-asia.com](mailto:angie_tiong@sg.msig-asia.com)



**MSIG**



Insurer Claims  
Team of the Year  
2016

MSIG Insurance (Singapore) Pte Ltd 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | T: +65 6220 9644 | F: +65 6225 6371 | Co. Reg. No. 200412212G | [msig.com.sg](http://msig.com.sg)



A Member of **MS&AD** INSURANCE GROUP

---

### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

**Veron Chen (LKKAuto)**

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 9 July 2018 11:55 AM  
**To:** 'Ary Chua'; Guo Qiang (LKKAuto); SUR; Admin-D (LKKAuto)  
**Cc:** Liew Thye Wui; Faeaz  
**Subject:** RE: Finalise TPDS: SLL4208L (LIBERTY) HIT BY BARRIER GATE B (MSIG) DOA: 27/12/2017@14.08PM

Dear Ary,

WITHOUT PREJUDICE

Confirmed amount \$2534.95 before GST @ 4 working days.

**Final invoice and all supporting documents sent over to MSIG.**

**MSIG ref: 546701 PLY**

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Ary Chua [mailto:arychua@honda.com.sg]  
**Sent:** Saturday, 7 July 2018 9:10 AM  
**To:** Guo Qiang (LKKAuto) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>; Admin-D (LKKAuto) <admin-d@lkkauto.com>  
**Cc:** Liew Thye Wui <twliew@honda.com.sg>; Faeaz <faeaz@honda.com.sg>  
**Subject:** Finalise TPDS: SLL4208L (LIBERTY) HIT BY BARRIER GATE B (MSIG) DOA: 27/12/2017@14.08PM

Hi Guo Qiang,

Kindly Finalise TPDS: SLL4208L (LIBERTY) HIT BY BARRIER GATE B (MSIG) DOA: 27/12/2017@14.08PM

<b>Final Repair Costs (include GST)</b>	<b>\$2,534.95 + (\$177.45) = \$2,712.40</b>
<b>Repair Period* (Working Day)</b>	<b>04</b>

**\*NOTES: The Repair Not Includes Public Holiday & Sunday.**

Please examine the above information carefully. If no discrepancy is reported within 7 days (exclude Sunday and Public Holiday) from the date of this email, the information will be considered as correct. Thereafter, no adjustment will be made.

Thank you.

Best Regards,

Ary Chua Wai Ngee

Bodyshop Service Advisor Kah Motor Co.Sdn.Bhd.15 Ubi Road 4 Singapore 408610

E-mail: arychua@honda.com.sg Fax: 67480770 DID:68465673 H/P:81006306

**HONDA**  
The Power of Dreams

**the Civic TYPE R**  
UPSIZE YOUR THRILL

REGISTER YOUR INTEREST



# QUOTATION

**KAH MOTOR CO. SDN. BHD.**  
 (A Member of the Oriental Holdings Berhad)  
 Service and Body Repair  
 Tel: +65 6841 3838 Website: www.honda.com.sg  
 For 24-hours Roadside Assistance, Call 98203838

GST Reg No.: M200050223  
 Company Ref. No.: S60FC1380G

LKK Auto: Katherine

**Customer** : MSIG INSURANCE (SINGAPORE) PTE  
 16 RAFFLES QUAY  
 HONG LEONG BUILDING  
 SINGAPORE 048581  
**Registration No** : SLL4208L  
**Chassis No** : JHMRU1810GX201858  
**Model** : HRV DX-SIN CVT YM 2016  
**Owner's Name** : CHOO KENG LOCK  
**Ins Policy No.** :  
**Date of Accident** : 27/12/2017

**Document No.** : SQT17005253 **Page** 1  
**Date** : 29. Dec 2017  
**Customer No.** : WZM003  
**Svc Advisor** : ARY CHUA WAI NGEN  
**Engine No** : L15B4531859  
**Date | Time** : 29. Dec 2017 9:19:55 AM  
**Surveyor Name** :  
**Survey Date** :  
**Authorisation Date** :  
 DT: +65 6845 5673  
 HP: +65 8100 6306  
 Email: arychua@honda.com.sg

Item	Description	Qty	Unit Price	Disc %	Amount	0% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 69683) OWNER: CHOO KENG LOCK OWNER INSURER: LIBERTY INSURANCE PTE LTD DATE OF ACCIDENT: 27/12/2017@2:08PM SURVEYED BY: REF NO: TP INSURER: MSIG INSURANCE (SINGAPORE) PTE LTD BARRIER AT GE1B HIT SLL4208L						
73125-T7A-003	MOLDINGFR.WINDSHIELD SIDE X	2	13.30	25	19.95	1.40	21.35
73150-T7A-003	MOLDINGFR.WINDSHIELD X	1	16.70	25	12.52	0.88	13.40
73226-SZW-000	DAMPERSTD 5X5 X	1	8.30	25	6.22	0.44	6.66
77466-SV4-000	SEALFR.INSTRUMENT X	1	11.10	25	8.32	0.58	8.90
73151-T7A-003	MOLDING.FR.WINDSHIELD LOWER X	1	39.80	25	29.85	2.09	31.94
BO-IU-BKT(NEW)	IU BRACKET TAPE(N) X	1	26.00		26.00	1.82	27.82
BO-WS-SEALANT	WINDSCREEN SEALANT (N) X	2	60.00		120.00	8.40	128.40
76208-T7A-J02	MIRROR SET,R. DM photo	1	606.60	25	454.95	31.85	486.80
76201-T7A-J01ZM	CAPR.SKULL Repair X	1	64.70	25	48.52	3.40	51.92
			<b>Sum Item</b>		<b>726.33</b>	<b>50.86</b>	<b>777.19</b>
BOSUN	SUNDRIES / n/c.	1	100.00	✓ 20	100.00	7.00	107.00
BG01D	REMOVE & INSTALL FR. WINDSCREEN.(N)	1	350.00	✓ 300	350.00	24.50	374.50
BKROK	STRAIGHTEN ALIGN ROOF PANEL	1	680.00	✓ 560	680.00	47.60	727.60
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	1350.00	✓ 1200	1350.00	94.50	1444.50
			<b>Sum Labor</b>		<b>2480.00</b>	<b>173.60</b>	<b>2,653.60</b>

LKK Auto Consultants hence notify the Repairer

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

NN  
 n/c.

Survey By: Kang G. Inf.  
 Date & Time: 02/01/18  
 Excess: \_\_\_\_\_

**Total Amount** 3,206.33 224.46 3,430.79  
**Total (Inclusive of GST)** **3,430.79**

4 Days  
 After paint photos



# SERVICE PRE-INVOICE

## KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223  
Company Ref. No.: S60FC1380G

**Customer:** WZM003 / MSIG INSURANCE  
**Chassis No:** JHMRU1810GX201858  
**License No:** SLL4208L  
**Mileage:** 26162  
**Engine No:** L15B4531859

**Document No:** SVO18038319  
**Printed By:** ARYCHUA  
**Order Date:** 2. July 2018  
**Order Time:** 1:58:32 PM  
**Service Advisor:** ARY CHUA WAI NGENE

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO: 69683) OWNER: CHOO KENG LOCK OWNER INSURER: LIBERTY INSURANCE PTE LTD DATE OF ACCIDENT: 27/12/2017@2:08PM SURVEYED BY: GUO QIANG(LKKAUTO)02/05/2018@14.14PM REF NO: 546701 PLY TP INSURER: MSIG INSURANCE (SINGAPORE) PTE LTD BARRIER AT GE1B HIT SLL4208L						
76208-T7A-J02	MIRROR SET,R.	1	606.60	25	454.95	31.85	486.80
			<b>SUM PARTS:</b>		<b>454.95</b>	<b>31.85</b>	<b>486.80</b>
BOSUN	0672 SUNDRIES	1	20.00		20.00	1.40	21.40
BG01D	EXT-YJ REMOVE & INSTALL FR. WINDSCREEN. (N)	1	300.00		300.00	21.00	321.00
BKROK	EXT-YJ STRAIGHTEN ALIGN ROOF PANEL.	1	560.00		560.00	39.20	599.20
BP03R	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(3P)	1	1,200.00		1,200.00	84.00	1,284.00
			<b>SUM LABOUR:</b>		<b>2,080.00</b>	<b>145.60</b>	<b>2,225.60</b>
			<b>TOTAL SGD</b>		<b>2,534.95</b>	<b>177.45</b>	<b>2,712.40</b>
			<b>Total Payable (SGD)</b>				<b>2,712.40</b>

*WD=4*

GST Amount is calculated from individual line(s)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18007930/Gvbn2

16 RAFFLES QUAY  
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 11-07-2018



Code : MSG

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	PUBLIC LIABILITY	Veh. Inspected	SLL 4208L
Policy No.		Coverage (\$)	0.00
Claim No.	546701 PLY	Excess (\$)	0.00
Assign From	ANGIE TIONG	Assign Date	30/04/2018

## 2. Vehicle Particulars & Condition

Make & Model	HONDA HRV	c.c	1497
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JHMRU1810GX201858	Colour	SILVER
Odometer	22689	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

## 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.  
DAMAGES SEE DETAILS.

## 5. General Information

Accident Date	27/12/2017	Inspection Date	02/05/2018
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

## 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLL 4208L

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
2	MOLDINGFR.WINDSHIELD SIDE (SN)	NOT NECESSARY	19.95	-
1	MOLDINGFR.WINDSHIELD (SN)	NOT NECESSARY	12.52	-
1	DAMPERSTD 5X5 (SN)	NOT NECESSARY	6.22	-
1	SEALFR INSTRUMENT (SN)	NOT NECESSARY	8.32	-
1	MOLDING,FR.WINDSHIELD LOWER (SN)	NOT NECESSARY	29.85	-
1	IU BRACKET TAPE (SN)	NOT NECESSARY	26.00	-
2	WINDSCREEN SEALANT (SN)	NOT NECESSARY	120.00	-
1	MIRROR SET.R (SN)	DAMAGED	454.95	454.95
1	CAPR SKULL (SN)	TO REPAIR SEE LABOUR	48.52	-
1	SUNDRIES (SN)	NECESSARY	100.00	20.00
			826.33	474.95
<b>LABOUR</b>				
	REMOVE & INSTALL FR WINDSCREEN.		350.00	300.00
	STRAUGHTEN ALIGN ROOF PANEL.INCLUSIVE OF THE REPAIR OF CAPR SKULL.		680.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		1,350.00	1,200.00
			2,380.00	2,060.00
<b>GRAND TOTAL</b>			<b>3,206.33</b>	<b>2,534.95</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,534.95</b>

Report Ref No. CS/MSG18007930/Gvbn2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.