



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

AIGAsia Insured's Veh No : SLB4567C

Date of Accident : 27 April 2018

51 Defu Lane 10 Singapore 539216

Tel : 68585151 (24 Hours) Fax : 68580877

GST Regn. No. : M2-8922054-2

Messrs Sky Transport Services Pte Ltd

Date : 30 April 2018

Estimate To Repair PC5234D - Toyota Hiace Commuter GL 3.0A

Chassis No : KDH2230027689

S/No	Quantity	Description	Amount
LIST ITEMS			
01	1 pc	tailgate lid <i>3.500</i>	\$ 1,765.00
02	1 pc	tailgate lid lock <i>70/144</i>	\$ 275.00
03	1 pc	tailgate lid lock striker <i>17</i>	\$ 86.00
04	1 pc	tailgate lid weatherstrip	\$ 395.00
05	1 pc	tailgate lid centre emblem badge <i>new</i>	\$ 75.00
06	2 ps	tailgate lid side catch @ \$35.00 <i>17</i>	\$ 70.00
07	2 ps	tailgate lid side catch latch @ \$90.00 <i>17</i>	\$ 180.00
08	1 pc	tailgate lid inner trimboard	\$ 175.00
09	1 pc	rear end panel	\$ 890.00
10	1 pc	rear end panel skid plate	\$ 332.00
11	2 ps	rear lamps @ \$398.00 <i>17</i>	\$ 796.00
12	1 pc	rear lamp lower apron <i>n</i>	\$ 89.20
13	1 pc	rear bumper <i>DD</i>	\$ 398.00
14	2 ps	rear bumper side retainers @ \$50.00 <i>17</i>	\$ 100.00
15	6 ps	rear bumper clips @ \$4.00 <i>new</i>	\$ 24.00
			\$ 5,650.20
Less 25 %			\$ 1,412.55
			\$ 4,237.65
SPECIAL NETT ITEMS			
16	1 pc	tailgate lid 70 Km/h sticker <i>new</i>	\$ 26.00
17	1 pc	rear windscreen glass sealant <i>new</i>	\$ 200.00
18	1 pc	rear windscreen glass inner sponge seal <i>new</i>	\$ 100.00
19	1 set	rear bumper parking sensor <i>NZ</i>	\$ 450.00
			\$ 776.00
LABOUR & MISC. CHARGES			
01		To remove and refit rear windscreen glass.	\$ 180.00
02		To reinstall of rear bumper parking sensor.	\$ <i>new</i> 120.00
03		To transfer of tailgate fittings, fixture and perform waterseepage test.	\$ 150.00
04		To rust-proofing of the affected areas.	\$ 180.00
05		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	\$ <i>17</i> 250.00
06		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.	\$ 1,200.00

*Not Approved
above
To be photo checked only
4 days
2/5/18*

*Manus 2/05/18
@ 1000h*

*11
X
?
X
?
?
?
?
?
X
?
X
10
40
30
X*

*120
X
60
60
?
?*



陳林摩哆私人有限公司
TAN LIM MOTOR PTE LTD

51 Defu Lane 10 Singapore 539216
Tel : 68585151 (24 Hours) Fax : 68580877
GST Regn. No. : M2-8922054-2

AIGAsia Insured's Veh No : SLB4567C
Date of Accident : 27 April 2018

Messrs Sky Transport Services Pte Ltd

Date : 30 April 2018

Estimate To Repair PC5234D - Toyota Hiace Commuter GL 3.0 A
Chassis No : KDH2230027689

S/No	Quantity	Description	Amount
07		LABOUR & MISC. CHARGES	
		Putty and spray painting of the affected portion.	\$ 900.00
			\$ 2,980.00
		Total	\$ 7,993.65

