

22/03/2007

ASS. REC. BY:

REF: CS/CT118007960/Rls b02

Special Instruction:

Surveyor

Paul

ASSIGNMENT (Office)

From (Person):

Shawn Han

of

CT1

Date/Time: 02052018 11:44am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKW 7305Z

Insured:

SKS 393

at Workshop m/s

Borneo Motor

Tel:

of

2 Pandan Crescent

Policy No:

DMP C9N3036121802

Claim No:

SNM18D02213102

Sum Insured:

Excess:

D.O.A.

28042018

Make of Veh:

(Client's Record)

03052018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS 'wp'

Thomas

Vehicle IN OUT

Date/Time:

02052018 12:11pm

Person Contacted:

Date/Time	Action/Instruction (✓) Estimate	
	SKW 7305Z - CS/msh17023233/Rlgbn2	DOA: 22.11.17
	SKS 393 - CS/ALH16005664/Khg392	DOA: 23/11/16

ASSIGNMENT

From: Date: 08/05/2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKW 7305Z

at Workshop m/s: Borneo Motor

of 2 Pandan Crescent

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:


(Client's Record)

Make of Veh:

Thomas

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKW 7305Z Yr Regn: 2015 / Nov

Type: ☒ M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: TOYOTA COROLLA ALTIS 1.6 c.c 1598

Colour: Grey A/C: Insured / Std / NI / NA

Sp. Reading: 22247 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MR053RKH104542237

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / ☒ STD A/Rim or

Tyre Size: F: 205/55R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 28/04/18

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 03/05/18

Survey held at: BORNEO MOTOR

Des. of Damages: Frt / Rear / O/S / ☒ U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

P/P \$14,491.70
\$30,571.12 - \$14,491.70 (Reduc - 52%)

RECEIVED 17 MAY 2018

Date/Time, File Pass to?

17/05/18

1) Typist

Date/Time, File Return to?

2)

☐ : Prel. Report

☒ : Final Report

Days Of Repair: 10

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

\$ - RS \$

Photos:

Others:

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ P/P \$14,491.70

TOTAL

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		02 May 2018 11:44 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	MA HUILIN, ID: S8113909A		
Main Claimant:	LEONG WAH CHIN, ID: S0104511C		
Vehicle Reg. No.:	SKW7305Z	Date of Loss:	28/04/2018 10:00 - :59
Claim Type:	TP / SNM18D02213C02	Policy/Cover Note No.:	DMPCSN3036121802 (Comprehensive)
Vehicle Reg. No. (Insured):	SKS39J	Policy No. (Claimant):	A 29022840 AT2
		Excess:	S\$0.00
Repairer:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent, 128462 West Coast - Tel: 66311857		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Sharon Han - 63896]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/05/2018]		
Driver/Custodian (Insured):	WU SHENGJIAO (32 / Female), NRIC: G2750490L, Tel: +6593705988		
Adj Asg. Remarks:	EST \$32,711.10, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Thursday, 17 May 2018 10:21 AM
To: Thomas Pang PTCBC
Cc: SUR
Subject: RE: Finalize report for SKw7305Z

Hi Thomas,

Finalised amount at \$ 14,491.70 / 10 days P/P before GST confirmed


Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto
Consultants
Pte Ltd

Save the Earth. Print only when necessary.

From: Thomas Pang PTCBC [mailto:Thomas.Pang@borneomotors.com.sg]
Sent: Wednesday, 16 May, 2018 2:41 PM
To: Rasul (LKKAuto); Admin A; SUR
Subject: Finalize report for SKw7305Z

Hi,

Attach finalize report and before paint for your perusal. 10 working days.

Thank you

Regards

Thomas

Borneo Motors

DID:6631 1860 FAX:6773 3094

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 30/04/2018 09:13
Date Of Accident 28/04/2018 10:30
Exact Location Of Accident BALESTIER RD & JLN DATOH
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SKW7305Z
Insured/Policyholder
Name Of Registered Owner LEONG WAH CHIN
NRIC No S0104511C
Email Address ELECTICK@HOTMAIL.COM
Mobile Phone No (LOCAL) +65-90121109
Alternative Phone No OFFICE-90121109

Vehicle Particulars

Manufacturer TOYOTA
Model COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR

Insurance Company

Name of Insurance Company MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number A 29022840 AT2
Cover Note Number

Driver

Name of Driver JOSEPH YEOW
NRIC No S8520785G
Date Of Birth 17/07/1985
Occupation INDOOR
Date Of Driving Pass 18/11/2004
Driving Experience 13 YEARS AND 5 MONTHS
Gender MALE
Mobile Number (LOCAL) +65-90121109
Fax Number
Contact Number
Email Address ELECTICK@HOTMAIL.COM

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured CHILDREN

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

General Information of the Accident

Type Of Accident

COLLISION - HEAD TO REAR

Weather Conditions

CLEAR

Road Surface

DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Number of vehicles involved in the accident

Was any body injured in the Accident? NO

Was any injured conveyed to hospital by ambulance? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Passenger 1

NAME: : YEO YUN FEN PAMELA

GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number

SKS39J

Vehicle Make/Model/Colour

BMW/WHITE

Details Of Properties

Vehicle Category

PRIVATE CAR

Name of Driver

WU SHENGJIAO

NRIC/Passport Number

G2750490L

Contact Number

66630630

Address

Postcode

Insurance Company Name

CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

B-lectier Road.

Describe Circumstances of the Accident

I, Toyota Altis is travelling along Balester Rd ^{main road} on the left side of the road. Suddenly white color BMW came out from small Road Jalan Datoh came out and hit the left side of my car.

Declaration

We declare the foregoing particulars are true in every respect.

Policyholder's Signature / Date & Time

 28/4/18
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1	
	Document No	
	0	
	Document Date	
	30/04/2018	
	Mdm Leong Wah Chin 7 Toh Yi Drive #12-273 Singapore 590007 Mobile: 96606770	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	13/11/2015	SKW7305Z	13103	30745 72/DS/SKW7305Z
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MR053REH104542237	1ZRX540882	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	-----------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: CHINA TAIPING INSURANCE TP VEH: SKS 39J DATE OF ACC: 28.04.2018				50 100.00
2	B	BP-LAB R/I REAR REVERSE SENSOR TO FAC REPAIR (N ETT)				17X 154.00
3	B	BP-LAB REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR (NETT)				17X 616.00
4	B	BP-LAB R/I LH SIDE SKIRTING TO FAC REPAIR (NETT)				154.00
5	B	BP-LAB REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR LH REAR DOOR & LH FRONT DOOR				616.00
6	B	BP-LAB CHECK WIRING AND CONDUCT WATER TEST (NET T)				154.00
7	Z	BP-SLANT SUPPLY SEALANT (NETT) new				200 200.00
8	B	BP-MECH CONDUCT FULL WHEEL ALIGNMENT (NETT)				308.00
9	B	BP-MECH REPLACE REAR UNDER CARRIAGE SYSTEM				1232.00
10	S	BP-SUBLET REPLACE RIM AND WHEEL BALANCING (NETT)				123.20
11	L	BP-LPO SUPPLY LH REAR TYRE				580.00
12	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)				616.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3667337

TO SECURITY GUARD

3667337

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES:

DATE
TIME 30/04/2018
10:23

VEHICLE NO
SKW7305Z

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631-1188

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail		Account No	Customer Detail	
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept		S1000003 / ICCI1	Mdm Leong Wah Chin 7 Toh Yi Drive #12-273 Singapore 590007 Mobile: 96606770	
		Document No		
		Document Date		
		0		
		30/04/2018		

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	13/11/2015	SKW7305Z	13103	30745 72/DS/SKW7305Z
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104542237	1ZRX540882	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
13	B	BP-LAB R/I AND REFOCUS HEADLAMP TO FAC REPAIR (NETT)				154.00
14	B	BP-LAB REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS				2464 3080.00
15	B	BP-RES RESPRAY ACC AFFECTED AREAS				3036 4048.00
16	B	BP-WS R/I REAR WINDSCREEN GLASS TO FAC REPAIR (NETT)				n n X 396.00
17	B	BP-MECH R/I FUEL TANK ASSY TO FAC REPAIR (NETT)				n n X 616.00
18	1	DTA342-02001 00 SPOILER, SIDE, SET	1.00	1073.10		Scd 1073.10
19	2	S52159-02904 COVER, RR BUMPER	1.00	539.90		Repair 539.90
20	3	S52161-0K040 PIECE, RR BUMPER	10.00	3.90		new 39.00
21	4	S52576-02140 RETAINER, RR BUMPER L	1.00	105.70		X 105.70
22	5	S52563-02250 RETAINER, RR BUMPER L	1.00	58.30		X 58.30
23	6	S52575-02140 RETAINER, RR BUMPER R	1.00	105.70		X 105.70
24	7	S52562-02250 RETAINER, RR BUMPER R	1.00	58.30		X 58.30
25	8	S53802-02220 FENDER SUB-ASSY, LH	1.00	877.10		Bl 877.10
26	9	S53828-02210 PROTECTOR, FR FENDER	1.00	96.90		Scd X 96.90
27	0	S53876-02680 LINER, FR FENDER LH	1.00	219.60		X Scd? 219.60
28	1	T90467-07215 CLIP	10.00	2.00		new 20.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Materials	Less
		Lubrication/Fluid	
		Others	
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3667338
3667338

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES:

DATE: 30/04/2018
TIME: 10:23

VEHICLE NO: SKW7305Z

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors

Co Reg No : 196700086Z

GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 30/04/2018	Mdm Leong Wah Chin 7 Toh Yi Drive #12-273 Singapore 590007 Mobile: 96606770

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	13/11/2015	SKW7305Z	13103	30745 72/DS/SKW7305Z
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MR053REH104542237	1ZRX540882	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00
-------------------	------------	----	-----------------	------------	------	------------	------

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	2	T90189-06013	10.00	1.80		18.00
30	3	S67002-02470	1.00	1209.90		1209.90
31	4	S67862-02290	1.00	174.40		174.40
32	5	S68610-02270	1.00	153.50		153.50
33	6	S75922-02220	1.00	46.50		46.50
34	7	S69040-02470	1.00	544.70		544.70
35	8	S68720-0D050	1.00	82.10		82.10
36	9	S68740-02100	1.00	92.10		92.10
37	0	S69802-0D190	1.00	307.50		307.50
38	1	S85720-0K010	1.00	590.20		590.20
39	2	S67004-02430	1.00	1198.50		1198.50
40	3	S67872-02260	1.00	174.40		174.40
41	4	S68630-02260	1.00	153.50		153.50
42	5	S75924-02250	1.00	42.10		42.10
43	6	S69060-02370	1.00	544.70		544.70
44	7	S68760-0D030	1.00	82.10		82.10
45	8	S68780-0D030	1.00	82.10		82.10
46	9	S69804-0D160	1.00	245.50		245.50
47	0	S85710-0K010	1.00	852.10		852.10
48	1	L90269-04051	10.00	1.20		12.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3667339

TO SECURITY GUARD

3667339

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE
TIME
30/04/2018
10:23

VEHICLE NO

SKW7305Z

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD


Inchcape

Borneo Motors

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Online Service Booking :
www.toyotasingsapore.com.sg
Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1188

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 30/04/2018	Mdm Leong Wah Chin 7 Toh Yi Drive #12-273 Singapore 590007 Mobile: 96606770

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGKZ	S2	ZRE171R	13/11/2015	SKW7305Z	13103	30745 72/DS/SKW7305Z
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104542237	12RX540882	60	Thomas Pang W T	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
49	2	T90269-06013 RIVETS	10.00	1.50		15.00
50	3	S61602-02280 PANEL SUB-ASSY, QUAR	1.00	1094.70		1094.70
51	4	S64813-02200 DAM, BACK WINDOW GLA	1.00	29.50		29.50
52	5	T08826-08115 PANEL BONDING AD	1.00	237.60		237.60
53	6	T08826-08609 SUPER FAST URETHANE BLACK	1.00	90.08		90.08
54	7	T08826-08682 SINGLE STEP PRIMER	1.00	173.44		173.44
55	8	S75444-02A20 PLATE, LUGGAGE COMPT	1.00	34.40		34.40
56	9	S42450-02211 HUB & BEARING ASSY	1.00	808.70		808.70
57	0	S42611-02C80 WHEEL, DISC	1.00	1682.10		1682.10
58	1	S42110-02520 REAR AXLE BEAM ASSY	1.00	2851.10		2851.10
59	2	S48812-02260 REAR STABILIZER BAR,	1.00	307.50		307.50
60	3	S48530-02C81 ABSORBER ASSY, RR	1.00	200.30		200.30

Repair 15.00
X 1094.70
X 29.50
X 237.60
X 90.08
X 173.44
X 34.40
X 808.70
X 1682.10
X 2851.10
X 307.50
X 200.30

Rasul
Hp 90010068
10 days
03/05/18 @ 1445
Repair 64 part

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

No illegal modification is allowed. The repairer must use genuine Toyota parts and accessories to maintain your Toyota. Service your Toyota every 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

Supplementary work must be resurveyed and is subject to final approval from Insurance Company.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
Acknowledged by Repairer	Please acknowledge receipt of vehicle	Parts 17,323.92	30,571.12
Signature:		Labour 12,544.00	GST 7.00% 2,139.98
Date:		Materials 703.20	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 32,711.10

PLEASE TEAR ALONG PERFORATED LINE

3667340

3667340

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 30/04/2018
TIME 10:23

VEHICLE NO SKW7305Z

CUSTOMER

SIGNATURE FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no: 6631 1188

ESTIMATE

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 15/05/2018	Mdm Leong Wah Chin 7 Toh Yi Drive #12-273 Singapore 590007 Mobile: 96606770

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEKXKZ	S2	ZRE171R	13/11/2015	SKW7305Z	13103	30745 72/DS/SKW7305Z
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	

MR053REH104542237 12RX540882 60 Thomas Pang W T 04/05/2018 8.00 15/05/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY TP INS: CHINA TAIPING INSURANCE TP VEH: SKS 39J DATE OF ACC: 28.04.2018 BY: LKK-RASUL @ 03.05.2018 10 WORKING DAYS				50.00
2	B	BP-LAB R/I LH SIDE SKIRTING TO FAC REPAIR (NETT *)				154.00
3	B	BP-LAB REMOVE AND TRANSFER DOOR COMPONENTS * ONTO NEW DOOR				616.00
4	B	BP-LAB LH REAR DOOR & LH FRONT DOOR CHECK WIRING AND CONDUCT WATER TEST (NETT * T)				154.00
5	Z	BP-SLANT SUPPLY SEALANT (NETT)				200.00
6	B	BP-MECH CONDUCT FULL WHEEL ALIGNMENT (NETT)	18			308.00
7	S	BP-SUBLET REPLACE RIM AND WHEEL BALANCING (NETT) C25 PO: 16838				123.20
8	B	BP-ECU TO RESET ECU AND REPROGRAMME (NETT)	18			616.00
9	B	BP-LAB R/I AND REFOCUS HEADLAMP TO FAC REPAIR (* NETT)				154.00

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

3668297

3668297

15/05/2018
13:38

SKW7305Z

WORKSHOP



Borneo Moto



Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

Join Toyota ME @ <http://toyotame.borneomotors.com.sg> & earn points to redeem for attractive items!

Borneo Motors (Singapore) Pte Ltd

Online Service Booking :
www.toyotasingsapore.com.sg

Toyota Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1100

ESTIMATE

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079909 Attn: Motor Claims Dept	S1000003 / ICCI1 Document No 0 Document Date 15/05/2018	Mdm Leong Wah Chin 7 Toh Yi Drive #12-273 Singapore 590007 Mobile: 96606770

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GEXGK2	S2	ZRE171R	13/11/2015	SKW7305Z	13103	30745 72/DS/SKW7305Z

Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On
MR053REH104542237	12RX540882	60	Thomas Pang W T	04/05/2018 8.00	15/05/2018 18.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-LAB REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	*			2464.00
11	B	BP-RES RESPRAY ACC AFFECTED AREAS	*			3036.00
12	1	DTA342-02001 00 SPOILER, SIDE, SET	1.00	1073.10		1073.10
13	2	S52161-OK040 PIECE, RR BUMPER	10.00	3.90		39.00
14	3	S53802-02220 FENDER SUB-ASSY, LH	1.00	877.10		877.10
15	4	T90467-07215 CLIP	10.00	2.00		20.00
16	5	T90189-06013 GROMMET	10.00	1.80		18.00
17	6	S67002-02470 PANEL ASSY, FR DR LH	1.00	1209.90		1209.90
18	7	S67862-02290 WEATHERSTRIP, FR DR L	1.00	174.40		174.40
19	8	S75922-02220 TAPE, BLACK OUT LH	1.00	46.50		46.50
20	9	S67004-02430 PANEL ASSY, RR DR LH	1.00	1198.50		1198.50
21	0	S67872-02260 WEATHERSTRIP, RR DR L	1.00	174.40		174.40
22	1	S75924-02250 TAPE, BLACK OUT LH	1.00	42.10		42.10
23	2	L90269-04051 RIVET	10.00	1.20		12.00
24	3	T90269-06013 RIVET	10.00	1.50		15.00
25	4	S75444-02A20 PLATE, LUGGAGE	1.00	34.40		34.40
26	5	S42611-02C80 WHEEL, DISC	1.00	1682.10		1682.10

Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 6,616.50 Labour 7,752.00 Materials 123.20 Lubrication/Fluid 0.00 Others 0.00	14,491.70
		GST 7.00%	1,014.42
		Less	0.00
		Amount Due	15,506.12

3668291

3668291

15/05/2018
13:38

SKW7305Z

WORKSHOP



Borneo Moto

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118007960/R1SBN2
Date: 22/05/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3036121802
Claimant Vehicle No :	SKW7305Z	Insured Vehicle No :	SKS39J
Date of Loss:	28/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D02213C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKW7305Z	Engine No:	1ZR540882
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104542237
Reg. Date:	13/11/2015 (Man. Year: 2015)	Odometer:	22247 km
Colour:	Grey		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,303.92	6,866.50	11,437.42	62.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	12,267.20	7,625.20	4,642.00	37.84
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	30,571.12	14,491.70	16,079.42	52.60
+ GST 7.00/7.00% (S\$)	2,139.98	1,014.42	1,125.56	52.60
Nett Amount (S\$)	32,711.10	15,506.12	17,204.98	52.60

INSPECTION

Date of Assignment:	02/05/2018	Inspected At:	Borneo Motors (S) Pte Ltd (Pandan) 2 Pandan Crescent Singapore 128462
Date Inspected:	03/05/2018		
Estimated Period of Repair:	10.0 days		

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 May 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKW7305Z)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET SPOILER,SIDE	Scratched	1,073.10 FS	*1,073.10 FS
2	1		*COVER,RR BUMPER	Repair	539.90 FS	*- FS
3	10		*PIECE,RR BUMPER	Necessary	39.00 FS	*39.00 FS
4	1		*RETAINER,RR BUMPER L	Serviceable	105.70 FS	*- FS
5	1		*RETAINER,RR BUMPER L	Serviceable	58.30 FS	*- FS
6	1		*RETAINER,RR BUMPER R	Serviceable	105.70 FS	*- FS
7	1		*RETAINER,RR BUMPER R	Serviceable	58.30 FS	*- FS
8	1		*FENDER SUB-ASSY,LH	Bent	877.10 FS	*877.10 FS
9	1		*PROTECTOR,FR FENDER	Serviceable	96.90 FS	*- FS
10	1		*LINER,FR FENDER LH	Serviceable	219.60 FS	*- FS
11	10		*CLIP	Necessary	20.00 FS	*20.00 FS
12	10		*GROMMET	Necessary	18.00 FS	*18.00 FS
13	1		*PANEL ASSY,FR DR LH	Bent	1,209.90 FS	*1,209.90 FS
14	1		*WEATHERSTRIP,FR DR L	Necessary	174.40 FS	*174.40 FS
15	1		*CHECK ASSY,FR DOOR	Serviceable	153.50 FS	*- FS
16	1		*TAPE,BLACK OUT LH	Necessary	46.50 FS	*46.50 FS
17	1		*LOCK ASSY,FR DOOR W	Serviceable	544.70 FS	*- FS
18	1		*L/FRT DOOR UPP HINGE	Serviceable	82.10 FS	*- FS
19	1		*HINGE ASSY,FR DOOR	Serviceable	92.10 FS	*- FS
20	1		*REGULATOR SUB-ASSY	Serviceable	307.50 FS	*- FS
21	1		*L/FRT REGULATOR MOTOR	Serviceable	590.20 FS	*- FS
22	1		*PANEL ASSY,RR DR LH	Bent	1,198.50 FS	*1,198.50 FS
23	1		*WEATHERSTRIP,RR DR L	Necessary	174.40 FS	*174.40 FS
24	1		*CHECK ASSY,RR DOOR	Serviceable	153.50 FS	*- FS
25	1		*TAPE,BLACK OUT LH	Necessary	42.10 FS	*42.10 FS
26	1		*LOCK ASSY,RR DOOR W	Serviceable	544.70 FS	*- FS
27	1		*L/RR DOOR TOP HINGE	Serviceable	82.10 FS	*- FS
28	1		*L/RR DOOR LOW HINGE	Serviceable	82.10 FS	*- FS
29	1		*REGULATOR SUB-ASSY	Serviceable	245.50 FS	*- FS
30	1		*L/R REGULATOR MOTOR	Serviceable	852.10 FS	*- FS
31	10		*RIVET	Necessary	12.00 FS	*12.00 FS
32	10		*RIVETS	Necessary	15.00 FS	*15.00 FS
33	1		*PANEL SUB-ASSY,QUAR	Repair	1,094.70 FS	*- FS
34	1		*DAM,BACK WINDOW GLA	Serviceable	29.50 FS	*- FS
35	1		*PANEL BONDING AD	Serviceable	237.60 FS	*- FS
36	1		*SUPER FAST URETHANE BLACK	Serviceable	90.08 FS	*- FS
37	1		*SINGLE STEP PRIMER	Serviceable	173.44 FS	*- FS
38	1		*PLATE,LUGGAGE COMPT	Necessary	34.40 FS	*34.40 FS
39	1		*HUB & BEARING ASSY	Serviceable	808.70 FS	*- FS
40	1		*WHEEL,DISC	Scratched	1,682.10 FS	*1,682.10 FS
41	1		*REAR AXLE BEAM ASSY	Serviceable	2,851.10 FS	*- FS
42	1		*REAR STABILIZER BAR	Serviceable	307.50 FS	*- FS
43	1		*ABSORBER ASSY,RR	Serviceable	200.30 FS	*- FS
44	1		*SUNDRY	Necessary	100.00 FS	*50.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
45	1		*LH REAR TYRE	Not Necessary	580.00 FS	*- FS
46	1		*SEALANT	Necessary	300.00 FS	*200.00 FS
F=Franchise part. S=SpcNett.						
				Total Parts (S\$)	18,303.92	6,866.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	R/I REAR REVERSE SENSOR TO FAC REPAIR	New	154.00	-
2	REMOVE INTERIOR UPHOLSTERY TO FAC REPAIR	New	616.00	0.00
3	R/I LH SIDE SKIRTING TO FAC REPAIR	New	154.00	154.00
4	REMOVE AND TRANSFER DOOR COMPONENTS ONTO NEW DOOR,LH REAR DOOR & LH FRONT DOOR	New	616.00	616.00
5	CHECK WIRING AND CONDUCT WATER TEST	New	154.00	154.00
6	CONDUCT FULL WHEEL ALIGNMENT	New	308.00	308.00
7	REPLACE REAR UNDER CARRIAGE SYSTEM	New	1,232.00	0.00
8	REPLACE RIM AND WHEEL BALANCING	New	123.20	123.20
9	TO RESET ECU AND REPROGRAMME	New	616.00	616.00
10	R/I AND REFOCUS HEADLAMP TO FAC REPAIR	New	154.00	154.00
11	REPLACE ACC DAMAGED PARTS AND STRAIGHTEN/REALIGN ACC AFFECTED AREAS	New	3,080.00	2,464.00
12	RESPRAY ACC AFFECTED AREAS	New	4,048.00	3,036.00
13	R/I REAR WINDSCREEN GLASS TO FAC REPAIR	New	396.00	-
14	R/I FUEL TANK ASSY TO FAC REPAIR	New	616.00	-
Gross Labour Cost (S\$)			12,267.20	7,625.20

Report was unsubmitted during this print-out.

< END OF ESTIMATES >