

ASS. REC. BY:

REF:

CS/E6218007962/G9b54

Special Instruction:

Surveyor:

PB

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

EHL

Date/Time:

02052018 11:58am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLA 7462G

Insured:

SGJ 908X

at Workshop m/s

Ethoz

Tel:

6654 7617

of

22 Tampines St 92.

Policy No:

Claim No:

DSMPCL1800830

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'wp'

07051018

H.O.D. Endorsement:

Date/Time:

02052018 1208pm

Person Contacted:

Boon Kui

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLA 7462 G - X
	SGJ 908X - CS/ALG10021573/Rnlf292
29/6/18 @ 2:32pm	raised to Steve via by email.

Def: 22.10.10

Surveyor

Ref.


REF:

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: \_\_\_\_\_  
 at Workshop n/s Ethos  
 of \_\_\_\_\_  
 Insured: \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record) \_\_\_\_\_  
 Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_  
 IDAC Accident Rpt.: \_\_\_\_\_ Consistent? : Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No  
 Est. Repairs: 5 days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No. SLA74626 Yr Regn: 15 Mar 2016  
 Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: Honda vezel C.C. 1496  
 Colour: white A/C: Insured / Std / NI / NA  
 Sp. Reading: 039283 T/Radio: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: RU11109263  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jammed / Leaked / Burnt or  
 Brake: In order / Jammed / Leaked / Burnt or  
 Mod: Nil / S/Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 245/60R16  
 R: 11  
 BS: DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
 TOYO / YOKO or \_\_\_\_\_  
 Front: \_\_\_\_\_ Rear: \_\_\_\_\_  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. \_\_\_\_\_ D.O.I. 07-05-18  
 Survey held at w/s 4pm  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction  
29/6 Finalized \$3328.36 with Jimmy.  
(Red \$6185.34, 6527)

RECEIVED 29 JUN 2016

Date/Time, File Pass to? ☐ : Preli. Report  
11/29/16 hmsr ☐ : Final Report  
 Date/Time, File Return to?

Days Of Repair: 5  
 Resurvey No. of Trip: 1

Survey Fee: 250

Transportation: \_\_\_\_\_

\_\_\_\_\_ S + RS. \_\_\_\_\_ SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)  
☐ : Interview (\$)  
☐ : Tech. Invs (\$)  
☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I.: (\$ 3328.36)



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18007962/Gqb

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 02-05-2018



Code : EGI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 908X	Veh. Inspected	SLA 7462G
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1800830	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	02/05/2018

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	27/04/2018	Inspection Date	07/05/2018
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

## Catherine Chong (LKK Auto)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>  
**Sent:** Wednesday, 2 May, 2018 11:58 AM  
**To:** admin-d@lkkauto.com  
**Subject:** OI : SGJ908X / TP : SLA7462G/LKK / DOA : 27/04/2018 (DSMPC1800830)  
**Attachments:** SGJ908X - SAS.pdf; SLA7462G - SAS.pdf; SLA7462G - ESTIMATE.pdf; SLA7462G - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANCY PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **ETHOZ GROUP LTD.**

ADDRESS : 22 TAMPINES ST 92  
SINGAPORE 528876

PERSON TO CONTACT : NG BOON KAI @ 6654 7617

ERGO OFFICER-IN-CHARGE : STEVE LIM

***Note: To survey on without prejudice basis. Please advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.***

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via [Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg).

Attached are estimate, insured and TP's SAS (**note: reports not to be released to any Third Party**).

Thank you.

### **Yee Pei Li**

Claims Assistant (Motor)  
ERGO Insurance Pte. Ltd.  
5 Temasek Boulevard  
#04-01 Suntec Tower Five  
Singapore 038985  
Tel.: 65 6829 9199 DID: 65 6829 9194  
Website: [www.ergo.com.sg](http://www.ergo.com.sg)

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

# ERGO

Date: 02.05.2018  
Our Reference: DSMPC1800830/SL/pl  
Your Reference: SLA 7462G  
  
To: ETHOZ GROUP LTD

Sent via Fax ☐  
or ☐  
Email BoonKai.Ng@ethozgroup.com

## Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLA 7462G  
Insured's Vehicle: SGJ 908X  
Date Of Accident: 27.04.2018

We acknowledge receipt of your request for PRS on: 30.04.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\* LKK Adg

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

- ☐ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.  
☐ Your request for inspection does not have your client's GIA report, kindly forward a copy.  
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.  
☐ Our Insured's driver has not reported the accident to us to date.  
☒ Others: OFFICER-IN-CHARGE - STEVE LIM

Prepared by:	<u>[Signature]</u>	Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				<u>FAX : 6829 9247</u>

### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:

### Workshop use only:

#### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

# ERGO

Date: 02.05.2018  
Our Reference: DSMPC1800830/SL/pl  
Your Reference: SLA 7462G  
  
To: ETHOZ GROUP LTD

Sent via Fax

or

Email

BoonKai.Ng@ethozgroup.com

## Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SLA 7462G  
Insured's Vehicle: SGJ 908X  
Date Of Accident: 27.04.2018

We acknowledge receipt of your request for PRS on: 30.04.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked \*.

\* LKK Auto

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPk	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>	Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
<input type="checkbox"/>	Your request for inspection does not have your client's GIA report, kindly forward a copy.
<input type="checkbox"/>	We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
<input type="checkbox"/>	Our Insured's driver has not reported the accident to us todate.
<input checked="" type="checkbox"/>	Others: <u>OFFICER-IN-CHARGE - STEVE LIM</u>

Prepared by:	<u>Pei Li</u>	6829 9194	<u>claims@ergo.com.sg</u>
Signature:	<u>[Signature]</u>		<b>FAX : 6829 9247</b>

### Assessor use only:

Assignment Date: \_\_\_\_\_  
Assignment Time: \_\_\_\_\_

Remarks:


### Workshop use only:

#### Assessor attended workshop on:

Date: \_\_\_\_\_  
Time: \_\_\_\_\_  
Inspector: \_\_\_\_\_

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Jimmy Goh  


Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.

## Shiau Chan (LKKAUTO)

---

**From:** Shiau Chan (LKKAUTO)  
**Sent:** Friday, 29 June 2018 2:32 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.); 'Steve Lim'  
**Cc:** SUR; assignments  
**Subject:** RE: SGJ908X / TP : SLA7462G/LKK / DOA : 27/04/2018 (DSMPC1800830)  
**Attachments:** CSEGI18007962Gqb.pdf

Dear Steve,

Enclosed herewith preliminary advice of SLA 7462G.

Best Regards,

**Shiau Chan (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [siewsc@lkkauto.com](mailto:siewsc@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAUTO)  
**Sent:** Wednesday, 2 May 2018 12:10 PM  
**To:** 'Survey Report (ERGO Insurance Pte. Ltd.)' <[Survey.Report@ergo.com.sg](mailto:Survey.Report@ergo.com.sg)>  
**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>  
**Subject:** RE: SGJ908X / TP : SLA7462G/LKK / DOA : 27/04/2018 (DSMPC1800830)

Dear Pei Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

**Catherine Chong** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6741-8434 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]  
**Sent:** Wednesday, 2 May, 2018 11:58 AM  
**To:** [admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)  
**Subject:** OI : SGJ908X / TP : SLA7462G/LKK / DOA : 27/04/2018 (DSMPC1800830)

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and Ergo Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANCY PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **ETHOZ GROUP LTD.**

ADDRESS : 22 TAMPINES ST 92  
SINGAPORE 528876



Auto  
Consultants  
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: DSMPC1800830

Date: 29<sup>th</sup> June 2018

Our Ref: CS/EGI18007962/Gqb

Without Prejudice

The Motor Claims Department  
ERGO Insurance Pte Ltd

Attn: Pei Li

Dear Sirs/Mdm

**PRELIMINARY ADVICE OF VEHICLE NO. SLA 7462G .**


We thank you for the instruction on 02/05/2018.

Please be informed that we had conducted the inspection of the abovementioned vehicle on 07/05/2018 at the premises of M/s ETHOZ and have the following to report:-

Workshop Estimate Amount	: S\$ <u>9,513.90</u> .
Revised Estimate Amount	: S\$ <u>3,328.36</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
Salvage Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages consistent.

Days of repair: 5 days.

We have NOT authorise repair.

Yours faithfully

Guo Qiang  
Automotive Assessor



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	27/04/2018 20:40
Date Of Accident	27/04/2018 15:15
Exact Location Of Accident	STILL ROAD TOWARDS GEYLANG
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLA7462G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	NORDIN BIN SULAIMAN
NRIC No	S0095845Z
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-92268682
Alternative Phone No	OTHERS-92268682

90602752

### Vehicle Particulars

Manufacturer	HONDA
Model	VEZEL 1.5X A
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	SOMPO INSURANCE SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	D17MTPV01003688
Cover Note Number	N.A

### Driver

Name of Driver	MOHAMED FAIZAL BIN NORDIN
NRIC No	S8232032F
Date Of Birth	01/10/1982
Occupation	INDOOR
Date Of Driving Pass	29/11/2010
Driving Experience	7 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92268682
Fax Number	
Contact Number	
Email Address	FAIZALPEK82@GMAIL.COM

Address	BLK 496DTAMPINES AVE 9
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	CHILDREN
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

Vehicle was stopped along the said location, on the first lane of three lane road, Traffic ahead start to move I released my brake and move forward, I noticed vehicle ahead stopped I applied my brake and stopped. Vehicle b driving on my rear did not stopped and hit onto the rear of my vehicle. There was no injuries.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SGJ908X
Vehicle Make/Model/Colour	VOLVO / V40 T2 (A) / RED
Details Of Properties	N.A
Vehicle Category	PRIVATE CAR
Name of Driver	TAN SEOK KHIM
NRIC/Passport Number	S1611954G
Contact Number	91179769
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	1

# Sketch Plan

## IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Roadside Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will be made available upon application by interested parties.
7. By the lodgement of this report to the Insurers, you hereby consent to the archiving of this report at the Centre and to copies of the report being made available at the Centre.
8. **Consent under the Personal Data Protection Act (PDPA)**  
I understand, acknowledge, agree and consent that:  
(a) My Insurer, my workshop and the General Insurance Association of Singapore ("GIA") may be permitted to collect, use, disclose and process my personal data/personal information set out in this form and any other personal information provided by me or provided by my Insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers who have insured vehicles involved in this accident (all Insurers) who have insured vehicles involved in the accident shall be truthfully referred to as the "Insurers", the Insurers' lawyers/claim firms, the Monetary Authority of Singapore and any relevant government agency/authority such as the police, for the purpose(s) of:  
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any request for investigation relating to the claims;  
(ii) investigating the accident and/or my claims;  
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by the;  
(iv) administering my claims including the making of correspondence, statements, invoices, receipts or notices to me, which, to all Insurers, disclosure of certain personal data about me to bring about delivery of the goods as well as on the external cover of all personal data packages; and/or  
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");  
(b) all Insurers who have insured vehicles involved in this accident and the Insurers' lawyers/claim firms, may be permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
(c) my Personal Information may also be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/claim firms, which may be based outside of Singapore) for one or more of the above Purposes.

VERIFIED BY AIAM MARK  
REPORTING OFFICER  
MOHAMAD HELMY BIN  
ALEHAM

Policyholder's Signature : Date & Time : Driver's Signature (if driver is not the policyholder) : Date & Time : Witnessed by Reporting Centre Personnel

## Sketch Plan

Sketch Plan

Scale 1:100

North

Sketch Plan

1. Sketch Plan

2. Sketch Plan

3. Sketch Plan

4. Sketch Plan

5. Sketch Plan

6. Sketch Plan

7. Sketch Plan

8. Sketch Plan

9. Sketch Plan

10. Sketch Plan

11. Sketch Plan

12. Sketch Plan

13. Sketch Plan

14. Sketch Plan

15. Sketch Plan

16. Sketch Plan

17. Sketch Plan

18. Sketch Plan

19. Sketch Plan

20. Sketch Plan

21. Sketch Plan

22. Sketch Plan

23. Sketch Plan

24. Sketch Plan

25. Sketch Plan

26. Sketch Plan

27. Sketch Plan

28. Sketch Plan

29. Sketch Plan

30. Sketch Plan

31. Sketch Plan

32. Sketch Plan

33. Sketch Plan

34. Sketch Plan

35. Sketch Plan

36. Sketch Plan

37. Sketch Plan

38. Sketch Plan

39. Sketch Plan

40. Sketch Plan

41. Sketch Plan

42. Sketch Plan

43. Sketch Plan

44. Sketch Plan

45. Sketch Plan

46. Sketch Plan

47. Sketch Plan

48. Sketch Plan

49. Sketch Plan

50. Sketch Plan

51. Sketch Plan

52. Sketch Plan

53. Sketch Plan

54. Sketch Plan

55. Sketch Plan

56. Sketch Plan

57. Sketch Plan

58. Sketch Plan

59. Sketch Plan

60. Sketch Plan

61. Sketch Plan

62. Sketch Plan

63. Sketch Plan

64. Sketch Plan

65. Sketch Plan

66. Sketch Plan

67. Sketch Plan

68. Sketch Plan

69. Sketch Plan

70. Sketch Plan

71. Sketch Plan

72. Sketch Plan

73. Sketch Plan

74. Sketch Plan

75. Sketch Plan

76. Sketch Plan

77. Sketch Plan

78. Sketch Plan

79. Sketch Plan

80. Sketch Plan

81. Sketch Plan

82. Sketch Plan

83. Sketch Plan

84. Sketch Plan

85. Sketch Plan

86. Sketch Plan

87. Sketch Plan

88. Sketch Plan

89. Sketch Plan

90. Sketch Plan

91. Sketch Plan

92. Sketch Plan

93. Sketch Plan

94. Sketch Plan

95. Sketch Plan

96. Sketch Plan

97. Sketch Plan

98. Sketch Plan

99. Sketch Plan

100. Sketch Plan

## ACCIDENT STATEMENT (2000 characters)

Vehicle was stopped along the said location, on the first lane of three lane road, Traffic ahead start to move I released my brake and move forward, I noticed vehicle ahead stopped I applied my brake and stopped. Vehicle b driving on my rear did not stopped and hit onto the rear of my vehicle. There was no injuries.

Taxi Voucher No.:

Are you claiming your own insurance policy for the repair of your vehicle?

No, Claim 3rd party

## DECLARATION

I/We declare that the above particulars &amp; information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MOHAMAD HELMY BIN ALEHAM

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

Date/Time:

PLEASE ARRANGE TO SURVEY  
VEHICLE AT 22 TAMPINES ST 92 (S  
528876)

Ng Boon Kai  
CLAIM DEPARTMENT  
DID : 6654\_7617  
FAX :

Date : 30/04/2018  
To : ERGO INSURANCE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NORDIN BIN SULAIMAN  
SOMPO INSURANCE SINGAPORE PTE. LTD.  
Certificate No : D17MIPV01003688 Accident Date : 27/04/2018  
Vehicle No : SLA-7462-G Make & Model : HONDA VEZEL 1.5X A  
Excess : 0.00 Add Excess : 0.00

### ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	TAILGATE / BUC .	953.30	/
1	TAILGATE WEATHERSTRIPE X NN	96.80	X
1	TAILGATE LOGO /	22.00	/
1	TAILGATE EMBLEM(VEZEL) / MEC	56.90	/
1	TAILGATE TRIMBOARD X NN	153.40	X
1	TAILGATE LOCK / BT	157.10	/
1	TAIL LAMP RH / SCR	240.00	428.7
1	TAIL LAMP LH X NN	240.00	X
1	TAILGATE LAMP RH X NN	428.70	X

Date : 30/04/2018

To : **ERGO INSURANCE PTE. LTD.**

## ESTIMATION

Attn : **Motor Claim Department**

FAX :

Owner : NORDIN BIN SULAIMAN

: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTPV01003688

Accident Date : 27/04/2018

Vehicle No : SLA-7462-G

Make & Model : HONDA VEZEL 1.5X A

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00

Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	TAILGATE LAMP LH <i>X NN</i>	428.70	<i>X</i>
1	REAR BUMPER <i>/ R</i>	463.70	<i>/</i>
10	REAR BUMPER CLIPS <i>/ MC</i>	55.00	<i>/</i>
1	REAR BUMPER SIDE RETAINER RH <i>X NN</i>	22.00	<i>X</i>
1	REAR BUMPER SIDE RETAINER LH <i>X NN</i>	22.00	<i>X</i>
1	REAR END PANEL <i>X Repair</i>	415.60	<i>X</i>
1	END PANEL TOP GARNISH <i>X</i>	92.30	<i>X</i>
1	SPARE TRYE COVER BOARD <i>X NN</i>	186.00	<i>X</i>
1	SPARE TRYE PANEL <i>X</i>		
1	REAR WINDSCREEN MOULDING <i>/ MC</i>	180.00	<i>/</i>

RESTORE

Date : 30/04/2018  
To : ERGO INSURANCE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NORDIN BIN SULAIMAN  
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTPV01003688 Accident Date : 27/04/2018  
Vehicle No : SLA-7462-G Make & Model : HONDA VEZEL 1.5X A

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR BUMPER SIDE GARNISH RH X { repair.	195.00	X
1	REAR BUMPER SIDE GARNISH LH X	195.00	X
1	WIPER MOTOR X NN	205.00	X
Sub Total		4808.50	2316.7
Add 20% On Parts		961.70	1853.46
<b>Special Nett Item</b>			
1	REAR WINDSCREEN SEALANT / ABC	80.00	/
1	END PANEL SEALANT X { NN	80.00	X
1	REVERSE SENSOR X	250.00	X
1	REAR NUMBER PLATE & HOLDER / sub.	35.00	/



Date : 30/04/2018  
To : ERGO INSURANCE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NORDIN BIN SULAIMAN  
: SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTPV01003688 Accident Date : 27/04/2018  
Vehicle No : SLA-7462-G Make & Model : HONDA VEZEL 1.5X A

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	Sub Total	445.00	
	<b>Labour &amp; Misc</b>		
	LABOUR TO FACILITATE REPAIR	1,200.00	500
	LABOUR TO SPRAY PAINT AFFECTED AREAS	1,400.00	600
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	-
	TO RUSH PROOF ON AFFECTED AREAS	80.00	40
	TO REMOVE & REFIT TAILGATE COMPONENTS	120.00	60
	TO REMOVE & REFIT REAR BOOTFLOOR COMPONENT	100.00	x NA
	TO REMOVE & REFIT REAR WINDSCREEN GLASS	150.00	100



Date : 30/04/2018  
To : ERGO INSURANCE PTE. LTD.

## ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : NORDIN BIN SULAIMAN  
: SOMPO INSURANCE SINGAPORE PTE. LTD.  
Certificate No : D17MTPV01003688 Accident Date : 27/04/2018  
Vehicle No : SLA-7462-G Make & Model : HONDA VEZEL 1.5X A

### ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO DETACH & RENEW REVERSE SENSOR	30.00	—
	<b>Sub Total</b>	<b>3110.00</b>	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

3328.36

Remarks:

5 Days.  
part by part

SUB TOTAL 9,325.20  
GST 7.0 % 652.76  
TOTAL 9,977.96

Surveyor's name: Ena Qiang - 82880282

Principal's name: NORDIN BIN SULAIMAN

Survey Date & Time: 07/5/18

*[Signature]*  
2/6/18

Amal: Quo Qianh,

**ETHOZ**

Date : 14/05/2018

To : ERGO INSURANCE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : NORDIN BIN SULAIMAN

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTPV01003688 Accident Date : 27/04/2018

Vehicle No : SLA-7462-G Make & Model : HONDA VEZEL 1.5X A

**FINAL ESTIMATED REPAIR COST DETAILS** Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
<u>List Item</u>			
1	TAILGATE	953.30	953.30
1	TAILGATE WEATHERSTRIPE	96.80	0.00
1	TAILGATE LOGO	22.00	22.00
1	TAILGATE EMBLEM(VEZEL)	56.90	56.90
1	TAILGATE TRIMBOARD	153.40	0.00
1	TAILGATE LOCK	157.10	157.10
1	TAIL LAMP RH	428.70	428.70
1	TAIL LAMP LH	428.70	0.00
1	TAILGATE LAMP RH	240.00	0.00
1	TAILGATE LAMP LH	240.00	0.00
1	REAR BUMPER	463.70	463.70
10	REAR BUMPER CLIPS	55.00	55.00
1	REAR BUMPER SIDE RETAINER RH	22.00	0.00
1	REAR BUMPER SIDE RETAINER LH	22.00	0.00

PAGE: 1



Date : 14/05/2018  
To : ERGO INSURANCE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : NORDIN BIN SULAIMAN

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTPV01003688 Accident Date : 27/04/2018

Vehicle No : SLA-7462-G Make & Model : HONDA VEZEL 1.5X A

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION		REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	REAR END PANEL	RESTORE	415.60	0.00
1	END PANEL TOP GARNISH		92.30	0.00
1	SPARE TRYE COVER BOARD		186.00	0.00
1	SPARE TRYE PANEL	RESTORE	0.00	0.00
1	REAR WINDSCREEN MOULDING		180.00	180.00
1	REAR BUMPER SIDE GARNISH RH	RESTORE	195.00	0.00
1	REAR BUMPER SIDE GARNISH LH	RESTORE	195.00	0.00
1	WIPER MOTOR		205.00	0.00
Sub Total			4002.90	2316.70
Discount 20% On Parts			(800.58)	(463.34)
<b>Special Nett Item</b>				
1	REAR WINDSCREEN SEALANT		80.00	80.00
1	END PANEL SEALANT		80.00	0.00
1	REVERSE SENSOR		250.00	0.00

PAGE : 2

Date : 14/05/2018  
To : ERGO INSURANCE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : NORDIN BIN SULAIMAN  
Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.  
Certificate No : D17MTPV01003688      Accident Date : 27/04/2018  
Vehicle No : SLA-7462-G      Make & Model : HONDA VEZEL 1.5X A

FINAL ESTIMATED REPAIR COST DETAILS      Excess : 0.00      Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
1	REAR NUMBER PLATE & HOLDER	35.00	35.00
	Sub Total	445.00	115.00
<b>Labour &amp; Misc</b>			
	LABOUR TO FACILIATE REPAIR	1200.00	500.00
	LABOUR TO SPRAY PAINT AFFECTED AREAS	1400.00	600.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	30.00	30.00
	TO RUSH PROOF ON AFFTECED AREAS	80.00	40.00
	TO REMOVE & REFIT TAILGATE COMPONENTS	120.00	60.00
	TO REMOVE & REFIT REAR BOOTFLOOR COMPONENT	100.00	0.00
	TO REMOVE & REFIT REAR WINDSCREEN GLASS	150.00	100.00

PAGE: 3

Date : 14/05/2018  
To : ERGO INSURANCE PTE. LTD.

Attn : Motor Claim Department

FAX :

Owner : NORDIN BIN SULAIMAN

Insured By : SOMPO INSURANCE SINGAPORE PTE. LTD.

Certificate No : D17MTPV01003688 Accident Date : 27/04/2018

Vehicle No : SLA-7462-G Make & Model : HONDA VEZEL 1.5X A

FINAL ESTIMATED REPAIR COST DETAILS Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR AMT (\$)
	TO DETACH & RENEW REVERSE SENSOR	30.00	30.00
	Sub Total	3110.00	1360.00

Sub Total	7,401.80	3,328.36
GST 7.0 %	518.13	232.99
Total	7,919.93	3,561.35

Materials : \$2,316.70 - 20%  
 Mark Up /  
 List Down : \$1,853.36  
 S/N Items : \$115.00  
 Labour : \$1,360.00  
 Total : \$3,328.36  
 Lump Sum : —  
 Excess : —  
 Total : \$3,328.36  
 7% GST : \$232.99  
 Grand Total : \$3,561.35 Repair Days : 05  
 Signature : [Signature]

Surveyor Name : GUO QIANG - LKK  
Date & Time : 07/05/2018 4:30:00 PM

Jimmy Goh Kl  
CLAIM DEPARTMENT  
DID : 66547618  
FAX : 6654 7648

PAGE : 4





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI18007962/Gqbs2

5 TEMASEK BOULEVARD  
#04-01 SUNTEC TOWER FIVE  
SINGAPORE 038985

Date : 02-07-2018



Code : EGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGJ 908X	Veh. Inspected	SLA 7462G
Policy No.		Coverage (\$)	0.00
Claim No.	DSMPC1800830	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	02/05/2018

### 2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU11109263	Colour	WHITE
Odometer	039283	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60R16	BRIDGESTONE	6 mm
L/H Front Tyre	215/60R16	BRIDGESTONE	6 mm
R/H Rear Tyre	215/60R16	BRIDGESTONE	6 mm
L/H Rear Tyre	215/60R16	BRIDGESTONE	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	27/04/2018	Inspection Date	07/05/2018
Survey held at	ETHOZ GROUP LTD 22 TAMPINES STREET 92 SINGAPORE 528876		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 7462G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b>REPLACEMENT OF PARTS</b>				
1	TAILGATE	BUCKLED	953.30	953.30
1	TAILGATE WEATHERSTRIPE	NOT NECESSARY	96.80	-
1	TAILGATE LOGO	NECESSARY	22.00	22.00
1	TAILGATE EMBLEM (VEZEL)	NECESSARY	56.90	56.90
1	TAILGATE TRIMBOARD	NOT NECESSARY	153.40	-
1	TAILGATE LOCK	BENT	157.10	157.10
1	TAIL LAMP RH	SCRATCHED	428.70	428.70
1	TAIL LAMP LH	NOT NECESSARY	240.00	-
1	TAILGATE LAMP RH	NOT NECESSARY	428.70	-
1	TAILGATE LAMP LH	NOT NECESSARY	428.70	-
1	REAR BUMPER	DEFORMED	463.70	463.70
10	REAR BUMPER CLIPS	NECESSARY	55.00	55.00
1	REAR BUMPER SIDE RETAINER RH	NOT NECESSARY	22.00	-
1	REAR BUMPER SIDE RETAINER LH	NOT NECESSARY	22.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	415.60	-
1	END PANEL TOP GARNISH	NOT NECESSARY	92.30	-
1	SPARE TYRE COVER BOARD	NOT NECESSARY	186.00	-
1	SPARE TYRE PANEL (NPA)	NOT NECESSARY	-	-
1	REAR WINDSCREEN MOULDING	NECESSARY	180.00	180.00
1	REAR BUMPER SIDE GARNISH RH	TO REPAIR SEE LABOUR	195.00	-
1	REAR BUMPER SIDE GARNISH LH	TO REPAIR SEE LABOUR	195.00	-
1	WIPER MOTOR	NOT NECESSARY	205.00	-
	LESS 20% DISCOUNT		-	-463.34
	COST PLUS 20%		999.44	-
			5,996.64	1,853.36
<b>SPECIAL NETT ITEMS</b>				
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	80.00
1	END PANEL SEALANT (SN)	NOT NECESSARY	80.00	-

Report Ref No. CS/EG18007962/Gqbs2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REVERSE SENSOR (SN)	NOT NECESSARY	250.00	-
1	REAR NUMBER PLATE & HOLDER (SN)	SCRATCHED	35.00	35.00
			445.00	115.00
	<b>LABOUR</b>			
	TO DETACH & RENEW REVERSE SENSOR.		30.00	30.00
	LABOUR TO FACILITATE REPAIR. INCLUSIVE OF THE REPAIR OF REAR END PANEL, REAR BUMPER SIDE GARNISH RH AND REAR BUMPER SIDE GARNISH LH.		1,200.00	500.00
	LABOUR TO SPRAY PAINT AFFECTED AREAS.		1,400.00	600.00
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS.		30.00	30.00
	TO RUSH PROOF ON AFFECTED AREAS.		80.00	40.00
	TO REMOVE & REFIT TAILGATE COMPONENTS.		120.00	60.00
	TO REMOVE & REFIT REAR BOOTFLOOR COMPONENT.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIT REAR WINDSCREEN GLASS.		150.00	100.00
			3,110.00	1,360.00
<b>GRAND TOTAL</b>			<b>9,551.64</b>	<b>3,328.36</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>3,328.36</b>

Report Ref No. CS/EGI18007962/Gqbs2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.