

22/03/2002

ASS. REC. BY:

REF:

CS/ALH18007963/Agon2

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

Insured

From (Person):

Mohd Imran

of

ALH

Date/Time:

02052018 11:57am

Estimated Cost:

Bill to:

OD / ☒ IN / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 9052D

Insured:

SLR 2160B

at Workshop m/s

Yi Hong

Tel:

6509 0052

of

Blk 1 Kaka Bukit Ave 6 #02-19

Policy No:

Claim No:

1847349829SK

Sum Insured:

Excess:

Make of Veh:

D.O.A.

29042018

(Client's Record)

CA / REV / REP. / REV 24 HRS WP

H.O.D. Endorsement:

Date/Time:

02052018 11:51am

Person Contacted:

Wan Ping

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SLR 9052D - X

SLR 2160B - X

LS \$1200, 3 days (Red to 7884.63, 87%)

ASS. REC. BY: Adrian Ling

REF:

ASSIGNMENT

16/06/18

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 3 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SLR9052D Yr Regn: 2008 / June.Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Nissan Letis C.C. 1498Colour: Silver A/C: Insured / Std / NI / NASp. Reading: 274515 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JN1BAAC120009552Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 195/60R15R: 195/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Maxxis

Front _____ Rear _____

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 02/05/18Survey held at Yi HengDes. of Damages: Frt / Rear / O/S / NIS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP AIG.

MV: 9K
PV: 7.5K
Nett: 1.5K

RECEIVED 14 JUN 2018

Date/Time, File Pass to?

11/4/18 Adrian

Date/Time, File Return to?

2)

☐ : Preli. Report☐ : Final ReportDays Of Repair: 3Resurvey No. of Trip: 1Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

Photos

Others

TOTAL

250

20

270

Report Format: MEK-TPLump Sum / I.B.A. (\$) 1200

-PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLQ2160B AND SLR9052R ON 29/04/2018

From: Md Ishak, Mohd Imran
To: assignments@lkkauto.com, admin-a@lkkauto.com
Cc: Tan, Lily (AIG), Fong, Andy-SY, Kaur, Baljit, Lim, Sheng Yang, Chan, Yoke Shi, Chin, Lee-Ying, Abu Kassim, Noor Mariesa, Fan, Winnie-LW, Supramaniam, Darshene
Sent: Wednesday, 2 May, 2018 11:57:24 AM
Attachments:  Fax445E.TIF  0740_001.pdf

WITHOUT PREJUDICE

Hi,

Please refer to the enclosed request from VISION LAW LLC

Claim no : 1847349829SG
Case Owner : BERNARD JI QIAN LER

If you have any queries/concerns, please let us know.
Kindly assist to assign **Adrian Ling** as Single Joint Expert as requested.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak
AIG
Express Claims Adjuster II, FNOL SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 ext.101266 | Fax +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

IMPORTANT NOTICE:
The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

From: Imran.Ishak@aig.com
To: annatan@visionlawllc.com
Cc: Lily Tan@aig.com, Andy-SY.Fong@aig.com, Baljit Kaur@aig.com, ShengYang.Lim@aig.com, yokeshi.chan@aig.com, Lee-Ying.Chin@aig.com, NoorMariesa.AbuKassim@aig.com, Winnie-LW.Fan@aig.com, Darshene Supramaniam@aig.com
Subject: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED VEHICLE SLQ2160B AND SLR9052R ON 29/04/2018
Date: Mon, 30 Apr 2018 07:20:44 +0000

WITHOUT PREJUDICE

Your Reference : AKN-atv-INS-Y44-SLR90552D-2018
Our Reference : 1847349829SG-003

Dear Sir/Madam,

We refer to your Notice of Accident of even date.

We intend to conduct a pre-repair survey of the damage to your client's/your customer's vehicle jointly with your client/your motor workshop. We propose to use one of the motor surveyors named in the attached list to conduct the joint pre-repair survey as a single joint expert.

Name of Surveyor	Company Name
Lim Kok Chong	AIG Asia Pacific Insurance Pte Ltd
Kumar Uthaya	AIG Asia Pacific Insurance Pte Ltd
Ken Wong	AIG Asia Pacific Insurance Pte Ltd
Lawrence Ng Chun Kee	Priority Services
Jeffrey Ong Leng Kiat	Priority Services
Jimmy Lee	Priority Services
EC Looi	Automobile Inspection Services Pte Ltd
Ricky Teng	RT Appraisal Pte Ltd
Elson Teng	RT Appraisal Pte Ltd
Michael Cheong	RT Appraisal Pte Ltd
Pang Kiah Keen (Frankie)	Formteam Adjusters Pte Ltd
Ng You Han	Formteam Adjusters Pte Ltd
Soon Han Xin (Gary)	Formteam Adjusters Pte Ltd
Chow Bo Xiong	Formteam Adjusters Pte Ltd
Chua Soo Teck (Benjamin)	Formteam Adjusters Pte Ltd

Kalvin Ang	LKK Auto Consultants Pte Ltd
Xing Guo Qiang	LKK Auto Consultants Pte Ltd
Marcus Chua	LKK Auto Consultants Pte Ltd
Mohamad Taufikh	LKK Auto Consultants Pte Ltd
Adrian Ling	LKK Auto Consultants Pte Ltd
Henry Ng	LKK Auto Consultants Pte Ltd
Mohammed Rasul	LKK Auto Consultants Pte Ltd
Steven Foong	LKK Auto Consultants Pte Ltd
Wei Jie	LKK Auto Consultants Pte Ltd
Ma Chin Fook	LKK Auto Consultants Pte Ltd
Kenneth Kong	LKK Auto Consultants Pte Ltd

Please let us know within two (2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert. You may select one or more of the listed motor surveyors. We will bear the cost of the pre-repair survey carried out by the single joint expert.

Thank you

Sincerely,

Imran

Mohd Imran Md Ishak

AIG

Express Claims Adjuster II, FNOL SG Claims Operations - Auto
Shared Services - Malaysia | Global Business Services

AIG Shared Services (M) Sdn Bhd (887191-D)
Menara Worldwide, Level 14, 198 Jalan Bukit Bintang, 55100 Kuala Lumpur, Malaysia
Tel +6 03 2719 6000 ext:1012661 | Fax +6 03 2685 5898

imran.ishak@aig.com | www.aig.com

VISION LAW LLC

Advocates & Solicitors - Rotary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

Company Registration No. 200721148H

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI DIO MUNIANDY
SEGA PARAM
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YINGXIAN SELWYN

Head Office:
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413
Branch:
490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

HEAD OFFICE:

TEL : 65342811 (Hunting)
FAX : 65356802 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH

TEL : 63580703
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to HEAD OFFICE for this matter

OUR REF: AKN-atv-INS-Y44-SLR9052D-2018 - please reply to: annatan@visionlawllc.com
YOUR REF: SLQ 2160 B

2 May 2018

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS Building
78 Shenton Way #08-16
Singapore 079120
Attn: Motor Claims Department

BY FAX 6835-7416 & EMAIL:
AIGSGP_ClaimsSurvey@aig.com

Dear Sirs

NAME OF CLAIMANT: APPLE CAR RENTAL & LEASING PTE LTD
VEHICLE NUMBER: SLR 9052 D
YOUR INSURED VEHICLE NUMBER: SLQ 2160 B
ACCIDENT ALONG CTE SLIP ROAD TOWARDS BUKIT TIMAH ON 29 APRIL 2018 AT ABOUT 2310 HOURS

We refer to your email dated 30 April 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **Adrian Ling - LKK Auto Consultant** as the Single Joint Expert for this matter.

Please be informed that the said vehicle can be inspected at :

YI HENG MOTOR WORKSHOP
1 KAKI BUKIT AVENUE 6
#02-19 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883
TEL: 6509 0052 (WAN PING)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully



(Head Office)

cc. SLR 9052 D - By fax 6747-9402 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature) :

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

- Petrol price keeps increasing!
- 10th Generation Honda Civic (2016)
- 2016 Hyundai Elantra / Avante

Post an Advertisement
Sell it yourself! Advertise it at just
\$58 until it's SOLD!

[Post an Ad](#) [Advertiser Login](#) [Ways of Selling](#)

The Only RB Ver.1.86 In SG.



Not For The Faint Hearted! Head
Turners Will Be Your New
Common Thing.
Direct Owner [Share Ad](#)

HIN LUNG AUTO
Ho Bee Group
One Stop Car Hub
Finance, Insurance, Workshop
New and Used Cars

30 years
of car sale

Browse by Category ▼

Sort by Date Posted ▼ 20 results/page ▼

18 vehicles

Nissan Latio

Advanced Search

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
Search Selection	Nissan Latio		Any	Any	2008	Any	Any	Any	Available
	Nissan Latio	Nissan Latio 1.5A (New 5-yr COE)	\$27,800	\$5,560 /yr	25-Apr-2008	1,498 cc	-	Sedan	Available
Original Condition, 100% Loan Available, Car Ready For Viewing, Please Call Us Now For Viewing.									
Posted: 14-Mar-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan									
	Nissan Latio	Nissan Latio 1.5A Sports (New 5-yr COE)	\$36,800	\$7,360 /yr	29-Apr-2008	1,498 cc	-	Hatchback	Available
Optional: 10 Years COE Renewal For \$55,800. Up To 90% Flexible Loan. We Provide Lowest Interest Rate. Flexible Loan And High Trade In Are Available. Package With Unrivaed Warranty Complete With Certi...									
Classic Credit Pte Ltd									
Posted: 20-Apr-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan									
	Nissan Latio	Nissan Latio 1.5A Premium	\$9,000	N.A	03-Jun-2008	1,498 cc	169,041 km	Sedan	Available
Silver Latio Is Up For Sale, One Of The Cheapest In The Market. Good On Fuel, Still In Good Shape, No Problem To Renew COE If Don't Wish To Scrap. Well Maintained, Selling Due To Overseas Posting.									
Posted: 30-Apr-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan									
	Nissan Latio	Nissan Latio 1.5A Sports Premium (New 5-yr COE)	\$31,800	\$6,360 /yr	05-Jun-2008	1,498 cc	78,615 km	Hatchback	Available
Low Down Payment 3K, In House Finance Avail, Agent Maintained And Services! Very Low Mileage, Rare Find, Well Kept In Tip Top Condition That You Will Be Amazed With. See It For Yourself To Believe! Buy...									
Posted: 21-Apr-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan									
Car Buying Car Aftermarket Car Selling On The Move Car Ownership Lifestyle Buy Tyres Online! Latest Special Offers from Tyrepac!									
	Nissan Latio	Nissan Latio 1.5A Premium (New 5-yr COE)	\$31,800	\$6,360 /yr	06-Jun-2008	1,498 cc	-	Sedan	Available
New 5 Year COE! 1 Owner Only! Fully Maintained With Agent From Day 1! Easy To Maintained And Good Fuel Consumption! New Paintwork Will Be Given, Just Like Buying A New Car! High/Flexible Loan Availabl...									
GS Automobiles Pte Ltd									
Posted: 01-May-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan									
	Nissan Latio	Nissan Latio 1.5A (New 5-yr COE)	\$29,800	\$5,960 /yr	18-Jun-2008	1,498 cc	-	Sedan	Available
Low Depreciation At \$490 Mthly Only. Tip Top Engine Condition, Excellent Interior And Exterior Condition. Well Maintained Car. Good Fuel Consumption. Reliable And Easy Maintenance. Spacious And Comfort...									
Posted: 22-Apr-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan									
	Nissan Latio	Nissan Latio 1.5A Sports Premium (New 5-yr COE)	\$29,800	\$5,960 /yr	26-Jun-2008	1,498 cc	124,000 km	Hatchback	Available
Sunroof Latio Sports! \$6,000 Down Payment Only! Monthly Installment Only \$520/=. Cheapest In Market, Bank Loan And In House Loan Available, No Repair Needed. Best Known For Its Fuel Efficiency And Rel...									
Posted: 28-Apr-2018 Tags: 2008 Nissan Latio, Nissan Latio, Nissan, Latio, Used Nissan									

Enquire PARF/COE Rebate for Registered Vehicle**Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	1343H

Vehicle Details

Vehicle No.:	SLR9052D
Vehicle to be Exported:	Yes
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	NISSAN
Vehicle Model:	LATIO 1.5L A
Primary Colour:	Silver
Manufacturing Year:	2007
Engine No.:	HR15257362A
Chassis No.:	JN1BAAC11Z0009552
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$14,631.00
Original Registration Date:	16 Jun 2008
First Registration Date:	16 Jun 2008
Transfer Count:	1
Actual ARF Paid:	\$14,631.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	15 Jun 2018
PARF Rebate Amount:	\$7,315.00

Intended COE Rebate Details

COE Expiry Date:	15 Jun 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$14,590.00
COE Rebate Amount:	\$182.00
Total Rebate Amount:	\$7,497.00

The information contained herein is correct as at 30 Apr 2018

OK

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

02-05-18

OUR REF NO. SLR 9052D

APPLE CAR RENTAL & LEASING PTE LTD
THE GRANDSTAND CARMALL
210, TURFCLUB ROAD
LOT A12/A27
SINGAPORE 287995

TPA19
xiao Chen

ESTIMATE BILL FOR VEHICLE NO. SLR 9052D MODEL : NISSAN LATIO

LIST ITEM

1) BOOT LID		1,321.20	x
2) BOOT LID OUTER GARNISH		218.00	x
3) BOOT LID TRIM BOARD		263.20	x
4) BOOT LID DAMPER	2 PCS @ \$ 113.20	226.40	x
5) TAIL LAMP ASSY	2 PCS @ \$ 320.20	640.40	x
6) TAIL LAMP BASE PANEL	2 PCS @ \$ 278.60	557.20	x
7) REAR BUMPER		1,189.70	x
8) REAR BUMPER LOWER SPOILER		883.00	x
9) REAR BUMPER BRACKET	2 PCS @ \$ 84.40	168.80	x
10) REAR BUMPER SIDE ATTACHMENT	2 PCS @ \$ 55.30	110.60	x
11) REAR PANEL ANTENNA SENSOR		322.10	x
12) REAR END PANEL		583.30	x

LESS DISCOUNT - 30%

6,483.90
1,945.17
4,538.73

NETT ITEM

1) BOOT LID WEATHERSTRIPE		189.60	x
2) BOOT LID BADGE		65.40	x
3) BOOT LID EMBLEM 'LATIO'		57.40	x
4) BOOT LID LOCK		184.20	x
5) BOOT LID STRIKER		47.80	x

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
#02-19 SINGAPORE 417883
TEL: 6 5090052 FAX: 6 7479402

6) BOOT LID ACTUATOR		98.20 +
7) BOOT LID STOPPER	2 PCS @ \$ 12.80	25.60 +
8) REAR WINDSCREEN MOULDING		114.50 +
9) TAIL LAMP CLIP	2 PCS @ \$ 14.60	29.20 +
10) REAR BUMPER CLIP	6 PCS @ \$ 5.50	33.00 ✓
11) REAR PANEL INNER TRIM		173.10 +
12) REAR SPLASH SHIELD	2 PCS @ \$ 48.50	97.00 +
13) REAR SPLASH SHIELD CLIP	6 PCS @ \$ 5.50	33.00 +
		1,148.00
	LESS DISCOUNT - 10%	114.80
		1,033.20

SPECIAL NETT ITEM

1) REAR WINDSCREEN GUM		60.00 +
2) REAR LICENCE PLATE (EMBOSS)		55.00 +
3) REVERSE SENSOR WITH CONTROL UNIT		350.00 200
4) REAR WINDSCREEN INNER SEAL		49.10 +
5) SPARE TYRE PANEL INSULATOR CLOTH		428.60 +
		942.70

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM		50.00 30
2) TO APPLY UNDER SEALING ON AFFECTED AREAS		120.00 +
3) TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT		120.00 50
4) TO REMOVE AND REFIX CUSHION, FLOOR BOARD, ROOF LINING, TRIM, GARNISH, UPHOLSTERY ETC		150.00 +
5) TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT		220.00 +
6) TO REMOVE AND REFIX PETROL TANK		150.00 +
7) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC		880.00 250
8) TO RESPRAY ON AFFECTED AREAS		880.00 400
		2,570.00
		9,084.63

the Repairer of the following:

- TO RESPRAY ON AFFECTED AREAS
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total 1893.42
h/s: 1.2K
Adrian L
h/s 02/03/18
03 Apr \$1.2K

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/AIG18007963/AQBN2

Date: 19/06/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700022998
 Claimant Vehicle No: SLR9052D Insured Vehicle No: SLQ2160B
 Date of Loss: 29/04/2018 Nature of Claim: TP Claim No: 1847349829SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLR9052D Engine No: HR15257362A
 Make & Model: NISSAN LATIO, 1.5 (A) Chassis No: JN1BAAC11Z0009552
 Reg. Date: 16/06/2008 (Man. Year: 2007) Odometer: 274515 km
 Colour: Silver
 Engine Capacity: 1498 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60R15 Rear Tyre Size: 195/60R15
 Front Left Side: Maxxis 6 mm Rear Left Side: Maxxis 6 mm
 Front Right Side: Maxxis 6 mm Rear Right Side: Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	6,514.63	1,163.42	5,351.21	82.14
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,570.00	730.00	1,840.00	71.60
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,084.63	1,893.42	7,191.21	79.16
Approved Total (Overridden) (S\$)		1,200.00		
Nett Amount (S\$)	9,084.63	1,200.00	7,884.63	86.79

INSPECTION

Date of Assignment: 02/05/2018
 Date Inspected: 02/05/2018 Inspected At: Yi Heng Motor Workshop (HQ)
 Blk 1 Kaki Bt Ave 6 #02-19
 Singapore 417883

Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Not Necessary	1,321.20 FL	*- FL
2	1		*BOOT LID OUTER GARNISH	Not Necessary	218.00 FL	*- FL
3	1		*BOOT LID TRIM BOARD	Not Necessary	263.20 FL	*- FL
4	2		*BOOT LID DAMPER	Not Necessary	226.40 FL	*- FL
5	2		*TAIL LAMP ASSY	Not Necessary	640.40 FL	*- FL
6	2		*TAIL LAMP BASE PANEL	Not Necessary	557.20 FL	*- FL
7	1		*REAR BUMPER	Deformed	1,189.70 FL	*509.00 FL
8	2		*REAR BUMPER BRACKET	Not Necessary	168.80 FL	*- FL
9	2		*REAR BUMPER SIDE ATTACHMENT	Necessary	110.60 FL	*110.60 FL
10	1		*REAR PANEL ANTENNA SENSOR	Not Necessary	322.10 FL	*- FL
11	1		*REAR END PANEL	Not Necessary	583.30 FL	*- FL
12	1		*BOOT LID WEATHERSTRIPE	Not Necessary	189.60 FN	*- FN
13	1		*BOOT LID BADGE	Not Necessary	65.40 FN	*- FN
14	1		*BOOT LID EMBLEM LATIO	Not Necessary	57.40 FN	*- FN
15	1		*BOOT LID LOCK	Not Necessary	184.20 FN	*- FN
16	1		*BOOT LID STRIKER	Not Necessary	47.80 FN	*- FN
17	1		*BOOT LID ACTUATOR	Not Necessary	98.20 FN	*- FN
18	2		*BOOT LID STOPPER	Not Necessary	25.60 FN	*- FN
19	1		*REAR WINDSCREEN MOULDING	Not Necessary	114.50 FN	*- FN
20	2		*TAIL LAMP CLIP	Not Necessary	29.20 FN	*- FN
21	6		*REAR BUMPER CLIP	Necessary	33.00 FN	*33.00 FN
22	1		*REAR PANEL INNER TRIM	Not Necessary	173.10 FN	*- FN
23	2		*REAR SPLASH SHIELD	Not Necessary	97.00 FN	*- FN
24	6		*REAR SPLASH SHIELD CLIP	Not Necessary	33.00 FN	*- FN
25	1		*REAR WINDSCREEN GUM	Not Necessary	60.00 FS	*- FS
26	1		*REAR LICENCE PLATE (EMBOSS)	Not Necessary	55.00 FS	*- FS
27	1		*REVERSE SENSOR WITH CONTROL UNIT	Necessary	350.00 FS	*200.00 FS
28	1		*REAR WINDSCREEN INNER SEAL	Not Necessary	49.10 FS	*- FS
29	1		*SPARE TYRE PANEL INSULATOR CLOTH	Not Necessary	428.60 FS	*- FS
30	1		*REAR BUMPER LOWER SPOILER	Cracked	618.10 FS	*500.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc. N=NettItemDisc.

Sub Total (\$\$)	8,309.70	1,352.60
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,680.27	185.88
- Nett Item Discount on N Items 10.00/10.00% (\$\$)	114.80	3.30
Total Parts (\$\$)	6,514.63	1,163.42

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM	New	50.00	30.00
2	TO APPLY UNDER SEALING ON AFFECTED AREAS	New	120.00	-
3	TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT	New	120.00	50.00
4	TO REMOVE AND REFIX CUSHION,FLOOR BOARD,ROOF LINNING,TRIM,GARNISH,UPHOLSTERY ETC	New	150.00	-
5	TO REMOVE AND REFIX BOOT LID FIXING AND REALIGNMENT	New	220.00	-
6	TO REMOVE AND REFIX PETROL TANK	New	150.00	-
7	TO REPLACE NEW PARTS,CUT,WELD,KNOCK ETC	New	880.00	250.00
8	TO RESPRAY ON AFFECTED AREAS	New	880.00	400.00
Gross Labour Cost (S\$)			2,570.00	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >