

*Not Notified
1/1/18 & ?
Resurvey After Painting
5 days*



ESTIMATE TO REPAIR

VEHICLE NO. : SGU 2673 B
MAKE : TOYOTA
MODEL : COROLLA AXIO 1.5 X M
YEAR : 2007
CHASSIS NO : NZE1416019382

| | |
|----------------|---|
| SURVEYOR NAME | : |
| DATE OF SURVEY | : |
| TIME OF SURVEY | : |

DATE : 30-Apr-18
DATE OF ACCIDENT : 27-Apr-18
THIRD PARTY REF : SGB 1968 H / AIG

| Qty | Parts Description/ Labour | Type | Unit Price | Nett Item Amt | Amount |
|---------|---|--------|------------|--------------------------|-------------|
| 1 pc | Rear Bumper | | | <i>NIS Dit</i> \$ 568.90 | ✓ |
| 2 pcs | Rear Bumper Retainer | | \$ 87.70 | \$ 175.40 | ✓ |
| 2 pcs | Rear Bumper Bracket | | \$ 55.44 | \$ 110.88 | ? |
| 1 pc | Rear End Panel | | | \$ 687.70 | ✓ |
| 1 pc | Rear End Panel Garnish | | | \$ 125.70 | ✓ |
| 2 pcs | Tailamp | | \$ 385.70 | \$ 771.40 | ✓ |
| 1 pc | Rear Boot Lid | | | \$ 987.50 | ✓ |
| 1 pc | Rear Boot Lock | | | \$ 95.40 | ✓ |
| 1 pc | Rear Boot Rubber | | | \$ 167.20 | ✓ |
| 1 pc | Rear Boot AXIO Emblem | | | \$ 85.40 | ✓ |
| 1 pc | Rear Boot COROLLA Emblem | | | \$ 55.61 | ✓ |
| 1 pc | Rear Boot X Emblem | | | \$ 57.40 | ✓ |
| | | | | \$ 3,888.49 | |
| | Less 25% | | | \$ 972.12 | |
| | | | | \$ 2,916.37 | |
| 1 set | Rear Bumper Sensor | S.Nett | | <i>Shan</i> \$ 200.00 | ✓ |
| | To putty & spray painting. | | | \$ 900.00 | 800 |
| | To check rear wiring and water leakage. | | | \$ 30.00 | 200 |
| | To anti-rust. | | | \$ 80.00 | 600 |
| | Labour Charges. | | | \$ 700.00 | 6500 |
| TG-RA/- | TOTAL | | | | \$ 4,826.37 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Lim Tan Motor Pte Ltd

Blk 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721
Tel:65-64520893 Fax:65-64589127 Website : www.LTM.sg
Co.Reg No.199307277D GST Reg No.M2-0019086-0