



**ESTIMATE TO REPAIR**

VEHICLE NO. : SGU 2673 B  
 MAKE : TOYOTA  
 MODEL : COROLLA AXIO 1.5 X M  
 YEAR : 2007  
 CHASSIS NO : NZE1416019382

SURVEYOR NAME	:
DATE OF SURVEY	:
TIME OF SURVEY	:

DATE : 30-Apr-18  
 DATE OF ACCIDENT : 27-Apr-18  
 THIRD PARTY REF : SGB 1968 H / AIG

Qty	Parts Description/ Labour	Type	Unit Price	Nett Item Amt	Amount
1 pc	Rear Bumper				\$ 568.90
2 pcs	Rear Bumper Retainer		\$ 87.70		\$ 175.40
2 pcs	Rear Bumper Bracket		\$ 55.44		\$ 110.88
1 pc	Rear End Panel				\$ 687.70
1 pc	Rear End Panel Garnish				\$ 125.70
2 pcs	Taillamp		\$ 385.70		\$ 771.40
1 pc	Rear Boot Lid				\$ 987.50
1 pc	Rear Boot Lock				\$ 95.40
1 pc	Rear Boot Rubber				\$ 167.20
1 pc	Rear Boot AXIO Emblem				\$ 85.40
1 pc	Rear Boot COROLLA Emblem				\$ 55.61
1 pc	Rear Boot X Emblem				\$ 57.40
					\$ 3,888.49
	Less 25%				\$ 972.12
					\$ 2,916.37
1 set	Rear Bumper Sensor	S.Nett			\$ 200.00
	To putty & spray painting.				\$ 900.00
	To check rear wiring and water l leakage.				\$ 30.00
	To anti-rust.				\$ 80.00
	Labour Charges.				\$ 700.00
TG-RA/-	<b>TOTAL</b>				\$ 4,826.37

Lim Tan Motor Pte Ltd

Bik 176 Sin Ming Drive #03-09 Sin Ming Autocare Singapore 575721  
 Tel:65-64520893 Fax:65-64589127 Website: www.LTM.sg  
 Co.Reg No.199307277D GST Reg No.M2-0019086-0