

REPAIR ESTIMATE*

DATE 28/4/2018 10:08

DVA: 27.04.18

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?		\$ 49.00	\$ 98.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	License Lamp Holder ✓			\$ 100.00
	SUB TOTAL			\$ 2,056.35
	LESS 20%			\$ 411.27
	DISCOUNTED TOTAL			\$ 1,645.08
	Rear No.Plates ✓			\$ 25.00
	Rear Bumper Reverse Sensor ✗			\$ 135.70
	Rear Bumper Advertisement Logo ✓			\$ 50.00
	Rear Fender Advertisement Logo (LH/RH) ✓		\$ 100.00	\$ 200.00
				\$ 410.70
	Labour Charge			
	Panel Beating			\$ 350.00 200
	Spray Painting Charge			\$ 250.00 200
	Wiring Charge			\$ 50.00 ✗
	Remove/Refix Reverse Sensor			\$ 120.00 20
	TOTAL LABOUR			\$ 770.00
	ESTIMATE TOTAL			\$ 2,825.78
	Kelvin LKKK ✓ 30/4/18 1030L 2 Days PIP Before Part photo			

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) allowed
- Supplementary item(s) must be resurveyed & is subject to final approval from Insurance Company.

Acknowledged by Repairer
Signature:
Date:

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.