



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0913050

Date: 30 Apr 2018

Policy No: P1764949

Veh Reg No: SFR8879M

Make/Model: BMW 216D GRAN

TOURER LED NAV 7
SEATER

Your Ref No: S8M00ETP

Claim Type: Own Damage

Accident Date: 20/04/2018

Not Authorised
1.B.1

Running 34 pain

Ex 8600

4 days

Estimate Repair Cost to Vehicle No :SFR8879M

Ref: 62564315

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
SPARE PARTS				
1 HEADLAMP WITH LED LH		1 PC	1,780.00	?
2 HEADLAMP WITH LED RH		1 PC	1,780.00	?
3 HEADLAMP TOP RUBBER LH		1 PC	15.00	?
4 HEADLAMP TOP RUBBER RH		1 PC	15.00	?
5 HEADLAMP CLIPS X 4 LH & RH		4 PC	20.00	?
6 FRONT GRILLE WITH OUTER CHROME LH		1 PC	80.00	?
7 FRONT GRILLE WITH OUTER CHROME RH		1 PC	80.00	?
8 FRONT BUMPER		1 PC	620.00	?
9 FRONT BUMPER TOP EMBLEM		1 PC	55.00	?
10 FRONT BUMPER TOP RUBBER		1 PC	18.00	X
11 FRONT BUMPER TOW COVER RH		1 PC	20.00	X
12 FRONT BUMPER REINFORCEMENT		1 PC	270.00	?
13 FRONT BUMPER REINFORCEMENT BRACKET LH		1 PC	65.00	?
14 FRONT BUMPER REINFORCEMENT BRACKET RH		1 PC	65.00	?
15 FRONT BUMPER SPONGE CENTRE		1 PC	35.00	?
16 FRONT BUMPER REINFORCEMENT LOWER		1 PC	100.00	?
17 FRONT BUMPER REINFORCEMENT LOWER BRACKET		1 PC	90.00	?
18 FRONT BUMPER SIDE PARKING SENSOR X 2		2 PC	320.00	X ?
19 FRONT BUMPER SIDE PARKING SENSOR HOLDER X 2		2 PC	8.00	X ?
20 FRONT BUMPER SIDE RETAINERS LH & RH		2 PC	30.00	X
21 FRONT BUMPER CLIPS X 12		12 PC	18.00	?
22 FRONT BUMPER LOWER GRILLE		1 PC	75.00	?
23 FRONT BUMPER LOWER GRILLE PARKING SENSOR		2 PC	320.00	X
24 FRONT BUMPER LOWER GRILLE PARKING SENSOR HOLDER		2 PC	8.00	X
25 FOGLAMP OUTER COVER		2 PC	140.00	?
26 FOGLAMP OUTER COVER CHROME MOULDING X 2		2 PC	90.00	?
27 RADIATOR SUPPORT PANEL TOP		1 PC	85.00	X
28 AIR DUCT ASSY		1 PC	195.00	?
29 AIR CON CONDENSER ASSY		1 PC	670.00	X
30 RADIATOR ASSY		1 PC	390.00	X
31 INTER COOLER ASSY		1 PC	520.00	X ?
32 FRONT NUMBER PLATE GARNISH		1 PC	50.00	?

8,027.00

Special Nett

33 NUMBER PLATE (BLACK)

1 PC 35.00



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288 FAX: 63382522
ATTN: Motor Claim Department

Estimate No: MC0913050

Date: 30 Apr 2018

Policy No: P1764949

Veh Reg No: SFR8879M

Make/Model: BMW 216D GRAN
TOURER LED NAV 7
SEATER

Your Ref No: S8M00ETP
Claim Type: Own Damage
Accident Date: 20/04/2018

Estimate Repair Cost to Vehicle No :SFR8879M

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
34 COOLANT		1 PC	60.00	95.00
LABOUR				
35 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.		1 PC	40.00	201
36 TO REMOVE AND REPLACE A/C CONDENSER AND PIPES, RADIATOR AND HOSES, VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.		1 PC	150.00	?
37 TO REMOVE AND REINSTALL/REPLACE FRONT BUMPER PARKING SENSOR CENTRE, SIDE		1 PC	160.00	801
38 TO RESET FRONT BUMPER PARKING SENSOR CENTRE, SIDE, HEADLAMP,ENGINE LIGHT		1 PC	400.00	?
39 TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL TOP,FRT BUMPER REINFORCEMENT & LOWER BRACKET. TO KNOCK & REPAIR FRONT FENDER LH & RH, HEADLAMP PANEL X 2 LH & RH, INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	800.00	300
40 TO SPRAY FRONT BUMPER, FRT BUMPER REINFORCEMENT & LOWER BRACKET, FRONT FENDER LH & RH, HEADLAMP PANEL LH & RH		1 PC	800.00	2501
				2,350.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modifications is allowed
- Supplementary item(s) must be resurveyed and
- Vehicle to be properly insured with insurance company

TOTAL: SINGAPORE DOLLAR ELEVEN THOUSAND TWO HUNDRED AND FIVE AND CENTS FOUR ONLY

Please arrange this vehicle to be properly insured with insurance company.

Thank You

Acknowledged by Repairer

Signature:

Date:

Amount Before Excess S\$ 10,472.00

Add GST @ 7% 733.04

Total Amount payable S\$ 11,205.04

For AH LIM MOTOR COMPANY



AUTHORIZED SIGNATURE