

2/03/2002

ASS. REC. BY:

REF:

CS/E1218007976/R1s3bn2

Special Instruction:

Surveyor:

Rasell

ASSIGNMENT (Office)

From (Person):

Yee Pei Li

of

RGL

Date/Time: 02082018 1003am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKG 203P

Insured:

GZ 3774Y

at Workshop m/s

Byrneo motor

Tel:

9847 6178

of

2 Pandan Crescent

Policy No:

Claim No:

GZ3774Y/SA/pi

Sum Insured:

Excess:

D.O.A. 25042018

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

03052018 @ 2.30pm

H.O.D. Endorsement:

Date/Time: 02052018 1055am

Person Contacted:

Wally

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SKG 203P - X

GZ 3774Y - X

08/05/18 @ 13:40 p.m. revised to Pei Li via email.

REF: **EGL**

58581

ASSIGNMENT

From: **03051018**

Date: **03051018**

Estimated Cost: **OD / TP / WS / TP RES / OD RES / EVA / INV / MV**

To Inspect Vehicle No: **SKG 203P**

at Workshop m/s: **Borneo Motor**

of: **2 Pandan Crescent**

Insured:

Policy No:

Claims No:

Sum Insured: **Wally**

Excess:

(Client's Record)

Make of Veh: **230pm**

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: **Consistent? : Yes or No**

GIA / PR Seen: **Consistent? : Yes or No**

Est. Repairs: **days Res.: Yes or No**

Lum Sum: **% 3 Val.: Yes or No**

CA / REV / REP. / 24 HRS 'DS'

Date: **Person Contacted:**

Vehicle: **IN / OUT**

Veh No: **SKG 203P** Yr Regn: **2017 / MAR**

Type: **M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or**

Make: **TOYOTA LEXUS ES300H** C.C: **2454**

Colour: **Black** A/C: **Insured / Std / NI / NA**

Sp. Reading: **34720** T/Radio: **Insured / Std / NI / NA**

Eng/No: **JTH BW 166 202 / 48931**

C/No: **215 / SSR17**

Gen. Cond: **Good / Fair / Poor / Burnt**

Steering: **Order / Jammed / Leaked / Burnt or**

Brake: **Order / Jammed / Leaked / Burnt or**

Modj: **Nil / S/Rim / STD A/Rim or**

Tyre Size: **F: 215 / SSR17**

R: 215 / SSR17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front: **6 mm** Rear: **6 mm**

R/Bal: **6 mm** L/Bal: **6 mm**

D.O.A: **25/04/18** D.O.I: **03/05/18**

Survey held at: **BORNEO MOTOR**

Des. of Damages: **Frt / Rear / O/S / N/S / U/C / Rooftop or**

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time: **24/05/18** Action / Instruction: **PIP \$ 4,032.50 / 3 days**

(\$ 6,171.10 - \$ 4,032.50) Reduction = 34%

RECEIVED 24 MAY 2018

Date/Time, File Pass to? **24/05/18**

1) **Typist**

Date/Time, File Return to?

2)

Days Of Repair: **3**

Resurvey No. of Trip: **1**

Survey Fee:

Transportation: **\$ + RS: \$**

Photos:

Others:

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I: **(PIP \$ 4,032.50)**

TOTAL

250



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: GZ3779Y/SA/pl

Date: 08 May 2018

Our Ref: CS/EG118007976/R1s3b

The Motor Claims Department
ERGO INSURANCE PTE LTD

Dear Sir/Madam,


PRELIMINARY ADVICE OF VEHICLE NO. SKG 203P

Please be informed that we had conducted the inspection of the abovementioned vehicle on 03/05/2018 at the premises of M/s Borneo Motors (Singapore) Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>6,015.40</u>
Revised Estimate Amount (Labour)	: S\$ <u>3,730.00</u>
"Check" Items Amount	: S\$ <u>1,779.00</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages at the rear n/s portion.



Comments/ Present Status:

Damages Consistent.

Repair days: 3 Days

Yours faithfully,

Rasul

Automotive Assessor

Shirley Hiew (LKK Auto)

From: Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>
Sent: Tuesday, 8 May 2018 1:40 PM
To: 'Catherine Chong (LKK Auto)'; 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: 'SUR'; 'assignments'
Subject: RE: GZ3779Y / TP : SKG203P/LKK / DOA : 25/04/2018
Attachments: SKG 203P - Preli Advise (ERGO).pdf

Dear Pei Li,

Enclosed herewith preliminary advice of SKG 203P.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Catherine Chong (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 2 May 2018 10:57 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: 'SUR' <sur@lkkauto.com>; 'assignments' <assignments@lkkauto.com>
Subject: RE: GZ3779Y / TP : SKG203P/LKK / DOA : 25/04/2018

Dear Pei Li,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [mailto:Survey.Report@ergo.com.sg]
Sent: Wednesday, 2 May, 2018 10:03 AM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GZ3779Y / TP : SKG203P/LKK / DOA : 25/04/2018

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **INCHCAPE - BORNEO MOTORS (S) PTE LTD**.

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 2 May, 2018 10:03 AM
To: 'admin-d@lkkauto.com'
Subject: OI: GZ3779Y / TP: SKG203P/LKK / DOA: 25/04/2018
Attachments: GZ3779Y - SAS.pdf; SKG203P - SAS.pdf; SKG203P - ESTIMATE.pdf; SKG203P - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please assist to conduct this survey from **INCHCAPE - BORNEO MOTORS (S) PTE LTD**.

ADDRESS : 2 PANDAN CRESCENT
INCHCAPE CENTRE LEVEL 4
SINGAPORE 128462

PERSON TO CONTACT : WALLY TAN @ 9847 6178 / 6631 1506

ERGO OFFICER-IN-CHARGE : SITI

Note: To survey on DIRECT SETTLEMENT basis. Please advise the consistency of damages to third party vehicle and inform the repairer in writing, that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop..

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are estimate, insured and Third Party's SAS (note: reports not to be released to any Third Party).

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Shirley Hiew (LKK Auto)

From: Rasul (LKKAuto) <Rasul@lkkauto.com>
Sent: Wednesday, 23 May 2018 5:39 PM
To: Wally Tan TCBC; Admin-D (LKKAuto)
Cc: Alvin Lee Yee Peng PTCBC
Subject: RE: Final bill and supplementary for SKG0203P

Hi Wally,

Finalised amount of \$ 4032.50 / 3 days confirmed

Best Regards,

Rasul | Assessor

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: Wally Tan TCBC [mailto:wally.tan@borneomotors.com.sg]

Sent: Wednesday, 23 May, 2018 12:35 PM

To: Rasul (LKKAuto); Admin-D (LKKAuto)

Cc: Alvin Lee Yee Peng PTCBC

Subject: RE: Final bill and supplementary for SKG0203P

Hi Rasul,

Please find attached final bill of SKG0203P for your kind perusal.

Thank you

Wally Tan TCBC

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

This e-mail (and any attachment) is intended for the addressee(s) only and contains information that is legally privileged and confidential. If you are not the intended recipient, please be advised that you have received this e-mail in error and that any use, dissemination, distribution, printing or copying of this communication is unauthorized and strictly prohibited. Kindly notify us by replying to the sender's e-mail address and delete this e-mail immediately. E-mail transmissions cannot be guaranteed to be secure or error-free as information could be intercepted, corrupted, lost, destroyed, delayed or incomplete, or could contain viruses. We therefore do not accept liability for any errors or omissions in the contents of this e-mail which arise as a result of e-mail transmission, and you are advised to carry out your own virus checks and confirm the accuracy of the contents of this e-mail before relying on it for any purpose.

ERGO

Date: 27.04.2018
Our Reference: GZ 3779Y/SA/pl
Your Reference: SKG 203P

Sent via Fax

or

Email

Siti.Nabilah@inchcape.com.sg

To: INCHCAPE - BORNEO MOTORS (S) P/L

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: SKG 203P
Insured's Vehicle: GZ 3779Y
Date Of Accident: 25.04.2018

We acknowledge receipt of your request for PRS on: 27.04.2018

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK AUTO

AIS	Automobile Inspection Services Pte Ltd	LBS	L.B.S Auto Consultants Pte Ltd
FTA	FormTeam Consultancy Pte Ltd	LKK	LKK Auto Consultants Pte Ltd
IAS	Infiniti Appraisal Service	PS	Priority Services
JPK	JP Knights Pte Ltd	VAC	Vicom Ltd

<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input type="checkbox"/>
<input checked="" type="checkbox"/>

Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.


Your request for inspection does not have your client's GIA report, kindly forward a copy.

We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.

Our Insured's driver has not reported the accident to us to date.

V

Others: We write to confirm our agreement to have a direct settlement of this claim with quantum to be agreed. OFFICER-IN-CHARGE - SITI

Prepared by:		Pei Li	6829 9194	<u>claims@ergo.com.sg</u>
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

--

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job .

Workshop Acknowledgement & Stamp.

Note: Our Inspection is on a without admission to liability basis.



TAX INVOICE

Borneo Motors (Singapore) Pte Ltd

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

www.lexus.com.sg

Lexus Bodycare Centre
No. 2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

ESTIMATE

Att: Sn & Sc, Wobility Check.

Account Detail		Account No	Customer Detail	
THIRD PARTY CLAIM		S1000020 / TPCLAIM	Mdm Tan Siew Lay	
Document No		0	767 Bedok Reservoir View	
Document Date		26/04/2018	#16-223	
			Singapore 470767	
			Mobile: 93885416	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	BEXGB	S4	15/03/2017	SKG0203P	0	15307	4TP/SKG0203P/250411
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHBW1GG202148931	2AR1660208	60	Wally Tan G H	25/04/2018	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES				80.00 net
		POLICY NO.: ACC DATE:				50
		TOW/DRIVE IN: EXCESS:				
		DATE-IN: DATE SURVEY:				
		NO OF REPAIR DAYS:				
		BY: AUTHORISED ON:				
2	B	BP-LAB REMOVE/REFIX REVERSE SENSORS. (NETT)				204.00
3	B	BP-LAB REMOVE/REPLACE REAR BUMPER				816 1020.00
		COVER AND REALIGN.				700 875.00
4	B	BP-RES SPRAY PAINT ON REAR BUMPER				
		COVER.				
5	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)				612.00
6	1	L52158-33030 SUPPORT, RR BUMPER LH	1.00	97.50		97.50
7	2	L52171-33160 REINFORCEMENT, RR	1.00	634.60		634.60
8	3	L52615-33140 ABSORBER, RR BUMPER	1.00	122.60		122.60
9	4	L52156-33010 SUPPORT, RR BUMPER LH	1.00	165.30		165.30
10	5	L52159-33951 COVER, RR BUMPER	1.00	989.00		989.00
11	6	L52463-33020 PAD RR BUMPER LH	1.00	18.30		18.30
12	7	L52162-33903 PLATE RR BUMPER	1.00	6.10		6.10
13	8	L52563-33030 RETAINER, RR BUMPER,	1.00	71.80		71.80

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 26/04/2018
TIME 08:27

VEHICLE NO SKG0203P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail	Account No	Customer Detail
THIRD PARTY CLAIM	S1000020 / TPCLAIM	Mdm Tan Siew Lay 767 Bedok Reservoir View #16-223 Singapore 470767 Mobile: 93885416
	Document No 0	
	Document Date 26/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	BEXGB	S4	15/03/2017	SKG0203P	0	15307	4TP/SKG0203P/250411
Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHBW1GG202148931	2AR1660208	60	Wally Tan G H	25/04/2018	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	9	S52161-0K040 BUMPER CLIPS	2.00	3.90		7.80
15	0	L81920-30040 REFLECTOR ASSY, LH	1.00	57.90		57.90
16	1	L89341-78010 C3 SENSOR, ULTRASONIC,	2.00	481.90		963.80
17	2	L89348-78020 RETAINER, ULTRASONIC	4.00	16.00		64.00
18	3	L89348-35030 CLIP, ULTRASONIC	4.00	3.60		14.40
19	4	L89348-50050 CLIP, ULTRASONIC	1.00	11.30		11.30

Resue
Hp 90010068
3 days
03/05/18 @ 1420

Resue by part

22/5/18

7.80
57.90
963.80
64.00
14.40
11.30

6220.40


- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total	6,015.40
	Please acknowledge receipt of vehicle	Parts 3,224.40	GST 7.00%	421.08
		Labour 2,791.00	Less	0.00
		Materials 0.00		
		Lubrication/Fluid 0.00		
		Others 0.00		
			Amount Due	6,436.48

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 26/04/2018
TIME 08:27

VEHICLE NO SKG0203P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Attn: Rasul
* Supplementary *

TAX INVOICE


Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail		Account No S1000010 / ICN13		Customer Detail				
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept		Document No 0		Mdm Tan Siew Lay 767 Bedok Reservoir view #16-223 Singapore 470767 Mobile: 93885416				
		Document Date 23/05/2018						
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks	
17	BEXGB	S4	15/03/2017	SKG0203P	0	15417	SKG0203P	
Chassis No		Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On	
JTHBW1GG202148931		2AR1660208	60	Wally Tan G H		--/--/----	0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUPPLEMENTARY T/P INS.: ERGO ACC DATE: 25.04.18 T/P VEHICLE NO.: GZ3779Y DATE-IN: 07.05.18 DATE SURVEY: 03.05.18 NO OF REPAIR DAYS: 3 DAYS BY: RASUL (LKK) *DIRECT SETTLEMENT* L52565-33030 RETAINER, RR BUMPER			1.00	155.70		155.70
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.								
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total		
		Please acknowledge receipt of vehicle		Parts		155.70		
				Labour		0.00		
				Materials		0.00		
				Lubrication/Fluid		0.00		
				Others		0.00		
				Amount Due		166.60		

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 23/05/2018
TIME 12:16

VEHICLE NO SKG0203P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



Attn: Rasul
Final Bill

TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg

Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail				Account No		Customer Detail			
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept				S1000010 / ICNI3		Mdm Tan Siew Lay 767 Bedok Reservoir View #16-223 Singapore 470767 Mobile: 93885416			
				Document No					
				0					
				Document Date					
				23/05/2018					

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
17	BEXGB	S4	15/03/2017	SKG0203P	34989	15307	4DS/SKG0203P/25041:

Chassis No	Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On
JTHBW1GG202148931	2AR1660208	60	Wally Tan G H	25/04/2018	0.00	23/05/2018 18.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES T/P INS.:ERGO ACC DATE:25.04.18 T/P VEHICLE NO.:GZ3779Y DATE-IN:07.05.18 DATE SURVEY:03.05.18 NO OF REPAIR DAYS:3 DAYS BY:RASUL (LKK) *DIRECT SETTLEMENT*				50.00
2	B	BP-LAB REMOVE/REFIX REVERSE SENSORS. (NETT)	*			204.00
3	B	BP-LAB REMOVE/REPLACE REAR BUMPER	*			816.00
4	B	BP-RES COVER AND REALIGN. SPRAY PAINT ON REAR BUMPER	*			700.00
5	B	BP-ECU TO RESET ECU AND REPROGRAMME. (NETT)	18			612.00
6	1	L52158-33030 SUPPORT,RR BUMPER LH	1.00	97.50		97.50
7	2	L52156-33010 SUPPORT,RR BUMPER LH	1.00	165.30		165.30
8	3	L52159-33951 COVER, RR BUMPER	1.00	989.00		989.00
9	4	L52463-33020 PAD RR BUMPER LH	1.00	18.30		18.30
10	5	L52162-33903 PLATE RR BUMPER	1.00	6.10		6.10
11	6	L52563-33040 RETAINER RR BUMPER	1.00	121.10		121.10
12	7	S52161-OK040 PIECE,RR BUMPER	2.00	3.90		7.80
13	8	L89348-78020 RETAINER, ULTRASONIC	4.00	16.00		64.00

Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

DATE 23/05/2018
TIME 12:11

VEHICLE NO SKG0203P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors



TAX INVOICE

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9
ESTIMATE

Borneo Motors (Singapore) Pte Ltd

www.lexus.com.sg
Lexus Bodycare Centre
No.2 Pandan Crescent
Singapore 128462
Tel no.: 6631 1388

Account Detail				Account No		Customer Detail				
Ergo Insurance Pte Ltd 5 Temasek Boulevard #04-01 Suntec Tower Five Singapore 038985 Attn: Motor Claims Dept				S1000010 / ICNI3		Mdm Tan Siew Lay 767 Bedok Reservoir View #16-223 Singapore 470767 Mobile: 93885416				
				Document No 0						
				Document Date 23/05/2018						
Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks			
17	BEXGB S4	AVV60R	15/03/2017	SKG0203P	34989	15307	4DS/SKG0203P/25041:			
Chassis No		Engine No	TWC No	Terms	Lexus Consultant	Vehicle In	Collected On			
JTHBW1GG202148931		2AR1660208	60	Wally Tan G H	25/04/2018	0.00	23/05/2018 18.00			
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount	
14	9	L89348-35030	CLIP, ULTRASONIC				4.00	3.60	14.40	
15	0	L89348-50050	CLIP, ULTRASONIC				1.00	11.30	11.30	
16	1	L52565-33030	RETAINER, RR BUMPER				1.00	155.70	155.70	
Borneo Motors is the only authorized workshop to maintain your Lexus. Service your Lexus every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.										
For & on behalf of Borneo Motors		Customer's Signature		Change Summary		Total 4,032.50				
		Please acknowledge receipt of vehicle 		Parts	1,650.50	GST 7.00%				282.28
				Labour	2,382.00	Less				0.00
				Materials	0.00					
				Lubrication/Fluid	0.00					
				Others	0.00					
						Amount Due 4,314.78				

PLEASE TEAR ALONG PERFORATED LINE

TO SECURITY GUARD

DATE 23/05/2018
TIME 12:11

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.

VEHICLE NO SKG0203P

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD



Borneo Motors




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ERGO INSURANCE PTE LTD			Ref : CS/EGI18007976/R1s3bn2	
5 TEMASEK BOULEVARD #04-01 SUNTEC TOWER FIVE SINGAPORE 038985			Date : 30-05-2018	
			Code : EGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GZ 3779Y	Veh. Inspected	SKG 203P	
Policy No.		Coverage (\$)	0.00	
Claim No.	GZ3779Y/SA/pl	Excess (\$)	0.00	
Assign From	YEE PEI LI	Assign Date	02/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA LEXUS ES300H	c.c	2494	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	JTHBW1GG202148931	Colour	BLACK	
Odometer	34720	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Front Tyre	215/55 R17	YOKOHAMA	6 mm	
R/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
L/H Rear Tyre	215/55 R17	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	25/04/2018	Inspection Date	03/05/2018	
Survey held at	BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKG 203P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	SUNDRIES (SN)	NECESSARY	80.00	50.00
1	SUPPORT,RR BUMPER LH (SN)	NECESSARY	97.50	97.50
1	REINFORCEMENT,RR (SN)	SERVICEABLE	634.60	-
1	ABSORBER,RR BUMPER (SN)	SERVICEABLE	122.60	-
1	SUPPORT,RR BUMPER LH (SN)	NECESSARY	165.30	165.30
1	COVER,RR BUMPER (SN)	DEFORMED	989.00	989.00
1	PAD RR BUMPER LH (SN)	NECESSARY	18.30	18.30
1	PLATE RR BUMPER (SN)	NECESSARY	6.10	6.10
1	RETAINER,RR BUMPER (SN)	NECESSARY	121.10	121.10
2	BUMPER CLIPS (SN)	NECESSARY	7.80	7.80
1	REFLECTOR ASSY,LH (SN)	SERVICEABLE	57.90	-
2	SENSOR,ULTRASONIC (SN)	SERVICEABLE	963.80	-
4	RETAINER,ULTRASONIC (SN)	NECESSARY	64.00	64.00
4	CLIP,ULTRASONIC (SN)	NECESSARY	14.40	14.40
1	CLIP,ULTRASONIC (SN)	NECESSARY	11.30	11.30
1	RETAINER,RR BUMPER (ADDITIONAL)(SN)	DEFORMED	155.70	155.70
			3,509.40	1,700.50
LABOUR				
REMOVE/REFIX REVERSE SENSORS.			204.00	204.00
REMOVE/REPLACE REAR BUMPER COVER AND REALIGN.			1,020.00	816.00
SPRAY PAINT ON REAR BUMPER COVER.			875.00	700.00
TO RESET ECU AND REPROGRAMME.			612.00	612.00
			2,711.00	2,332.00
GRAND TOTAL			6,220.40	4,032.50
RECOMMENDED COST OF REPAIRS				4,032.50

Report Ref No. CS/EGI18007976/R1s3bn2

MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.