

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 7349Z

DATE 30/4/2018

MAKE :

MODEL : HYUNDAI i40

EQ Ins

TS

LKK - Kalvin

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper <i>X Apr</i>			\$ 603.60	
	Rear Bumper Reinforcement <i>?</i>			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH) <i>?</i>		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket <i>?</i>			\$ 49.00	
	Rear Bumper Clips <i>X</i>			\$ 22.00	
	Rear Bumper Sponge <i>?</i>			\$ 143.40	
	Rear Bumper Under Cover <i>X</i>			\$ 225.00	
	SUB TOTAL			\$ 1,907.35	
	LESS 20%			\$ 381.47	
	DISCOUNTED TOTAL			\$ 1,525.88	
	Rear Bumper Reverse Sensor <i>X</i>			\$ 135.70	Nett
	Rear Bumper Rubber Mat <i>—</i>			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge				
	Panel Beating			\$ 280.00	<i>100</i>
	Spray Painting Charge			\$ 200.00	<i>CP</i>
	Wiring Charge			\$ 50.00	<i>X</i>
	R/Refix Reverse Sensor			\$ 120.00	<i>CP</i>
	TOTAL LABOUR			\$ 650.00	
	ESTIMATE TOTAL			\$ 2,361.58	
<i>Kalvin (1/1/14)</i> <i>30/4/18 1035h</i> <i>2 Rg</i> <i>4s</i> <i>After Rr p H</i>					
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal motor insurance allowed - Supplementary claims must be resurveyed and is subject to final approval by insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					