

INS. CASE OWNER:

CC 6/CTI1800

7986, Keb3 91

LKK:

IDAC:

Surveyor:

Fenneth

DOI:

ASSIGNMENT

70/4/18

Date / Time:

30/6/18

Registered in Merimen:

Pre-assign / CCU / FTE

GY 3554J



Insured Vehicle No.:

Claim No.:

SN M1800794007

Name of Insured:

PYLON ELECTRICAL ENGINEERING

Policy No.:

OMLWSN 1613881802

Insured Tel No.:

HP:

Make / Model:

NISSAN

Excess Sec II :SS

D.O.A.:

70/4/18

Place of Accident:

JUNE EUNOS ARE 5 & EUNOS RD 3

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

TAN HEN HOF

OI GIA REPORT: ☒ YES / NO ; TP GIA REPORT: ☒ YES / NO

Driver Tel No.:

(V/L: ☒ YES / NO)

Insured Liability:

%

Final? Yes / No

SJH 6497A



INSRS:

WSP:

Tel:

Liability:

RMKS:

wei
leo

INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

7/5/18

Waher

GY 3554J 2 km/16/180794/18 70/4/18
SJH 6497A 3

FILE REVIEW: LIABILITY PENDING.

PENDING TP EVIDENCE.

18.7.18

CLAIMANT PROCEED LEGAL CLAIM

19.7.18

MEOM CTI TP PREP WORKER, WE WILL SUBMIT WP REPORT.

RECEIVED 23 JUL 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

G:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

50

(Agreed / Assessed) BOLA S/N No.:

NIL

If NO or B 28, Ass. Lia:

Repair Cost:

SS

CONFIRMING VERSION.

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

(Tick only one)

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/Independent)

Legal Cost

SS

1) Claim status: Normal/Reject/Private Settle / WP

2) Report Format:

TP

3) Survey fee:

350

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

COPY SENT
M/7/18



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD			Ref : CC6/CTI18007986/Keb3	
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Date : 02-05-2018	
			Code : CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 3554J		Veh. Inspected	SJH 6497A
Policy No.			Coverage (\$)	0.00
Claim No.			Excess (\$)	0.00
Assign From			Assign Date	02/05/2018
2. Vehicle Particulars & Condition				
Make & Model			c.c	0
Engine No.	HIDDEN		Year of Reg.	
Chassis No.			Colour	
Odometer	-		Steering	
Brakes			Modification	
General				
3. Conditions of Tyres				
	Size		Make	Balance
R/H Front Tyre				mm
L/H Front Tyre				mm
R/H Rear Tyre				mm
L/H Rear Tyre				mm
4. Description of Damages				
5. General Information				
Accident Date	26/04/2018		Inspection Date	30/04/2018
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: To Be Advised
Our ref: CC6/CTI18007986/Keb3

Date: 02.05.2018

The Motor Claims Department
M/s CHINA TAIPING INSURANCE (S) PTE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO.

SJH6497A

We refer to the above matter.

Please be informed that we had conducted the inspection of the above mentioned vehicle on 30.04.2018 at the premises of M/s Wei Lee Motor Works and have the following to report:-

Workshop Estimate Amount	: S\$	7,483.93
Revised Estimate Amount	: S\$	3,791.60
"Check" Items Amount	: S\$	1,770.84
Market Value	: S\$	-
LTA Reimbursement Value	: S\$	-
Nett Value	: S\$	-

Description of Damage:

The vehicle sustained damages at the
N/S Front portion



Comments/Present Status:

Damages Consistent

Estimated normal period for repairs: 5 days

Yours faithfully,

KENNETH KONG
Licensed Appraiser

威利摩多 KE WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~456 3986~~ 6450 0128
Business Regn No : 269436/00J

we take photo

27, Apr 2018

China Taiping Insurance (S) PL
36 Robinson Road
#16-01 City House
S 068877

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle No; GY3554J
Accident involving vehicle No: SJH6497A/GY3554J
DOA: 26/04/2018 AT Eunus Ave 5

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SJH6497A

To supply

Not Authorised
L1 Sup 82900h
Penny After Paint
5 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplement(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Description	Qty	Amount
Front fender	1	Rh 689.90 N ✓
Fender lamp	1	Rh 47.00 N ✓
Fender cowl	1	cm 77.10 N ✓
Cowling clip		rh 42.00 N ✓
Front bumper	1	Rh 479.60 N ✓
Bumper retainer @22.10	2	rh 44.40 N ✓
Front bumper lower skirt	1	Bumper 322.00 N ✓
Grille @106	2	rh 212.00 N ✓
Headlamp	1	cm 344.30 N ✓
Tyre rim	1	Rh 220.00 N ✓
Tyre	1	Rh 180.00 N 30d
Front door	1	Rh 1,123.80 N X
Lower arm	1	rh 181.30 N ✓
Nuckle arm	1	rh 376.80 N ✓
Drive shaft	1	Rh 867.50 N ✓
Absorber, Rh	1	rh 330.00 N ✓
	Parts	5,537.70
	Parts less 10%	553.77
		4,983.93

To transfer door glass, power window mechanism and all attachments to new door

160.00 X

To remove damaged parts and attachments.

Cur n weld damaged panel.

Repair/reshape dented areas.

Straighten front Lh pillar.

Replace/align all parts into position.

900.00 5401

To repair undercarriage, replace parts

300.00 1601

To spray paint

1,000.00 8001

Redo computerize wheel alignment

60.00 ✓

Tow fee

80.00 501

7,483.93

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.

TEL: 456 9830 • FAX: ~~456 3086~~ 6458 0128
Business Regn No : 269436/00J

27, Apr 2018

China Taiping Insurance (S) PL
36 Robinson Road
#16-01 City House
S 068877

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle No; GY3554J
Accident involving vehicle No: SJH6497A/GY3554J
DOA: 26/04/2018 AT Eunus Ave 5

Dear officer incharge

Re: Estimate cost of repair for vehicle No: SJH6497A

To supply

Not Authorised
L1 Sup 87
Pursuing After Paint
5 days

Description	Qty	Amount
Front fender	1	689.90 N ✓
Fender lamp	1	47.00 N —
Fender cowl	1	77.10 N —
Cowling clip		42.00 N —
Front bumper	1	479.60 N —
Bumper retainer @22.10	2	44.40 N Lt
Front bumper lower skirt	1	322.00 N —
Grille @106	2	212.00 N ?
Headlamp	1	344.30 N —
Tyre rim	1	220.00 N —
Tyre	1	180.00 N —
Front door	1	1,123.80 N X
Lower arm	1	181.30 N ?
Nuckle arm	1	376.80 N ?
Drive shaft	1	867.50 N ?
Absorber, Rh	1	330.00 N ?
	Parts	5,537.70
	Parts less 10%	553.77
		4,983.93

LiK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

To transfer door glass, power window mechanism and all attachments to new door

na 160.00 X

To remove damaged parts and attachments.

Cur n weld damaged panel.

Repair/reshape dented areas.

Straighten front Lh pillar.

Replace/align all parts into position.

To repair undercarriage, replace parts

To spray paint

Redo computerize wheel alignment

Tow fee

900.00 5401
300.00 1601
1,000.00 8001
60.00 ✓
800.00 501

7,183.93

Shu Pei (LKKAUTO)

From: Lucas Lee <lucas.lee@sg.cntaiping.com>
Sent: Thursday, 3 May 2018 3:03 PM
To: Shu Pei (LKKAUTO)
Subject: RE: Direct Settlement - Accident Involving GY3554J (OI : CTI - SNM18D02194C02) and SJH6497A (TP : LKK REF - CC6/CTI18007986/Keb3) on 26.04.2018
Attachments: leeSZ_SNM18D02194C02-GY3554J-LKKDirectSettlementAccidentLtr_CLCR95.178.pdf; MNA118055746-GY3554J.pdf

Dear Sirs,

Kindly refer to the above attachment.

Case Handler: Chong Boon Sen

Lucas Lee

Claims Department (Motor)
China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road #16-00 Springleaf Tower Singapore 079909
Direct (65) 6389 6181
Fax (65) 6222 7175
Email: lucas.lee@sg.cntaiping.com
Website: www.sg.cntaiping.com



Disclaimer :

This message is confidential; its contents do not constitute a commitment by China Taiping Insurance (Singapore) Pte. Ltd. except where provided for in a written agreement between you and China Taiping Insurance (Singapore) Pte. Ltd. Any unauthorized disclosure, use or dissemination, either in whole or partial, is prohibited. If you are not the intended recipient of the message, please notify the sender immediately.

From: Shu Pei (LKKAUTO) [mailto:shupeil@lkkauto.com]
Sent: Wednesday, 2 May, 2018 6:23 PM
To: Claims Dept of CTI
Cc: Chong Boon Sen; Lucas Lee; Admin A; Asher Sng (LKKAUTO)
Subject: Direct Settlement - Accident Involving GY3554J (OI : CTI - TBA) and SJH6497A (TP : LKK REF - CC6/CTI18007986/Keb3) on 26.04.2018

WITHOUT PREJUDICE

Dear Boon Sen,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SJH 6497A at M/s Wei Lee Motor Works.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Our case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



中国太平
CHINA TAIPING

中国太平保险(新加坡)有限公司
CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD

3 Anson Road #16-00 Springleaf Tower Singapore 079909
Tel: 6389 6111 Fax: 6222 1033
Website: www.sg.ctaiping.com
Co. Reg. No. 200208384E

Our Reference: **SNM18D02194/C02/7**

Date : **03 MAY 2018**

via Ordinary & Registered Mail

**PYLON ELECTRICAL ENGINEERING
3013 BEDOK INDUSTRIAL PARK E
#02-2120
SINGAPORE 489979**

Dear Sir / Madam

**ACCIDENT INVOLVING GY3554J AND SJH6497A ON 26 APRIL 2018
ALONG JUNCTION OF EUNOS AVE 5 & EUNOS ROAD 3**

We refer to the abovementioned accident.

Please be advised that the third party vehicle, **SJH6497A** , is filing a third party property claim against your vehicle.

We have appointed **LKK Auto Consultants Pte Ltd**, to administer the said claim on our behalf and they will contact you for more information about the accident.

Kindly render your assistance and co-operation accordingly.

Yours truly,
Claims Department

(This is a computer generated letter and no signature is required.)

CC : LKK Auto Consultants Pte Ltd

Attn : ASHER
Ref : CC6/CT18007986/KEB3
Contact No : 68416051
via Email : ASHER@LKKAUTO.COM

CC : Agent - (AN0335A) - AIK CHONG INSURANCE AGENCY PTE LTD

F01/LKKDS-2013

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Thursday, 19 July 2018 11:18 AM
To: Shu Pei (LKKAUTO); Claims Dept of CTI
Cc: Chong Boon Sen; Lucas Lee; Admin A
Subject: RE: Direct Settlement - Accident Involving GY3554J (OI : CTI - TBA) and SJH6497A (TP : LKK REF - CC6/CTI18007986/Keb3) on 26.04.2018
Attachments: SJH6497A

Hi Boon Sen,

We refer to the above matter.

We were informed by TP workshop that claimant have decided to proceed legal claims.

In view of the above, We will proceed to close file and submit our without prejudice report to your office

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shu Pei (LKKAUTO)

Sent: Wednesday, 2 May 2018 6:23 PM

To: Claims Dept of CTI <claimsdept@sg.cntaiping.com>

Cc: Chong Boon Sen <boonsen.chong@sg.cntaiping.com>; Lucas Lee <lucas.lee@sg.cntaiping.com>; Admin A <admin-a@lkkauto.com>; Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>

Subject: Direct Settlement - Accident Involving GY3554J (OI : CTI - TBA) and SJH6497A (TP : LKK REF - CC6/CTI18007986/Keb3) on 26.04.2018

WITHOUT PREJUDICE

Dear Boon Sen,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SJH 6497A at M/s Wei Lee Motor Works.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Enclosed for your perusal is:

- Estimated cost of repair
- Preliminary advice
- TP GIA report

Our case handler in-charge is Asher and she can be contacted at DID: 6841 6051.

Thank You.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD		Ref : CC6/CTI18007986/Keb3q2		
3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909		Date : 24-07-2018		
		Code : CTI		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GY 3554J	Veh. Inspected	SJH 6497A	
Policy No.	DMCVSN1613881802	Coverage (\$)	0.00	
Claim No.	SNM18D02194/C02/7	Excess (\$)	0.00	
Assign From		Assign Date	30/04/2018	
2. Vehicle Particulars & Condition				
Make & Model	NISSAN LATIO (A)	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	JN1BAAC11Z0004516	Colour	METALLIC GOLD	
Odometer	134599	Steering	JAMMED	
Brakes	JAMMED	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/55 R15	TOYO	3 mm	
L/H Front Tyre	195/55 R15	TOYO	3 mm	
R/H Rear Tyre	195/55 R15	TOYO	1 mm	
L/H Rear Tyre	195/55 R15	TOYO	1 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	26/04/2018	Inspection Date	30/04/2018	
Survey held at	WEI LEE MOTOR WORKS BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 SINGAPORE 575644.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJH 6497A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRONT FENDER (N)	BENT	689.90	689.90
1	FENDER LAMP (N)	BROKEN	47.00	47.00
1	FENDER COWLING (N)	CRACKED	77.10	77.10
1	COWLING CLIP (N)	NECESSARY	42.00	42.00
1	FRONT BUMPER (N)	BENT	479.60	479.60
2	BUMPER RETAINER @\$22.10 (N)	N/S DISTORTED	44.40	22.10
1	FRONT BUMPER LOWER SKIRT (N)	BROKEN/ DENTED	322.00	322.00
2	GRILLE @\$106.00 (N)	SERVICEABLE	212.00	-
1	HEADLAMP (N)	CRACKED	344.30	344.30
1	TYRE RIM (N)	DENTED	220.00	220.00
1	FRONT DOOR (N)	TO REPAIR SEE LABOUR	1,123.80	-
1	LOWER ARM (N)	SERVICEABLE	181.30	-
1	NUCKLE ARM (N)	SERVICEABLE	376.80	-
1	DRIVE SHAFT (N)	TO REPAIR SEE LABOUR	867.50	-
1	ABSORBER ,RH (N)	SERVICEABLE	330.00	-
	LESS 10% DISCOUNT		-535.77	-224.40
			4,821.93	2,019.60
1	TYRE (30%) (SN)	PUNCTURE	180.00	54.00
	LESS 10% DISCOUNT		-18.00	-
			162.00	54.00
LABOUR				
	TO TRANSFER DOOR GLASS ,POWER WINDOW MECHANISM AND ALL ATTACHMENTS TO NEW DOOR.	NOT NECESSARY	160.00	-
	TO REMOVE DAMAGED PARTS AND ATTACHMENTS.CUT N WELD DAMAGED PANEL REPAIR/RESHAPE DENTED AREAS.STRAIGHTEN FRONT LH PILLAR.REPLACE /ALIGN ALL PARTS INTO POSITION.INCLUSIVE OF THE REPAIR OF FRONT DOOR AND DRIVE SHAFT .		900.00	540.00
	TO REPAIR UNDERCARRIAGE ,REPLACE PARTS .		300.00	160.00

Report Ref No. CC6/CT118007986/Keb3q2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO SPRAY PAINT.		1,000.00	800.00
	REDO COMPUTERIZE WHEEL ALIGNMENT.		60.00	60.00
	TOWING FEE.		80.00	50.00
			2,500.00	1,610.00
GRAND TOTAL			7,483.93	3,683.60

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				2,900.00
---	--	--	--	----------

Report Ref No. CC6/CTI18007986/Keb3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.