

22/03/2002

AS REC. BY:

REF: CG/CTU 800 7988 / m/6622

Special Instruction:

SUIVADJ

ASSIGNMENT (Office)

From (Person): Elaine Cheong of CTL Date/Time: 02/05/2018 1:15pm

Estimated Cost: Bill to:

OD / TW / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SHH 1645H Insured: SLA 535B

at Workshop m/s Cycle & Carriage Tel: 9186 5109

of 188 Pandan Loop

Policy No: DM PCSN 3001681800 Claim No: SNM18D 02219C 02

Sum Insured: Excess:

Make of Veh: D.O.A. 26/04/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS w/p 14/05/2018

H.O.D. Endorsement:

Date/Time: 02/05/2018 229pm Person Contacted: Yik Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHH 1645H - X
	SLA 535B - X

REF: 077

ASSIGNMENT

From: Date: 14052018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SRH 1645H Yr Regn: FEB 2012
Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or

Make: MTRC 2200 C.C. 1796

Colour: BROWN A/C: Insured / Std / NI / NA

Sp. Reading: 66725 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WND2D0482A526253

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 245/40/17R
R: 265/35/17R

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 8 mm R/Bal. 8 mm

L/Bal. 8 mm L/Bal. 8 mm

D.O.A. 26/04/2018 D.O.I. 14/5/2018

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

(\$1,529.48 Red - 10%)

P/P \$14,505.43 / 5 days

3/7/2018

RECEIVED 04 JUL 2018

Date/Time, File Pass to?

04/07/18

1) - 5p.5t

Date/Time, File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

Report Format :

Lump Sum / I.B.F. : P/P \$14,505.43

220

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		02 May 2018 13:15 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

Show All

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	LEE GEOK POH, ID: S7177755C		
Main Claimant:	LAU JIN LOONG, ID: S8242712J		
Vehicle Reg. No.:	SGH1645H	Date of Loss:	26/04/2018 16:00 - :59
Claim Type:	TP / SNM18D02219C02	Policy/Cover Note No.:	DMPCSN3001681800 (Comprehensive)
Vehicle Reg. No. (Insured):	SLA535B	Policy No. (Claimant):	5099559800
		Excess:	S\$0.00
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/05/2018]		
Driver/Custodian (Insured):	NG LUO WEI (22 / Female), NRIC: S9670377E, Tel: +6596260270		
Adj Asg. Remarks:	EST \$12,979.75, CASE WITH SJE.		

ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/04/2018 03:39
Date Of Accident	26/04/2018 16:40
Exact Location Of Accident	BKE(WDLD) BEF TURF CLUB EXIT LANE 3
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGH1645H
Insured/Policyholder	
Name Of Registered Owner	LAU JIN LOONG
NRIC No	S8242712J
Email Address	MIKKILAU1982@GMAIL.COM
Mobile Phone No	(LOCAL) +65-90227500
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	MERCEDES-BENZ
Model	E200-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5099559800
Cover Note Number	

Driver

Name of Driver	LAU JIN LOONG
NRIC No	S8242712J
Date Of Birth	15/12/1982
Occupation	INDOOR
Date Of Driving Pass	11/08/2006
Driving Experience	11 YEARS AND 8 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-90227500
Fax Number	
Contact Number	OFFICE-NOPHONE
EMail Address	MIKKILAU1982@GMAIL.COM

Address	BLK 571B #09-910 WOODLANDS AVENUE 1
Postcode	732571
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO SKETCH PLAN

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLA535B
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	NG LUO WEI
NRIC/Passport Number	S9670377E
Contact Number	96260270
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 26/01/18 17:10ms

Driver's Signature

(If driver is not the policyholder)

Date & Time:


Reporting Centre Personnel's Signature

Name: Perry Ng

NRIC/FIN No: 51431533B

Sketch Plan #2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

Temp. was rising and slow rising. My vehicle was stationary
when (SWASSG) walked onto my ramp.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature _____
Date & Time: 26/04/18

Driver's Signature _____
(If driver is not the policyholder)
Date & Time: _____

Reporting Centre Personnel's Signature
Name: Hong
NRIC/FIN No.: 84-315838

THE SCHEDULE

osit Insurance
formation on t
ontact your ins

Private Car Insurance Policy

This Policy sets out the terms of a contract between NTUC Income Insurance Co-operative Limited (INCOME) and you (the policyholder named in the schedule to this Policy).

The statements, information and declaration provided by you at the time of proposal shall form the basis of this contract. We (INCOME) will provide the insurance set out in this Policy in respect of events occurring during the Period of Insurance shown in the Schedule and any further period for which we may accept a renewal premium.

The provision of this insurance is subject to:

1. any Endorsement specified as operative in the Schedule
2. the Conditions and General Exclusions of this Policy, and
3. the payment of the premium specified in the Schedule.

This Policy, the Schedule and the Certificate of Insurance are to be read together as one document.

GST Reg No. M4-0003030-8

Policy Number	: 5099559800
The Policyholder	: LAU JIN LOONG BLK 571B #09-910 WOODLANDS AVENUE 1 SINGAPORE 732571

Period of Insurance	: 05 Apr 2018 To 31 Jan 2019
Sum Insured	: Market Value of Insured Vehicle at Time of Loss
Premium (inclusive GST)	: S\$1,018.75

Interest Insured

Cover Type	: drive PREMIUM		
Primary Driver	: LAU JIN LOONG (LIU JINLONG)		
Named Driver (1)	: ALYSSA TAY KAI SI		
Named Driver (2)	: N/A		
Make/Model	: MERCEDES BENZ/E200	Capacity	: 1800cc
Registration Number	: SLU1348M	Registration Year	: 2012
Chassis Number	: WDD2120482A536253	Off-peak Car	: No
Repair at Owner's Preferred Workshop	: Yes	Insure with COE	: Yes
Excess (Section 1)	: N/A	NCD Entitlement	: 50%
Excess (Section 2)	: N/A	NCD Protection	: Yes
Windscreen Excess	: S\$100	Loyalty Discount	: 5%
Additional Excess	: N/A		
Unnamed Driver Excess	: Please refer to Terms and Conditions		
Hire Purchase Company	: UNITED OVERSEAS BANK LIMITED		

Optional Cover

Transport Allowance	: No
Excess Waiver	: Yes

Memo A : N/A

Endorsement Operative : M4, M7, M8

Agency	: ALFA CREDIT PTE LTD (00000613905)
Date of Issue	: 05 Apr 2018 10:17 hrs

DUTY OF DISCLOSURE

We would remind you that you must disclose to us, fully and faithfully, the facts you know or ought to know, otherwise you may not receive any benefit from your Policy.

Signed in Singapore by order of the Board of Directors



Chief Executive

REPUBLIC OF SINGAPORE **DRIVING LICENCE**

Licence Number: **S 8242712J**
Name: **LAU JIN LOONG**
(LIU JINLONG)

Birth Date: **15 Dec 1982**
Issue Date: **11 Aug 2006**



 001438185J

FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES):

PASS DATE

Class 3 Motor Cars= \leq 3000kg with \leq 7 passengers, exclusive of the driver; and other motor vehicles \leq 2500kg 11 Aug 2006

FOR C&C USE ONLY

NP 428A

 Licence No: S8242712J



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGH1645H*RA

Mr Lau

Blk 571B Woodlands Avenue 1
#09-910
Singapore 732571

Mobile: 90227500

Vehicle & Document Information

WIP No **23270**
Reg No/Reg Date **SGH1645H*RA / 01/02/2012**
Date In/Mileage **/ 0**
Chassis No **WDD2120482A536253**
Engine No **27186030369411**
Make/Model **MB/E 200 CGI SEDAN (W212)**
Colour/Trim **024 497 Cuprite Bro/ 042 201 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	30/04/2018/ 15:42	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE : 5099559800 // 26/04/2018 DRIVE IN/EXCESS : 27/04/2018 // TP VEH NO SLA535B CHINA TAIPING DATE IN/DATE SURVEY: BY/AUTHORIZED ON :				1920.00 2280.00
A BPILAB PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.				1200.00
A BPIRES RESPRAY BOOT LID AND REAR BUMPER				1800.00
A BPILAB USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.			0.10	380.00
A BPILAB CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT				120.00
M REAR CROSS MEMBER	1.00	789.45	00.00	789.45
M RIGHT REAR BUMPER BOTTOM BRACKET	1.00	16.18	00.00	16.18
M LEFT REAR BUMPER BOTTOM BRACKET	1.00	16.18	00.00	16.18
M REAR PARKTRONIC SENSOR SPACER RING	4.00	6.93	00.00	27.72
M REAR PARKING SENDER UNIT	4.00	273.79	00.00	1095.16
M CENTRAL REAR BUMPER GARNISH MOULDING	1.00	172.55	00.00	172.55
M RIGHT REAR BUMPER GARNISH MOULDING	1.00	128.17	00.00	128.17
M LEFT REAR BUMPER GARNISH MOULDING	1.00	128.17	00.00	128.17
M REAR BUMPER	1.00	1602.72	00.00	1602.72
M RUBBER STOPPER	2.00	9.41	00.00	18.82
M BOOT LID TYPE DESIGNATION EMBLEM	1.00	75.34	00.00	75.34
M BOOT LID E200 EMBLEM	1.00	75.34	00.00	75.34
M BOOT LID CHROME MOULDING	1.00	113.13	00.00	113.13
M MB STAR GROMMET	3.00	2.23	00.00	6.69
M BOOT LID MERCEDES STAR	1.00	46.63	00.00	46.63
M BOOT LID WEATHERSTRIP	1.00	175.69	00.00	175.69
M BOOT LID HANDLE MOLDING	1.00	232.97	00.00	232.97

Confirmed & accepted by

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
BID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: shanhoe.yik@cyclecarriage.com.sg

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGH1645H*RA

Mr Lau

Blk 571B Woodlands Avenue 1
#09-910
Singapore 732571

Mobile: 90227500

Vehicle & Document Information

WIP No **23270**
Reg No/Reg Date **SGH1645H*RA / 01/02/2012**
Date In/Mileage **/ 0**
Chassis No **WDD2120482A536253**
Engine No **27186030369411**
Make/Model **MB/E 200 CGI SEDAN (W212)**
Colour/Trim **024 497 Cuprite Bro/ 042 201 Black**

Account No	Terms	Date/Time Printed	CSE	Operator
CSM00128	Cash	30/04/2018/ 15:42	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BOOT LID	1.00	2709.70	00.00	2709.70 DP

THIS IS NOT AN OFFICIAL TAX INVOICE

ESTIMATE

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Not Authorised
PP Repw.
Before Joint Photo
Lok Auto (WIP)
14/5/2018
S.W. day 1

3/7/2018

16 034.91

Confirmed & accepted by

	Nett	12,130.61
7% GST on	12130.61	849.14
Total Payable		12,979.75

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

SUPPLEMENTARY

ESTIMATE FOR SGH1645H*RA

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 23270
Reg No/Reg Date SGH1645H*RA / 01/02/2012
Date In/Mileage 16/05/2018/ 66725
Chassis No WDD2120482A536253
Engine No 27186030369411
Make/Model MB/E 200 CGI SEDAN (W212)
Colour/Trim 024 497 Cuprite Bro/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	28/05/2018/ 13:28	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
---------------------------------	-----	------------	-------	--------

M BPNSUN
POLICY NO/ACC DATE : 35099559800 // 26/04/2018
DRIVE IN/EXCESS : 27/04/2018 // TP VEH NO SEA538B CHINA TAIPING
DATE IN/DATE SURVEY: 14/05/2018 @ 1315 // BEH LKK
BY/AUTHORIZED ON : DIRECT SETTLEMENT // ALFRED CHINA TAIPING

A BPILAB				1440.00
ADDITIONAL LABOUR TO REPAIR REAR END PANEL				
A BPIRES				600.00
ADDITIONAL LABOUR TO RESPRAY REAR END PANEL				
A BPILAB				480.00
ADDITIONAL LABOR TO REMOVE AND REFIT REAR UPHOLSTERY TRIMS GARNISHES AND SEATS FOR NEC. REPAIRS.				
X RIVETED NUT	4.00	3.66	00.00	NEC 14.64 ✓
X PLUG	3.00	0.92	00.00	NEC 2.76 ✓
X LEFT TAIL LAMP	1.00	611.59	00.00	SCR 611.59 ✓
M TS TWO-COMPONENT ADHESIVE	1.00	755.31	00.00	NEC 755.31 ✓

ESTIMATE

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

7% GST on **Nett** 3,904.30
3904.30 273.30

Authorized signatory and company stamp

Total Payable 4,177.60

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGH1645H*RA

Finalization

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information

WIP No 23270
Reg No/Reg Date SGH1645H*RA / 01/02/2012
Date In/Mileage 16/05/2018/ 66725
Chassis No WDD21204822536253
Engine No 27186030369411
Make/Model MB/E 200 CGI SEDAN (W212)
Colour/Trim 024 497 Cuprite Bro/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	28/05/2018/ 13:27	YK	395 / Yik Chan Hoe
Description of Goods / Services				Attn: Unit Price Qty % Amount

M. BPNSUN POLICY NO/ACC DATE : 5099559800 // 26/04/2018 DRIVE IN/EXCESS : 27/04/2018 // TP VEH NO SBA638B CHINA TAIPING DATE IN/DATE SURVEY: 14/05/2018 @ 1315 // BEH LKK BY/AUTHORIZED ON : DIRECT SETTLEMENT // ALFRED CHINA TAIPING				
A BPILAB	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH.			1920.00
A BPIRES	RESPRAY BOOT LID AND REAR BUMPER			1200.00
A BPILAB	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS.		0.10	380.00
A BPILAB	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE.NETT			120.00
A BPILAB	ADDITIONAL LABOUR TO REPAIR REAR END PANEL			1440.00 (A)
A BPIRES	ADDITIONAL LABOUR TO RESPRAY REAR END PANEL			600.00
A BPILAB	ADDITIONAL LABOR TO REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHES AND SEATS FOR NEC. REPAIRS.			480.00
X	REAR CROSS MEMBER	1.00	789.45 00.00	789.45
X	RIGHT REAR BUMPER BOTTOM BRACKET	1.00	16.18 00.00	16.18
X	LEFT REAR BUMPER BOTTOM BRACKET	1.00	16.18 00.00	16.18
X	REAR PARKTRONIC SENSOR SPACER RING	4.00	6.93 00.00	27.72
X	REAR PARKING SENDER UNIT	3.00	273.79 00.00	821.37
X	CENTRAL REAR BUMPER GARNISH MOULDING	1.00	172.55 00.00	172.55
X	RIGHT REAR BUMPER GARNISH MOULDING	1.00	128.17 00.00	128.17
X	LEFT REAR BUMPER GARNISH MOULDING	1.00	128.17 00.00	128.17
X	REAR BUMPER	1.00	1602.72 00.00	1602.72
X	RUBBER STOPPER	2.00	9.41 00.00	18.82

Confirmed & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SGH1645H*RA

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 23270
Reg No/Reg Date SGH1645H*RA / 01/02/2012
Date In/Mileage 16/05/2018/ 86725
Chassis No WDD21204824536253
Engine No 27186030369411
Make/Model MB/E 200 CGI SEDAN (W212)
Colour/Trim 024 497 Cuprite Bro/ 042 201 Black

Account No	Terms	Date/Time Printed	CSE	Operator
WC000668	Credit	28/05/2018/ 13:27	YK	395 / Yik Chan Hoe

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
X BOOT LID TYPE DESIGNATION EMBLEM	1.00	75.34	00.00	75.34
X BOOT LID E200 EMBLEM	1.00	75.34	00.00	75.34
X MOLDING	1.00	113.13	00.00	113.13
X MB STAR GROMMET	3.00	2.23	00.00	6.69
X BOOT LID MERCEDES STAR	1.00	46.63	00.00	46.63
X BOOT LID HANDLE MOLDING	1.00	232.97	00.00	232.97
X BOOT LID	1.00	2709.70	00.00	2709.70
X RIVETED NUT	4.00	3.66	00.00	14.64
X PLUG	3.00	0.92	00.00	2.76
X LEFT TAIL LAMP	1.00	611.59	00.00	611.59
M TS TWO-COMPONENT ADHESIVE	1.00	755.31	00.00	755.31

THIS IS NOT AN OFFICIAL TAX INVOICE
ESTIMATE

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6774 4353 HP: 9186 5109 Fax: 6872 1272
Email: chankoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 14,505.43
7% GST on 14505.43 1015.38

Authorized signatory and company stamp

Total Payable 15,520.81

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2018		02 May 2018 13:15 Edit Adj Rpt	S\$14,505.43 Edit Estimates	S\$14,505.43 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	LEE GEOK POH , ID: S7177755C								
Main Claimant:	LAU JIN LOONG , ID: S8242712J								
Vehicle Reg. No.:	SGH1645H	Date of Loss:	26/04/2018 16:00 - :59 [74 Months and 25 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02219C02	Policy/Cover Note No.:	DMPCSN3001681800 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLA535B	Policy No. (Claimant):	5099559800						
		Excess:	S\$0.00						
Repairer:	Cycle & Carriage Industries Pte Ltd (Pandan Loop) 188 Pandan Loop, 128378 West Coast - Tel: 91865300								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 11/05/2018]								
Driver/Custodian (Insured):	NG LUO WEI (22 / Female), NRIC: S9670377E, Tel: +6596260270								
Adj Asg. Remarks:	EST \$12,979.75 , CASE WITH SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGH1645H (SNM18D02219C02)**
[SLA535B]




























TP

LAU JIN LOONG

Apr 26 2018 4:00PM



[LEE GEOK POH]

Cycle & Carriage Industries Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View View in Browser	
Assessment Reports							1 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print			
1	27/04/18 03:52	Accident Statement			Load HTM			
Photos/Images							3 per page	<input checked="" type="checkbox"/>
No	Finalized On	NTUC Income Insurance Co-operative Ltd (HQ)		Thumbnail	Print			
1	27/04/18 03:47	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
2	27/04/18 03:47	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
3	27/04/18 03:47	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
4	27/04/18 03:47	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
5	27/04/18 03:47	Accident Photo [Linked Accident Report Documents]			Load JPG		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print			
1	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
2	08/06/18 12:08	Odometer Reading			Load JPG		<input checked="" type="checkbox"/>	
3	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
4	08/06/18 12:08	Chassis Number			Load JPG		<input checked="" type="checkbox"/>	
5	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
6	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
7	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
8	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
9	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
10	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
11	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
12	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
13	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
14	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
15	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
16	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
17	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
18	08/06/18 12:08	General View			Load JPG		<input checked="" type="checkbox"/>	
19	03/07/18 10:28	Reinspection Photo			Load JPG		<input checked="" type="checkbox"/>	
20	03/07/18 10:28	Reinspection Photo			Load JPG		<input checked="" type="checkbox"/>	
21	03/07/18 10:28	Reinspection Photo			Load JPG		<input checked="" type="checkbox"/>	
22	03/07/18 10:28	Reinspection Photo			Load JPG		<input checked="" type="checkbox"/>	
23	03/07/18 10:28	Reinspection Photo			Load JPG		<input checked="" type="checkbox"/>	
24	03/07/18 10:28	Reinspection Photo			Load JPG		<input checked="" type="checkbox"/>	
25	03/07/18 10:28	Reinspection Photo			Load JPG		<input checked="" type="checkbox"/>	
26	03/07/18 10:28	Reinspection Photo			Load JPG		<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
27	03/07/18 10:28	NTUC Income Insurance Co-operative Ltd (HQ) Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
28	03/07/18 10:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
29	03/07/18 10:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
30	03/07/18 10:28	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	02/05/18 13:14	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) REPAIR EST	 Load PDF	
2	02/05/18 13:14	OI GIA REPORT	 Load PDF	
No	Finalized On		Thumbnail	Print
1	27/04/18 03:46	NTUC Income Insurance Co-operative Ltd (HQ) Sketch Plan [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
2	27/04/18 03:46	Sketch Plan #2 [Linked Accident Report Documents]	 Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder		Thumbnail	Print
1	11/07/18 13:58	LKK Auto Consultants Pte Ltd (HQ) Supplementary	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	27/04/18 03:52	NTUC Income Insurance Co-operative Ltd (HQ) Accident Statement	 Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	27/04/18 03:47	NTUC Income Insurance Co-operative Ltd (HQ) Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
2	27/04/18 03:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
3	27/04/18 03:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
4	27/04/18 03:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
5	27/04/18 03:47	Accident Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On		Thumbnail	Print
1	27/04/18 03:46	NTUC Income Insurance Co-operative Ltd (HQ) Sketch Plan	 Load JPG	<input checked="" type="checkbox"/>
2	27/04/18 03:46	Sketch Plan #2	 Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT18007988/M1SBE2

Date: 11/07/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3001681800

Claimant Vehicle
No : SGH1645HInsured Vehicle
No : SLA535B

Date of Loss: 26/04/2018

Nature of Claim: TP

Claim
No: SNM18D02219C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGH1645H**

Make & Model: MERCEDES-BENZ E200, 1.8 (A)

Engine No: 27186030369411

Reg. Date: 01/02/2012 (Man. Year: 2011)

Chassis No: WDD2120482A536253

Colour: Brown

Odometer: 66725 km

Engine Capacity: 1796 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R18

Rear Tyre Size: 265/35 R18

Front Left Side: Yokohama 8 mm

Rear Left Side: Yokohama 8 mm

Front Right Side: Yokohama 8 mm

Rear Right Side: Yokohama 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,814.91	8,365.43	449.48	5.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,220.00	6,140.00	1,080.00	14.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	16,034.91	14,505.43	1,529.48	9.54
+ GST 7.00/7.00% (S\$)	1,122.44	1,015.38	107.06	9.54
Nett Amount (S\$)	17,157.35	15,520.81	1,636.54	9.54

INSPECTION

Date of Assignment: 02/05/2018

Date Inspected: 14/05/2018 Inspected At:

Cycle & Carriage Industries Pte Ltd
(Pandan Loop)
188 Pandan Loop
Singapore 128378

Estimated Period of Repair: 5.0 days

Adjuster: MA CHIN FOOK

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Jul 2018)
Parts:	143	MERCEDES-BENZ E200 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGH1645H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR CROSS MEMBER	Bent	789.45 FS	*789.45 FS
2	1	*RIGHT REAR BUMPER BOTTOM BRACKET	Bent	16.18 FS	*16.18 FS
3	1	*LEFT REAR BUMPER BOTTOM BRACKET	Bent	16.18 FS	*16.18 FS
4	4	*REAR PARKTRONIC SENSOR SPACER RING	Bent	27.72 FS	*27.72 FS
5	1	*REAR PARKING SENDER UNIT (4 PCS)	Shorted-3 pcs only	1,095.16 FS	*821.37 FS
6	1	*CENTRAL REAR BUMPER GARNISH MOULDING	Necessary	172.55 FS	*172.55 FS
7	1	*RIGHT REAR BUMPER GARNISH MOULDING	Necessary	128.17 FS	*128.17 FS
8	1	*LEFT REAR BUMPER GARNISH MOULDING	Necessary	128.17 FS	*128.17 FS
9	1	*REAR BUMPER	Dented	1,602.72 FS	*1,602.72 FS
10	2	*RUBBER STOPPER	Necessary	18.82 FS	*18.82 FS
11	1	*BOOT LID TYPE DESIGNATION EMBLEM	Necessary	75.34 FS	*75.34 FS
12	1	*BOOT LID E200 EMBLEM	Necessary	75.34 FS	*75.34 FS
13	1	*BOOT LID CHROME MOULDING	Necessary	113.13 FS	*113.13 FS
14	3	*MB STAR GROMMET	Necessary	6.69 FS	*6.69 FS
15	1	*BOOT LID MERCEDES STAR	Necessary	46.63 FS	*46.63 FS
16	1	*BOOT LID WEATHERSTRIP	Not Necessary	175.69 FS	*- FS
17	1	*BOOT LID HANDLE MOLDING	Dented	232.97 FS	*232.97 FS
18	1	*BOOT LID	Dented	2,709.70 FS	*2,709.70 FS
19	4	*RIVETED NUT	Necessary	14.64 FS	*14.64 FS
20	3	*PLUG	Necessary	2.76 FS	*2.76 FS
21	1	*LEFT TAIL LAMP	Scratched	611.59 FS	*611.59 FS
22	1	*TS TWO-COMPONENT ADHESIVE	Necessary	755.31 FS	*755.31 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$)	8,814.91	8,365.43
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING TO REPAIR AFFECTED AREAS, REMOVE AND REPLACE WITH NEW BODY PANELS WITH REFINISH	New	2,400.00	1,920.00
2	RESPRAY BOOT LID AND REAR BUMPER	New	1,800.00	1,200.00
3	USING XENTRY SYSTEM TO CHECK CONTROL UNITS, RESET MEMORY TO STANDARD SETTINGS	New	380.00	380.00
4	CHECK REAR LIGHTING SYSTEM AND CONDUCT WATER TEST FOR ANY LEAKAGE	New	120.00	120.00
5	ADDITIONAL LABOUR TO REPAIR REAR END PANEL	New	1,440.00	1,440.00
6	ADDITIONAL LABOUR TO RESPRAY REAR END PANEL	New	600.00	600.00
7	ADDITIONAL LABOR TO REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHS AND SEATS FOR NEC. REPAIRS.	New	480.00	480.00
Gross Labour Cost (S\$)			7,220.00	6,140.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >