



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SGH1645H*RA

SUPPLEMENTARY

CHINA TAIPING INSURANCE (S) PTE
LTD
ATTN: MOTOR CLAIM DEPARTMENT
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
62222366

Vehicle & Document Information
WIP No 23270
Reg No/Reg Date SGH1645H*RA / 01/02/2012
Date In/Mileage 16/05/2018 / 66725
Chassis No WDD21204824536253
Engine No 27186030369411
Make/Model MB/E 200 CGI SEDAN (W212)
Colour/Trim 024 497 Cuprite Bro/ 042 201 Black

| Account No | Terms | Date/Time Printed | CSE | Operator |
|------------|--------|-------------------|-----|--------------------|
| WC000668 | Credit | 28/05/2018/ 13:28 | YK | 395 / Yik Chan Hoe |

| Description of Goods / Services | Qty | Unit Price | Disc% | Amount |
|---------------------------------|-----|------------|-------|--------|
|---------------------------------|-----|------------|-------|--------|

| | | | | |
|--|------|--------|-------|--------------|
| <p>M BPNSUN POLICY NO/ACC DATE : 5099559800 // 26/04/2018 DRIVE IN/EXCESS : 27/04/2018 // 1P VEH NO SLA535B CHINA TAIPING DATE IN/DATE SURVEY: 14/05/2018 @ 1315 // BEH LKK BY/AUTHORIZED ON : DIRECT SETTLEMENT // ALFRED CHINA TAIPING</p> | | | | |
| A BPILAB ADDITIONAL LABOUR TO REPAIR REAR END PANEL | | | | 1440.00 |
| A BPIRES ADDITIONAL LABOUR TO RESPRAY REAR END PANEL | | | | 600.00 |
| A BPILAB ADDITIONAL LABOR TO REMOVE AND REFIT REAR UPHOLSTERY, TRIMS GARNISHES AND SEATS FOR NEC. REPAIRS. | | | | 480.00 |
| X RIVETED NUT | 4.00 | 3.66 | 00.00 | NEC 14.64 ✓ |
| X PLUG | 3.00 | 0.92 | 00.00 | NEC 2.76 ✓ |
| X LEFT TAIL LAMP | 1.00 | 611.59 | 00.00 | SCR 611.59 ✓ |
| M TS TWO-COMPONENT ADHESIVE | 1.00 | 755.31 | 00.00 | NEC 755.31 ✓ |

ESTIMATE

Yik Chan Hoe
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4353 HP: 9186 5109 Fax: 6872 1272
Email: chanhoe.yik@cyclecarriage.com.sg

Confirmed & accepted by

Nett 3,904.30
7% GST on 3904.30 273.30

Authorized signatory and company stamp

Total Payable 4,177.60

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS



Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg