

REPAIR ESTIMATE*

VEHICLE NO : SH 8264K

DATE 30/4/2018 10:40

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bonnet <i>X repair</i>			\$ 1,526.00
	Bonnet Lock <i>X su</i>			\$ 50.90
	Radiator Grille <i>— cra</i>			\$ 1,480.00
	Front Bumper Cover <i>— Behind</i>			\$ 1,052.20
	Front Bumper Sponge <i>X su</i>			\$ 142.20
	Front Bumper Reinforcement <i>X su</i>			\$ 526.10
	Front Bumper Bracket Top (LH/RH) <i>X su</i>		\$ 22.40	\$ 44.80
	Front Bumper Side Bracket <i>X su</i>		\$ 14.30	\$ 28.60
	Headlamp Support Panel Assy <i>X su</i>			\$ 1,067.50
	Headlamp (LH/RH) <i>LH X su RH ✓ cra</i>		\$ 1,388.00	\$ 2,776.00
	SUB TOTAL			\$ 8,694.30
	LESS 20%			\$ 1,738.86
	DISCOUNTED TOTAL			\$ 6,955.44
	Labour Charge			
	Panel Beating			\$ 850.00 <i>400</i>
	Spray Painting Charge			\$ 400.00 <i>360</i>
	Wiring Charge			\$ 50.00 <i>20</i>
	Tuff Kote			\$ 50.00 <i>X su</i>
	Remove/Refix Aircon & Refill Gas			\$ 150.00 <i>X su</i>
	TOTAL LABOUR			\$ 1,500.00
	ESTIMATE TOTAL			\$ 8,455.44
<i>Kahn CLK</i> <i>30/4/18 11:05hr</i> <i>2 bps</i> <i>P/P</i> <i>Before Part p/c</i> LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company Acknowledged by Repairer Signature _____ Date: _____ This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				