



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmco@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S: AXA INSURANCE PTE LTD

8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288

ATTN: Motor Claim Department

Estimate No: MC0912989

Date: 06 Apr 2018

Policy No: GA001686

Veh Reg No: SKK7725H

Make/Model: BMW 520I AT D/AB

2WD

Your Ref No: S8M00D7F

Claim Type: Own Damage

Accident Date: 05/04/2018

FAX: 63382522

LCC

or lost

1:30 pm

n/s body

Not Authorised

Refuse by painting

145pm

8 days

Ex 89000

Estimate Repair Cost to Vehicle No :SKK7725H

Description	U/Price	Quantity	Cost	Amount
			SS	SS
SPARE PARTS				
1 FRONT BUMPER	1 PC	1	900.00	X
2 FRONT BUMPER SIDE RETAINER LH	1 PC	1	8.00	X
3 FRONT BUMPER CLIPS	15 PC	15	22.50	X
4 FRONT FENDER LH	1 PC	1	450.00	✓
5 FRONT FENDER COWLING (FRONT SECTION)	1 PC	1	90.00	?
6 FRONT FENDER COWLING CLIPS	8 PC	8	12.00	?
7 FRONT FENDER COWLING (REAR SECTION)	1 PC	1	90.00	✓
8 FRONT FENDER COWLING CLIPS	8 PC	8	12.00	✓
9 FRONT FENDER CHROME MOULDING	1 PC	1	85.00	✓
10 FRONT DOOR LH	1 PC	1	1,150.00	✓
11 FRONT DOOR HINGE TOP & LOWER	2 PC	2	80.00	X
12 FRONT DOOR CHECKER	1 PC	1	85.00	X
13 FRONT DOOR RUBBER (AT DOOR)	1 PC	1	125.00	✓
14 FRONT DOOR RUBBER TOP - CHECK PRICE	1 PC	1	0.0000	?
15 FRONT DOOR RUBBER LOWER	1 PC	1	35.00	?
16 FRONT DOOR RUBBER (AT BODY)	1 PC	1	150.00	X
17 FRONT DOOR POWER WINDOW MOTOR	1 PC	1	220.00	?
18 FRONT DOOR POWER WINDOW REGULATOR	1 PC	1	260.00	?
19 FRONT DOOR INNER LOCK	1 PC	1	215.00	X
20 FRONT DOOR OUTER HANDLE WITH CHROME MOULDING	1 PC	1	580.00	X
21 SIDE MIRROR ARM LH	1 PC	1	680.00	?
22 SIDE MIRROR SIGNAL LAMP LH - CHECK PRICE	1 PC	1	0.0000	X
23 SIDE MIRROR LOWER COVER LH - CHECK PRICE	1 PC	1	0.0000	✓
24 REAR DOOR LH	1 PC	1	1,150.00	✓
25 REAR DOOR HINGE TOP	1 PC	1	40.00	X
26 REAR DOOR HINGE LOWER	1 PC	1	40.00	X
27 REAR DOOR CHECKER	1 PC	1	85.00	X
28 REAR DOOR RUBBER (AT DOOR)	1 PC	1	125.00	✓
29 REAR DOOR RUBBER TOP - CHECK PRICE	1 PC	1	0.0000	?
30 REAR DOOR RUBBER LOWER	1 PC	1	55.00	?
31 REAR DOOR RUBBER (AT BODY)	1 PC	1	145.00	X
32 REAR DOOR POWER WINDOW MOTOR	1 PC	1	220.00	?
33 REAR DOOR POWER WINDOW REGULATOR	1 PC	1	220.00	?
34 REAR DOOR INNER TRIMBOARD	1 PC	1	1,680.00	X
35 REAR DOOR INNER LOCK	1 PC	1	170.00	X
36 SIDE SKIRT LH - CHECK PRICE	1 PC	1	0.0000	X
37 SIDE SKIRT BRACKET FRONT - CHECK PRICE	1 PC	1	0.0000	X
38 SIDE SKIRT BRACKET REAR - CHECK PRICE	1 PC	1	0.0000	✓
39 SIDE SKIRT CLIPS	10 PC	10	15.00	X



myself

photo



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimne@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288
ATTN: Motor Claim Department

FAX: 63382522

Estimate No: MC0912989

Date: 06 Apr 2018

Policy No: GA001686

Veh Reg No: SKK7725H

Make/Model: BMW 520I AT D/AB
2WD

Your Ref No: S8M00D7F
Claim Type: Own Damage
Accident Date: 05/04/2018

Estimate Repair Cost to Vehicle No :SKK7725H

Description	U/Price	Quantity	Cost	Amount
			<u>S\$</u>	<u>S\$</u>
40 REAR FENDER LH		1 PC	1,150.00	X
41 REAR FENDER COWLING LH		1 PC	110.00	X
42 REAR FENDER COWLING CLIPS		8 PC	12.00	X
43 REAR BUMPER		1 PC	1,050.00	X
44 REAR BUMPER SIDE RETAINERS LH		1 PC	120.00	X
45 REAR BUMPER CLIPS		15 PC	22.50	X
46 FRONT WHEEL BEARING LH		1 PC	330.00	X
47 REAR WHEEL BEARING LH		1 PC	145.00	?
				12,134.00

Special Nett

48 SPORT RIM LHR, LHF	2 PC	2,000.00	X
49 TYRE LHR - CHECK PRICE	2 PC	0.0000	?
50 INNER SEAL (REAR-W/S)	1 PC	20.00	X
51 WINDSCREEN SEALANT (REAR-W/S)	1 PC	40.00	X
52 INNER SEAL (RR QUARTER GLASS LH)	1 PC	20.00	X
53 WINDSCREEN SEALANT (RR QUARTER GLASS LH)	1 PC	40.00	X
			2,120.00

LABOUR

54 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	301
55 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	601
56 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	150.00	X
57 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	160.00	✓
58 TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS.	1 PC	80.00	601
59 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	250.00	801
60 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - FRONT	1 PC	180.00	X
61 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - REAR	1 PC	180.00	?
62 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	120.00	601 X
63 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	1 PC	280.00	?
64 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	150.00	X





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0912989

Date: 06 Apr 2018

Policy No: GA001686

Veh Reg No: SKK7725H

Make/Model: BMW 520I AT D/AB
2WD

Your Ref No: S8M00D7F

Claim Type: Own Damage

Accident Date: 05/04/2018

Estimate Repair Cost to Vehicle No :SKK7725H

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
65 TO DISMANTLE ALL DAMAGED PARTS.TO CUT & WELD REAR FENDER LH.TO KNOCK & REPAIR FRONT DOOR PILLAR LH,ROCKER PANEL LH,CTR PILLAR LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	2,000.00	8001
66 TO SPRAY FRONT BUMPER,FRONT FENDER LH,FRONT DOOR LH,SIDE MIRROR LH,FROTN DOOR PILLAR LH, SIDE SKIRT LH,ROCKER PANEL LH,REAR DOOR LH,RR FENDER LH,REAR BUMPER.		1 PC	2,000.00	12001
				5,670.00

Amount Before Excess SS 19,924.00

Add GST @ 7% 1,394.68

Total Amount payable SS 21,318.68

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND THREE HUNDRED EIGHTEEN AND CENTS SIXTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9121 / 6745 9920



Dept Direct: 6417 8704

Dept Direct: 6417 9735

Dept Direct: 6417 9195

Dept Direct: 6417 9795

Wiper blade: NWB (Nippon Wiper blade), S-liper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

=====

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201805-1117
DATE : 22/05/2018
CUSTOMER ID : AHL00
VEH REG. NO. : SKK7725
TERMS : 30 day
PO NO. :
PAGE NO. : Page 1 of
CURR. : SG

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUN
1. 36116857671 F10	LIGHT ALLOY RIM 8JX17	U2	1	810.00	810.0
	SUPPLIER				

90924

SUB-TOTAL : 810.0
ADD GST 7.00 % 56.7

E. & O.E TOTAL AMOUNT SGD : 866.7

[P] 22/05/2018 10:02:45AM

[E] 22/05/2018 10:02:01A

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : XIAN



* AR201805-11175 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Arrange By
Dept Direct: 6417 9791 / 6745 9939



Dept Direct: 6305 0610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Silper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL: 64831244 FAX: 64836170
ATTN: SIMON 96205405

TAX INVOICE : AR201805-08393
DATE : 16/05/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKK7725H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1: 51777184775	SIDE SKIRT BRACKET LH	CC	1	8.00	8.00
=		CC2-I-08AP			

Page 3

SUB-TOTAL : 8.00
ADD GST 7.00 % 0.56

E. & O.E TOTAL AMOUNT SGD: 8.56

[P] 16/05/2018 2:37:18PM

[E] 16/05/2018 2:33:39PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: XIAN

This is computer generated document.

No signature is required.



AR201805-08393

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450816 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

=====

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

WINDSCREEN GLASS
Dept Direct: 6417 9191 / 6745 9239



Dept Direct: 6365 9610

Dept Direct: 6365 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWS (Nippon Wiper blade), Sliper (Made in Korea)

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

=====

TAX INVOICE : AR201805-07364
DATE : 15/05/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKK7725H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
51777262663 F10	SIDE SKIRT LH	U2	1	330.00	330.00
		SUPPLIER			

Page 2.

SUB-TOTAL : 330.00
ADD GST 7.00 % 23.10

E. & O.E

TOTAL AMOUNT SGD : 353.10

[P] 15/05/2018 10:23:30AM

[E] 15/05/2018 10:23:05AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : XIAN



* A R 2 0 1 8 0 5 - 0 7 3 6 4 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司 JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9930



Dept Direct: 6305 9610

Dept Direct: 6305 9511

Dept Direct: 6417 9792

TOYOTA

GENEVE PARIS

LEXUS

DAIHATSU



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)
Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201805-07350
DATE : 15/05/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKK7725H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 2
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 41357248659 ✓ F10	FRT FENDER LH	CC CC2-B-02C	1	450.00 ✓	450.00
2. 51717186723 ✓ F10	FRT FENDER SHIELD LH (RR)	CC CC3-B-09F	1	90.00 ✓	90.00
3. 51161881149 ✓ F10	EXPANDING RIVE1	CC CC2-I-08AE	8	1.50 ✓	12.00
4. 51137336645 ✓ F10	FINISHER LH	CC CC2-K-05AT	1	85.00 ✓	85.00
5. 41007206107 ✓ F10	FRT DOOR LH	CC CC2-D-01A	1	1150.00 ✓	1,150.00
6. 51767182269 ✓ F10	FRT DOOR W/STRIPE L/R	CC CC2-K-09C	1	125.00 ✓	125.00
7. 51167308647 ✓ F10	MIRROR LOWER HOUSING ,LH	CC CC2-K-07A	1	60.00 ✓	60.00

CONTINUE NEXT PAGE

[F] 15/05/2018 10:21:39AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 15/05/2018 10:14:38AM

Page 1



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9701 / 6745 9920



Dept Direct: 6305 9610

Dept Direct: 6305 9311

Dept Direct: 6417 9702



Dept Direct: 6417 9704

Dept Direct: 6417 9705

Dept Direct: 6417 9706

Dept Direct: 6417 9703

Wiper blade: IWB (Nippon Wiper blade), Siliper (Made in Korea),
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AHLIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201805-07350
DATE : 15/05/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKK7725H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 2 of 2
CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8. 41007206113 ✓ F10	RR DOOR LH	CC CC2-H-03A	1	1150.00 ✓	1,150.00
9. 51767182287 ✓ F10	RR DOOR W/SRIP L/R	CC CC2-L-06A	1	125.00 ✓	125.00
10. 51718259788 ✓ F10	DOOR SILL COVER CLIP	CC CC2-K-06AN	10	1.50 ✓	15.00

Page 1

SUB-TOTAL : 3,262.00
ADD GST 7.00 % 228.34

R & O R TOTAL AMOUNT SGD : 3,490.34

[P] 15/05/2018 10:21:39AM

[E] 15/05/2018 10:14:38AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : XIAN

This is computer generated document.
No signature is required.



* AR 201805-07350 *

ORIGINAL

Goods Received in Good Order

Signature X Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 6745 9039



Dept Direct: 6365 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9793

Wiper blade: NWB (Nippon Wiper blade, Silper i Made in Korea)
Forch i Made in Germany i

Spark plug: Nippon Denso, NGK (Made in Japan)

=====

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201805-08663
DATE : 17/05/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKK7725H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 51167308639 F10	SUPPORTING RING LH	U2	1	54.00	54.00
	SUPPLIER				

SUP
P133

SUB-TOTAL : 54.00
ADD GST 7.00 % 3.78

E. & O.E TOTAL AMOUNT SGD : 57.78

[P] 17/05/2018 9:12:01AM

[E] 17/05/2018 9:11:34AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : XIAN



* AR 201805-08663 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSCREEN GLASS
Dept Direct: 6417 9791 / 0745 0020



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blade: HWB (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

=====

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201805-1117
DATE : 22/05/2018
CUSTOMER ID : AHL00
VEH REG. NO. : SKK7725
TERMS : 30 day
PO NO. :
PAGE NO. : Page 1, of
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUN
1. 36116857671 F10	LIGHT ALLOY RIM 8JX17	U2	1	810.00	810.0
	SUPPLIER				

PO 204

	SUB-TOTAL :	810.0
	ADD GST 7.00 %	56.7
	TOTAL AMOUNT SGD :	866.7

[P] 22/05/2018 10:02:45AM

[E] 22/05/2018 10:02:01A

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : XIAN



This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WINDSHIELD GLASS
Dept Direct: 6417 9791 / 6745 9033



Dept Direct: 6305 9610

Dept Direct: 6305 9611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9797

Wiper blades: NWB (Nippon Wiper blades), Silper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AHLIM MOTOR COMPANY

10 ANG MO KIO PARKS 2A

#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL : 64831244 FAX : 64836170

ATTN : SIMON 96205405

TAX INVOICE : AR201805-08393

DATE : 16/05/2018

CUSTOMER ID : AHL008

VEH REG. NO. : SKK7725H

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 1

CURR : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 51777184775	SIDE SKIRT BRACKET LH	CC	1	8.00	8.00
		CC2-I-08AP			

Page 3

SUB-TOTAL : 8.00
ADD GST 7.00 % 0.56

E. & O.E TOTAL AMOUNT SGD : 8.56

[P] 16/05/2018 2:37:18PM

[E] 16/05/2018 2:33:39PM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : XIAN

This is computer generated document.

No signature is required.



* AR 201805 - 08393 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

=====
AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

WINDSCREEN GLASS
Dept Direct: 6417 0791 / 0746 9230



Dept Direct: 6305 6610

Dept Direct: 6305 9811

Dept Direct: 6417 8792



Dept Direct: 6417 0701

Dept Direct: 6417 0725

Dept Direct: 6417 0796

Dept Direct: 6417 0793

Wiper blade: NWB (Nippon Wiper blade), Sliper (Made in Korea)
Fench (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

TAX INVOICE : AR201805-07364
DATE : 15/05/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKK7725H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SO STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 51777262663 F10	SIDE SKIRT LH	U2	1	330.00	330.00
		SUPPLIER			

Page 2.

SUB-TOTAL : 330.00
ADD GST 7.00 % 23.10

E. & O.E

TOTAL AMOUNT SGD : 353.10

[P] 15/05/2018 10:23:30AM

[E] 15/05/2018 10:23:05AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : XIAN



* A R 2 0 1 8 0 5 - 0 7 3 6 4 *

This is computer generated document.
No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

ARRANGE BY
Driver: **BLACK**
Dept Direct: 6417 9701 / 6745 9929



Dept Direct: 6417 0704

Dept Direct: 6417 9705

Dept Direct: 6417 9706

Dept Direct: 6417 9702

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY

10 ANG MO KIO PARKS 2A

#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL : 64831244 FAX : 64836170

ATTN : SIMON 96205405

TAX INVOICE : AR201805-07350

DATE : 15/05/2018

CUSTOMER ID : AHL008

VEH REG. NO. : SKK7725H

TERMS : 30 days

PO NO. :

PAGE NO. : Page 1 of 2

CURR : SGD

SQ	STOCKID	DESCRIPTION	Stk Loc	QTY	U/PRICE	AMOUNT
1.	41357248659 ✓ F10	FRT FENDER LH	CC CC2-B-02C	1	450.00 ✓	450.00
2.	51717186723 ✓ F10	FRT FENDER SHIELD LH (RR)	CC CC3-B-09F	1	90.00 ✓	90.00
3.	51161881149 ✓ F10	EXPANDING RIVE1	CC CC2-I-08AE	8	1.50 ✓	12.00
4.	51137336645 ✓ F10	FINISHER LH	CC CC2-K-05AT	1	85.00 ✓	85.00
5.	41007206107 ✓ F10	FRT DOOR LH	CC CC2-D-01A	1	1150.00 ✓	1,150.00
6.	51767182269 ✓ F10	FRT DOOR W/STRIP L/R	CC CC2-K-09C	1	125.00 ✓	125.00
7.	51167308647 ✓ F10	MIRROR LOWER HOUSING ,LH	CC CC2-K-07A	1	60.00 ✓	60.00

CONTINUE NEXT PAGE

[P] 15/05/2018 10:21:39AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

ORIGINAL

[E] 15/05/2018 10:14:38AM

Page 1



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 3018 UBI ROAD 1 #01-121 SINGAPORE 408710

TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:

48A SUNGEI KADUT AVE SINGAPORE 729672

TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

WHILE GREEN GLASS
Dept Direct: 6417 9791 / 6745 0629



Dept Direct: 6305 1618

Dept Direct: 6305 0611

Dept Direct: 6417 9792



Dept Direct: 6417 9794

Dept Direct: 6417 9795

Dept Direct: 6417 9796

Dept Direct: 6417 9799

Wiper blade: NWB (Nippon Wiper blade), Siliper (Made in Korea).

Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AHLIM MOTOR COMPANY

10 ANG MO KIO PARKS 2A

#01-09 AMK AUTO POINT

SINGAPORE 568047

TEL : 64831244 FAX : 64836170

ATTN : SIMON 96205405

TAX INVOICE : AR201805-07350

DATE : 15/05/2018

CUSTOMER ID : AHL008

VEH REG. NO. : SKK7725H

TERMS : 30 days

PO NO. :

PAGE NO. : Page 2 of 2

CURR : SGD

SQ	STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
8.	41007206113 ✓ F10	RR DOOR LH	CC CC2-H-03A	1	1150.00 ✓	1,150.00
9.	51767182287 ✓ F10	RR DOOR W/STRIP L/R	CC CC2-L-06A	1	125.00 ✓	125.00
10.	51718259788 ✓ F10	DOOR SILL COVER CLIP	CC CC2-K-06AN	10	1.50 ✓	15.00

Page 1

SUB-TOTAL : 3,262.00
ADD GST 7.00 % 228.34

E & O E

TOTAL AMOUNT SGD : 3,490.34

[P] 15/05/2018 10:21:39AM

[E] 15/05/2018 10:14:38AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive: XIAN

This is computer generated document.

No signature is required.



* A R 2 0 1 8 0 5 - 0 7 3 5 0 *

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date



日美汽車私人有限公司

JAE AUTO PTE LTD

Blk 301B UBI ROAD 1 #01-121 SINGAPORE 408710
TEL: 67453833 FAX: 67454442, 67450616 (Account)

WAREHOUSE:
48A SUNGEI KADUT AVE SINGAPORE 729672
TEL: 6365 1255 FAX: 6365 2580

Email: jaeauto@pacific.net.sg

GST REG. NO.: M2-0119201-3 CO. REG. NO.: 199307741M

Dep't Direct: 6417 9791 / 6745 6033



Dep't Direct: 6305 9610

Dep't Direct: 6305 9611

Dep't Direct: 6417 9782



Dep't Direct: 6417 9794

Dep't Direct: 6417 9725

Dep't Direct: 6417 9795

Dep't Direct: 6417 9792

Wiper blade: NWB (Nippon Wiper blade), Sniper (Made in Korea)
Forch (Made in Germany)

Spark plug: Nippon Denso, NGK (Made in Japan)

AH LIM MOTOR COMPANY
10 ANG MO KIO PARKS 2A
#01-09 AMK AUTO POINT

SINGAPORE 568047
TEL : 64831244 FAX : 64836170
ATTN : SIMON 96205405

TAX INVOICE : AR201805-08663
DATE : 17/05/2018
CUSTOMER ID : AHL008
VEH REG. NO. : SKK7725H
TERMS : 30 days
PO NO. :
PAGE NO. : Page 1 of 1
CURR. : SGD

SQ STOCKID	DESCRIPTION	StkLoc	QTY	U/PRICE	AMOUNT
1. 51167308639 F10	SUPPORTING RING LH	U2	1	54.00	54.00
	SUPPLIER				

51P
P135

SUB-TOTAL : 54.00
ADD GST 7.00 % 3.78

E. & O.E TOTAL AMOUNT SGD : 57.78

[P] 17/05/2018 9:12:01AM

[E] 17/05/2018 9:11:34AM

Goods Sold are not refundable for Cash.

Interest Rate of 1.5% per month will be imposed on OverDue Account(s).

JAE Auto Pte. Ltd.

Sales Executive : XIAN



* AR201805-08663 *

This is computer generated document.

No signature is required.

ORIGINAL

Goods Received in Good Order

Signature / Co Stamp / Date

Service Request Details

Claim	S8M0007F
Reference	CS/ASM18007991/Ksbs2
Loss Date	April 5, 2018
Request Date	April 30, 2018
Due Date	May 2, 2019
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (OD)
Type of Loss	Own Damage
Services	Accelerated workshop survey

Actions

Next Step

Complete Work

Finish the work

More »

Vehicle Information	
Incident Vehicle Registration #	SKK7725H
Make	BMW
Model	520 i
Service Address	

10 Ang Mo Kio Ind. Park 2A, , 568047

Primary Contact/Insured

LOY SIEW ENG
NO. 33 LEITH PARK, 547948, Singapore
96868286

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

Additional Instructions

EXCESS \$400 + \$500 TOTAL \$900

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
------	------	----------	--------	------------------

Service Request Details

Claim SBM0007F

Reference CS/ASM18007991/Ksbs2

Loss Date April 5, 2018

Request Date April 30, 2018

Due Date May 2, 2019

Vendor Name LKK AUTO CONSULTANTS PTE LTD (000)

Type of Loss Own Damage

Services Accelerated workshop survey

Actions

Next Step: Finish the work

Complete Work

More

Vehicle Information

Incident Vehicle Registration #

SKK7725H

Make

BMW

Model

520 I

Service Address

10 Ang Mo Kio Ind. Park 2A, ., 568047

Primary Contact/Insured

LOY SIEW ENG
NO. 33 LEITH PARK, 547948, Singapore
96868286

Claim Handler

ANG Yvonne
6568804461
yvonne.ang@axa.com.sg

EXCESS \$400 - \$500 TOTAL \$900

Additional Instructions

MessagesInvoicesHistoryDocumentsAssessmentMetricsNotes

Add

CREATED USER	VERSION DATE	ESTIMATED AMOUNT	APPROVED AMOUNT	STATUS	SHARE	CLONE
--------------	--------------	------------------	-----------------	--------	-------	-------

User Portal	5/4/18 2:06 PM	5954	5954	In Review	Share	Clone
-------------	----------------	------	------	-----------	-------	-------



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details		Vehicle Condition		Taxes & Ratio		Parts & Labour		Miscellaneous		Summary	
General Details				Workshop Details									
Involving		1 2013 BMW 520 I (SKK7725H)											
Date of Loss		April 5, 2018											
Time of Loss		10.15											
Loss Description		SKK7725H (INSD) C/W SJG8512G											
Comment													



Assessment Details

General & Workshop Details Vehicle & Driver Details Taxes & Ratio Parts & Labour Miscellaneous Summary

Vehicle & Driver Details

Vehicle Registration# SKK7725H

Purchase Date mm/dd/yyyy

Registration State SINGAPORE

Registration Date * 08/30/2013

Mileage 95718

Age of Vehicle 4

CATEGORY POLICY INFORMATION ASSESSMENT INFORMATION

Manufacturing Year 2013

2013

CATEGORY FNOL INFORMATION POST SURVEY INFORMATION

Make BMW

B.M.W.

Driver Name GOH DOH TAN

Model 520 I

520I AT D/AB 2WD 4D

Date of Birth July 19, 1940

mm/dd/yyyy

Type

Age 78

Type of Paint

Occupation Unknown

Chassis No

WBASA320X0D333765

WBASA320X0D33376

Education Qualification

Other

Engine No

A8120572N20B20B

A8120572N20B20B

Driving Experience

51

Engine Capacity

Driver License #



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Detailed Assessment

Condition of Vehicle at time of survey

Inspection Date *	05/02/2018		General condition	Good
Total Loss	Yes	No	Steering (Serviceable)	Yes No
Towing Charges	0		Footbrake (Serviceable)	Yes No
Voluntary Excess	0		Handbrake (Serviceable)	Yes No
Compulsory Excess	900		Engine Modification	Yes No
Young/Inexperienced/Unarmed Driver Excess	0		Pre-accident condition	Good
Other Excess				

Tyre Condition

Age of Tyres		Spare wheel	
Front Tyre Size	225/55R17	Rear Tyre Size	225/55R17
Front left side	BRIDGESTONE 7mm	Rear left side	BRIDGESTONE 7mm
Front right side	BRIDGESTONE 7mm	Rear right side	BRIDGESTONE 7mm

SERVICE REQUESTS MESSAGES CLAIMS

« Assessment Details

General & Workshop Details Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts

Add

Approve

Deny

Submit All

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPRJ BTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	1	1			FRONT BUMPER			Serviceable	0				0	Reviewing	
	2	1			FRONT BUMPER SIDE RETAINER LH			Serviceable	0				0	Reviewing	
	3	15			FRONT BUMPER CLIPS			Serviceable	0				0	Reviewing	
	4	1			FRONT FENDER LH			Bent	450				450	Reviewing	
	5	1			FRONT FENDER COWLING (FRONT SECTION)			Serviceable	0				0	Reviewing	
	6	8			FRONT FENDER COWLING CLIPS			Serviceable	0				0	Reviewing	
	7	1			FRONT FENDER COWLING (REAR SECTION)			Cracked	90				90	Reviewing	
	8	8			FRONT FENDER COWLING CLIPS			Necessary	1.5				12	Reviewing	
	9	1			FRONT FENDER CHROME MOULDING			Necessary	85				85	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LBT PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	24	1			REAR DOOR LH			Bent	1150				1150	Reviewing	
	25	1			REAR DOOR HINGE TOP			Repair	0				0	Reviewing	
	26	1			REAR DOOR HINGE LOWER			Repair	0				0	Reviewing	
	27	1			REAR DOOR CHECKER			Serviceable	0				0	Reviewing	
	28	1			REAR DOOR RUBBER (AT DOOR)			Necessary	125				125	Reviewing	
	29	1			REAR DOOR RUBBER TOP (NPA)			Serviceable	0				0	Reviewing	
	30	1			REAR DOOR RUBBER LOWER			Serviceable	0				0	Reviewing	
	31	1			REAR DOOR RUBBER LOWER			Serviceable	0				0	Reviewing	
	32	1			REAR DOOR POWER WINDOW MOTOR			Serviceable	0				0	Reviewing	
	33	1			REAR DOOR POWER WINDOW REGULATOR			Serviceable	0				0	Reviewing	
	34	1			REAR DOOR INNER TRIMBOARD			Serviceable	0				0	Reviewing	
	35	1			REAR DOOR INNER LOCK			Repair	0				0	Reviewing	
	36	1			SIDE SKIRT LH (MTG)			Cracked	330				330	Reviewing	
	37	1			SIDE SKIRT BRACKET FRONT			Damaged	8				8	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPIL/ BTR%	DISC COUNT%	SALV AGEN	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	52	1			INNER SEAL (RR QUARTER GLASS LH)			Serviceable	0				0	Reviewing	
	53	1			WINDSCREEN SEALANT (RR QUARTER GLASS LH)			Serviceable	0				0	Reviewing	
	54	1			DOOR VIEW MIRROR SURROUND			Cracked	54				54	Reviewing	

Labour

Add

Approve

Cancel

Report All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		TO DISCONNECT AND CHECK ELECTRICAL WIRING. WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS. TEST AND RECTIFY FOR PROPER FUNCTIONING.	30	0	0	Reviewing		
	2		TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	60	0	0	Reviewing		
	3		TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	0	0	0	Reviewing		
	4		TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR	160	0	0	Reviewing		
	5		TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS	80	0	0	Reviewing		
	6		TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - FRONT	0	0	0	Reviewing		
	7		TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - REAR	0	0	0	Reviewing		
	8		TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	0	0	0	Reviewing		

SERVICE REQUESTS MESSAGES CLAIMS

<<

Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Claim Amount

\$5,954.00

Claim Amount

\$5,954.00

CATEGORY	ESTIMATE	REVISED AMOUNT
Spare Parts	\$14,254.00	\$4,464.00
Labour	\$5,670.00	\$2,390.00
Excess	-\$900.00	-\$900.00