



AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlmmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811
TEL: 63387288
ATTN: Motor Claim Department

Estimate No: MC0912989
Date: 06 Apr 2018
Policy No: GA001686
Veh Reg No: SKK7725H
Make/Model: BMW 520i AT D/AB
2WD

Your Ref No: S8M00D7F
Claim Type: Own Damage
Accident Date: 05/04/2018

FAX: 63382522

n/s body
02/05/18
1:30 pm
Not Authorised
Today
Refuse by painting
Ex 890ch

Estimate Repair Cost to Vehicle No :SKK7725H

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
SPARE PARTS				
1 FRONT BUMPER		1 PC	900.00	X
2 FRONT BUMPER SIDE RETAINER LH		1 PC	8.00	X
3 FRONT BUMPER CLIPS		15 PC	22.50	X
4 FRONT FENDER LH		1 PC	450.00	✓
5 FRONT FENDER COWLING (FRONT SECTION)		1 PC	90.00	?
6 FRONT FENDER COWLING CLIPS		8 PC	12.00	?
7 FRONT FENDER COWLING (REAR SECTION)		1 PC	90.00	✓
8 FRONT FENDER COWLING CLIPS		8 PC	12.00	✓
9 FRONT FENDER CHROME MOULDING		1 PC	85.00	✓
10 FRONT DOOR LH		1 PC	1,150.00	✓
11 FRONT DOOR HINGE TOP & LOWER		2 PC	80.00	X
12 FRONT DOOR CHECKER		1 PC	85.00	X
13 FRONT DOOR RUBBER (AT DOOR)		1 PC	125.00	✓
14 FRONT DOOR RUBBER TOP - CHECK PRICE		1 PC	0.0000	?
15 FRONT DOOR RUBBER LOWER		1 PC	35.00	?
16 FRONT DOOR RUBBER (AT BODY)		1 PC	150.00	X
17 FRONT DOOR POWER WINDOW MOTOR		1 PC	220.00	?
18 FRONT DOOR POWER WINDOW REGULATOR		1 PC	260.00	?
19 FRONT DOOR INNER LOCK		1 PC	215.00	X
20 FRONT DOOR OUTER HANDLE WITH CHROME MOULDING		1 PC	580.00	X
21 SIDE MIRROR ARM LH		1 PC	680.00	?
22 SIDE MIRROR SIGNAL LAMP LH - CHECK PRICE		1 PC	0.0000	X
23 SIDE MIRROR LOWER COVER LH - CHECK PRICE		1 PC	0.0000	✓
24 REAR DOOR LH		1 PC	1,150.00	✓
25 REAR DOOR HINGE TOP		1 PC	40.00	X
26 REAR DOOR HINGE LOWER		1 PC	40.00	X
27 REAR DOOR CHECKER		1 PC	85.00	X
28 REAR DOOR RUBBER (AT DOOR)		1 PC	125.00	✓
29 REAR DOOR RUBBER TOP - CHECK PRICE		1 PC	0.0000	?
30 REAR DOOR RUBBER LOWER		1 PC	55.00	?
31 REAR DOOR RUBBER (AT BODY)		1 PC	145.00	X
32 REAR DOOR POWER WINDOW MOTOR		1 PC	220.00	?
33 REAR DOOR POWER WINDOW REGULATOR		1 PC	220.00	?
34 REAR DOOR INNER TRIMBOARD		1 PC	1,680.00	X
35 REAR DOOR INNER LOCK		1 PC	170.00	X
36 SIDE SKIRT LH - CHECK PRICE		1 PC	0.0000	X
37 SIDE SKIRT BRACKET FRONT - CHECK PRICE		1 PC	0.0000	X
38 SIDE SKIRT BRACKET REAR - CHECK PRICE		1 PC	0.0000	X
39 SIDE SKIRT CLIPS		10 PC	15.00	X





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
 TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
 GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
 8 SHENTON WAY
 #27-01 AXA TOWER
 SINGAPORE 068811

TEL: 63387288 FAX: 63382522
 ATTN: Motor Claim Department

Estimate No: MC0912989
 Date: 06 Apr 2018
 Policy No: GA001686
 Veh Reg No: SKK7725H
 Make/Model: BMW 520i AT D/AB
 2WD

Your Ref No: S8M00D7F
 Claim Type: Own Damage
 Accident Date: 05/04/2018

Estimate Repair Cost to Vehicle No :SKK7725H

Description	U/Price	Quantity	Cost	Amount
			SS	SS
40 REAR FENDER LH		1 PC	1,150.00 X	
41 REAR FENDER COWLING LH		1 PC	110.00 X	
42 REAR FENDER COWLING CLIPS		8 PC	12.00 X	
43 REAR BUMPER		1 PC	1,050.00 X	
44 REAR BUMPER SIDE RETAINERS LH		1 PC	120.00 X	
45 REAR BUMPER CLIPS		15 PC	22.50 X	
46 FRONT WHEEL BEARING LH		1 PC	330.00 X	
47 REAR WHEEL BEARING LH		1 PC	145.00 ?	
				12,134.00

Special Nett

48 SPORT RIM LHR, LHF	1 PC	2,000.00	LT
49 TYRE LHF LHR - CHECK PRICE	2 PC	0.0000	?
50 INNER SEAL (REAR W/S)	1 PC	20.00	X
51 WINDSCREEN SEALANT (REAR W/S)	1 PC	40.00	X
52 INNER SEAL (RR QUARTER GLASS LH)	1 PC	20.00	X
53 WINDSCREEN SEALANT (RR QUARTER GLASS LH)	1 PC	40.00	X
			2,120.00

LABOUR

54 TO DISCONNECT AND CHECK ELECTRICAL WIRING, WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS, TEST AND RECTIFY FOR PROPER FUNCTIONING.	1 PC	40.00	301
55 TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	1 PC	80.00	601
56 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR WINDSCREEN.	1 PC	150.00	X
57 TO DISMANTLE AND TRANSFER DOOR FITTINGS AND MECHANISM SUCH AS POWER WINDOW MOTOR AND REGULATOR TO NEW DOOR/FACILITATE REPAIR.	1 PC	160.00	✓
58 TO REMOVE AND REINSTALL/REPLACE QUARTER GLASS.	1 PC	80.00	601
59 TO REMOVE AND REINSTALL CUSHIONS, SEATS, BACKREST, INNER TRIM, GARNISH, ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	1 PC	250.00	801
60 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - FRONT	1 PC	180.00	X
61 TO DISMANTLE, REPLACE AND REINSTALL UNDERCARRIAGE - REAR	1 PC	180.00	?
62 TO REMOVE AND REINSTALL/REPLACE FRONT/REAR BUMPER SENSORS.	1 PC	120.00	601 X
63 LABOUR TO RESET ENGINE MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT	1 PC	280.00	?
64 TO SPRY ANTI-RUST COATING ON AFFECTED AREAS.	1 PC	150.00	X





AH LIM MOTOR COMPANY

No. 10 Ang Mo Kio Ind. Park 2A #01-09 AMK Autopoint Singapore 568047
TEL: 6483 1244 (4 lines) FAX: 6483 6170 Email: ahlimmc@singnet.com.sg
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : AXA INSURANCE PTE LTD
8 SHENTON WAY
#27-01 AXA TOWER
SINGAPORE 068811

TEL: 63387288

FAX: 63382522

ATTN: Motor Claim Department

Estimate No: MC0912989

Date: 06 Apr 2018

Policy No: GA001686

Veh Reg No: SKK7725H

Make/Model: BMW 520i AT D/AB
2WD

Your Ref No: S8M00D7F

Claim Type: Own Damage

Accident Date: 05/04/2018

Estimate Repair Cost to Vehicle No :SKK7725H

Description	U/Price	Quantity	Cost	Amount
			<u>SS</u>	<u>SS</u>
65 TO DISMANTLE ALL DAMAGED PARTS,TO CUT & WELD REAR FENDER LH,TO KNOCK & REPAIR FRONT DOOR PILLAR LH,ROCKER PANEL LH,CTR PILLAR LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.		1 PC	2,000.00	8001
66 TO SPRAY FRONT BUMPER,FRONT FENDER LH,FRONT DOOR LH,SIDE MIRROR LH,FRONT DOOR PILLAR LH, SIDE SKIRT LH,ROCKER PANEL LH,REAR DOOR LH,RR FENDER LH,REAR BUMPER.		1 PC	2,000.00	12001
				5,670.00

Amount Before Excess SS 19,924.00

Add GST @ 7% 1,394.68

Total Amount payable SS 21,318.68

TOTAL: SINGAPORE DOLLAR TWENTY ONE THOUSAND THREE HUNDRED EIGHTEEN AND CENTS SIXTY EIGHT ONLY

Please arrange this vehicle to be surveyed soonest possible.

Thank You

For AH LIM MOTOR COMPANY



AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: