

2/28/2007

ASS. REC. BY:

REF: CS / II / 18007994 / Abs²

Special Instruction:

Survivor

#drsm

ASSIGNMENT (Office)

From (Person): Mulman Gubari Wdo

of II

Date/Time: 30042008 526pm

Estimated Cost:

Bill to:

OD / II / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLT 407A

Insured: SH 80611

at Workshop m/s Yi Heng

Tel: 6509 0052

of BK 1 Kaki Bukit Ave 6 #02-19

Policy No:

Claim No:

Sum Insured:

Excess:

Make of Veh:
(Client's Record)

D.O.A. 25042006

CA / REV / REP. / REV 24 HRS Wp

H.O.D. Endorsement:

Date/Time: 02052008 930am

Person Contacted:

Wen Ping

Vehicle (D) / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLT 407A - X
	SHD 2378E - X
	Confirm L/S \$500 @ 3 day
	Red: \$2459.90, 83%

REF: II

ASSIGNMENT

03/05/08

From:

Date:

02052018

Veh No:

SLT4027A

Yr Regn:

2008

May

Estimated Cost:

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

Make:

Toyota Altis.

C.C. 1598

To Inspect Vehicle No:

SLT 4027A

Colour:

Blue.

A/C: Insured / Std / NI / NA

at Workshop m/s

Yi Heng

Sp Reading

152636

T/Radio: Insured / Std / NI / NA

of

81E 1 Kaka Bukit Ave 6 # 02-19

Insured:

Eng/No:

MROS37EE106107523

Policy No.:

C/No:

Claims No.:

Gen. Cond: Good / Fair / Poor / Burnt

Sum Insured:

Excess:

Steering: Inorder / Jammed / Leaked / Burnt or

(Client's Record)

Brake: Inorder / Jammed / Leaked / Burnt or

Make of Veh:

Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Tyre Size:

F:

195/65R15

R:

195/65R15.

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Bal. or Market Value:

Front

Rear

IDAC Accident Rpt:

Consistent?: Yes or No

R/Bal.

06

mm

R/Bal.

06

mm

GIA / PR Seen:

Consistent?: Yes or No

L/Bal.

06

mm

L/Bal.

06

mm

Est. Repairs:

days

Res.: Yes or No

D.O.A.

D.O.I.

02/05/18

Lump Sum:

%

3 Val.: Yes or No

Survey held at

Yi Heng.

CA / REV / REP. / 24 HRS

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

Vehicle: IN / OUT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP III

MV: 9K

RV: 8.4K

Nett: 600.

RECEIVED 14 JUN 2018

Date/Time, File Pass to?

: Preli. Report

Days Of Repair:

3

1) Expint

: Final Report

Resurvey No. of Trip:

1

Survey Fee:

250

Date/Time, File Return to?

Transportation:

2)

Add Fee:

: Site Insp (\$

) S + RS \$

: Interview (\$

) Photos

: Tech Invs (\$

) Others

: Weekend (\$

)

10

Report Format:

TP

Lump Sum / ~~LD~~ (\$ 500)

TOTAL

Catherine Chong (LKK Auto)

From: Motor Claim - III <motorclaim@iii.com.sg>
Sent: Monday, 30 April, 2018 5:26 PM
To: ct-admin@visionlawllc.com; Anna Tan; 'sur@lkkauto.com'; Nivitha (LKK Auto)
Cc: Zuhaidah Samsuri
Subject: RE: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLT4027A (Accident involving SLT4027A and SH8061D on 25.04.2018)
Attachments: 3493_001.pdf; 0743_001.pdf

Dear Sir / Mdm,

Please conduct a survey on TP vehicle SHD2878E and let us have your report urgently.

This claim will be handled by Ms Aida.

*Kindly upload this survey request email to merimen.

Thank You.

02052018 @ 930am
wan ping veh in.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: Motor Claim - III
Sent: 30 April, 2018 11:10 AM
To: 'ct-admin@visionlawllc.com' <ct-admin@visionlawllc.com>; 'Anna Tan' <annatan@visionlawllc.com>
Subject: PRE-REPAIR INSPECTION FOR VEHICLE NO. SLT4027A (Accident involving SLT4027A and SG8061D on 25.04.2018)

Dear Sir / Mdm,

We acknowledge receipt of your email.

We propose using one of the following motor surveyors:

- LKK Auto Consultants Pte Ltd
- Vicom Assessment Centre Pte Ltd

Please notify us within 02 days of receipt of this letter for surveyor agreed on or if you have any objections to the above list.

Best Regards,

Gabriel Wee

Motor Claims Dept.

India International Insurance Pte Ltd

64 Cecil Street | #05 IOB Building | Singapore 049711

Tel: 6347 6100, Ext - 248

From: ct-admin@visionlawllc.com [mailto:ct-admin@visionlawllc.com]

Sent: 30 April, 2018 10:35 AM

To: Motor Claim - III <motorclaim@iii.com.sg>

Subject: Scan Image

Kindly note that by submitting this claim to us, you are deemed to have agreed to us collecting, using, disclosing and processing your personal data, sharing your personal data with our service providers (located both inside and outside Singapore) and/or with other insurers in the general insurance industry, including the General Insurance Association of Singapore. This enables us to ensure proper processing, handling and/or dealing with your claim, which includes investigating the said claim, and complying with applicable laws. If you do not agree to the same, kindly let us know immediately.

DISCLAIMER:

This email is intended solely for the person to whom it has been addressed.

It may contain confidential and/or legally privileged information.

If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as information could be intercepted, corrupted, lost, delayed or contain viruses.

Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification.

Print this email only if it is absolutely necessary and help in preservation of environment.

India International Insurance Pte Ltd.

Registration No. 198703792-K

VISION LAW LLC

Advocates & Solicitors - Notary Public - Commissioner for Oaths
Agents for Trade Marks
(Incorporated with limited liability)

ERIC NG CHING BOON
WONG KENG LEONG RAYNEY
AUDREY WONG SU-HSIEN
PAUL YAP TAI SAN
ANJALI D/O MUNIANDY
SEGA PARAM
ONG BOCK KEE
DIANE ANG KIM NOI
RAVENDRA KRISHNASAMY
TAY HAO RAN
JANICE HAN JIA LIN
TAN YINGXIAN SELWYN

Company Registration No. 200721148H

Head Office:
133 New Bridge Road
#18-01/02 Chinatown Point
Singapore 059413

Branch:
490 Toa Payoh Lorong 6
#03-11 HDB Hub
Singapore 310490

HEAD OFFICE:

TEL : 65342811 (Hunting)
FAX : 65356802 (General)

E-MAIL: annatan@visionlawllc.com

BRANCH

TEL : 63580703
FAX : 63580448(conveyancing)

WHEN REPLYING PLEASE QUOTE OUR REFERENCE - Please reply to **HEAD OFFICE** for this matter

OUR REF: AKN-atv-INS-Y44-SLT4027A-2018
YOUR REF: SH 8061 D

30 April 2018

INDIA INTERNATIONAL INSURANCE PTE LTD
64 Cecil Street
#04/#05 IOB Building
Singapore 049711
Attn: Motor Claims Department

BY FAX 6224-4174 & EMAIL:
motorclaim@iii.com.sg

Dear Sirs

NAME OF CLAIMANT: ST RENT & DRIVE PTE LTD
VEHICLE NUMBER: SLT 4027 A
YOUR INSURED VEHICLE NUMBER: SH 8061 D
ACCIDENT ALONG PIE TOWARDS JURONG ON 25-APR-18 AT ABOUT 1714HOURS

We refer to your email dated 30 April 2018 informing that you wish to conduct a pre-repair survey and your List of Surveyors.

Our client confirmed appointment of **MR ADRIAN LING OF LKK AUTO CONSULTANTS PTE LTD** as the Single Joint Expert for this matter.


Please be informed that the said vehicle can be inspected at :

YI HENG MOTOR WORKSHOP
1 KAKI BUKIT AVENUE 6
#02-19 AUTOBAY @ KAKI BUKIT
SINGAPORE 417883
TEL: 6509 0052 (WAN PING)

Contact Person:

If you fail to conduct the pre-repair inspection within the next 2 working days excluding any intervening Saturday, Sunday or Public Holiday, the said workshop will commence repairs thereafter without further reference to you.

Yours faithfully



(Head Office)

cc. SLT 4027 A - By fax 6747-9402 only

FOR SURVEYOR

Please initial here after completion of pre-repair inspection. Thank you.

Appointed surveyor :
(Name & Signature) :

Date & Time of Inspection :

CONFIDENTIALITY

THE INFORMATION CONTAINED IN THESE DOCUMENTS MAY BE PRIVILEGED AND CONFIDENTIAL AND IS INTENDED FOR THE EXCLUSIVE USE OF THE ADDRESSEE DESIGNATED ABOVE. If you are not the addressee, any disclosure, reproduction, distribution or other dissemination or use of this communication is strictly prohibited. If you have received this transmission in error please contact us immediately by telephone so that we can arrange for its return.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	27/04/2018 16:47
Date Of Accident	25/04/2018 17:15
Exact Location Of Accident	PIE TWDS JURONG
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLT4027A
Insured/Policyholder	
Name Of Registered Owner	ST RENT & DRIVE PTE LTD
Co Reg No	20161537C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-64649098

Vehicle Particulars

Manufacturer	TOYOTA
Model	ALTIS
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	NO
Policy Number	5081178524-01
Cover Note Number	

Driver

Name of Driver	NUR'ATIQAHI'ZZAH BINTE ABDUL RAHMAN
NRIC No	S9047954G
Date Of Birth	16/12/1990
Occupation	OUTDOOR
Date Of Driving Pass	16/12/1990
Driving Experience	27 YEARS AND 4 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-91504266
Fax Number	
Contact Number	
Email Address	NOEMAIL

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

SGQ5238B

Vehicle Make/Model/Colour

Details Of Properties

VEHICLE C

Vehicle Category

PRIVATE CAR

Name of Driver

NRIC/Passport Number

Contact Number

Address


Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

(VEH A - 9T 4027A)

ON 25/04/2018 @ 5:14PM I WAS DRIVING ALONG PIE TOWARDS JURONG. I WAS ON STATIONARY ON THE EXTREME RIGHT LANE AND SUDDENLY VEH C - SG 5238B BEHIND OF VEH B - SH 8061D WHICH WAS ALSO STATIONARY AT THE TIME HIT VEH B - SH 8061D AND CAUSES A CHAIN COLLISION. VEH B - SH 8061D COLLIDED ONTO MY REAR PORTION. SG 5238B COULD NOT STOP IN TIME AND HIT SH 8061D. SH 8061D HIT MY REAR PORTION COLLIDED INTO MY CAR AND HIT MY REAR PORTION

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (if driver is not the policyholder)
 Date & Time:

27/4/18 @ 4.47pm
 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.:

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	5374C
Vehicle Details	
Vehicle No.:	SLT4027A
Vehicle to be Exported:	Yes
Intended De-registration Date:	30 Apr 2018
Vehicle Make:	TOYOTA
Vehicle Model:	COROLLA ALTIS 1.6 AUTO
Primary Colour:	Blue
Manufacturing Year:	2008
Engine No.:	3ZZ4761866
Chassis No.:	MR053ZEE106107523
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$16,777.00
Original Registration Date:	08 May 2008
First Registration Date:	08 May 2008
Transfer Count:	1
Actual ARF Paid:	\$16,777.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 May 2018
PARF Rebate Amount:	\$8,388.00
Intended COE Rebate Details	
COE Expiry Date:	07 May 2018
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,600.00
COE Rebate Amount:	\$29.00
Total Rebate Amount:	\$8,417.00

The information contained herein is correct as at 30 Apr 2018

OK

YI HENG MOTOR WORKSHOP

BLK 1, KAKI BUKIT AVENUE 6
 #02-19 SINGAPORE 417883
 TEL: 6 5090052 FAX: 6 7479402

30-04-18

OUR REF NO. SLT 4027A

ST RENT & DRIVE PTE LTD
 THE GRANDSTAND CARMALL
 210, TURFCLUB ROAD
 LOT A12/A27
 SINGAPORE 287995

*TP111
 Jance*

ESTIMATE BILL FOR VEHICLE NO. SLT 4027A
MODEL : TOYOTA ALTIS

LIST ITEM

1) REAR BUMPER	<i>red</i>		387.60	✓
2) REAR BUMPER SIDE ATTACHMENT	<i>me</i>	2 PCS @ \$ 43.20	86.40	✓
3) REAR BUMPER BRACKET	<i>Not New</i>		121.20	✗
4) REAR SPLASH SHIELD	<i>Ymea</i>	2 PCS @ \$ 74.00	148.00	✗
5) REAR SPLASH SHIELD CLIP		10 PCS @ \$ 8.90	89.00	✓
6) REAR END PANEL	<i>Repr</i>		581.00	✗

			1413.20	
LESS DISCOUNT - 25%			353.30	
				1059.90

*474
 355.50*

SPECIAL NETT ITEM

1) REVERSE SENSOR WITH CONTROL UNIT	<i>Byd</i>	200	350.00	<i>200</i>
				350.00

LABOUR CHARGE

1) TO CHECK WIRING SYSTEM			50.00	<i>30</i>
2) TO APPLY UNDER SEALING ON AFFECTED AREAS		570	120.00	✗
3) TO REMOVE AND REFIX TRIM, GARNISH, UPHOLSTERY			220.00	✗
4) TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT			120.00	<i>40</i>
5) TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC			800.00	<i>200</i>
6) TO RESPRAY ON THE AFFECTED AREAS			240.00	<i>300</i>
			1550.00	
GRAND TOTAL			<u>2959.90</u>	

total 1125.5

A/S: 500

*Adrian Lij
 L/S 02/05/18*

\$500

03 Apr 18

...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	04 May 2018 Edit Reg		30 Apr 2018 00:00 Edit Adj Rpt	S\$500.00 Edit Estimates	S\$500.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS				[Created by adjuster]					
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	ST RENT & DRIVE PTE LTD , Co. Reg. No.: 20161537C								
Vehicle Reg. No.:	SLT4027A	Date of Loss:	25/04/2018 17:00 - :59 [119 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18040717	Policy/Cover Note No.:	MCOM0016						
Vehicle Reg. No. (Insured):	SH8061D	Policy No. (Claimant):							
		Excess:							
Repairer:	Yi Heng Motor Workshop (HQ) Blk 1 Kaki Bt Ave 6 #02-19, 417883 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Zuhaidah Bte Samsuri - 6347 6070]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by ADRIAN LING] ... [Final Rpt due 14/05/2018]								
ASSOCIATED MAIL RECEIVED				View All Compose Case Mail					
There are no mail for this case.									
ALL ASSOCIATED TASKS				View All Search Tasks Create New Task Complete					
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLT4027A (MCT18040717)
[SH8061D]
TP
ST RENT & DRIVE PTE LTD
Apr 25 2018 5:00PM
[COMFORT TRANSPORTATION PTE LTD]
Yi Heng Motor Workshop**

Upload Documents | Upload Photos | Compose New Letter

View View in Browser ▾

Photos/Images			3 per page ▾	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	14/06/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
2	14/06/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
3	14/06/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
4	14/06/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
5	14/06/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
6	14/06/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
7	14/06/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
8	14/06/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
9	14/06/18 09:46	General View	Load JPG	<input checked="" type="checkbox"/>
10	14/06/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>
11	14/06/18 09:46	Reinspection Photo	Load JPG	<input checked="" type="checkbox"/>

Documentation			1 per page ▾	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	04/05/18 09:36	Singapore Accident Statement-IV	Load PDF	
2	14/06/18 14:54	Letter of Demand from Third Party VISION LAW LLC	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset | Save | Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: Handling Insurer
 Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/III18007994/ARBS2
Date: 21/06/2018

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0016
Claimant Vehicle No : SLT4027A **Insured Vehicle No :** SH8061D
 Date of Loss: 25/04/2018 Nature of Claim: TP Claim No: MCT18040717

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLT4027A**
 Make & Model: TOYOTA COROLLA ALTIS, 1.6 (A) Engine No: 3ZZ4761866
 Reg. Date: 08/05/2008 (Man. Year: 2008) Chassis No: MR053ZEE106107523
 Colour: Blue Odometer: 152636 km
 Engine Capacity: 1598 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Michelin 6 mm Rear Left Side: Michelin 6 mm
 Front Right Side: Michelin 6 mm Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,409.90	555.50	854.40	60.60
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,550.00	570.00	980.00	63.23
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,959.90	1,125.50	1,834.40	61.98
Approved Total (Overridden) (S\$)		500.00		
Nett Amount (S\$)	2,959.90	500.00	2,459.90	83.11

INSPECTION

Date of Assignment: 30/04/2018
 Date Inspected: 02/05/2018 Inspected At: Yi Heng Motor Workshop (HQ)
 Singapore 417883
 Estimated Period of Repair: 3.0 days

Adjuster: ADRIAN LING

Manager: Janice Lee Si Hua

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS**Reference**

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 21 Jun 2018)
Parts: 143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLT4027A)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER	Deformed	387.60 FL	*387.60 FL	
2	2		*REAR BUMPER SIDE ATTACHMENT	Necessary	86.40 FL	*86.40 FL	
3	1		*REAR BUMPER BRACKET	Not Necessary	121.20 FL	*- FL	
4	2		*REAR SPLASH SHIELD	Not Necessary	148.00 FL	*- FL	
5	10		*REAR SPLASH SHIELD CLIP	Not Necessary	89.00 FL	*- FL	
6	1		*REAR END PANEL	Repair	581.00 FL	*- FL	
7	1		*REVERSE SENSOR WITH CONTROL UNIT	Damaged	350.00 FS	*200.00 FS	
					Sub Total (S\$)	1,763.20	674.00
					- List Item Discount on L Items 25.00/25.00% (S\$)	353.30	118.50
					Total Parts (S\$)	1,409.90	555.50

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING SYSTEM.	New	50.00	30.00
2	TO APPLY UNDER SEALING ON AFFECTED AREAS.	New	120.00	0.00
3	TO REMOVE AND REFIX TRIM, GARNISH, UPHOLSTERY.	New	220.00	0.00
4	TO REMOVE AND REFIX REVERSE SENSOR WITH CONTROL UNIT.	New	120.00	40.00
5	TO REPLACE NEW PARTS, CUT, WELD, KNOCK ETC.	New	800.00	200.00
6	TO RESPRAY ON THE AFFECTED AREAS.	New	240.00	300.00
Gross Labour Cost (S\$)			1,550.00	570.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >