

INS. CASE OWNER:

Lynthia

CC 4/AXA1800

2998, UN6357

LKK:
IDAC:

Surveyor:

mary

DOI:

ASSIGNMENT

2/5/18

Date / Time:

2/5/18

Registered in Merimen:

4/5/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 50315

Name of Insured:

TRANS-UPS SERVICES PTE

Insured Tel No.:

HP:

Claim No.:

C0433398

Policy No.:

V7X/P1680500

Make / Model:

REPAIRIT

Place of Accident:

PTE TRANS LAMBI MERPAT

Excess Sec II :S\$

5000

D.O.A.:

2/4/18

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

KOH KIN HOLT

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SLN M774

INSRS:
WSP:
Tel:
Liability:
RMKS:

persons

INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:INSRS:
WSP:
Tel:
Liability:
RMKS:

Date/Time

9/5/18
LynthiaSLN M774 -
- M774.

SHC 50315 - 7

9/11/18

- SPOKE TO AXA XINYOU. HE SAID TO
SUBMIT WP REPORT. TP PERS LAWYER
- TO CLOSE CASE.

RECEIVED 08 NOV 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OE:

After call ltr to OE:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OE:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

8/5/18

Sent By:

me

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

10

S\$

4,600.00 (6 days) Reduction: 64 %

Email ☐ Call ☐

FINAL SETTLEMENT

Date/Time:

Confirm with

Email ☐ Call ☐

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 289

Repair Cost:

S\$

-

Loss of Rental (LOR):

S\$

-

(days)

Loss of Use (LOU):

S\$

-

(\$ x days)

Loss of Income (LOI):

S\$

-

(\$ x days)

LOR only ☐LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$

-

Medical:

S\$

-

Disbursement:

S\$

-

Legal Cost

S\$

-

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

WP REPORT

3) Survey fee:

\$250.00

Total:

S\$

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email ☐ Call ☐

Payee 1:

S\$

-

Name 1:

Payee 2: (Strike if N.A.)

S\$

-

Name 2:

Payee 3: (Strike if N.A.)

S\$

-

Name 3:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SKN 22574at Workshop m/s Negesus

of _____

Insured: SK/C 50315

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 70k.

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: e Consistent?: Yes or NoEst. Repairs: 6 days Res.: Yes or NoLum Sum: 10 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No: SKN 22574 Yr Regn: 4, 17Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: mazda 3 C.C. 1496Colour: (grey) A/C: Insured / Std / NI / NASp. Reading: 65686 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BN22A8H015088PGen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or otherBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 205/60 R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FalkenFront 7 mm Rear 7 mmR/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 27/4/18 D.O.I. 2/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooktop or

o/s R/d

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction AXA 53665next 1033546 & 6,000.00CRUD: 48,015.40 (54%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS, \$ _____

Photos _____

Others _____

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/AXA18007998/Uwb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811			Date : 02-05-2018	
			Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 5031S	Veh. Inspected	SLN 2257Y	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	27/04/2018	Inspection Date	02/05/2018	
Survey held at	PEGASUS ENGINEERING & TRADING PTE LTD 51 DEFU LANE 10 SINGAPORE 539216			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		04 May 2018 17:01 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS									
[Created by insurer]									
Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K, Email: CLAIMS@TRANSCAB.COM.SG								
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G								
Vehicle Reg. No.:	SLN2257Y	Date of Loss:	27/04/2018 22:00 - :59						
Claim Type:	TP / C0473398	Policy/Cover Note No.:	P1680520 (Third Party Only)						
Vehicle Reg. No. (Insured):	SHC5031S	Policy No. (Claimant):							
		Excess:	S\$5,000.00						
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846								
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Cynthia Loh - 68804843]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/05/2018]								
Driver/Custodian (Insured):	KOH KIN HOCK (), NRIC: S1569636B, Tel: +6586933117								
ASSOCIATED MAIL RECEIVED									
There are no mail for this case.									
View All Compose Case Mail									
ALL ASSOCIATED TASKS									
View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

07052018 @ 10:46am

Alvin vth in

marcus.

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

not Authorised
2/5 \$6600?
6dy.
Uik 2/5/18
The file file

Quotation No : QO18/04-1338	Quotation Date : 30/04/2018	Terms : 30 DAYS
Vehicle No : SLN2257Y	Chassis No : JM6BN22A8H0150989	Third Party Insurer :
Model : MAZDA 3		Date of Accident :
Remarks : TP INSURER: AXA, INSURED'S VEH NO: SHC5031S, DATE OF ACCIDENT: 27.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
1	BONNET RUBBER STOPPER 11	2	12.0000	24.00 X
2	BONNET OUTER WEATHERSTRIP 11	1	64.0000	64.00 X
3	BONNET INNER WEATHERSTRIP 11	1	26.0000	26.00 X
4	BONNET LOCK 11	1	198.0000	198.00 X
5	BONNET LOCK CABLE 11	1	53.0000	53.00 X
6	BONNET LOCK COVER 11	1	11.0000	11.00 X
7	BONNET LOCK STAY 11	1	39.0000	39.00 X
8	FRONT SUPPORT PANEL - METAL 11	1	140.0000	140.00 X
9	FRONT SUPPORT PANEL - FIBRE 11	1	470.0000	470.00 X
10	O/S HEAD LAMP ASSY 11	1	1,020.0000	1,020.00 —
11	FRONT BUMPER 11	1	825.0000	825.00 —
12	FRONT BUMPER REINFORCEMENT 11	1	480.0000	480.00 —
13	FRONT BUMPER REINFORCEMENT COVER 11	1	67.0000	67.00 X
14	FRONT BUMPER REINFORCEMENT COVER CLIPS 11	4	5.0000	20.00 X
15	O/S FRONT BUMPER AIR GUIDE 11	1	32.0000	32.00 —
16	FRONT BUMPER AIR GUIDE CLIPS 11	4	5.0000	20.00 —
17	O/S FRONT BUMPER INDICATION LIGHT 11	1	140.0000	140.00 —
18	O/S FRONT BUMPER INDICATION LIGHT GARNISH 11	1	38.0000	38.00 —
19	O/S FRONT BUMPER INDICATION LIGHT GARNISH EXTENSION 11	1	20.0000	20.00 X
20	FRONT BUMPER LOWER SPLASHIELD COVER 11	1	95.0000	95.00 —
21	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS 11	10	5.0000	50.00 —
22	O/S FRONT BUMPER CENTRE AIR GRILLE SIDE COVER 11	1	35.0000	35.00 X
23	FRONT BUMPER INDICATION LIGHT INNER HOLDER BRACKET 11	1	18.0000	18.00 X

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : WEE TZE FAH Tel : Email :

Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

Quotation No : QO18/04-1338	Quotation Date : 30/04/2018	Terms : 30 DAYS
Vehicle No : SLN2257Y	Chassis No : JM6BN22A8H0150989	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AXA, INSURED'S VEH NO: SHC5031S, DATE OF ACCIDENT: 27.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)	
				B/F	0.00
24	FRONT BUMPER TOW COVER	1 <i>11</i>	14.0000	14.00	X
25	FRONT BUMPER SIDE RETAINER <i>0/3</i>	1 <i>one</i>	19.0000	19.00	/
26	FRONT BUMPER LOWER SUPPORT GARNISH	1 <i>11</i>	96.0000	96.00	X
27	O/S FRONT FENDER	1 <i>3uc</i>	334.0000	334.00	/
28	O/S FRONT FENDER INNER WHEEL HOUSE PANEL	1 <i>R</i>	550.0000	X 550.00	X
29	O/S FRONT FENDER INNER COWLING	1 <i>7.11</i>	130.0000	130.00	/
30	O/S FRONT FENDER INNER COWLING CLIPS	6 <i>2u</i>	5.0000	30.00	/
31	O/S FRONT FENDER INSULATION FOAM	1 <i>11</i>	36.0000	36.00	X
32	O/S FRONT FENDER STAY BRACKET	1 <i>3uc</i>	40.0000	40.00	/
33	O/S FRONT FENDER TOP GARNISH	1 <i>7.11</i>	46.0000	46.00	/
34	O/S FRONT FENDER TOP GARNISH CLIPS	3 <i>2u</i>	5.0000	15.00	/
35	AIR CLEANER TANK	1 <i>11</i>	156.0000	156.00	X
36	AIR RESONATOR TANK	1 <i>11</i>	71.0000	71.00	X
37	AIR CLEANER INTAKE DUCT	1 <i>11</i>	93.0000	93.00	X
38	FUSE BOX ASSY	1 <i>11</i>	479.0000	479.00	X
39	WINDSHIELD WASHER TANK	1 <i>0.5</i>	105.0000	105.00	2
40	O/S ENGINE MOUNTING	1 <i>11</i>	402.0000	402.00	X
41	ENGINE MOUNTING REAR	1 <i>11</i>	315.0000	315.00	X
42	O/S GEARBOX MOUNTING	1 <i>11</i>	335.0000	335.00	X
43	ENGINE SUSPENSION CROSS MEMBER	1 <i>2/bul</i>	1,791.0000	1,791.00	X
44	ENGINE SUSPENSION CROSS MEMBER BRACKET	2 <i>11</i>	59.0000	118.00	X
45	FRONT WHEEL HUB CAP	1 <i>3uc</i>	120.0000	120.00	/

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/04-1338	Quotation Date : 30/04/2018	Terms : 30 DAYS
Vehicle No : SLN2257Y	Chassis No : JM6BN22A8H0150989	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AXA, INSURED'S VEH NO: SHC5031S, DATE OF ACCIDENT: 27.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
46	O/S FRONT SHOCK ABSORBER	1 <i>Sub</i>	287.0000	287.00 <i>2</i>
47	FRONT SHOCK ABSORBER TOP MOUNT	1 <i>11</i>	92.0000	92.00 <i>X</i>
48	FRONT LOWER ARM	1 <i>Sub</i>	485.0000	485.00 <i>2</i>
49	FRONT WHEEL KNUCKLE	1 <i>Sub</i>	384.0000	384.00 <i>2</i>
50	FRONT WHEEL BEARING WITH HUB	1 <i>Sub</i>	542.0000	542.00 <i>2</i>
51	FRONT WHEEL ABS SENSOR	2 <i>11</i>	133.0000	266.00 <i>X</i>
52	FRONT STABILISER BAR LINK	2 <i>11</i>	65.0000	130.00 <i>X</i>
53	O/S ENGINE SIDE SPLASHIELD COVER	1 <i>11</i>	19.0000	19.00 <i>X</i>
54	ENGINE LOWER SPLASHIELD COVER	1 <i>Repair</i>	287.0000	287.00 <i>-</i>
55	STEERING RAD ASSY	1 <i>Sub</i>	916.0000	916.00 <i>X</i>
56	LESS 20% (ITEM 1 - 55)	1	-2,517.6000	-2,517.60
57	O/S FRONT WHEEL RIM	1 <i>DD</i>	600.0000	600.00 <i>100</i>
58	O/S FRONT WHEEL HUB CAP	1 <i>Repair</i>	65.0000	65.00 <i>X</i>
59	TOWING CHARGES	1	100.0000	100.00 <i>50</i>
60	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	80.0000	80.00 <i>20</i>
61	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	150.0000	150.00 <i>60</i>
62	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING	1	480.0000	480.00 <i>350</i>
63	TO TRANSFER OF TYRE, RIM AND ON WHEEL BALANCING	1	50.0000	50.00 <i>11 X</i>
64	TO RUST-PROOFING OF THE AFFECTED AREAS	1	220.0000	220.00 <i>50</i>
65	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	200.0000	200.00 <i>11 X</i>

C/F 0.00
Page 3 of 4

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/04-1338	Quotation Date : 30/04/2018	Terms : 30 DAYS
Vehicle No : SLN2257Y	Chassis No : JM6BN22A8H0150989	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AXA, INSURED'S VEH NO: SHC5031S, DATE OF ACCIDENT: 27.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
66	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,500.0000	800 1,500.00
67	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,100.0000	1000 1,100.00
				2330

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

P-7315
20%
5852
S.N - 100
1600 - 2330
8282
6625

Sub Total	14,615.40
GST(7.00%)	1,023.08
Total (SGD)	15,638.48

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :
PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :
GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

Quotation No : QO18/04-1338	Quotation Date : 30/04/2018	Terms : 30 DAYS
Vehicle No : SLN2257Y	Chassis No : JM6BN22A8H0150989	Third Party Insurer :
Model : MAZDA 3		Date of Accident :

Remarks : TP INSURER: AXA, INSURED'S VEH NO: SHC5031S, DATE OF ACCIDENT: 27.04.2018

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)	
1	BONNET RUBBER STOPPER 11	2	12.0000	24.00	X
2	BONNET OUTER WEATHERSTRIP 11	1	64.0000	64.00	X
3	BONNET INNER WEATHERSTRIP 11	1	26.0000	26.00	X
4	BONNET LOCK 11	1	198.0000	198.00	X
5	BONNET LOCK CABLE 11	1	53.0000	53.00	X
6	BONNET LOCK COVER 11	1	11.0000	11.00	X
7	BONNET LOCK STAY 11	1	39.0000	39.00	X
8	FRONT SUPPORT PANEL - METAL	1	140.0000	140.00	X
9	FRONT SUPPORT PANEL - FIBRE	1	470.0000	470.00	?
10	O/S HEAD LAMP ASSY BRO	1	1,020.0000	1,020.00	—
11	FRONT BUMPER 11	1	825.0000	825.00	—
12	FRONT BUMPER REINFORCEMENT 11	1	480.0000	480.00	—
13	FRONT BUMPER REINFORCEMENT COVER 11	1	67.0000	67.00	X
14	FRONT BUMPER REINFORCEMENT COVER CLIPS 11	4	5.0000	20.00	X
15	O/S FRONT BUMPER AIR GUIDE To.1	1	32.0000	32.00	—
16	FRONT BUMPER AIR GUIDE CLIPS 11	4	5.0000	20.00	—
17	O/S FRONT BUMPER INDICATION LIGHT 11	1	140.0000	140.00	—
18	O/S FRONT BUMPER INDICATION LIGHT GARNISH To.1	1	38.0000	38.00	—
19	O/S FRONT BUMPER INDICATION LIGHT GARNISH EXTENSION 11	1	20.0000	20.00	X
20	FRONT BUMPER LOWER SPLASHIELD COVER To.1	1	95.0000	95.00	—
21	FRONT BUMPER LOWER SPLASHIELD COVER CLIPS 11	10	5.0000	50.00	—
22	O/S FRONT BUMPER CENTRE AIR GRILLE SIDE COVER	1	35.0000	35.00	?
23	FRONT BUMPER INDICATION LIGHT INNER HOLDER BRACKET	1	18.0000	18.00	?

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : WEE TZE FAH Tel : Email :

Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :

Quotation No : QO18/04-1338	Quotation Date : 30/04/2018	Terms : 30 DAYS
Vehicle No : SLN2257Y	Chassis No : JM6BN22A8H0150989	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AXA, INSURED'S VEH NO: SHC5031S, DATE OF ACCIDENT: 27.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
24	FRONT BUMPER TOW COVER	1 <i>11</i>	14.0000	14.00 <i>X</i>
25	FRONT BUMPER SIDE RETAINER <i>o/s</i>	1 <i>one</i>	19.0000	19.00 <i>/</i>
26	FRONT BUMPER LOWER SUPPORT GARNISH	1	96.0000	96.00 <i>?</i>
27	O/S FRONT FENDER	1 <i>34c</i>	334.0000	334.00 <i>/</i>
28	O/S FRONT FENDER INNER WHEEL HOUSE PANEL	1 <i>1</i>	550.0000	550.00 <i>?</i>
29	O/S FRONT FENDER INNER COWLING	1 <i>7.11</i>	130.0000	130.00 <i>/</i>
30	O/S FRONT FENDER INNER COWLING CLIPS	6 <i>24</i>	5.0000	30.00 <i>/</i>
31	O/S FRONT FENDER INSULATION FOAM	1 <i>11</i>	36.0000	36.00 <i>X</i>
32	O/S FRONT FENDER STAY BRACKET	1 <i>344</i>	40.0000	40.00 <i>/</i>
33	O/S FRONT FENDER TOP GARNISH	1 <i>7.11</i>	46.0000	46.00 <i>/</i>
34	O/S FRONT FENDER TOP GARNISH CLIPS	3 <i>24</i>	5.0000	15.00 <i>/</i>
35	AIR CLEANER TANK	1 <i>2.3</i>	156.0000	156.00 <i>/</i>
36	AIR RESONATOR TANK	1	71.0000	71.00 <i>?</i>
37	AIR CLEANER INTAKE DUCT	1	93.0000	93.00 <i>?</i>
38	FUSE BOX ASSY	1 <i>11</i>	479.0000	479.00 <i>X</i>
39	WINDSHIELD WASHER TANK	1	105.0000	105.00 <i>?</i>
40	O/S ENGINE MOUNTING	1	402.0000	402.00 <i>?</i>
41	ENGINE MOUNTING REAR	1	315.0000	315.00 <i>?</i>
42	O/S GEARBOX MOUNTING	1	335.0000	335.00 <i>?</i>
43	ENGINE SUSPENSION CROSS MEMBER	1	1,791.0000	1,791.00 <i>?</i>
44	ENGINE SUSPENSION CROSS MEMBER BRACKET	2	59.0000	118.00 <i>?</i>
45	FRONT WHEEL HUB CAP	1 <i>344</i>	120.0000	120.00 <i>/</i>

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From : PEGASUS ENGINEERING & TRADING PTE LTD C/O 51 DEFU LANE 10 SINGAPORE 539216 Officer in Charge : WEE TZE FAH Tel : Email :	Customer : GRAB RENTALS PTE LTD 18 SIN MING LANE #01-08 MIDVIEW CITY SINGAPORE 573960 Attn : Tel : Fax :
---	---

Quotation No : QO18/04-1338	Quotation Date : 30/04/2018	Terms : 30 DAYS
Vehicle No : SLN2257Y	Chassis No : JM6BN22A8H0150989	Third Party Insurer :
Model : MAZDA 3	Date of Accident :	
Remarks : TP INSURER: AXA, INSURED'S VEH NO: SHC5031S, DATE OF ACCIDENT: 27.04.2018		

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
			B/F	0.00
46	O/S FRONT SHOCK ABSORBER	1	287.0000	287.00 ?
47	FRONT SHOCK ABSORBER TOP MOUNT	1	92.0000	92.00 ?
48	FRONT LOWER ARM	1	485.0000	485.00 ?
49	FRONT WHEEL KNUCKLE	1	384.0000	384.00 ?
50	FRONT WHEEL BEARING WITH HUB	1	542.0000	542.00 ?
51	FRONT WHEEL ABS SENSOR	2	133.0000	266.00 ?
52	FRONT STABILISER BAR LINK	2	65.0000	130.00 ?
53	O/S ENGINE SIDE SPLASHIELD COVER	1	19.0000	19.00 ?
54	ENGINE LOWER SPLASHIELD COVER	1 <i>Repair</i>	287.0000	287.00 ✓
55	STEERING RAD ASSY	1	916.0000	916.00 ?
56	LESS 20% (ITEM 1 - 55)	1	-2,517.6000	-2,517.60
57	O/S FRONT WHEEL RIM	1 <i>DD</i>	600.0000	600.00 100
58	O/S FRONT WHEEL HUB CAP	1 <i>Repair</i>	65.0000	65.00 X
59	TOWING CHARGES	1	100.0000	50 100.00 S
60	TO CHECK ELECTRICAL LIGHTING CONCERNED	1	80.0000	20 80.00
61	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	1	150.0000	? < 150.00
62	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING	1	480.0000	480.00
63	TO TRANSFER OF TYRE, RIM AND ON WHEEL BALANCING	1	50.0000	1 X 50.00
64	TO RUST-PROOFING OF THE AFFECTED AREAS	1	220.0000	50 220.00
65	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR	1	200.0000	11 X 200.00

C/F 0.00

PEGASUS ENGINEERING & TRADING PTE LTD

GST / ROC COMPANY NO : 201101753C

Quotation

From :

PEGASUS ENGINEERING & TRADING PTE LTD
C/O 51 DEFU LANE 10
SINGAPORE 539216

Officer in Charge : WEE TZE FAH
Tel :
Email :

Customer :

GRAB RENTALS PTE LTD
18 SIN MING LANE
#01-08 MIDVIEW CITY
SINGAPORE 573960

Attn :
Tel :
Fax :

Quotation No : QO18/04-1338

Quotation Date : 30/04/2018

Terms : 30 DAYS

Vehicle No : SLN2257Y

Chassis No : JM6BN22A8H0150989

Third Party Insurer :

Model : MAZDA 3

Date of Accident :

Remarks : TP INSURER: AXA, INSURED'S VEH NO: SHC5031S, DATE OF ACCIDENT: 27.04.2018

ITEM	DESCRIPTION	QTY	UNIT PRICE	AMOUNT (SGD)
				B/F 0.00
66	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL OF PARTS, ADJUST AND REALIGN THE SAME	1	1,500.0000	for 1,500.00
67	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	1	1,100.0000	1000 1,100.00

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Sub Total	14,615.40
GST(7.00%)	1,023.08
Total (SGD)	15,638.48

Please conduct the survey at
Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	28/04/2018 18:23
Date Of Accident	27/04/2018 22:20
Exact Location Of Accident	PIE TOWARDS CHANGI AIRPORT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLN2257Y
Insured/Policyholder	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-66550005

Vehicle Particulars

Manufacturer	MAZDA
Model	3-1.5 4 DOOR SEDAN SP (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE

Insurance Company

Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	YES
Policy Number	A29069766MKF
Cover Note Number	01/02/2018 TO 31/01/2019

Driver

Name of Driver	NUR HABIBAH ADAWIYAH BINTE MD HANAPI
NRIC No	S8036348F
Date Of Birth	14/11/1980
Occupation	OUTDOOR
Date Of Driving Pass	27/07/2007
Driving Experience	10 YEARS AND 9 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-98449042
Fax Number	
Contact Number	
EMail Address	NHADAWIYAH@GMAIL.COM

Address	BLOCK 690A WOODLANDS DRIVE 75 #06-152
Postcode	731690
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	3
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : GRAB PASSENGER - UNKNOWN GENDER: : MALE
Passenger 2	NAME: : GRAB PASSENGER - UNKNOWN GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

Refer to sketch plan

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC5031S
Vehicle Make/Model/Colour	RENAULT LATITUDE, RED COLOUR
Details Of Properties	TRANSCAB
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	

Insurance Company Name	AXA INSURANCE PTE LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number	SJE9415H
Vehicle Make/Model/Colour	HYUNDAI
Details Of Properties	SALOON CAR
Vehicle Category	PRIVATE CAR
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder)
Date & Time: 29/4/2018 (11:22am)

Reporting Centre Personnel's Signature
Name: Tan A' Lan
NRIC/FIN No: S7236702A

Sketch Plan Pg. 2

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 27/04/2018 @ 2220 hrs, I was driving along PIE towards Changi Airport direction on the 2nd lane from the right. The traffic was smooth on my lane. Suddenly, a taxi (B: SJC 5031 S) traveling on the 1st lane (on my right) suddenly swerved out to my lane. I quickly sound my horn but to no avail. The taxi collided onto the right front portion of my car. I alighted and realised the taxi had also hit onto another vehicle (SJE 9415 H).

I have 2 passengers in my car (1 male, 1 female). The other 2 vehicles have 1 passenger each.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time:

Driver's Signature

(If driver is not the policyholder)

Date & Time: 28/04/2018

Reporting Centre Personnel's Signature

Name: Tan A'lan

NRIC/FIN No.: S723674

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		04 May 2018 17:01 Edit Adj Rpt	S\$6,600.00 Edit Estimates	S\$6,600.00 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K, Email: CLAIMS@TRANSCAB.COM.SG		
Main Claimant:	GRAB RENTALS PTE LTD, Co. Reg. No.: 201617200G		
Vehicle Reg. No.:	SLN2257Y	Date of Loss:	27/04/2018 22:00 - :59 [12 Months and 1 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0473398	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHC5031S	Policy No. (Claimant):	A29069766MKF
		Excess:	S\$5,000.00
Repairer:	Pegasus Engineering & Trading Pte Ltd (HQ) 51 DEFU LANE 10, 539216 Defu Lane - Tel: 68581846		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Chen Xinyou - 6880 4269]		
Claimant's Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/05/2018]		
Driver/Custodian (Insured):	KOH KIN HOCK (), NRIC: S1569636B, Tel: +6586933117		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (30/10/2018): Re: Pls submit Final Report
- AXA_SG (28/08/2018): Pls submit Final Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SLN2257Y (C0473398)**
[SHC5031S]
TP
GRAB RENTALS PTE LTD
Apr 27 2018 10:00PM
[TRANS-CAB SERVICES PTE LTD]
Pegasus Engineering & Trading Pte Ltd

Upload Documents	Upload Photos	Compose New Letter	Upload Video	Upload Audio	View	View in Browser
------------------	---------------	--------------------	--------------	--------------	------	-----------------

Letters/Correspondences				1 per page	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	16/05/18 10:23	Reminder to LKK to obtain TP video footage (refer to mail dd 02.05.18)	1	Load TIF	

Photos/Images				3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/11/18 15:42	LKK INSPECTION PHOTOS	1	Load PDF	
2	07/11/18 15:42	LKK REINSPECTION PHOTOS	1	Load PDF	

Documentation				1 per page	☒
No	Finalized On	AXA Insurance Pte Ltd (HQ)		Thumbnail	Print
1	02/05/18 08:43	EMAIL_ABS	1	Load PDF	
2	02/05/18 08:43	SHC5031S INSD GIA_ABS	1	Load PDF	
3	02/05/18 08:43	SJE9415H GIA REPORT_ABS	1	Load PDF	
4	02/05/18 08:43	SLN2257Y ESTIMATE & TP GIA_ABS	1	Load PDF	
5	02/05/18 08:46	EMAIL TO WORKSHOP (LIST OF SURVEYOUR)_ABS	1	Load PDF	
6	02/05/18 09:44	E-filed GIA report - TP SLN2257Y	1	Load PDF	

No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print
1	07/05/18 18:37	TP ESTIMATE- MARKED	1	Load PDF	
2	08/05/18 19:21	Immediate Advice	1	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

[Reset](#) [Save](#) [Print](#)

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18007998/UHB3S2
Date: 28/11/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1680520
Claimant Vehicle No : SLN2257Y **Insured Vehicle No :** SHC5031S
 Date of Loss: 27/04/2018 Nature of Claim: TP Claim No: C0473398

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLN2257Y**
 Make & Model: MAZDA 3, 1.5 (A) Engine No: P520442230
 Reg. Date: 26/04/2017 (Man. Year: 2017) Chassis No: JM6BN22A8H0150989
 Colour: Grey Odometer: 65686 km
 Engine Capacity: 1496 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60R16 Rear Tyre Size: 205/60R16
 Front Left Side: Falken 7 mm Rear Left Side: Falken 7 mm
 Front Right Side: Falken 7 mm Rear Right Side: Falken 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,735.40	5,952.00	4,783.40	44.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,880.00	2,330.00	1,550.00	39.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,615.40	8,282.00	6,333.40	43.33
Approved Total (Overridden) (S\$)		6,600.00		
(S\$)	14,615.40	6,600.00	8,015.40	54.84
+ GST 7.00/7.00% (S\$)	1,023.08	462.00	561.08	54.84
Nett Amount (S\$)	15,638.48	7,062.00	8,576.48	54.84

INSPECTION

Date of Assignment: 04/05/2018
 Date Inspected: 02/05/2018 Inspected At: Pegasus Engineering & Trading Pte Ltd (HQ)
 51 DEFU LANE 10
 Singapore 539216
 Estimated Period of Repair: 6.0 days

Adjuster: MARCUS CHUA**Manager:** VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=gen_printprt&caseid=704856&extid=271517&CFID=44496413&C... 1/5

any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Nov 2018)
Parts:	144	MAZDA 3 1.5 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLN2257Y)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	2		*BONNET RUBBER STOPPER (CONSISTENT)	Not Necessary	24.00 FL	*- FL
2	1		*BONNET OUTER WEATHERSTRIP (CONSISTENT)	Not Necessary	64.00 FL	*- FL
3	1		*BONNET INNER WEATHERSTRIP (CONSISTENT)	Not Necessary	26.00 FL	*- FL
4	1		*BONNET LOCK (CONSISTENT)	Not Necessary	198.00 FL	*- FL
5	1		*BONNET LOCK CABLE (CONSISTENT)	Not Necessary	53.00 FL	*- FL
6	1		*BONNET LOCK COVER (CONSISTENT)	Not Necessary	11.00 FL	*- FL
7	1		*BONNET LOCK STAY (CONSISTENT)	Not Necessary	39.00 FL	*- FL
8	1		*FRONT SUPPORT PANEL - METAL (CONSISTENT)	Not Necessary	140.00 FL	*- FL
9	1		*FRONT SUPPORT PANEL - FIBRE (CONSISTENT)	Repair	470.00 FL	*- FL
10	1		*O/S HEAD LAMP ASSY (CONSISTENT)	Broken	1,020.00 FL	*1,020.00 FL
11	1		*FRONT BUMPER (CONSISTENT)	Distorted	825.00 FL	*825.00 FL
12	1		*FRONT BUMPER REINFORCEMENT (CONSISTENT)	Bent	480.00 FL	*480.00 FL
13	1		*FRONT BUMPER REINFORCEMENT COVER (CONSISTENT)	Not Necessary	67.00 FL	*- FL
14	4		*FRONT BUMPER REINFORCEMENT COVER CLIPS (CONSISTENT)	Not Necessary	20.00 FL	*- FL
15	1		*O/S FRONT BUMPER AIR GUIDE (CONSISTENT)	Torn	32.00 FL	*32.00 FL
16	4		*FRONT BUMPER AIR GUIDE CLIPS (CONSISTENT)	Necessary	20.00 FL	*20.00 FL
17	1		*O/S FRONT BUMPER INDICATION LIGHT (CONSISTENT)	Cracked	140.00 FL	*140.00 FL
18	1		*O/S FRONT BUMPER INDICATION LIGHT GARNISH (CONSISTENT)	Torn	38.00 FL	*38.00 FL
19	1		*O/S FRONT BUMPER INDICATION LIGHT GARNISH EXTENSION (CONSISTENT)	Not Necessary	20.00 FL	*- FL
20	1		*FRONT BUMPER LOWER SPLASHIELD COVER (CONSISTENT)	Torn	95.00 FL	*95.00 FL
21	10		*FRONT BUMPER LOWER SPLASHIELD COVER CLIPS (CONSISTENT)	Necessary	50.00 FL	*50.00 FL
22	1		*O/S FRONT BUMPER CENTRE AIR GRILLE SIDE COVER (CONSISTENT)	Not Necessary	35.00 FL	*- FL
23	1		*FRONT BUMPER INDICATION LIGHT INNER HOLDER BRACKET (CONSISTENT)	Not Necessary	18.00 FL	*- FL
24	1		*FRONT BUMPER TOW COVER (CONSISTENT)	Not Necessary	14.00 FL	*- FL
25	1		*FRONT BUMPER SIDE RETAINER O/S (CONSISTENT)	Cracked	19.00 FL	*19.00 FL
26	1		*FRONT BUMPER LOWER SUPPORT GARNISH (CONSISTENT)	Not Necessary	96.00 FL	*- FL
27	1		*O/S FRONT FENDER (CONSISTENT)	Buckled	334.00 FL	*334.00 FL
28	1		*O/S FRONT FENDER INNER WHEEL HOUSE PANEL (CONSISTENT)	Repair	550.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
29	1		*O/S FRONT FENDER INNER COWLING (CONSISTENT)	Torn	130.00 FL	*130.00 FL
30	6		*O/S FRONT FENDER INNER COWLING CLIPS (CONSISTENT)	Necessary	30.00 FL	*30.00 FL
31	1		*O/S FRONT FENDER INSULATION FOAM (CONSISTENT)	Not Necessary	36.00 FL	*- FL
32	1		*O/S FRONT FENDER STAY BRACKET (CONSISTENT)	Bent	40.00 FL	*40.00 FL
33	1		*O/S FRONT FENDER TOP GARNISH (CONSISTENT)	Twisted	46.00 FL	*46.00 FL
34	3		*O/S FRONT FENDER TOP GARNISH CLIPS (CONSISTENT)	Necessary	15.00 FL	*15.00 FL
35	1		*AIR CLEANER TANK (CONSISTENT)	Not Necessary	156.00 FL	*- FL
36	1		*AIR RESONATOR TANK (CONSISTENT)	Not Necessary	71.00 FL	*- FL
37	1		*AIR CLEANER INTAKE DUCT (CONSISTENT)	Not Necessary	93.00 FL	*- FL
38	1		*FUSE BOX ASSY (CONSISTENT)	Not Necessary	479.00 FL	*- FL
39	1		*WINDSHIELD TANK (CONSISTENT)	Distorted	105.00 FL	*105.00 FL
40	1		*O/S ENGINE MOUNTING (CONSISTENT)	Not Necessary	402.00 FL	*- FL
41	1		*ENGINE MOUNTING REAR (CONSISTENT)	Not Necessary	315.00 FL	*- FL
42	1		*O/S GEARBOX MOUNTING (CONSISTENT)	Not Necessary	335.00 FL	*- FL
43	1		*ENGINE SUSPENSION CROSS MEMBER (CONSISTENT)	Dented / Bent	1,791.00 FL	*1,791.00 FL
44	2		*ENGINE SUSPENSION CROSS MEMBER BRACKET (CONSISTENT)	Not Necessary	118.00 FL	*- FL
45	1		*FRONT WHEEL HUB CAP (CONSISTENT)	Bent	120.00 FL	*120.00 FL
46	1		*O/S FRONT SHOCK ABSORBER (CONSISTENT)	Bent	287.00 FL	*287.00 FL
47	1		*FRONT SHOCK ABSORBER TOP MOUNT (CONSISTENT)	Not Necessary	92.00 FL	*- FL
48	1		*FRONT LOWER ARM (CONSISTENT)	Buckled	485.00 FL	*485.00 FL
49	1		*FRONT WHEEL KNUCKLE (CONSISTENT)	Bent	384.00 FL	*384.00 FL
50	1		*FRONT WHEEL BEARING WITH HUB (CONSISTENT)	Necessary	542.00 FL	*542.00 FL
51	2		*FRONT WHEEL ABS SENSOR (CONSISTENT)	Not Necessary	266.00 FL	*- FL
52	2		*FRONT STABILIZER BAR LINK (CONSISTENT)	Not Necessary	130.00 FL	*- FL
53	1		*O/S ENGINE SIDE SPLASHIELD COVER (CONSISTENT)	Not Necessary	19.00 FL	*- FL
54	1		*ENGINE LOWER SPLASHIELD COVER (CONSISTENT)	Damaged	287.00 FL	*287.00 FL
55	1		*STEERING RAD ASSY (CONSISTENT)	Serviceable	916.00 FL	*- FL
56	1		*O/S FRONT WHEEL RIM (CONSISTENT)	Dented	600.00 FS	*100.00 FS
57	1		*O/S FRONT WHEEL HUB CAP (CONSISTENT)	Repeated	65.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,253.00	7,415.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,517.60	1,463.00
Total Parts (\$\$)	10,735.40	5,952.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING CHARGES.	New	100.00	50.00
2	TO CHECK ELECTRICAL LIGHTING CONCERNED.	New	80.00	20.00
3	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	New	150.00	60.00
4	TO DROP FRONT SUSPENSION UNDERCARRIAGE PARTS, REMOVE AND RENEWAL OF THE NECESSARY PARTS, TO PERFORM FINAL CHECKING AND TESTING.	New	480.00	350.00
5	TO TRANSFER OF TYRE, RIM AND ON WHEEL BALANCING.	New	50.00	0.00
6	TO RUST-PROOFING OF THE AFFECTED AREAS.	New	220.00	50.00
7	TO REMOVE AND REFIT INTERIOR FITTINGS, TRIMMINGS, GARNISH AND OTHER, TO ENABLE REPAIR.	New	200.00	0.00
8	PANEL BEATING, KNOCKING AND STRAIGHTEN THE NECESSARY PORTION, REMOVE AND RENEWAL F PARTS, ADJUST AND REALIGN THE SAME.	New	1,500.00	800.00
9	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.	New	1,100.00	1,000.00
Gross Labour Cost (S\$)			3,880.00	2,330.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >