

INS. CASE OWNER:

CC 6 / AIG1800

LAA:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

HP:

Excess Sec II :SS

D.O.A.:

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Driver Tel No.:

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

3-5-18 @ 230, CALLED - NO ANSW.
4-6-18 @ 253 W/ OI MR. WONG
CONFIRMED ACC.
AGREED & AWARE
NCD ISSUE.

RECEIVED 27 JUL 2018

PRELIMINARY ADVICE		Date/Time:	Sent By:	Confirm with:	Confirm by:
FINALIZATION		Date/Time:	Confirm with:	Confirm by:	
Repair Cost:	S\$	(days)	Reduction:	%	Email <input type="checkbox"/> Call <input type="checkbox"/>
FINAL SETTLEMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Final Liability:	%	100	(Agreed / Assessed) BOLA S/N No.:	910	If NO or B 28, Ass. Lia:
Repair Cost:	S\$	4,066			
Loss of Rental (LOR):	S\$	4.00	(4 days)	100	
Loss of Use (LOU):	S\$	—	(\$ x days)		
Loss of Income (LOI):	S\$	—	(\$ x days)		
LOR only <input type="checkbox"/> LOU only <input type="checkbox"/>	LOR + LOU <input type="checkbox"/> LOR + LOI <input type="checkbox"/>	[Tick only one]			
GIA/LTA Search	S\$	2.00			
Medical:	S\$	—			
Disbursement:	S\$	—	(e.g. Tow/ Independent)		
Legal Cost	S\$	4,468			
Total:	S\$	4,468	Global Sum S\$:		
FINAL PAYMENT		Date/Time:	Confirm with:	Email <input type="checkbox"/> Call <input type="checkbox"/>	
Payee 1:	S\$	4,468	Name 1:	HOCK WAH MOTOR WORKSHOP PTE LTD	
Payee 2: (Strike if N.A.)	S\$	X	Name 2:	X	
Payee 3: (Strike if N.A.)	S\$	X	Name 3:	X	

10/8/11/13) wef

ASS. REC. BY: Marcus

REF:

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: Sam 5694Mat Workshop m/s hockanah

of _____

Insured: GAB 537H

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 22

ID/C Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: 4 Consistent? : Yes or NoEst. Repairs: 4 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: Sam 5694M Yr Regn: 10.06

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA 1Make: Honda Fit c.c. 1339Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 125434 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: G012348453

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 175/65-12 14

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 6 Rear 6

R/Bal. _____ mm R/Bal. _____ mm

L/Bal. 6 mm L/Bal. 6 mmD.O.A. 11/5/18 D.O.I. 18/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

11A 17859 22-10-2021 col. 3yrs. Snd. c. Net 414/
steering rack have noise.

26/6/18 Confirmed m/s \$2750 with Jay.

2/7/18 Reconfirmed m/s \$3800 with Jay.

R(15,672.32/60%)

Date/Time, File Pass to?

☐ : Preli. Report

Days Of Repair: _____

1) Date/Time, File Return to?

☐ : Final Report

Resurvey No. of Trip: _____

2) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + RS _____ SI

Photos _____

Others _____

TOTAL

Report Format : _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD		Ref : CC6/AIG18008001/Uja3		
78 SHENTON WAY #08-16 CHARTIS BUILDING SINGAPORE 079120		Date : 02-05-2018		
Code : AIG				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBG 537H	Veh. Inspected	SGM 5694M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/05/2018	Inspection Date	18/05/2018	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S6808656F
SIM WEI CHOON
BLK 14 BEDOK SOUTH AVENUE 2
07-584
SINGAPORE 460014
TEL : FAX :
PH : 91809498
ATTN :

ESTIMATE BILL

Number : EB00004811
Date : 02/05/2018
Case No : AD00009705
Vehicle No : SGM5694M
Chassis : GD12348453
Year of Mfr : 2006
Policy No : 5084989574-01
Model : HONDA FIT 1.3 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	FRONT BUMPER <i>DIS</i>	1.0	505.20	20	404.16
2	FRONT BUMPER SIDE RETAINER LH <i>11</i>	1.0	13.00	30	10.40
3	FRONT BUMPER SIDE RETAINER RH <i>Buy</i>	1.0	13.00	20	10.40
4	FRONT BUMPER CLIPS <i>all</i>	10.0	3.70	20	29.60
5	FRONT HEADLAMP RH <i>320</i>	1.0	468.20	20	374.56
6	FRONT HEADLAMP LOWER BRACKET RH <i>11</i>	1.0	25.00	20	20.00
7	FRONT FENDER RH <i>Buy</i>	1.0	375.60	20	300.48
8	FRONT FENDER LAMP RH <i>CR</i>	1.0	30.10	20	24.08
9	FRONT FENDER INNER SHIELD RH <i>Torn</i>	1.0	70.20	20	56.16
10	FRONT FENDER INNER SHIELD CLIPS <i>all</i>	8.0	3.70	20	23.68
11	FRONT WING MIRROR RH <i>Buy</i>	1.0	498.40	20	398.72
12	FRONT WHEEL RIM RH <i>1</i>	1.0	658.40	20	526.72
13	FRONT SHOCK ABSORBER WITH SPRING RH <i>11</i>	1.0	337.40	20	269.92
14	FRONT KNUCKLE ARM RH <i>Buy</i>	1.0	245.50	20	196.40
15	FRONT LOWER ARM RH <i>11</i>	1.0	237.40	20	189.92
16	FRONT ROTOR <i>11</i>	1.0	204.50	20	163.60
17	FRONT BRAKE (SET) <i>11</i>	1.0	227.30	20	181.84
18	FRONT DRIVESHAFT LH <i>11</i>	1.0	996.70	20	797.36
19	FRONT DRIVESHAFT RH <i>11</i>	1.0	996.70	20	797.36
20	REAR BUMPER <i>1</i>	1.0	470.60	20	376.48
21	REAR BUMPER SIDE RETAINER LH <i>11</i>	1.0	17.10	20	13.68
22	REAR BUMPER SIDE RETAINER RH <i>11</i>	1.0	17.10	20	13.68
List Price - Parts Sub Total					5,179.20
Parts Total					5,179.20
23	FRONT DOOR RH - REPAIR <i>11 X</i>	1.0			
24	REAR DOOR RH - REPAIR <i>11 X</i>	1.0			
25	REAR FENDER RH - REPAIR <i>11 X</i>	1.0			
26	FRONT SUPPORT PANEL - REPAIR <i>11 X</i>	1.0			
27	FRONT BONNET - REPAIR <i>11 X</i>	1.0			
28	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	900.00	0	900.00
29	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,200.00	0	1,200.00
30	ANTI-RUST COATING	1.0	280.00	0	280.00
31	WIRING	1.0	40.00	0	40.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S6808656F
SIM WEI CHOON
BLK 14 BEDOK SOUTH AVENUE 2
07-584
SINGAPORE 460014
TEL : FAX :
PH : 91809498
ATTN :

ESTIMATE BILL

Number : EB00004811
Date : 02/05/2018
Case No : AD00009705
Vehicle No : SGM5694M
Chassis : GD12348453
Year of Mfr : 2006
Policy No : 5084989574-01
Model : HONDA FIT 1.3 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
32	TWO WHEEL ALIGNMENT	1.0	80.00	0	80.00
33	TO REMOVE & REFIT UNDERCARRIAGE	1.0	250.00	0	250.00
	Labour 1 Sub Total				2,750.00
					2030
					P-2741.68
					1440 - 2030
					4771.68
					3817
SINGAPORE DOLLARS : EIGHT THOUSAND FOUR HUNDRED EIGHTY-FOUR AND CENTS TWENTY-FOUR ONLY			Less Excess		0.00
			SUBTOTAL		7,929.20
			GST 7.00%		555.04
			TOTAL		8,484.24

SERVICE DUE : DATE 16/08/2018 MILEAGE 191,457

Date of accident : 01/05/2018 10:20 PM. Place : JALAN RAJA & KIM KEAT ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E,
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No 20-0104141-D

TO : S6808656F
SIM WEI CHOON
BLK 14 BEDOK SOUTH AVENUE 2
07-584
SINGAPORE 460014
TEL : FAX :
PH : 91809498
ATTN :

ESTIMATE BILL

Number : EB00004873
Date : 28/06/2018
Case No : AD00009705
Vehicle No : SGM5694M
Chassis : GD12348453
Year of Mfr : 2006
Policy No : 5084989574-01
Model : HONDA FIT 1.3 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	POWER STEERING RACK PINION <i>Self/Dome</i>	1.0	1,154.30	20	923.44 ✓
	Nett Price - Parts Sub Total				923.44
	Parts Total				923.44
SINGAPORE DOLLARS : NINE HUNDRED EIGHTY-EIGHT AND CENTS EIGHT ONLY			Less Excess		0.00
			SUBTOTAL		923.44
			GST 7.00%		64.64
			TOTAL		988.08

SERVICE DUE : DATE 16/08/2018 MILEAGE 191,457

Date of accident : 01/05/2018 10:20 PM. Place : JALAN RAJA & KIM KEAT ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

Hock Wah Motor Workshop PTE LTD

Blk 3011 Bedok North Ave4
#01-2008/2010/2012/2014 Singapore 489977

Phone Number: 6441 5655

Fax Number: 64415355

Customer:

Company:

Vehicle No:

sgm5694m

Date:

27/6/2018 2:19:29 PM

VIN

Technician:

Order No.:

VEHICLE ALIGNMENT REPORT

HONDA, 2004, FIT, All(Custom)

Primary Angles

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	2.4°	1.1°	3.1°	2.4°
		Right	2.6°	1.1°	3.1°	
	Camber	Left	-0.7°	-1.0°	1.0°	-0.7°
		Right	-3.3°	-1.0°	1.0°	
	Toe	Left	-2.5	-1.3mm	1.3mm	-2.5
		Right	21.2	-1.3mm	1.3mm	
Total		18.7	-2.5	2.5	21.2	
Rear	Camber	Left	-1.2°	-2.0°	0.0°	-1.2°
		Right	-1.2°	-2.0°	0.0°	
	Toe	Left	2.6	-----	-----	2.6
		Right	-0.4	-----	-----	
		Total	2.2	0.8	3.4	
	Thrust Angle			-0.2°	-----	-----
Secondary Angles			Initial	Specifications		Final

Secondary Angles

Secondary Angles		Initial	Specifications		-0.2°
			Min.	Max.	Final
W	Left	13.8°	-----	-----	13.8°
	Right	12.7°	-----	-----	
Included Angle	Left	13.1°	-----	-----	12.7°
	Right	9.4°	-----	-----	13.1°
Camber Turns	Left	-2.5°	-----	-----	9.4°
	Right	-1.7°	-----	-----	-2.5°
Toe Curve Turns	Left	-----	-----	-----	-1.7°
	Right	-----	-----	-----	-----
Toe Curve Change	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Sotback	Front	-0.4"	-----	-----	-----
	Rear	0.2"	-----	-----	-0.5"
Steering Diff		0.3"	-----	-----	0.1"
Steering Diff		-0.6"	-----	-----	0.3"
Ride Height	Left	-----	-----	-----	-0.6"
	Right	-----	-----	-----	-----
Rear Ride Height	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Camber Angle		-----	-----	-----	-----

Hock Wah Motor Workshop PTE LTD

Blk 3011 Bedok North Ave4
#01-2008/2010/2012/2014 Singapore 489977

Phone Number: 6441 5655

Fax Number: 64415355

Customer:	Date:
Company:	27/6/2018 2:19:29 PM
Model:	VIN
sgm5694m	Technician:
	Order No.:

VEHICLE ALIGNMENT REPORT

HONDA, 2004, FIT, All(Custom)

Primary Angles

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	2.4°	1.1°	3.1°	2.4°
		Right	2.6°	1.1°	3.1°	2.6°
	Camber	Left	-0.7°	-1.0°	1.0°	-0.7°
		Right	-3.3°	-1.0°	1.0°	-3.3°
	Toe	Left	-2.5	-1.3mm	1.3mm	-2.5
		Right	21.2	-1.3mm	1.3mm	21.2
Total		18.7	-2.5	2.5	18.7	
Camber	Left	-1.2°	-2.0°	0.0°	-1.2°	
	Right	-1.2°	-2.0°	0.0°	-1.2°	
Rear	Toe	Left	2.6	-----	-----	2.6
		Right	-0.4	-----	-----	-0.4
		Total	2.2	0.8	3.4	2.2
	Thrust Angle		-0.2°	-----	-----	-0.2°

Secondary Angles

Boundary Angles		Initial	Specifications		Final
			Min.	Max.	
Included Angle	Left	13.8°	-----	-----	13.8°
	Right	12.7°	-----	-----	12.7°
	Left	13.1°	-----	-----	13.1°
	Right	9.4°	-----	-----	9.4°
Over Turns	Left	-2.5°	-----	-----	-2.5°
	Right	-1.7°	-----	-----	-1.7°
Under Turns	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Toe Curve Change	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Sethback	Front	-0.4"	-----	-----	-0.5"
	Rear	0.2"	-----	-----	0.1"
Front Diff		0.3"	-----	-----	0.3"
Rear Diff		-0.6"	-----	-----	-0.6"
Front Ride Height	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Rear Ride Height	Left	-----	-----	-----	-----
	Right	-----	-----	-----	-----
Camber Angle		-----	-----	-----	-----

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

Ref : SGM5694M

Date : 02.07.2018

Motor Claims Dept
AIG Asia Pacific Insurance Pte Ltd
NO 78 Shenton Way
07-16 CHARTIS Building
SINGAPORE 079120
Fax : 68357416

Dear Sir/Mdm

DIRECT SETTLEMENT - Accident Involving vehicle no SGM5694M and GBG537H On 01/05/2018 Along JALAN RAJA & KIM KEAT ROAD

We refer to the above matter.

We are instructed by our clients, SIM WEI CHOON of vehicle number SGM5694M to claim damages against your insured GBG537H in connection with a road traffic accident on 01/05/2018 10:20:15PM

We are instructed that the accident was caused by your insured's negligent driving and /or management of this vehicle. As a result, our client's vehicle was damaged and our clients have to put to loss and expenses, particulars of which are as follows:

Cost Of Repair			\$	4,066.00
Loss of Use			\$	0.00
Car Rental Fee	5	Days X \$	120.00	\$ 600.00
LTA Search Fee			\$	2.00
Survey Fee			\$	0.00
GIA Fees			\$	0.00
Total			\$	4,668.00

Please revert within the next **SEVEN (7) Days** so that we can advise out third party claimant for the next course of action.

We/I support our/my claim with documents enclosed.



Motor Claims Dept

Lee Jia Yi
Claims Advisor
motor@hockwah.com.sg

Joy Irene (LKKAuto)

From: Joy Irene (LKKAuto)
Sent: Thursday, 3 May 2018 2:43 PM
To: 'dyxim@gmail.com'
Cc: Admin A
Subject: ACCIDENT INVOLVING GBG 537H AND SGM 5694M ON 01/05/2018 ALONG JALAN RAJA AND KIM KEAT ROAD

Our ref: CC6/AIG18008001/ja3

DY EXIM SERVICES

Policy Holder

Dear Sir/Madam,

ACCIDENT INVOLVING GBG 537H AND SGM 5694M ON 01/05/2018 ALONG JALAN RAJA AND KIM KEAT ROAD

We refer to the above accident where we are acting for AIG Asia Pacific Insurance Pte Ltd to resolve the claim against you under the Auto Insurance policy taken up with them.

Based on the accident report and accident scenario, liability is down against us. We will therefore proceed to negotiate for an amicable settlement with the Third Party.

Should you however wish to further discuss on the matter prior to our negotiations and settlement, please contact us within 7 days from the date of this letter.

Please note that your No-Claim Discount (NCD)(if any) will be affected and reduced by 30% (20% for commercial vehicles) upon next renewal due to this Third Party claim. However, if your policy has a NCD protector feature, it will be deemed utilized for this claim and your NCD will be protected.

Please call us if you have further queries.

Best Regards,

Joy Irene | Case Handler

LKK Auto Consultants Pte Ltd

DID: 6841-2409 | email: joyirene@lkkauto.com | Fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

All contents of this email is intended strictly for the addressee(s) only. It may contain confidential and/or privileged information. If you are not the intended recipient (or have received this email in error) please notify the sender immediately and destroy this email. Any unauthorized copying, disclosure or distribution of the material in this email is strictly forbidden.


AUTHORIZATION TO ACT
(AIG Asia Pacific – EXPRESS THIRD PARTY CLAIM)

I, SIM WEI CHUAN ("the third party claimant")
of BLK 14 BEDOK SOUTH AVENUE 2 # 07-584 SINGAPORE 460014 (address),
owner of SGM5694M (vehicle no.) hereby authorize
HOCK WAH MOTOR WORKSHOP PTE LTD
("the workshop") to act for me with respect to my claim for repair costs and/or
rental and/or loss of use ("claim") for my vehicle no. SGM5694M that was
damaged pursuant to the accident which occurred on 01-05-2018 (date) along
JALAN RAJA & KIM KEAT ROAD (location)
involving vehicle no/s G8G53TH ("the accident").

I further authorize the workshop to settle the above mentioned claim in a
manner that they deem fit and the workshop is further authorized to receive
payment further to settlement of my claim with payment cheque/s being made in
favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my
behalf is on a without prejudice and without admission of liability basis insofar
as the driver/owner/insurers of the other vehicle/s is concerned.

Date this 02 day of 05 (month) 20 18 (year)


Signed by "the third party claimant"


Signed by "the workshop"



RELEASE VOUCHER
(AIG Asia Pacific - Express Third Party Claim)

"We/I, HOCK WAH MOTOR WORKSHOP PTE LTD ("the workshop") hereby confirm that we/I have reached an agreement with the appointed surveyor of AIG Asia Pacific Insurance Pte Ltd LKK AUTO CONSULTANTS PTE LTD (name of surveyor) with respect to the amount claimed for S\$4,066.00 (Repair Cost), S\$400.00 (Loss of Rental), S\$2.00 (Disbursement) for vehicle no. SGM 5694M that was damaged pursuant to the accident which occurred on 01/05/2018 (date) along JALAN RAJA AND KIM KEAT ROAD (location) involving vehicle no/s GBG 537H. This is pursuant to the inspection conducted on 18/05/2018 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner SIM WEI CHOON ("the third party claimant") of vehicle no. SGM 5694M make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify AIG Asia Pacific Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to costs of repairs and/or rental and/or loss of use pursuant to the damage to SGM 5694M (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of any claim of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

Dated this 27 (day) of 7 (month) **2018** (year)



cks

Signed by appointed surveyor



Signed by "the workshop" (with chop)

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : S6808656F

AIG Asia Pacific Insurance Pte Ltd
NO 78 Shenton Way
07-16 CHARTIS Building
SINGAPORE 079120
TEL : 1800 4193000 FAX : 68357416
PH :
ATTN :

TAX INVOICE

Number : IV00055777
Date : 02/07/2018
Case No : JS00058273
Vehicle No : SGM5694M
Chassis : GD12348453
Year of Mfr : 2006
Policy No : 5084989574-01
Model : HONDA FIT 1.3 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
1	LUMPSUM REPAIR	1.0	3,800.00	0	3,800.00
	Sub Total				3,800.00
	Parts Total				3,800.00
SINGAPORE DOLLARS : FOUR THOUSAND SIXTY-SIX AND CENTS ZERO ONLY			Less Excess		0.00
			SUBTOTAL		3,800.00
			GST 7.00%		266.00
			TOTAL		4,066.00

SERVICE DUE : DATE 16/08/2018 MILEAGE 191,457

Date of accident : 01/05/2018 10:20 AM. Place : JALAN RAJA & KIM KEAT ROAD

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD



CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

H W CAR RENTAL

Registration no.: 52902602C
3011 Bedok Industrial Park E
#01-2010 Singapore 489977
Tel: 6441 5655 / 8339 6888

CINV - 200037

INVOICE

Refer to Rental Agreement: CRA 200039

Reference Vehicle: SGM5694M

Date: 02.07.2018

Customer Information

Name: SIM WEI CHOUN NRIC No.: S6808656F

Address: BLK 14 BEDOK SOUTH AVENUE 2 # 07-584

S (460014)

Contact No: 9180 9498

Rental Car Information

Vehicle No.: SLR5878P

Make & Model: TOYOTA VIOS

Start Date: 27 / 06 / 2018

End Date: 30 / 06 / 2018

Rent for (No. of Days) 5 days

Rate at (Per Day) \$120.00

Total Amount \$ 600.00



Customer Signature



Authorized Signature



H W CAR RENTAL

Registration no.: 52902602C
3011 Bedok Industrial Park E
#01-2010 Singapore 489977
Tel: 6441 5655 / 8339 6888

R.Vehicle No. SGM5694M**CRA# -200039****RENTAL AGREEMENT - CLAIM****Hirer's Particulars**

Name: SIM WEI CHOON NRIC No.: S6808656F
Address: BLK 14 BEDOK SOUTH AVENUE 2 # 07-584
S (460014) Contact No: 9180 9498
Licence Date: 14 / 04 / 1993 Birth Date: 19 / 02 / 1968

Additional Driver's Particulars

Name: _____ NRIC No.: _____
Licence Date: / / Contact No: _____

Rental Vehicle

Vehicle No.: SLR5878P Start Date: 27 / 06 / 2018
Rate (Per day): \$120.00 No. of days: 5 End Date: 02 / 07 / 2018
PL (Out): _____ PL (In): OK / Time out/in: 8:30am 9:30am

The Hirer agreed to the Rental Agreement as followed: -

- ☐ Rental vehicle is restricted to SINGAPORE use only, check water and engine oil daily.
- ☐ No refund if vehicle return early.
- ☐ Hirer is liable to pay all fines, summons, claims, excess within rental period.
- ☐ Hirer shall bear the responsibility if any damages found on/in vehicle.
- ☐ Extension: One day in advance notice is required otherwise no extension will be allowed.
- ☐ Car collection and return shall be within the office operating hour.
- ☐ Excess: In the event when accident occurred, the Hirer is liable to bear the excess of at least S\$4,000 / S\$8,000 (Young, Inexperience Driver) in cash plus loss of earnings.

Any problem arises to vehicle within rental period, Hirer must inform 6441 5655 immediately.

Hirer acknowledges all T&C and signifies acceptance upon signing.



Hirer and Driver Signature

Date & Company Stamp (if any)

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

Third Party Insurer Enquiry

Our Ref No: GR-18-065890

Date of Request: 02/05/2018

Your Ref No: Online Purchase

Hock Wah Motor Workshop Pte Ltd
Blk 3011, Bedok Industrial Park E,
#01-2008/2010/2012
Singapore 489977

Dear Sir/Madam,

Enquiry Date 02/05/2018
Enquiry By Mavis Er Shieh Yin
TP Vehicle No. GBG537H
Accident Date 01/05/2018

Enquiry Result

TP Vehicle No.	Insurer	Period of Insurance	Insurer Tel. No.
GBG537H	AIG Asia Pacific Insurance Pte. Ltd.	30/05/2017-29/05/2018	65-6419-3000

Thank You.

The images provided to you are taken from the original reports forwarded to the centre by the members of the General Insurance Association of Singapore and we take no responsibility for their accuracy or contents and shall be under no liability whatsoever for any loss or damage arising out of or in connection with the reports or their images.

This is a computer generated document and requires no signature.

**GENERAL INSURANCE ASSOCIATION OF SINGAPORE
RECORDS MANAGEMENT CENTRE**

6 Raffles Quay #18-00, Singapore 048580
Phone: +65 6224 0010 Fax: +65 6224 0030
Operating Hours: Monday to Friday 9am to 5pm
GST Registration No: M400017735

TAX INVOICE

Our Ref No: GR-18-065890
Date of Request: 02/05/2018

Your Ref No: Online Purchase

Hock Wah Motor Workshop Pte Ltd
Blk 3011, Bedok Industrial Park E,
#01-2008/2010/2012
Singapore 489977

Dear Sir/Madam,

Enquiry Date 02/05/2018
Enquiry By Mavis Er Shieh Yin
TP Vehicle No. GBG537H
Accident Date 01/05/2018

DESCRIPTION	AMOUNT (S\$)
TP Insurer Enquiry	1.87
GST Amount	0.13
Total Amount Due (GST Inclusive)	2.00

Thank You.

This is a computer generated document and requires no signature.

For GIARMC Official use:

Date:

☒ GIRO ☐ Cash ☐ Cheque

...CLAIM SUBFOLDER...(Pending for Survey Report)

Fastlane

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	02 May 2018 Edit Reg		18 May 2018 00:00 Edit Adj Rpt	\$3,800.00 Edit Estimates	\$3,800.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS		[Created by adjuster]							
Insured:	DY EXIM SERVICES , Co. Reg. No.: 52891284D								
Main Claimant:	SIM WEI CHOON , ID: S6808656F								
Vehicle Reg. No.:	SGM5694M	Date of Loss:	01/05/2018 10:00 - :59 [138 Months and 8 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 3786450236SG	Policy/Cover Note No.:	1700011158 (Comprehensive)						
Vehicle Reg. No. (Insured):	GBG537H	Policy No. (Claimant):	5084989574-01						
		Excess:							
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E,, #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Kesaval, Jaclyn-M] Jaclyn-M.Kesaval@aig.com								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/05/2018]								
ASSOCIATED MAIL RECEIVED		View All Compose Case Mail							
There are no mail for this case.									
ALL ASSOCIATED TASKS		View All Search Tasks Create New Task Complete							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SGM5694M (3786450236SG)**
[GBG537H]

TP
















































SIM WEI CHOON

May 1 2018 10:15AM

[DY EXIM SERVICES]

Hock Wah Motor Workshop Pte Ltd

Upload Documents			Upload Photos			Compose New Letter			Upload Video			Upload Audio			View			View in Browser		
Letters/Correspondences															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	(Draft)	Third Party Express Settlement – Payment Breakdown													Edit					
Assessment Reports															1 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)												Thumbnail		Print				
1	03/05/18 11:25	Accident Statement From: SC - Reg. No: GBG537H, Claimant: DY EXIM SERVICES													Load HTM					
Photos/Images															3 per page		<input type="button" value="v"/>	<input checked="" type="checkbox"/>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)												Thumbnail		Print				
1	18/05/18 16:47	Chassis Number													Load JPG	<input checked="" type="checkbox"/>				
2	18/05/18 16:47	Odometer Reading													Load JPG	<input checked="" type="checkbox"/>				
3	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
4	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
5	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
6	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
7	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
8	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
9	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
10	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
11	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
12	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
13	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
14	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
15	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
16	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
17	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
18	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
19	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
20	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
21	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
22	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
23	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
24	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
25	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
26	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
27	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
28	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
29	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				
30	18/05/18 16:47	General View													Load JPG	<input checked="" type="checkbox"/>				

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
31	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
32	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
33	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
34	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
35	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
36	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
37	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
38	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
39	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
40	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
41	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
42	18/05/18 16:47	General View	 Load JPG	<input checked="" type="checkbox"/>
43	28/06/18 16:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	28/06/18 16:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	28/06/18 16:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	28/06/18 16:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	28/06/18 16:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	28/06/18 16:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	28/06/18 16:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	28/06/18 16:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	28/06/18 16:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	28/06/18 16:56	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	30/06/18 10:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/18 16:01	TP GIA REPORT	 Load PDF	
2	27/05/18 14:42	TP ESTIMATE - MARKED	 Load PDF	
3	27/07/18 13:57	LETTER TO INSURED	 Load PDF	
4	31/07/18 09:35	WORKSHOP INVOICE	 Load PDF	
5	31/07/18 09:35	AUTHORISATION TO ACT FORM	 Load PDF	
6	31/07/18 09:35	Release Voucher	 Load PDF	
7	31/07/18 09:35	RENTAL RECEIPT	 Load PDF	
8	31/07/18 09:35	GIA SEARCH	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
<div></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer			
<small>Note: Remarks are private unless you show it to other parties.</small>			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	GBG537H (Insd veh)	Model:	HONDA FIT 1.3 (A)
	SGM5694M (TP veh)		
Date of Accident:	01/05/2018		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	9,472.32
Final Repair Cost	:	\$	4,066.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	400.00 4 days
LTA / GIA Search Fee	:	\$	2.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	4,468.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For **Non GIA Registered Workshop**: Agreed Liability ____ 100 ____ (%)

B) For **GIA Registered Workshop**: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	Hock Wah Motor Workshop Pte Ltd	:	\$ 4,468.00
2)		:	\$
3)		:	\$

JOANNE LEE KHANG MIN

31 Jul

2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18008001/UJA3Q2

Date: 31/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1700011158
 Claimant Vehicle No: SGM5694M Insured Vehicle No: GBG537H
 Date of Loss: 01/05/2018 Nature of Claim: TP Claim No: 3786450236SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SGM5694M**
 Make & Model: HONDA FIT, 1.3 (A) Engine No: L13A2265291
 Reg. Date: 23/10/2006 (Man. Year: 2006) Chassis No: GD12348453
 Colour: Grey Odometer: 185434 km
 Engine Capacity: 1339 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 175/65 R14 Rear Tyre Size: 175/65 R14
 Front Left Side: Dunlop 6 mm Rear Left Side: Dunlop 6 mm
 Front Right Side: Dunlop 6 mm Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,102.64	2,741.68	3,360.96	55.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,750.00	2,030.00	720.00	26.18
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,852.64	4,771.68	4,080.96	46.10
Approved Total (Overridden) (S\$)		3,800.00		
(S\$)	8,852.64	3,800.00	5,052.64	57.07
+ GST 7.00/7.00% (S\$)	619.68	266.00	353.68	57.07
Nett Amount (S\$)	9,472.32	4,066.00	5,406.32	57.07
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		4,468.00		

INSPECTION

Date of Assignment: 18/05/2018

Date Inspected: 18/05/2018 Inspected At:

Hock Wah Motor Workshop Pte Ltd
(Bedok)

Blk 3011, Bedok Industrial Park E., #01-

2008/2010/2012
Singapore 489977

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: Joy Irene Bascao

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	505.20 FL	*505.20 FL
2	1		*FRONT BUMPER SIDE RETAINER LH	Not Necessary	13.00 FL	*- FL
3	1		*FRONT BUMPER SIDE RETAINER RH	Bent	13.00 FL	*13.00 FL
4	10		*FRONT BUMPER CLIPS	Necessary	37.00 FL	*37.00 FL
5	1		*FRONT HEADLAMP RH	Broken	468.20 FL	*468.20 FL
6	1		*FRONT HEADLAMP LOWER BRACKET RH	Not Necessary	25.00 FL	*- FL
7	1		*FRONT FENDER RH	Buckled	375.60 FL	*375.60 FL
8	1		*FRONT FENDER LAMP RH	Cracked	30.10 FL	*30.10 FL
9	1		*FRONT FENDER INNER SHIELD RH	Torn	70.20 FL	*70.20 FL
10	8		*FRONT FENDER INNER SHIELD CLIPS	Necessary	29.60 FL	*29.60 FL
11	1		*FRONT WING MIRROR RH	Cut	498.40 FL	*498.40 FL
12	1		*FRONT WHEEL RIM RH	Repair	658.40 FL	*- FL
13	1		*FRONT SHOCK ABSORBER WITH SPRING RH	Not Necessary	337.40 FL	*- FL
14	1		*FRONT KNUCKLE ARM RH	Bent	245.50 FL	*245.50 FL
15	1		*FRONT LOWER ARM RH	Not Necessary	237.40 FL	*- FL
16	1		*FRONT DOOR	Not Necessary	204.50 FL	*- FL
17	1		*SET FRONT BRACKE	Not Necessary	227.30 FL	*- FL
18	1		*FRONT DRIVESHAFT LH	Not Necessary	996.70 FL	*- FL
19	1		*FRONT DRIVESHAFT RH	Not Necessary	996.70 FL	*- FL
20	1		*REAR BUMPER	Repair	470.60 FL	*- FL
21	1		*REAR BUMPER SIDE RETAINER LH	Not Necessary	17.10 FL	*- FL
22	1		*REAR BUMPER SIDE RETAINER RH	Not Necessary	17.10 FL	*- FL
23	1		*FRONT DOOR RH (NPA)	Repair	0.00 FS	*- FS
24	1		*REAR DOOR RH (NPA)	Repair	0.00 FS	*- FS
25	1		*REAR FENDER RH (NPA)	Repair	0.00 FS	*- FS
26	1		*FRONT SUPPORT PANEL (NPA)	Repair	0.00 FS	*- FS
27	1		*FRONT BONNET (NPA)	Repair	0.00 FS	*- FS
28	1		*POWER STEERING RACK PINION	Bent / Damaged	1,154.30 FL	*1,154.30 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	7,628.30	3,427.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,525.66	685.42
Total Parts (\$\$)	6,102.64	2,741.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	900.00	600.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	1,200.00	1,100.00
3	ANTI-RUST COATING	New	280.00	50.00
4	WIRING	New	40.00	20.00
5	TWO WHEEL ALIGNMENT	New	80.00	60.00
6	TO REMOVE & REFIT UNDERCARRIAGE	New	250.00	200.00
Gross Labour Cost (S\$)			2,750.00	2,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >