

INS. CASE OWNER:

CC6 / III1800

8003

U 1/15/18

LKK:

IDAC:

Surveyor:

MARINS

DOI:

ASSIGNMENT

Date / Time:

2/15/18

Region: Lia Merimee:

2/15/18

Pre-assign / CCU / FTE



Insured Vehicle No. : SHA 1782 U

Name of Insured : CTP

Insured Tel No. : HP: 115/18

Excess Sec II : SS D.O.A: 115/18

Is driver the owner? (YES / NO) Nature of Accident :

If NO, Driver Name / Age:

Driver Tel No. :

Lee Thoy Lin
97902292

(V/L: YES / NO)

Claim No. : m10001

Policy No. : H-Santa

Make / Model : Grand Seik 57i 7 Gearh Red

Place of Accident :

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability : % Final ? Yes / No



INSRS:

WSP: Hock Wan

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:



INSRS:

WSP:

Tel :

Liability :

RMKS:

Date/ Time

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

%

(Agreed / Assessed) BOLA S/N No. :

If NO or B 28, Ass. Lia :

Repair Cost:

SS

Loss of Rental (LOR):

SS

(

days)

Loss of Use (LOU):

SS

(\$

x

days)

Loss of Income (LOI):

SS

(\$

x

days)

LOR only ☐ LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

Name 1:

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format: TP/WP

3) Survey fee: \$ 250

COPY SENT
13/12/17

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: 555124Hat Workshop m/s Woolworth Co

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____

Consistent? : Yes or No

GIA / PR Seen: 2

Consistent? : Yes or No

Est. Repairs: 1

days

Res.: Yes or No

Lum Sum: 1.81

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: 555124HYr Regn: 7.09Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Mit Lancer

c.c

1499Colour: GreyA/C: Insured / Std / NI / NASp. Reading: 191907T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JMYSRCY2A94000212Gen. Cond: Good / Fair / Poor / BurntSteering: Inorder / Jammed / Leaked / Burnt orBrake: Inorder / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F:R:225/45-20R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6

mm

R/Bal. 6

mm

L/Bal. 6

mm

L/Bal. 6

mm

D.O.A. 11/5/18D.O.I. 18/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

27A1028618/5/18Conf. andfinal by350 with JALICE.

(RED: + 1,738.60 83%)

Date/Time, File Pass to?



: Prel. Report

1)



: Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL		Ref : CC5/III18008003/Uja3		
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 02-05-2018		
		Code : III2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1782U	Veh. Inspected	SJS 124H	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/05/2018	Inspection Date	18/05/2018	
Survey held at	HOCK WAH MOTOR WORKSHOP PTE LTD 3011 BEDOK INDUSTRIAL PARK E #01-2008 SINGAPORE 489977			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53344017C
METAL GLASS DECO
NO

SINGAPORE
TEL : FAX :
PH : 96465265
ATTN :

Term:

ESTIMATE BILL

Number : EB00004810
Date : 02/05/2018
Case No : AD00009702
Vehicle No : SJS124H
Chassis : JMYSRCY2A9U000212
Year of Mfr : 2008
Policy No : 5093981862
Model : MITSUBISHI
LANCER 1.5 MIVEC

Sn	DESCRIPTION	QTY	U PRICE	GLX AT DISC	ABS D/AB DWD IDR	AMOUNT
1	REAR BUMPER	1.0	832.00	10	1	748.80
2	REAR BUMPER TOWING COVER	1.0	22.00	10	1	19.80
List Price - Parts Sub Total						768.60
3	REAR BUMPER LOWER SPOILER- REPAIR	1.0		20	1	
4	REVERSE SENSOR	1.0	280.00	0	1	280.00
Special Nett Price - Parts Sub Total						280.00
Parts Total						1,048.60
5	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0	1	500.00
6	SPRAY PAINT ON THE AFFECTED AREAS	1.0	300.00	0	1	300.00
7	ANTI-RUST COATING	1.0	80.00	0	1	80.00
8	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	1	150.00
Labour 1 Sub Total						1,030.00
SINGAPORE DOLLARS : TWO THOUSAND TWO HUNDRED TWENTY-FOUR AND CENTS TEN ONLY						
Less Excess						0.00
SUBTOTAL						2,078.60
GST 7.00%						145.50
TOTAL						2,224.10

Date of accident : 01/05/2018 07:30 PM. Place : LIANG SEAH STREET

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Business
Owner ID:	4017C
Vehicle Details	
Vehicle No.:	SJ5124H
Vehicle to be Exported:	No
Intended De-registration Date:	18 May 2018
Vehicle Make:	MITSUBISHI
Vehicle Model:	LANCER 1.5 MIVEC GLX AT ABS D/AB 2WD 4DR
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	4A910106506
Chassis No.:	JMY5RCY2A9U000212
Maximum Power Output:	80.0 kW (107 bhp)
Open Market Value:	\$15,347.00
Original Registration Date:	27 Jul 2009
First Registration Date:	27 Jul 2009
Transfer Count:	2
Actual ARF Paid:	\$15,347.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Jul 2019
PARF Rebate Amount:	\$8,440.00
Intended COE Rebate Details	
COE Expiry Date:	26 Jul 2019
COE Category:	A - Car (1600cc & below)
COE Period(Years):	10
QP Paid:	\$15,291.00
COE Rebate Amount:	\$1,816.00
Total Rebate Amount:	\$10,256.00

The information contained herein is correct as at 18 May 2018

OK

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Wednesday, 11 December 2019 3:01 PM
To: Sherini Pillai
Subject: Your Ref: MCT18050090, ACCIDENT INVOLVING SHA 1782U AND SJS 124H ON 01/05/2018

Your Ref: MCT18050090

Hi Sherini,

We refer to the above matter.

ACCIDENT INVOLVING SHA 1782U AND SJS 124H ON 01/05/2018

We were informed by TP workshop that claimant withdrew claim from the workshop.

In view of the above, We will proceed to close file and submit our report.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: asher.sng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



...CLAIM SUBFOLDER...(Pending for Survey Report)

WP

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	03 May 2018 Edit Reg		18 May 2018 00:00 Edit Adj Rpt	S\$350.00 Edit Estimates	S\$350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Main Claimant:	METAL GLASS DECO, Co. Reg. No.: 53344017C								
Vehicle Reg. No.:	SJS124H	Date of Loss:	01/05/2018 19:00 - :59 [105 Months and 4 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT18050090	Policy/Cover Note No.:	MCOMD015						
Vehicle Reg. No. (Insured):	SHA1782U	Policy No. (Claimant):	5093981862						
		Excess:							
Repairer:	Hock Wah Motor Workshop Pte Ltd (Bedok) Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012, 489977 Bedok - Tel: 6441 5655								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Sherini Pillai]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 11/05/2018]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• III_SG (04/06/2018): Alert - Adj Mandate Maintained - SJS124H - Claim Handler: Sherini Pillai									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SJS124H (MCT18050090)
[SHA1782U]
TP
METAL GLASS DECO
May 1 2018 7:00PM
[COMFORT TRANSPORTATION PTE LTD]
Hock Wah Motor Workshop Pte Ltd

[Upload Documents](#) | [Upload Photos](#) | [Compose New Letter](#)

View View in Browser

Video			1 per page	☒
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	04/06/18 11:25	Video - OID		Load MP4

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	29/06/18 15:14	General View		Load JPG ☒
2	29/06/18 15:14	General View		Load JPG ☒
3	29/06/18 15:14	General View		Load JPG ☒
4	29/06/18 15:14	General View		Load JPG ☒
5	29/06/18 15:14	General View		Load JPG ☒
6	29/06/18 15:14	General View		Load JPG ☒
7	29/06/18 15:14	General View		Load JPG ☒
8	29/06/18 15:14	General View		Load JPG ☒
9	29/06/18 15:14	General View		Load JPG ☒
10	29/06/18 15:14	General View		Load JPG ☒
11	29/06/18 15:14	General View		Load JPG ☒
12	29/06/18 15:14	General View		Load JPG ☒
13	29/06/18 15:14	General View		Load JPG ☒
14	29/06/18 15:14	General View		Load JPG ☒
15	29/06/18 15:14	General View		Load JPG ☒
16	29/06/18 15:14	General View		Load JPG ☒
17	29/06/18 15:14	General View		Load JPG ☒
18	29/06/18 15:14	General View		Load JPG ☒

Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	02/05/18 16:13	TP GIA REPORT		Load PDF
2	27/05/18 14:44	TP ESTIMATE - MARKED		Load PDF
3	29/06/18 15:09	TP WITNESS STATEMENT		Load PDF
4	11/12/19 15:02	EMAIL TO III DD 111219		Load PDF
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	25/05/18 10:41	Singapore Accident Statement		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18008003/UEA3Q2

Date: 18/12/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: MCOM0015
 Claimant Vehicle No : SJS124H Insured Vehicle No : SHA1782U
 Date of Loss: 01/05/2018 Nature of Claim: TP Claim No: MCT18050090

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJS124H
 Make & Model: MITSUBISHI LANCER, 1.5 MIVEC (A) Engine No: 4A910106506
 Reg. Date: 27/07/2009 (Man. Year: 2008) Chassis No: JMYSRCY2A9U000212
 Colour: Grey Odometer: 191907 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45Z R17 Rear Tyre Size: 225/45Z R17
 Front Left Side: Goodyear 6 mm Rear Left Side: Goodyear 6 mm
 Front Right Side: Goodyear 6 mm Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,048.60	0.00	1,048.60	100.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	350.00	680.00	66.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,078.60	350.00	1,728.60	83.16
+ GST 7.00/7.00% (S\$)	145.50	24.50	121.00	83.16
Nett Amount (S\$)	2,224.10	374.50	1,849.60	83.16
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment: 18/05/2018
 Date Inspected: 18/05/2018 Inspected At: Hock Wah Motor Workshop Pte Ltd (Bedok)
 Blk 3011, Bedok Industrial Park E., #01-2008/2010/2012 Singapore 489977
 Estimated Period of Repair: 1.0 days

Adjuster: MARCUS CHUA

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 17 Dec 2019)
Parts:	143	MITSUBISHI LANCER 1.5 MIVEC (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SJS124H)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Repair	832.00 FL	*- FL
2	1		*REAR BUMPER TOWING COVER	Not Necessary	22.00 FL	*- FL
3	1		*REAR BUMPER LOWER SPOILER (NPA)	Repair	0.00 FS	*- FS
4	1		*REVERSE SENSOR	Not Necessary	280.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	1,134.00	0.00
- List Item Discount on L Items 10.00/10.00% (S\$)	85.40	0.00
Total Parts (S\$)	1,048.60	0.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE & REFIT NECESSARY PARTS	New	500.00	100.00
2	SPRAY PAINT ON THE AFFECTED AREAS	New	300.00	250.00
3	ANTI-RUST COATING	New	80.00	0.00
4	TO REMOVE & REFIT REVERSE SENSOR	New	150.00	0.00
Gross Labour Cost (S\$)			1,030.00	350.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >