

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 53344017C
METAL GLASS DECO
NO

SINGAPORE
TEL : FAX :
PH : 96465265
ATTN :

Term:

ESTIMATE BILL

Number : EB00004810
Date : 02/05/2018
Case No : AD00009702
Vehicle No : SJS124H
Chassis : JMYSRCY2A9U000212
Year of Mfr : 2008
Policy No : 5093981862
Model : MITSUBISHI
LANCER 1.5 MIVEC

Sn	DESCRIPTION	QTY	U PRICE	GLX AT ABS D/AR DISC 2WD 4DR	AMOUNT
1	REAR BUMPER	1.0	832.00	10	748.80
2	REAR BUMPER TOWING COVER	1.0	22.00	10	19.80
List Price - Parts Sub Total					768.60
3	REAR BUMPER LOWER SPOILER- REPAIR	1.0		20	280.00
4	REVERSE SENSOR	1.0	280.00	0	280.00
Special Nett Price - Parts Sub Total					280.00
Parts Total					1,048.60
5	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	500.00	0	500.00
6	SPRAY PAINT ON THE AFFECTED AREAS	1.0	300.00	0	300.00
7	ANTI-RUST COATING	1.0	80.00	0	80.00
8	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	150.00
Labour 1 Sub Total					1,030.00
SINGAPORE DOLLARS : TWO THOUSAND TWO HUNDRED TWENTY-FOUR AND CENTS TEN ONLY				Less Excess	0.00
				SUBTOTAL	2,078.60
				GST 7.00%	145.50
				TOTAL	2,224.10

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Date of accident : 01/05/2018 07:30 PM. Place : LIANG SEAH STREET

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE