INS. CASE OWNER.	Tridyn CC 6/AIG1800 8006	, MUGIS ON DAC
Surveyor:	WITHUS DOI: ASSIGNMENT	Date / Time: MAY
Insured Vehicle No. Name of Insured Insured Tel No. Excess Sec II :SS Is driver the owner? If NO, Driver Nam Driver Tel N INSRS: WSP. Tel: Liability:	Claim No Policy No HP: Make / M Place of A C/YES / NO) Nature of Accident: C / Age: (V/L: YES / NO) INSRS: INSRS: INSRS: INSRS: INSRS: INSRS	odel: T. CIEW A Nocident: VES / NO; TP GIA REPORT: YES / NO iability: % Final? Yes / No INSRS: WSP: Tel:
RMKS:	RMKS: RMKS:	RMKS:
Date/Time	Stem 11 45 C - X SBJ 15 G - X Repeat Case By (statil) : Thin This Expressed by 1 Chie : 18/05/18 Date/Time: Sent By:	STAGE Non-Reporting ltr (1st): Non-Reporting ltr (2nd): Non-Reporting ltr (Final): Notification ltr (if non-pickup): Call OI: After call ltr to OI: Documentation Check List: Handler Typist Notification ltr (if non-pickup) After call ltr to OI: Authorisation To Act: Release Voucher: Final Repair Bill: Car Rental Invoice: Towing Invoice LTA / GIA: Medical Bill: PIR: Mandate/Reject Instruction: LOD Payment Breakdown Form: Post-Repair Photos:
	**************************************	Others:
The state of the s	Date/Time: Confirm with:	Confirm by:
FINAL SETTLEMENT Final Liability: Repair Cost: Loss of Rental (LOR): Loss of Use (LOU):	SS (days) Reduction: % Date/Time: Confirm with % % (Agreed / Assessed) BOLA S/N No. : SS SS (days) SS (\$ x days)	Email Call If NO or B 28, Ass. Lin:
LOR only LOU only GIA/LTA Search	S\$ (\$ x days) LOR + LOU LOR + LOI Tick only one	1) Claim status: Normal/Rejea/Private Settle 2) Report Format: 3) Survey fee: 63 × 4 1 × 2
Total:	SS Global Sum SS:	A Committee of the Comm
Payer 2: (Strike if N.A.) Payer 3: (Strike if N.A.)	Date/Time: Confirm with: S\$ Name 1: S\$ Name 2: S\$ Name 3:	Email Call

(68/11/13) Well REF:	1 / /	10
ASS. REC. BY: MOICES	Alal	
ų <u>A</u>	SSIGNMENT	8 9
From: Date:	Veh No. SKM	5/45 GRegn: 14/4/09
Estimated Cost		Van / Lorry / Taxl / Prime Mover /
OD / POWS / TP RES / OD RES / EVA / INV / MV		A /
To Inspect Vehicle No: SKM 614	FC Make: RM	/
at Workshop m/s	3/ /-) 320 j co 1985-
of RIM Chief		A/C: Insured / Std / NI / NA
Insured: SATICA		T/Radio: Insured / Std / NI / NA
Policy No.	Eng/No: WR	121 6/12 11 12 777
Cfairns No.	Gen Cond Cond Fair (Page	47656070NL 22777
Sum Insured: Excess:	Gen. Cond: Good / Fair / Poor	
(Client's Record)	Steering: In order / Jammed / L	SOMMODE IT PERSONALING
Make of Veh:	Brake: Inforder / Jammed / L	
Make of Veri	Modi: Nil Kirim / STD A!	
	Tyre Size: F:	225/45tng
(Policy Condition)	R:	
Remark: The veh had commenced its N/S O/ repair at the time of inspection.	DO I DON'T EXNOVATOTIFS	/LIZA/MIC/OHTSU/PIR/SUMI/
28	TOYO / YOKO or	(Lumflo
Ball, or Market Value:	Front /	Rear
IDAC Accident Rport: Consistent? ; Yes or No	R/Bal. 0 mm	R/Bal. mm
GIA / PR Seen: Consistent?: Yes or No	L/Bal. 1 6 mm	L/Bal. 6 mm
Est Repairs: days Res.: Yes or No	D.O.A. 2/1/18	D.O. 2/5/18
Lum Sum: % 3 Val.: Yes or No	Survey held at /	
CA / REV / REP. / 24 HRS	The same of the sa	OIS / N/S / U/C / Rooftop or
Vehicle: IN / O		7
Date: Person Contacted:	The U/C / Chassis frame /	Body Structure affected due to collision.
Date / Time Action / Instruction // Action / Action / Instruction // Action / Actio		
- 17A 18873 Dep 1	26. netf 11127	home Get No Dage for
14/0/5 4/1 = 12 000 5 1	and whe Alex	
14/5/8 4/5 \$ 10.000 Cent	was were Her	24 :
	CANDAD A DA ADS	,
	(Red: \$ 19732.	04/661.)
Date/Time: File Pass to? : Prell. Report		
	Days Of Repair:	
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip:	Survey Fee:
2) Add F	ee: Site Insp (\$	Transportation:
Addit)\$ +RS;\$I
Report Format :	: Interview (\$) Photos
Lump Sum / I.B.I: (\$: Tech. Invs (\$) Others
)	:Weekend (\$)
		TOTAL

(08/11/13) Wef REF:	AIG/ Unas
ASS. REC. BY: MCreus	GIGNMENT
From: Date:	Veh No: SKM6/45 GAREGIN: 14/4/09
Estimated Cost:	Type: M.Carl M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD (P) NS / TP RES / OD RES / EVA / INV / MY	Truck/Traller or
To Inspect Vehicle No: SKM 61 450	Make: BMW 3W; ac 1985
at Workshop m/s land chie	Colour A/C: Insured / Std / NI / NA
of	Sp.Reading 25526 T/Radio: Insured / Std / NI / NA
Insured: SK9 / SK	Eng/No:
Policy No.	ONO: WBATG56070NL 2277;
Claims No.	Gen. Cond: Good / Fair / Poor / Burnt
Sum Insured: Excess:	Steering: Ingran / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inorder / Jammed / Leaked / Burnt or
Make of Veh	Modi: Nil (Skim / STD A/Rim or
	Tyre Size: F: 225/Usitner
(Policy Condition)	R: 25 C 97
Remark: The veh had commenced its N/S C/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO OF /LUMFID
Bal. or Market Value: 30	Eront / Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal 6
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 1 6 mm L/Bal. 6 mm
Est Repairs: days Res.: Yes or No	D.O.A. 2/1/18 D.O.I. 2/1/18
Lum Sum: % 3 Val.: Yes or No	Survey held at
CAUCO 0201	Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS & ZXO Vehicle: IN / OUT	
Data: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	The state of the s
114 18873	
Date/Time, File Pass to? Pro!! Report	
- Tren. Report	Days Of Repair:
1) : Final Report Date/Time, File Return to?	Resurvey No. of Trip: Survey Fee:
2 Add Fee	Transportation:
Add Fee	Historia /e
Report Format :	: Interview (\$) Photos
Lump Sum / I.B.I: (\$: Tech. Invs (\$) Others
)	:Weekend (\$)
	TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Affiliated to Federation Inte	rnationale Des Experts En Auton	nobile
AIG ASIA PACIFIC IN	NSURANCE PTE LTD	Ref : CC6/AIG18008	006/Uua3
78 SHENTON WAY # CHARTIS BUILDING SINGAPORE 079120		Date: 02-05-2018	
1.7	Policy Particu	lars :- THIRD PARTY CLA	M
Insured Veh.	SBJ 15G	Veh. Inspected	SKM 6145C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	02/05/2018
2.	Vehicle F	Particulars & Condition	DOLLAR BOARD
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	*	Steering	
Brakes		Modification	
General			
3.	Co	nditions of Tyres	
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4.	Desc	ription of Damages	A STATE OF THE PARTY.
5.	Ge	neral Information	
Accident Date	02/05/2018	Inspection Date	02/05/2018
Survey held at	KIM CHWEE AUTO PTE L	TD	
	1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883		
5a.		Remarks	Value - Walks Fish
A)THE INSPECT B)IN ACCORDA	TION WAS CONDUCTED ON A	N'WITHOUT PREJUDICE" BAS IS, WE HAVE NOT AUTHORIS	SIS. SED REPAIRS.

* Not Albard ~ Not Albard ~ 10.000 1 Lg \$ 10.000

KIM CHWEE AUTO PTE LTD 1 Kaki Bukit Ave 6 #01-46/48/50 Autobay SINGAPORE 417883

VEHCILE NO: SKM 6145C

			1 1 2
QTY	PARTICULAR		AMOUNT
1 PCS	BOOTLID	11	\$1,518.32
1 PCS	BOOTLID REAR LOGO	17	\$68.00 4
1 PCS	BOOTLID WEATHERSTRIP	17	\$266.00 00
1 PCS 10% 617:16	REAR BUMPER 5. ~ / 23512	20/00	\$1,650.00
2 PCS	REAR BUMPER SIDE HOLDERS@\$115.00	11	\$230.00 ×
1 SET	REAR BUMPER CLIPS	ner	\$50.00
1 PCS	REAR BUMPER REIMFORCEMENT	n	\$715.000
1 PCS	REAR BUMPER TOP RETAINER	11	\$181.22
1 PCS	REAR END PANEL	n	\$988.45 X
1 PCS	REAR END PANEL TOP GARNISH	11	\$266.00 🗙
2 PCS	TAILLAMPS @\$650.00	17	\$1,300.00 🛭
1 PCS	REAR EXHAUST	1	\$1,152.39 X
2 PCS	REAR BUMPER PDC SENSORS @\$225.00 / 81	shall	\$450.00 126
1 PCS	BONNET	100/Bul	\$1,866.23
1 PCS	BONNET LOGO	ren	\$60.00
1 PCS	FRONT BUMPER	80/De	\$1,285.00
1 PCS	FRONT BUMPER CENTRE GRILLE	TOPA	\$118.23
2 PCS	FRONT BUMPER SIDE HOLDER @\$115.00	34	\$230.00
1 SET	FRONT BUMPER CLIPS	ren	\$50.00
1 PCS	FRONT BUMPER REINFORCEMNT	1	\$696.00 ×
2 PCS	FRONT BUMPER TOP GRILLES @\$225.00	cre	\$450.00
2 PCS	FRONT BUMPER FOG LAMPS @\$430.00	. 11	\$860.00 🗷
2 PCS	FRONT BUMPER FOG LAMP GRILLES @\$145.00	MIS two	\$290.00 12 0
2 PCS	HEADLAMPS @\$2660.00 2071. fox 2 = 414360	cre	\$5,320.00
1 PCS	FRONT SUPPORT PANEL	cru	\$897.00
1 PCS	FRONT SUPPORT PANEL TOP GARNISH	NS	\$311.20 🗶
1 PCS	BONNET INNER LOCK	TWI	\$105.00
2 PCS	BONNET LOCK CATCHES @\$166.00	Tui	\$332.00
1 PCS	AIR CON CONDENSER	11	\$824.00 A
1 PCS	RADIATOR	11	\$822.00
2 PCS	FRONT FENDERS @\$785.00	1 1	\$1,570.00
	7,	/	\$24,922.04
	Add to the touchest		

S.NETT

9921.06 944.00

1 PCS	FRONT LICENCE PLATE W/HOLDER		cn	\$50.00	40
1 BOT	RADIATOR COOLANT		nec	\$50.00	0.00
1 PCS	REAR END PANEL SEALANT		17	\$50.00	×
	LABOUR CHARGES:				
	TO CHECK WIRING			\$80.00	30
	TO DISMENTLE & REPLACING PDC SENSOR			\$80.00	50
	TO DISMENTLE & REFIX REAR EXHAUST		11	\$100.00	×
	TO DISMENTLE & REFIX SEAT, CUSHION UPHOLSTREY		926	\$150.00	60
	TO SPRAY RUST PROOFING			\$100.00	50
	TO REFILL AIR CON GAS			\$150.00	100
	LABOUR FOR PANEL BEATING, & REPLACING PARTS		3	\$1,800.00	900
	TO PUTTY & SPRAY PAINTING		3	\$2,200.00	1200
		TOTAL	\$	29,732.04	2880

LKK Auto Consultants nence notify the Reporter of the following:

To reside tiefore after sonly painting

- To display damaged partial during resurvey
- . Parts prices are subject to confirmation Third party survey is on a "Viridious Prejudice" basis
- No illegal modificación s à la wed
- Subtlementary names must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Business
Owner ID: Vehicle Details	8250J
Vehicle No.:	SKM6145C
Vehicle to be Exported:	No
Intended De-registration Date:	03 May 2018
Vehicle Make:	B.M.W.
Vehicle Model:	320I AT 2.0L ABS D/AIRBAG 2WD 4DR
Primary Colour:	Grey
Manufacturing Year:	2008
Engine No.:	A384I317N46B20BD
Chassis No.:	WBAPG56070NL22777
Maximum Power Output:	115.0 kW (154 bhp)
Open Market Value:	\$36,802.00
Original Registration Date:	14 Apr 2009
First Registration Date:	14 Apr 2009
Transfer Count:	1
Actual ARF Paid: Intended PARF Rebate Details	\$36,802.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	13 Apr 2019
PARF Rebate Amount: Intended COE Rebate Details	\$18,401.00
COE Expiry Date:	13 Apr 2019
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$5,982.00
COE Rebate Amount:	\$472.00
Total Rebate Amount:	\$18,873.00

The information contained herein is correct as at 03 May 2018

OK

SGCARMART.COM

New Cars

Used Cars

Sell My Car

Directory

Products

Insurance

Article



CONNECTING CAR BUYERS & SELLERS.

We'll handle your loans, insurance & other paperwork for FREE.

Find o

bmw 320

Price Range

Depreciation

2009

Vehicle Type

Map

More Actions

Home » Used Cars » Direct Owners » BMW 3 Series 320i

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle



BMW 3 Series 320i

Overview	Financial	Accessories	Similar	Research	Photo
Add to Sho		dd to Compare	Add a Note	Report	Error
Car Details					
Price	\$37,50	00			
Depreciatio	n \$21,55	0 /yr			0
	View m	odels with similar o	depreciation		8000

(10mths 28days COE left) Manufactured 2008

117,000 km (12.9k /yr)

o

Auto

01-Apr-2009

Reg Date

Mileage

Power

ARF

Transmission

Engine Cap 1,995 cc

115.0 kW (154 bhp)

Road Tax \$1,208 /yr 0

View specs of the BMW 3 Series Sedan (2005-2012)

Curb Weight 1,390 kg 0

Features

Accessories

Low Mileage, Well Maintained Regularly, Recent Description

Change Of Tyres.

COE \$5,700

OMV \$35,790

\$18,413 as of today (change) Dereg Value

No. of Owners

Type of Veh Luxury Sedan

Category PARF Car, Direct Owner Sale

\$35,790

Compare

Preferred Viewing A

Seller Infor

Contact Perso

Contact No.

Enquiry

SGCARMART.COM

New Cars .

Used Cars

Sell My Car

Directory

Products

Insurance

Article



bmw 320

Price Range

Depreciation

2009

Vehicle Type

Home » Used Cars » Speedo Motoring » BMW 3 Series 320i XL

Resources

Car Buying

Car Selling

Car Ownership

Car Aftermarket

On The Move

Lifestyle

Car Leasing CL LEASING YOUR PREFERRED GARDERS OPTION IN SINGAPORE 6769 7117 8720 5000 8720 8000

BMW 3 Series 320i XL

Overview

Financial

Accessories

Similar

Research

i ü

Photos

Map



Speedo Motoring Pt

スピードモータリング 有限会社 (Amember of Singapore Vehi

Add to Shortlist

Add to Compare

Add a Note

Report Error

o

o

0

0

More Actions

Car Details

Price

\$30,800

Depreciation

\$10,300 /yr

View models with similar depreciation

Reg Date

04-May-2009

(Tyr COE left)

Manufactured

2008

Mileage

117,995 km (13.1k /yr)

Transmission

Auto

Engine Cap

1,995 cc

Road Tax

\$1,208 /yr

Power

115.0 kW (154 bhp)

View specs of the BMW 3 Series Sedan (2005-2012)

Curb Weight

1,390 kg

Features

Powerful 2.0L 4 Cylinder Engine, Producing 154bhp, 6 Speed Automatic Transmission, Airbags, ABS, Cruise

Control, Navigation, Multi Function Steering,

Accessories

BMW Professional Audio System, GPS, Electric Leather Seat, Rear Sensor, Fog Lamps, Angel Eyes Ring With

Xenon HID Auto Head Lamps, 16" Sport Rims.

Description

In House Finance And Low Monthly Instalment \$624 Available! PML Unit! PML Serviced! Very High OMV Of

\$41,009 With Lowest Depreciation At \$10,000!





Company



Thin Thin (LKKAuto)

From: Thin Thin (LKKAuto)

Sent: Friday, 18 May 2018 1:22 PM

To: 'Jason Fastech Auto'
Cc: Vivian Lau (LKKAuto)

Subject: ACCIDENT ON 02/05/2018 INVOLVING VEHICLES SBJ 15G AND SKM 6145C

Attachments: Video - Accident (4).avi

Dear Jason, "Without

Prejudice"

ACCIDENT ON 02/05/2018 INVOLVING VEHICLES SBJ 15G AND SKM 6145C

We refer to the below matter.

We have our Principal instruction to denying liability due to no contact in between your client vehicle and our insured vehicle.

Please see the attached video footage.

Under such a circumstances, we are denying liability and unable to look into your client's claim, unless you have concrete evidence to prove otherwise.

Best Regards,

Thin Thin Hlaing | Case Handler LKK Auto Consultants Pte Ltd

Phone: 6841-2360 | email: <u>thinthin@lkkauto.com</u> | fax: 6741-4108 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Thin Thin (LKKAuto)

From:

Kesaval, Jaclyn-M < Jaclyn-M.Kesaval@aig.com>

Sent:

Monday, 7 May 2018 2:36 PM

To:

Thin Thin (LKKAuto)

Subject:

Our ref: 4591791588SG-003; Accident involving SBJ 15G and SKM 6145C

Hi Thin Thin,

As spoken, there is no contact between OI vehicle and TP vehicle.

We had sent for internal investigations and outcome is the same.

As such, please proceed to reject TP claims and let us know if TP persists on this claim.

Thank you.

Jaclyn M K AIG

Complex Claims Examiner Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1953 | Fax +(65) 6835 7416

Jaclyn-M.Kesaval@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by AIG for any loss or damage arising in any way from its use.

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.

Merimen e-Claims Page 1 of 1

...CLAIM SUBFOLDER...(Pending for Survey Report) Revoked / No settlement

LAIM SUB	FOLDER TRA	CKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj	Submitted	Ins Auth ed	Status	
Main	02 May 2018 Edit Reg		02 May 2018 00:00 Edit Adj Rpt	S\$10,000.00 Edit Estirnates		10,000.00 new Rpt		Pending for Report Cancel Cas	10940190101911 -504
	Main	R	eference	Claim t	etails		Documents		Show All
CLAIM SU	BFOLDER DE	TAILS				[Created b	oy adjuster]		
Insured:	Bay Chun	g Seng, 10: S6	806669G						
Main Claimant:	POH HUA	T CAR SERVICE	S, Co. Reg. No.: 53	3182503					
Vehicle Reg No.:	SKM614	5C		Date	of Loss:		08:00 - :59 s and 18 Days Fr	om LTA Reg Dat	e (Man Yr)]
Claim Type	TP / 459	P / 4591791588SG			/Cover	210049883	8 (Comprehensive)	
Vehicle Reg No. (Insured):	SBJ15G		Policy No. (Claimant): 5095054831						
				Exces	SI.				
Repairer	Kim Chwe	e Auto Pte Ltd	(HQ) 1 Kaki Bukit Av	renue 6 #01-48, /	utoBay	ØKaki Bukit,	417883 Eunos - T	el: 67465405/6	7417244
Handling Insurer:		Pacific Insurance esaval@aig.com	e Pte. Ltd. (Expres	s) - Tel: 65-6419	-3000	[Handled by	Kesaval, Jaclyr	1-M]	
Claimant's Insurer:	NTUC Inc	ome Insurance	Co-operative Ltd (HQ) + Tel:					
Adjuster:	LKK Auto	Consultants Pte	Ltd (HQ) - Tel: 62	56-3561 [Hand	ed by M	ARCUS CHU	A] [Final Rp	t due 11/05/	2018]
ASSOCIAT	ED MAIL RE	CEIVED					Vie	w All Compo	se Case Mail
	ALCOHOLD STATE OF THE STATE OF	NO OI GIA REPOR							
100000000000000000000000000000000000000	CIATED TAS	A MANAGEMENT OF RESIDEN		o masowers.				eate New Task	Complete
Due Date No results.	e Priority	Type Task	Group Subject	Handler	Assign	ed By	Completed On	Created O	Done

Merimen e-Claims Page 1 of 3

Claim Documents

*SKM6145C (4591791588SG)

[SBJ15G]

TP

POH HUAT CAR SERVICES

May 2 2018 8:15AM

[Bay Chung Seng]

Kim Chwee Auto Pte Ltd

Vic	ieo		1 per	page V	V
Nα	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	-
1	03/05/18 14:39	Video - Accident	0	Load AVI	
Ph	otos/Images		[2 nan	eree Ivi	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	3 per	Thumbnail	-
1	02/05/18 19:57	Chassis Number	0	Load JPG	V
2	02/05/18 19:57	General View	0	Load JPG	V
3	02/05/18 19:57	General View	0	Load JPG	N.
4	02/05/18 19:57	General View	0	Load JPG	50
5	02/05/18 19:57	General View	0	Load JPG	V
6	02/05/18 19:57	General View	0	Load JPG	V
7	02/05/18 19:57	General View	0	Load JPG	3
8	02/05/18 19:57	General View	0	Load JPG	S)
9	02/05/18 19:57	General View	0	Load JPG	V
10	02/05/18 19:57	General View	0	Load JPG	N/
11	02/05/18 19:57	General View	0	Load JPG	Ø
12	02/05/18 19:57	General View	0	Load JPG	V
13	02/05/18 19:57	General View	0	Load JPG	V
14	02/05/18 19:57	General View	0	Load JPG	V
15	02/05/18 19:57	General View	0	Load JPG	N.
16	02/05/18 19:57	General View	0	Load JPG	V
17	02/05/18 19:57	General View	0	Load JPG	V
18	02/05/18 19:57	General View	0	Load JPG	V
19	02/05/18 19:57	General View	0	Load JPG	V
20	02/05/18 19:58	General View	0	Load JPG	V
21	02/05/18 19:58	General View	0	Load JPG	V
22	02/05/18 19:58	General View	0	Load JPG	V
23	02/05/18 19:58	General View	0	Load JPG	V
24	02/05/18 19:58	General View	0	Load JPG	2
25	02/05/18 19:58	General View	0	Load JPG	V
26	02/05/18 19:58	General View	0	Load 3PG	V
27	02/05/18 19:58	General View	0	Load JPG	V
28	02/05/18 19:58	General View	0	Load JPG	Z
29	02/05/18 19:58	General View	0	Load JPG	V
30	02/05/18 19:58	General View	0	Load JPG	V
31	02/05/18 19:58	General View	0	Load JPG	V
32	02/05/18 19:58	General View	0	Load JPG	V
33	02/05/18 19:58	General View	0	Load JPG	V
34	02/05/18 19:58	General View	0	Load JPG	

VIG	eo		1 per page	V	V
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thum	bnail	The same of
20	2202200000000000				V
35	02/05/18 19:58	General View	€ Load	JPG	8
36	02/05/18 19:58	General View	€ Load	JPG	V
37	02/05/18 19:58	General View	€ Load	JPG	Y
38	02/05/18 19:58	General View	1 Load	JPG	V
39	02/05/18 19:58	General View	1 Load	JPG	V
40	02/05/18 19:58	General View	€ Load	JPG	V
41	02/05/18 19:58	General View	O Load	JPG	V
42	02/05/18 19:58	General View	1 Load	JPG	V
43	02/05/18 19:58	General View	3 Load	JPG	V
44.	02/05/18 19:58	General View	1 Load	JPG	V
45	02/05/18 19:58	General View	1 Load	JPG	V
46	02/05/18 19:58	General View	€ Load	JPG	V
47	02/05/18 19:58	General View	£ Load	JPG	V
48	02/05/18 19:58	General View	O Load	JPG	V
49	02/05/18 19:58	General View	0 Load	JPG	V
50:	02/05/18 19:58	General View	O Load	JPG	V
51	02/05/18 19:58	General View	1 Load	JPG.	V
52	02/05/18 19:58	General View	1 Load	JPG	V
53	02/05/18 19:58	General View	1 Load	JPG	1
54.	02/05/18 19:58	General View	1 Load	JPG	V
55	02/05/18 19:58	General View	Load	JPG	V
56	02/05/18 19:58	General View	€ Load	JPG	V
57	02/05/18 19:58	General View	1 Load	JPG.	V
58	02/05/18 19:58	General View	◎ Load	JPG	V
59	02/05/18 19:58	General View	O Load	JPG	W
60	02/05/18 19:58	General View	O Load	JPG	V
61	02/05/18 19:58	General View	€ Load	JPG.	V
62	02/05/18 19:58	General View	O Load	JPG	V
63	02/05/18 19:58	General View	€ Load	JPG	V
64	02/05/18 19:58	General View	€ Load	1000	N.
65	02/05/18 19:58	General View	■ Load		V
66	02/05/18 19:58	General View	€ Load		SZ.
67	02/05/18 19:58	General View	10 Load	200	V
68	02/05/18 19:58	General View	O Load	11.000	V
69	02/05/18 19:58	General View	O Load		S.
70	02/05/18 19:58	General View	O Load	-	∀
71	02/05/18 19:58	General View	O Load		N.
72	02/05/18 19:58	General View	O Load		✓
73	02/05/18 19:58	General View	O Load	Protection	V
74	03/05/18 14:37	Reinspection Photo	3 Load	showed what two	A
75	03/05/18 14:37	Reinspection Photo	O Load		∀
76	03/05/18 14:37	Reinspection Photo	O Load	Drain!	₩.
77	03/05/18 14:37	Reinspection Photo	0 Load	- Harrison	V
78	03/05/18 14:37	Reinspection Photo	O Load		S
79	03/05/18 14:37	Reinspection Photo	1 Load		□ Z1
80	03/05/18 14:37	Reinspection Photo	€ Load		V
31	03/05/18 14:37	Reinspection Photo	0 Load	1	V
32	03/05/18 14:37	Reinspection Photo Reinspection Photo	1 Load		\(\frac{1}{2} \)

Vid	eo		1 per	page 🔻	1
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (5G)		Thumbnail	_
84	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
85	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
86	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
87	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
88	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
89	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
90	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
91	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
92	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
93	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
94	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
95	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
96	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
97	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
98	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
99	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
100	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
101	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
102	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
103	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
104	03/05/18 14:37	Reinspection Photo	0	Load JPG	S)
105	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
106	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
107	03/05/18 14:37	Reinspection Photo	0	Load JPG	V
Doc	umentation		1 per s	page V	V
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	-
1	10/05/18 19:54	TP GIA REPORT	0	Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)		Thumbnail	Print
1	03/05/18 15:42	OI GIA report	0	Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
			^
			V
Show Remarks To: Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG18008006/UUA3Q2

25/05/2018 Date:

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100498838

Claimant Vehicle No:

SKM6145C

Insured Vehicle No: SBJ15G

Date of Loss:

02/05/2018 Nature of Claim: TP Claim No: 4591791588SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:

SKM6145C

Make & Model:

BMW 3201, 2.0 (A)

Engine No:

A384I317N46B20BD

Reg. Date:

14/04/2009 (Man. Year: 2008)

Chassis No: Odometer:

WBAPG56070NL22777

258386 km

Colour:

Engine Capacity: Market Value/New Car Price: N/A

1995 cc

Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:

Sum Insured (S\$):

Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:

225/45Z R17

Rear Tyre Size:

225/45Z R17

Front Left Side: Front Right Side: Kumho 6 mm Kumho 6 mm Rear Left Side: Rear Right Side: Kumho 6 mm Kumho 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	25,072.04	10,132.57	14,939.47	59.59
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,660.00	2,390.00	2,270.00	48.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	29,732.04	12,522.57	17,209.47	57.88
Approved Total (Overridden) (S\$)		10,000.00		
(S\$)	29,732.04	10,000.00	19,732.04	66.37
+ GST 7.00/7.00% (S\$)	2,081.24	700.00	1,381.24	66.37
Nett Amount (S\$)	31,813.28	10,700.00	21,113.28	66.37
Global Sum S	Settlement (S\$)	0.00		

INSPECTION

Date of Assignment:

02/05/2018

Date Inspected:

02/05/2018 Inspected At:

Kim Chwee Auto Pte Ltd (HQ) 1 Kaki Bukit Avenue 6 #01-48,

AutoBay@Kaki Bukit Singapore 417883

Estimated Period of Repair:

7.0 days

Adjuster Report Page 2 of 4

Adjuster:	MARCUS CHUA	Manager:	THIN THIN HLAING	

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,518.32 F	*-FL
2	1		*BOOTLID REAR LOGO	Not Necessary	68.00 F	*+FL
3	1.		*BOOTLID WEATHERSTRIP	Not Necessary	266.00 F	*-FL
4	1		*REAR BUMPER (50%)	Dented / Deformed	1,650.00 FS	*617.56 FS
5	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	230.00 F	*-FL
6	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
7	1		*REAR BUMPER REINFORCEMENT	Repair	715.00 F	*-FL
8	1		*REAR BUMPER TOP RETAINER	Not Necessary	181.22 F	*-FL
9	1		*REAR END PANEL	Repair	988.45 F	*-FL
10	1		*REAR END PANEL TOP GARNISH	Not Necessary	266.00 F	*-FL
11	2		*TAILLAMPS	Not Necessary	1,300.00 F	*-FL
12	1		*REAR EXHAUST	Repair	1,152.39 F	*-FL
13	2		*REAR BUMPER PDC SENSORS	Shorted (1 PCS ONLY)	450.00 F	*189.00 FL
14	1		*BONNET	Dented / Buckled	1,866.23 F	*1,866.23 FL
15	1		*BONNET LOGO	Necessary	60.00 F	*60.00 FL
16	1		*FRONT BUMPER	Dented / Deformed	1,285.00 F	*1,285.00 FL
17	1		*FRONT BUMPER CENTRE GRILLE	Torn	118.23 F	*118.23 FL
18	2		*FRONT BUMPER SIDE HOLDER	Bent	230.00 F	*230.00 FL
19	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
20	1		*FRONT BUMPER REINFORCEMENT	Repair	696.00 F	*-FL
21	2		*FRONT BUMPER TOP GRILLES	Cracked	450.00 F	*450.00 FL
22	2		*FRONT BUMPER FOG LAMPS	Not Necessary	860.00 F	*-FL
23	1		*FRONT BUMPER FOG LAMP GRILLES	N/S Twisted	290.00 F	*145.00 FL
24	2		*HEADLAMPS	Cracked	5,320.00 F	*4,143.60 FL
25	1		*FRONT SUPPORT PANEL	Cracked	897.00 F	*897.00 FL
26	1		*FRONT SUPPORT PANEL TOP GARNISH	No such part	311.20 F	*-FL
27	1		*BONNET INNER LOCK	Twisted	105.00 F	*105.00 FL
28	2		*BONNET LOCK CATCHES	Twisted	332.00 F	*332.00 FL
29	1		*AIR CON CONDENSER	Not Necessary	824.00 F	*-FL
30	1		*RADIATOR	Not Necessary	822.00 F	*-FL
31	2		*FRONT FENDERS	Repair	1,570.00 F	*- FL
32	1		*FRONT LICENCE PLATE W/HOLDER	Cracked	50.00 FS	*40.00 FS
33	1		*BOT RADIATOR COOLANT	Necessary	50.00 FS	*50.00FS
34	1		*REAR END PANEL SEALANT	Not Necessary	50.00 FS	*-FS
=Fra	inchise	part. S=Spcl	Nett. L=ListItemDisc.			
				Sub Total (S\$)		10,628.62
			- List Item Discount	on L Items 0.00/5.00% (S\$)	0.00	496.05

Total Parts (S\$) 25,072.04 10,132.57

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO CHECK WIRING	New	80.00	30.00
2	TO DISMANTLE & REPLACING PDC SENSOR	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
4	TO DISMANTLE & REFIX SEAT , CUSHION UPHOLSTERY	New	150.00	60.00
5	TO SPRAY RUST PROOFING	New	100.00	50.00
6	TO REFILL AIR CON GAS	New	150.00	100.00
7	LABOUR FOR PANEL BEATING & REPLACING PARTS	New	1,800,00	900.00
8	TO PUTTY & SPRAY PAINTING	New	2,200.00	1,200.00
	Gross Lab	our Cost (S\$)	4,660.00	2,390.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >