

INS. CASE OWNER:

CC 6 / QBE1800

8007

U 6352

LKK:

IDAC:

Surveyor:

DOI:

Date / Time:

Registered in Merimen:

Pre-assign / CCU / FTE



Insured Vehicle No.:

Name of Insured:

Insured Tel No.:

Excess Sec II : \$\$

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age: DAREN PERMIRA BIN SAHARUDIN

Driver Tel No.:

(VL: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

OI GIA REPORT: YES / NO : TP GIA REPORT: YES / NO

Insured Liability: %

Final ? Yes / No

SGP 6918x



INSRS:

WSP:

Tel:

Liability:

RMKS:

Fastech



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time:

21/5/18
Bekas

SGP 6918x

-4

XD 64675 -4

q.p. 1200, ended 7P. Email to OI.

18/11/18

File pass for type monelade

15/11/18

DV sent

21/1/19

File pass ke shu pi to don

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

18/1/19

Sent By:

JH.

FINALIZATION

Date/Time:

1

Confirm with:

Confirm by:

Repair Cost:

SS

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

18/12/18

Confirm with:

JAHUN

Email

Call

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No.:

21

If NO or B 28, Ass, Lia:

Repair Cost:

SS

12626.00

Loss of Rental (LOR):

SS

840.00

(

7

days)

X 15120.00

Loss of Use (LOU):

SS

-

(\$

x

days)

Loss of Income (LOI):

SS

-

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

SS

2.00

Medical:

SS

Disbursement:

SS

Legal Cost

SS

(e.g. Tow/ Independent)

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

\$400.00

Total:

SS

13468.00

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

13468.00

Name 1:

Fastech Auto Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

M

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / 6 / WS / TP RES / OD RES / EVA / INV / MVTo Inspect Vehicle No: SGP 6918Xat Workshop m/s PLof XD 64675

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 88k

IDAC Accident Rpt: _____ Consistent? : Yes or No

GLA / PR Seen: 2 Consistent? : Yes or NoEst. Repairs: 12 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SGP 6918X Yr Regn: 11/16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAIMake: Wish c.c. 1798Colour: silver A/C: Insured / Std / NI / NASp. Reading: 38887 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: YTDA620W30J006119Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65-R15

R: _____

BS / DUN / EXNOVA / GS / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front 7 mm Rear 7 mmR/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. 2/5/18 D.O.I. 2/5/18

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear &

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27A 6305314/5/18 2/5 211803 confirmed with AlanCreed # 16664.34/5971

Date/Time, File Pass to?

☐

Prel. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

\$ + RS, \$

Photos

Others

TOTAL

Report Format: _____

Lump Sum / I.B.I: (\$ _____)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No: 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC6/QBE18008007/Umb3		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 02-05-2018		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 6467S	Veh. Inspected	SGP 6918X	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	02/05/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/05/2018	Inspection Date	02/05/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6

#01-46/48/50 Autobay

SINGAPORE 417883

VEHCILE NO: SGP 6918X

not Authorized
note
n/s @ 11,800
12dy.
2/5/18

QTY	PARTICULAR	AMOUNT
1 PCS	REAR BUMPER 658.10	Dis \$830.20
2 PCS	REAR BUMPER SIDE RETAINERS @\$65.50	sent \$131.00
2 PCS	REAR BUMPER BRACKETS @\$68.50	Dis \$137.00
1 SET	REAR BUMPER CLIPS	rec \$50.00
2 PCS	REAR BUMPER REFLECTORS @\$49.70	11 \$99.40
1 PCS	REAR WINDSCREEN	11 \$1,545.10
1 PCS	REAR WINDSCREEN MOULDING	rec \$128.10
1 PCS	TAILGATE 1345.10	As Jm \$1,680.10
1 PCS	TAILGATE REAR LOGO	rec \$68.10
1 PCS	TAILGATE 'ELEGANCE' EMBLEM	rec \$62.50
1 PCS	TAILGATE 'VALVEMATIC' EMBLEM	rec \$48.50
1 PCS	TAILGATE OUTER CHROME MOULDING	Butler \$345.10
2 PCS	TAILGATE REFLECTORS @\$650.10 480x2=960	cre \$1,300.20
1 PCS	TAILGATE INNER LOCK	ro/jm \$409.10
1 PCS	TAILGATE INNER TRIM BOARD	De/cre \$605.10
1 SET	TAILGATE INNER TRIM BOARD CLIPS	rec \$50.00
1 PCS	TAILGATE WEATHERSTRIP	twi \$299.10
1 PCS	TAILGATE REAR WIPER MOTOR	shut/jm \$688.20
1 PCS	REAR END PANEL	As Jm \$650.10
1 PCS	REAR END PANEL TOP GARNISH	twi \$345.50
1 PCS	REAR END PANEL LOWER	As Jm \$241.50
1 PCS	REAR FLOOR PANEL	cramped/sec \$1,125.10
1 PCS	REAR FLOOR PANEL TOP BOARD	wor/jm \$456.60
2 PCS	REAR FENDERS @\$1148.10	n/s As Jm/sec 0/s R \$2,296.20
2 PCS	REAR FENDER INNER TRIM BOARDS @\$655.10	De/cro \$1,310.20
2 PCS	TAILLAMPS @\$589.10	cre \$1,178.20
2 PCS	TAILLAMP HOUSING PANELS @\$245.10	n \$490.20
1 PCS	REAR EXHAUST	n \$985.10
2 PCS	REAR EXHAUST MOUNTINGS @\$45.50	11 \$91.00
1 PCS	REAR EXHAUST HEAT SHIELD	11 \$185.40
1 PCS	REAR FENDER GLASS N/S	shotted \$680.10
1 PCS	REAR DOOR N/S	n \$1,125.10
1 PCS	REAR DOOR INNER LOCK N/S	rm/jm \$392.50

25/18

1 PCS	REAR END PANEL LOCK SENSOR
2 PCS	REAR BUMPER SPLASH SHIELDS @\$105.10
1 PCS	REAR AIR VENT
1 PCS	REAR CHASSIS MEMBER N/S
1 PCS	REAR FLOOR PANEL N/S PANEL
1 PCS	REAR SPARE TYRE CARRIER

310	\$248.50	✓
0/5 70-11	\$210.20	1PC
one	\$62.50	✓
n	\$665.10	x
n	\$168.30	x
11	\$345.10	x
	\$21,729.30	
	13927	

	S.NETT
1 SET	REAR BUMPER REVERSE SENSOR
1 PCS	REAR REVERSE CAMERA
1 PCS	REAR WINDSCREEN SEALANT
1 PCS	REAR FENDER GLASS SEALANT N/S
1 PCS	REAR FLOOR PANEL INSULATOR
1 PCS	REAR LICENCE PLATE W/HOLDER

shuf	\$280.00	200
shuf	\$680.00	300
ru	\$50.00	40
ru	\$50.00	40
ru	\$200.00	100
3ent	\$50.00	40

LABOUR CHARGES:

TOWING CHARGE	
TO CHECK WIRING	
TO DISMENTLE & REPLACING REVERSE SENSOR	
TO DISMENTLE & REFIX REAR WINDSCREEN	
TO DISMENTLE & REPLACING REAR FENDER GLASS	
TO DISMENTLE & REFIX REAR EXHAUST	
TO DISMENTLE & REFIX SEAT,CUSHION UPHOLSTREY	
TO DISMENTLE & REFIX PETROL TANK	
TO MOUNT VEHICLE ON CAR O-LINER	
LABOUR FOR PANEL BEATING,CUT,WELD,STRIAGHTENED	
REPLACING PARTS	
TO PUTTY & SPRAY PAINTING	

11	\$65.00	x
	\$80.00	30
	\$80.00	50
	\$150.00	120
	\$150.00	100
11	\$100.00	x
	\$120.00	80
	\$100.00	60
11	\$380.00	x
	\$2,200.00	200
	\$2,000.00	1200

TOTAL \$28,464.30

14605.25

- 1.4- Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Shu Pei (LKKAuto)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Monday, 7 May 2018 8:57 AM
To: Shu Pei (LKKAuto)
Cc: Admin A; Bevan Lim (LKK Auto)
Subject: RE: Direct Settlement - Accident Involving XD6467S (OI : QBE - TBA) AND SGP6918X (TP : LKK REF - CC6/QBE18008007/Umb3) on 02.05.2018
Attachments: XD6467S-02052018.pdf

Our Ref. VC011435


Hi

Attached OI report for your retention.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAuto) [mailto:shupeil@lkkauto.com]
Sent: Thursday, 3 May, 2018 6:45 PM
To: Joyce Foo <joyce.foo@qbe.com>
Cc: Admin A <admin-a@lkkauto.com>; Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>
Subject: Direct Settlement - Accident Involving XD6467S (OI : QBE - TBA) AND SGP6918X (TP : LKK REF - CC6/QBE18008007/Umb3) on 02.05.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SGP 6918X at M/s Fastech Auto Pte Ltd.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Bevan and he can be contacted at DID: 6749 4274.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupej@lkkauto.com | fax: 6741-4108

Blk S1, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

Hsiao Tong (LKKAUTO)

From: Hsiao Tong (LKKAUTO)
Sent: Saturday, 1 December 2018 12:31 PM
To: 'Joyce Foo'
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving XD6467S (OI : QBE - VC011435) AND SGP6918X (TP : LKK REF - CC6/QBE18008007/Umb3) on 02.05.2018
Attachments: LKKInspection.pdf; LKKAdjustment1.pdf; LKK Survey Photos.pdf; LKK Resurvey Photos 1.pdf; LKK Resurvey Photos 2.pdf; TP LOD_SGP6918X.pdf

Your ref : **VC011435**

Our ref : CC6/QBE18008007/Umb3s2

Dear Sirs/Madam,

We refer to the above matter.

This is a head-to-rear collision. Liability is not in our insured driver's favour.

We seek your approval to offer Third Party repairer "**Fastech Auto Pte Ltd**" at **\$13,608.00(all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 30,456.80	\$ 12,626.00
2. Loss of Rental (7days x \$180.00)	\$ 1,260.00	\$ 980.00 (7days x \$140.00)
3. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 31,718.80	<u>\$ 13,608.00</u>

**12days recommendation for repair.

Enclosed here with all the relevant documents for your perusal.

For your approval/instruction please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAUTO)

Sent: Thursday, 18 October 2018 11:33 AM

To: 'Joyce Foo' <joyce.foo@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving XD6467S (OI : QBE - VC011435) AND SGP6918X (TP : LKK REF - CC6/QBE18008007/Umb3) on 02.05.2018

Hsiao Tong (LKKAUTO)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Tuesday, 4 December 2018 2:53 PM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: RE: Direct Settlement - Accident Involving XD6467S (OI : QBE - VC011435) AND SGP6918X (TP : LKK REF - CC6/QBE18008007/Umb3) on 02.05.2018

Your ref : **VC011435**
Our ref : CC6/QBE18008007/Umb3s2

Dear Sirs/Madam,

Please proceed to settle as advised.

Thanks & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific - Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Hsiao Tong (LKKAUTO) <chewht@lkkauto.com>
Sent: Saturday, 1 December 2018 12:31 PM
To: Joyce Foo <joyce.foo@qbe.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving XD6467S (OI : QBE - VC011435) AND SGP6918X (TP : LKK REF - CC6/QBE18008007/Umb3) on 02.05.2018

Your ref : **VC011435**
Our ref : CC6/QBE18008007/Umb3s2

Dear Sirs/Madam,

We refer to the above matter.

This is a head-to-rear collision. Liability is not in our insured driver's favour.

We seek your approval to offer Third Party repairer "**Fastech Auto Pte Ltd**" at **\$13,608.00(all-in).**

The summary is as follows: -

	Amount Claimed	Amount Revised
1. Cost of Repair (w/GST)	\$ 30,456.80	\$ 12,626.00
2. Loss of Rental (7days x \$180.00)	\$ 1,260.00	\$ 980.00 (7days x \$140.00)
3. LTA/ GIA Search Fee	\$ 2.00	\$ 2.00
Total	\$ 31,718.80	\$ 13,608.00

**12days recommendation for repair.

Enclosed here with all the relevant documents for your perusal.

For your approval/instruction please.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Hsiao Tong (LKKAuto)

Sent: Thursday, 18 October 2018 11:33 AM

To: 'Joyce Foo' <joyce.foo@qbe.com>

Cc: Admin A <admin-a@lkkauto.com>

Subject: RE: Direct Settlement - Accident Involving XD6467S (OI : QBE - VC011435) AND SGP6918X (TP : LKK REF - CC6/QBE18008007/Umb3) on 02.05.2018

Dear Sirs/ Mdm,

We refer to the above matter.

Enclosed for your perusal is: -

- Estimated cost of repair
- Preliminary advice
- Photographs of TP vehicle in its damaged condition

Thank you.

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Joyce Foo <joyce.foo@qbe.com>
Sent: Monday, 7 May 2018 8:57 AM
To: Shu Pei (LKKAuto) <shupeil@lkkauto.com>
Cc: Admin A <admin-a@lkkauto.com>; Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>
Subject: RE: Direct Settlement - Accident Involving XD6467S (OI : QBE - TBA) AND SGP6918X (TP : LKK REF - CC6/QBE18008007/Umb3) on 02.05.2018

Our Ref. VC011435


Hi

Attached OI report for your retention.

Thank You & Best Regards

Joyce Foo
Senior Assistant - Claims
QBE Asia Pacific – Singapore

QBE Insurance (Singapore) Pte Ltd
Phone: +65 6477 1184
Email: joyce.foo@qbe.com
Visit us on the web at www.qbe.com.sg



From: Shu Pei (LKKAuto) [<mailto:shupeil@lkkauto.com>]
Sent: Thursday, 3 May, 2018 6:45 PM
To: Joyce Foo <joyce.foo@qbe.com>
Cc: Admin A <admin-a@lkkauto.com>; Bevan Lim (LKK Auto) <bevanlim@lkkauto.com>
Subject: Direct Settlement - Accident Involving XD6467S (OI : QBE - TBA) AND SGP6918X (TP : LKK REF - CC6/QBE18008007/Umb3) on 02.05.2018

WITHOUT PREJUDICE

Dear Sir/Madam,

We refer to the above matter.

This is a TP direct settlement case. We had inspected TP vehicle SGP 6918X at M/s Fastech Auto Pte Ltd.

Enclosed for your perusal is:

- TP GIA report

Please be informed that estimated cost of repair and preliminary advice is not ready yet.

Meanwhile, kindly let us have a copy of your insured's GIA report for our necessary action.

Kindly take note that the case handler in-charge is Bevan and he can be contacted at DID: 6749 4274.

Thank you.

Best Regards,

Shu Pei | Admin

LKK Auto Consultants Pte Ltd

Phone: 6366-0055 | email: shupeil@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

IMPORTANT NOTICE : The information in this email is confidential and may also be privileged. If you are not the intended recipient, any use or dissemination of the information and any disclosure or copying of this email is unauthorised and strictly prohibited. If you have received this email in error, please promptly inform us by reply email or telephone. You should also delete this email and destroy any hard copies produced.

From: Jason Fastech Auto <jason@fastechauto.com.sg>
Sent: Monday, 10 December 2018 10:07 AM
To: Hsiao Tong (LKKAUTO)
Cc: Admin A
Subject: RE: Your ref: SGP 6918X *Our Ref: CC6/QBE18008007/Umb3s2 [ACCIDENT INVOLVING XD 6467S(QBE) & SGP 6918X ON 02/05/2018]

1

3. LTA/ GIA Search Fee

\$ 2.00

TOTAL \$13,468.00

Please confirm acceptance.

"Kindly note that this negotiation between parties on this matter is purely on a without prejudice basis with the sole intention of resolving the matter amicably without parties resorting to legal proceedings. No admission of liability, whatsoever, should be deemed / inferred from this negotiation of terms/settlement.

In the event of new evidence being discovered or subsequently produced by either party that will materially affect/influence on the issues of liability/damages, either party is not bound, thereafter, by the negotiation terms/settlement."

Best Regards,

Hsiao Tong, Chew | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6742-3197 | email: chewht@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
QBE INSURANCE (SINGAPORE) PTE LTD		Ref : CC6/QBE18008007/Upb3s2		
1 RAFFLES QUAY #29-10 SOUTH TOWERSINGAPORE 048583		Date : 09-01-2019		
		Code : QBE		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	XD 6467S	Veh. Inspected	SGP 6918X	
Policy No.	8-V0016105-MVA	Coverage (\$)	0.00	
Claim No.	VC011435	Excess (\$)	0.00	
Assign From		Assign Date	02/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA WISH (A)	c.c	1798	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JTDGG20W30J006119	Colour	SILVER	
Odometer	38887	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65R15	GOODYEAR	7 mm	
L/H Front Tyre	195/65R15	GOODYEAR	7 mm	
R/H Rear Tyre	195/65R15	GOODYEAR	7 mm	
L/H Rear Tyre	195/65R15	GOODYEAR	7 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. THE CHASSIS FRAME AFFECTED DUE TO COLLISION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/05/2018	Inspection Date	02/05/2018	
Survey held at	FASTECH AUTO PTE LTD 1 KAKI BUKIT AVENUE 6 #01-46/48/50 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		12 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGP 6918X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DISTORTED	830.20	656.10
2	REAR BUMPER SIDE RETAINERS @ \$65.50	BENT	131.00	131.00
2	REAR BUMPER BRACKETS @ \$68.50	DISTORTED	137.00	137.00
1	SET REAR BUMPER CLIPS	NECESSARY	50.00	50.00
2	REAR BUMPER REFLECTORS @ \$49.70	NOT NECESSARY	99.40	-
1	REAR WINDSCREEN	NOT NECESSARY	1,545.10	-
1	REAR WINDSCREEN MOULDING	NECESSARY	128.10	128.10
1	TAILGATE	BADLY DENTED	1,680.10	1,345.10
1	TAILGATE REAR LOGO	NECESSARY	68.10	68.10
1	TAILGATE 'ELEGANCE' EMBLEM	NECESSARY	62.50	62.50
1	TAILGATE 'VALVEMATIC' EMBLEM	NECESSARY	48.50	48.50
1	TAILGATE OUTER CHROME MOULDING	BENT / CRACKED	345.10	345.10
2	TAILGATE REFLECTORS @ \$650.10	CRACKED	1,300.20	960.00
1	TAILGATE INNER LOCK	DENTED / JAMMED	409.10	409.10
1	TAILGATE INNER TRIM BOARD	DEFORMED / CRACKED	605.10	605.10
1	SET TAILGATE INNER TRIM BOARD CLIPS	NECESSARY	50.00	50.00
1	TAILGATE WEATHERSTRIP	TWISTED	299.10	299.10
1	TAILGATE REAR WIPER MOTOR	SHORTED / JAMMED	688.20	688.20
1	REAR END PANEL	BADLY DENTED	650.10	650.10
1	REAR END PANEL TOP GARNISH	TWISTED	345.50	345.50
1	REAR END PANEL LOWER	BADLY DENTED	241.50	241.50
1	REAR FLOOR PANEL	CRUMPLED / BUCKLED	1,125.10	1,125.10
1	REAR FLOOR PANEL TOP BOARD	WARPED / DENTED	456.60	456.60
2	REAR FENDERS @ \$1148.10	N/S BADLY DENTED/BUCKLED/O/S TO REPAIR SEE LABOUR	2,296.20	1,148.10
2	REAR FENDER INNER TRIM BOARDS @ \$655.10	DEFORMED / CRACKED	1,310.20	1,310.20
2	TAILLAMPS @ \$589.10	CRACKED	1,178.20	1,178.20

Report Ref No. CC6/QBE18008007/Upb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	TAILLAMP HOUSING PANELS @ \$245.10	TO REPAIR SEE LABOUR	490.20	-
1	REAR EXHAUST	TO REPAIR SEE LABOUR	985.10	-
2	REAR EXHAUST MOUNTINGS @ \$45.50	NOT NECESSARY	91.00	-
1	REAR EXHAUST HEAT SHIELD	NOT NECESSARY	185.40	-
1	REAR FENDER GLASS N/S	SHORTED	680.10	680.10
1	REAR DOOR N/S	TO REPAIR SEE LABOUR	1,125.10	-
1	REAR DOOR INNER LOCK N/S	TWISTED / JAMMED	392.50	392.50
1	REAR END PANEL LOCK SENSOR	BROKEN	248.50	248.50
2	REAR BUMPER SPLASH SHIELDS @ \$105.10	O/S TORN	210.20	105.10
1	REAR AIR VENT	CRACKED	62.50	62.50
1	REAR CHASSIS MEMBER N/S	TO REPAIR SEE LABOUR	665.10	-
1	REAR FLOOR PANEL N/S PANEL	TO REPAIR SEE LABOUR	168.30	-
1	REAR SPARE TYRE CARRIER	NOT NECESSARY	345.10	-
	LESS 25% DISCOUNT		-	-3,481.75
			21,729.30	10,445.25
	<u>SPECIAL NETT ITEMS</u>			
1	SET REAR BUMPER REVERSE SENSOR (SN)	SHORTED	280.00	200.00
1	REAR REVERSE CAMERA (SN)	SHORTED	680.00	300.00
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	50.00	40.00
1	REAR FENDER GLASS SEALANT N/S (SN)	NECESSARY	50.00	40.00
1	REAR FLOOR PANEL INSULATOR (SN)	NECESSARY	200.00	100.00
1	REAR LICENCE PLATE W/HOLDER (SN)	BENT	50.00	40.00
			1,310.00	720.00
	<u>LABOUR</u>			
	TOWING CHARGE.	NOT NECESSARY	65.00	-
	TO CHECK WIRING.		80.00	30.00
	TO DISMANTLE & REPACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX REAR WINDSCREEN.		150.00	120.00
	TO DISMANTLE & REPLACING REAR FENDER GLASS.		150.00	100.00

Report Ref No. CC6/QBE18008007/Upb3s2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO DISMANTLE & REFIX REAR EXHAUST.	NOT NECESSARY	100.00	-
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		120.00	80.00
	TO DISMANTLE & REFIX PETROL TANK.		100.00	60.00
	TO MOUNT VEHICLE ON CAR-O-LINER.	NOT NECESSARY	380.00	-
	LABOUR FOR PANEL BEATING, CUT, WELD, STRAIGHTENED REPLACING PARTS. INCLUSIVE OF THE REPAIR OF O/S REAR FENDERS, TAILLAMP HOUSING PANELS, REAR EXHAUST, REAR DOOR N/S, REAR CHASSIS MEMBER N/S AND REAR FLOOR PANEL N/S PANEL.		2,200.00	2,000.00
	TO PUTTY AND SPRAY PAINTING.		2,000.00	1,200.00
			5,425.00	3,640.00
GRAND TOTAL			28,464.30	14,805.25
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				11,800.00

Report Ref No. CC6/QBE18008007/Upb3s2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.