

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
SOMPO INSURANCE SINGAPORE PL			Ref:	CS3/SMO18008008/	Gz4be2	
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND TOWERSINGAPORE 048623			Date:	18-07-2018		
			Code:	SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)						
	Insured Veh.	FR 5006K	Veh. Inspected		JPX 1425	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	CMTD1801860/GPL	Excess (\$)		0.00	
	Assign From	GRACE TEO	Assign Date		02/05/2018	
2. Vehicle Particulars & Condition						
	Make & Model	YAMAHA	c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour		BLACK	
	Odometer	84564 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modifi	cation	NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	70/90-17	MAXXI	S	5 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	80/90-17	MAXXI	S	5 mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
	THE VEHICLE SUS PORTION.	HICLE SUSTAINED DAMAGES AT THE O/S, N/S BODY AND FRONT N.				
5.	General Information					
	Accident Date	25/04/2018	Insped	ct Date / Time	03/05/2018 (06:00 PM)	
	Survey held at	at CARZ AUTO SERVICES PTE LTD				
		1 KAKI BUKIT AVE 6 #02-35 AUTOBAY @ KAKI BUKIT SINGAPORE 417883				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000					
5b.	Estimate Days of Repair					

Report Ref No. CS3/SMO18008008/Gz4be2

Inspected By

ESTIMATED NORMAL PERIOD FOR REPAIR:

XING GUO QIANG

K.K.LAU CPT(RET)

5 Working Days

M.MATAI, AMSAE-A BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

Automotive Assessor REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.