

22/03/2002

ASS. REC. BY:

REF: CS/FCU8008015/Gtber

Special Instruction:

Surveyor

GA

ASSIGNMENT (Office)From (Person): WBS Karen Tan of FCL Date/Time: 02052018 1459pm

Estimated Cost: _____ Bill to: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: STV 1001G Insured: SHC 8936Lat Workshop m/s Auto N Cars Tel: 6555 2909of B1k 1 Kaki Bukit Ave 6 #07-04Policy No: _____ Claim No: D18003402MFSH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 29042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'up' 07052018 @ 10amDate/Time: 02052018 533pm Person Contacted: Darla H.O.D. Endorsement: _____Vehicle IN / OUT

Date/Time Action/Instruction (✓) Estimate

STV 1001G - CA / ALG 10003407 / p1 DCA: 17022010

SHC 8936L - PC3 / ALG 14003335 / H1ro3c3 DCA: 17022014

21/5/18 3:03pm inform by insurance cancel case.

Submit preli advise.

Signature: Xhe

REF: FCL

2798F

ASSIGNMENT

From: Date: 07052018

Estimated Cost:

OD TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SJV 1001G

at Workshop m/s

of

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Cycle / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Air / or

Tyre Size:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 13 JUL 2018

Date/Time, File Pass to?

1) 13/7/18 Typist

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)

☒ Preli. Report

☐ Final Report

Days Of Repair: 8

Resurvey No. of Trip: -

Add Fee:

☐

Site Insp (\$)

☐

Interview (\$)

☐

Tech. Invs (\$)

☐

Weekend (\$)

Survey Fee:

Transportation

\$ + RS \$

Photo

Other

TOTAL

11x15-165

170x165

50

38

423

MOTOR SURVEY ASSIGNMENT

Date	02-05-2018	Our Ref No. D18003402MFSH
Accident Date	29-04-2018	Claim Type. Third Party
Insured Vehicle	SHC8936L	Third Party Vehicle. SJV1001G
Survey Location	AUTOBAY @ KAKI BUKIT BLK 1 AREA "A" KAKI BUKIT AVE 6#01-04	
Contact Person.	DARLA BALINGIT	
Contact No.	65552909/ 84993326	Fax No. 68417181
Survey Type	WITHOUT PREJUDICE:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	AUTO N CARS SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	KARENT	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.

This is a computer generated letter, no signature required.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department

MS First Capital Insurance Limited

From: Catherine Chong (LKK Auto) [<mailto:admin-d@lkkauto.com>]
Sent: Wednesday, May 02, 2018 3:07 PM
To: 'Claim Workflow System'; ASSIGNMENTS@LKKAUTO.COM
Cc: KARENTAN@MSFIRSTCAPITAL.COM.SG; 'SUR'
Subject: RE: SURVEY ASSESSMENT - D18003402MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 2 May, 2018 4:59 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG;
KARENTAN@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003402MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

Tel : 6507 3848

Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	29/04/2018 15:10
Date Of Accident	29/04/2018 11:15
Exact Location Of Accident	JUNCTION OF ROCHOR ROAD AND BEACH ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJV1001G
Insured/Policyholder	
Name Of Registered Owner	CHEW HOCK LENG
NRIC No	S7212798F
Email Address	COLIN@CISEERN.COM
Mobile Phone No	(LOCAL) +65-91010011
Alternative Phone No	OTHERS-91010011

Vehicle Particulars

Manufacturer	AUDI
Model	Q5 2.0 SUV
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	EQ INSURANCE COMPANY LTD
Type Of Coverage	COMPRÉHENSIVE
Fleet Policy	NO
Policy Number	DMPPHQ17-005393
Cover Note Number	N.A

Driver

Name of Driver	CHEW HOCK LENG
NRIC No	S7212798F
Date Of Birth	17/04/1972
Occupation	INDOOR
Date Of Driving Pass	27/09/1993
Driving Experience	24 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-91010011
Fax Number	
Contact Number	OTHERS-91010011
Email Address	COLIN@CISEERN.COM

Address	HEDGES PARK CONDOMINIUM, 83 FLORA DRIVE #03-39
Postcode	506887
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - CHANGE/CROSS LANE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : CAELYN CHEW GENDER: : FEMALE
Passenger 2	NAME: : CAERISSE CHEW GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

I was at the traffic junction of Rochor Road and Beach Road. I was on the 2nd lane from the right on Rochor Road making a right turn into the 2nd lane from the right on Beach Road when a taxi SHC8936L on my right side turn into my lane and its front left side collided onto my car right rear side. Damages to my car were on the right side and right rear portion. No injuries were involved.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8936L
Vehicle Make/Model/Colour	HYUNDAI I40 1.7 / BLU
Details Of Properties	NIL
Vehicle Category	TAXI
Name of Driver	
NRIC/Passport Number	
Contact Number	
Address	

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes");
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

[Signature]


Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

VERIFIED BY AJAX MARS
REPORTING OFFICER
Muhammad Faizal
Bin Pablia

Witnessed by Reporting Centre
Personnel

Sketch Plan



Common Statement Pg. 1

ACCIDENT STATEMENT (2000 characters)

I was at the traffic junction of Rochor Road and Beach Road. I was on the 2nd lane from the right on Rochor Road making a right turn into the 2nd lane from the right on Beach Road when a taxi SHC8936L on my right side turn into my lane and its front left side collided onto my car right rear side. Damages to my car were on the right side and right rear portion. No injuries were involved.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -
MUHAMMAD FAIZAL BIN PABILA

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

29 April 2018 at 1:56 PM

Date/Time:

29 April 2018 at 1:56 PM

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	2798F
Vehicle Details	
Vehicle No.:	SJV1001G
Vehicle to be Exported:	No
Intended De-registration Date:	08 May 2018
Vehicle Make:	AUDI
Vehicle Model:	Q5 2.0 TFSI A
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	CDN139691
Chassis No.:	WAUZZZ8R6BA013866
Maximum Power Output:	155.0 kW (207 bhp)
Open Market Value:	\$40,464.00
Original Registration Date:	04 Nov 2010
First Registration Date:	04 Nov 2010
Transfer Count:	0
Actual ARF Paid:	\$40,464.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	03 Nov 2020
PARF Rebate Amount:	\$24,278.00
Intended COE Rebate Details	
COE Expiry Date:	03 Nov 2020
COE Category:	E - Open Category
COE Period(Years):	10
QP Paid:	\$44,001.00
COE Rebate Amount:	\$10,942.00
Total Rebate Amount:	\$35,220.00
Message	

Please note that the National Environment Agency (NEA) is offering an incentive of up to \$3,500 for owners of older, more pollutive motorcycles which were registered before 1 July 2003, to de-register their motorcycles on or before 5 April 2023.

The last registered owner of this motorcycle will receive \$2,000 if it is de-registered on or before 5 April 2023. If this motorcycle's COE is not renewed on or after 7 April 2018, the last registered owner will receive an additional \$1,500 upon its de-registration on or before 5 April 2023.

This motorcycle will no longer be allowed for use on Singapore's roads after 30 June 2028.

► audi q5 Used Vehicle List (12 vehicles)

Car Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Company	Availabi
Audi Q5 2.0A TFSI Quattro	\$62,838	\$15,660 /yr	03-Dec-2010	1,984 cc	93,000 km	Hoe Beng Auto Trading	Availat
Beautiful Q5 Among Its Class! Non Smoker Unit! Always Parked Under Shelter. Service Regulary Without Fail! Original Paint, Beautiful Leather Seats. 6 Months Warranty In Engine And Gearbox! We Deliver ... Office No. - 67450138 / 65523003 Eric - 83538778 Agnes - 93680138							
Audi Q5 2.0A TFSI Quattro	\$63,800	\$17,080 /yr	25-Nov-2010	1,984 cc	80,000 km	Alyon Motoring	Availat
Nice SUV With Panoramic Roof, Paddle Shift, Audi Symphony Audio System. Super Low Mileage. Responsive And Fun Drive. Well Taken Care. Call Us For Your Viewing Appointment. Office No. - 61005105 Jason - 96627277 Jaslyn - 97383617 Yang Han - 97984297							
Audi Q5 2.0A TFSI Quattro	\$58,800	\$15,130 /yr	08-Sep-2010	1,984 cc	93,000 km	Henly Enterprises Co	Availat
Elegant And Powerful Q5 Family SUV. Moderate Mileage Clocked Matching Leather Trim, Definitely The Better Q5 Which You Need To Check Out, Viewing Appointment, So Please Call. Sales Mobile Line And ... Office No. - 67476011 Alan Seah - 96622171 Edwin - 92331607							
Audi Q5 2.0A TFSI Quattro	\$55,000	\$14,050 /yr	20-Aug-2010	1,984 cc	115,000 km		Availat
Serviced And Maintained By Renowned Audi Specialist. Always Parked Under Shelter. Accident Free And Well Maintained By Owner. Office No. - - Benjamin - 93362266							
Audi Q5 2.0A TFSI Quattro	\$52,000	\$15,430 /yr	28-Jun-2010	1,984 cc	91,014 km	Prem Roy Motoring	Availat
Careful Lady Driver. Car Is In Immaculate Condition. Beautiful M4 Austin Yellow Spray Work And To Top It Of Black Rims. Surely A Rare Colour Combinat On An Audi Q5, Definitely A Head Turner! View T... Office No. - 66028046 Raj - 98474881 Ashvini - 98896985							
Audi Q5 2.0A TFSI Quattro	\$49,800	\$13,180 /yr	01-Jun-2010	1,984 cc	-	Hui Hua Credit Pte Ltd	Availat
Agent Unit! Beautifully Maintained, Parked Under Shelter, Accident Free, Trade In And Flexible In House Loan Options Available! Call Now To View! Office No. - 64666611 Jian Rong - 91830337 Jevon Ng - 88588388 Weisley Koh - 84888000 Jarryl Ng - 85888000							
Audi Q5 2.0A TFSI Quattro	\$48,600	\$12,820 /yr	22-Apr-2010	1,984 cc	166,123 km		Availat
Orig. Condition From Audi, Replace Engine Top Timing Cover Set, Coolant Pump Set, Oil Pressure Switch, Engine Starter, Engine Mounting Set, Front Anti Roll Bar Bush, DSG Gearbox Clutch, ATF, Strainer/... Office No. - - Philip - 92383353							
Audi Q5 2.0A TFSI Quattro	\$45,888	\$13,770 /yr	21-Apr-2010	1,984 cc	-	Cosmo Automobiles	Availat
Comes With Panoramic Roof! Rarely Driven/Parked Sheltered Carpark. Owner Only Use Company Car. Overhauled Major Engine/Gearbox Parts, All New Parts! Best Condition Unit In The Market Perfect To Drive ... Office No. - 64651090 Derrick - 91012525							
Audi Q5 2.0A TFSI Quattro	\$53,800	\$18,060 /yr	05-Apr-2010	1,984 cc	-	GA Auto Enterprise	Availat
Purchase Car With Ease Of Mind As It Comes With One Year Extended Warranty. Quattro With Panoramic Full Screen Moonroof. Ultra Metallic New Paint. Service Records And Well Maintained. Low Mileage... Office No. - 66598588 Jie - 93857523 Susan - 81237475							



Co. Reg: 200922097K GST Reg.No: 200922097K
 Auto Bay @ Kaki Bukit Blk 1 Area "A" Kaki Bukit Ave 6 #01-04 (S) 417883
 • Tel: (65) 6555 2909 • Fax: (65) 6841 7181 • Web: www.autoncars.com.sg

Date : 4/5/2018

Total Pages : 2

TO: **First Capital Insurance Ltd**
 36 Robinson Road
 #16-01 City House
 Singapore 068877

Our Customer : CHEW HOCK LENG
 Vehicle No : **SJV1001G**
 Model : AUDI Q5 2.0 SUV
 Manufacture Year : 2010
 Date of Accident : 29/04/2018

Total Estimate Repair Days : 10

Attn : Motor Claim Department
 Email :

Re: Repair Estimate For Third Party Claim against : SHC8936L

No.	Item Descriptions	Qty	Unit Price	Amount	Remarks from Surveyor
A.	Spare Parts				
1	RH front door / <i>BMC</i>	1	\$2,100.50	\$2,100.50	
2	RH front door rubber beading / <i>MCL</i>	1	\$255.80	\$255.80	
3	RH front door lower protector / <i>Cut</i>	1	\$255.20	\$255.20	
4	RH front door lower protector clips / <i>MCL</i>	8	\$3.80	\$30.40	
5	RH front door lower inner moulding / <i>MCL</i>	1	\$115.20	\$115.20	
6	RH rear door / <i>BMC</i>	1	\$1,950.80	\$1,950.80	
7	RH rear door rubber beading / <i>MCL</i>	1	\$250.10	\$250.10	
8	RH rear door lower protector / <i>Cut</i>	1	\$250.10	\$250.10	
9	RH rear door lower inner moulding / <i>MCL</i>	1	\$115.20	\$115.20	
10	RH rear door arch rubber moulding / <i>MCL</i>	1	\$135.10	\$135.10	
11	RH rear door hinges X <i>wn</i>	2	\$68.50	\$137.00	
12	RH rear door lock mechanism X <i>wn</i>	1	\$520.20	\$520.20	
13	RH rear door fender / <i>BMC (before first photo)</i>	1	\$3,250.80	\$3,250.80	
14	RH rear fender arch rubber moulding / <i>TR</i>	1	\$135.20	\$135.20	
15	RH rear fender splash shield / <i>CRA</i>	1	\$280.10	\$280.10	
16	RH rear fender splash shield clips / <i>MCL</i>	14	\$3.80	\$53.20	
17	Rear bumper retainers / <i>MCL</i>	2	\$98.10	\$196.20	
18	RH rear sport rim / <i>Cut</i>	1	\$1,540.50	\$1,540.50	?
19	RH rear tyre / <i>Cut</i>	1	\$380.00	\$380.00	200.
20	RH rear knuckle with bearing assembly ?	1	\$1,310.90	\$1,310.90	
21	RH rear lower arm X <i>wn</i>	1	\$952.10	\$952.10	
22	RH rear shock absorber X <i>wn</i>	1	\$298.50	\$298.50	
23	RH rear upper arm X <i>wn</i>	1	\$598.50	\$598.50	
24	Body sealant / <i>MCL</i>	2	\$25.00	\$50.00	
25	Rear axle assembly X <i>wn</i>	1	\$3,350.20	\$3,350.20	
	<i>Rocker panel Rubber / MCL</i>		Sub Total	\$18,511.80	
			Less 10%	\$1,851.18	
			Sub Total 1	\$16,660.62	
B.	Labour				
1	To knock and straighten RH center pillar. Cut and weld damaged panel. To adjust and realign the same		\$1,600.00		800-1000
2	To putty and spray RH front door, RH center pillar, RH rocker panel, RH rear door, RH front, RH rear door protector, Rh rear fender and rear bumper		\$1,300.00		800
3	To remove and refit rear seat, rear sport rim, roof lining to assist workload		\$300.00		60.
4	To remove and refit RH rear fender 1/4 glass		\$100.00		60
5	To remove and transfer RH front and RH rear door fitting and fixture. To conduct water seepage and window noise test		\$350.00		120




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18008015/Gtbe2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 20-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 8936L	Veh. Inspected	SVJ 1001G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003402MFSH	Excess (\$)	0.00	
Assign From	KAREN TAN	Assign Date	02/05/2018	
2. Vehicle Particulars & Condition				
Make & Model	AUDI Q5	c.c	1984	
Engine No.	HIDDEN	Year of Reg.	2010	
Chassis No.	WAUZZZ8R6BA013866	Colour	BLACK	
Odometer	145141	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/65 R17	MICHELIN	6 mm	
L/H Front Tyre	235/65 R17	MICHELIN	6 mm	
R/H Rear Tyre	235/65 R17	MICHELIN	6 mm	
L/H Rear Tyre	235/65 R17	MICHELIN	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY.THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/04/2018	Inspection Date	07/05/2018	
Survey held at	AUTO N CARS SERVICES PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-90 AUTOBAY @ KAKI BUKIT SINGAPORE 417883.			
5a. Remarks				
A)DAMAGES CONSISTENT TO ACCIDENT REPORT. B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJV 1001G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH FRONT DOOR	BUCKLED	2,100.50	2,100.50
1	RH FRONT DOOR RUBBER BEADING	NECESSARY	255.80	255.80
1	RH FRONT DOOR LOWER PROTECTOR	CUT	255.20	255.20
8	RH FRONT DOOR LOWER PROTECTOR CLIPS @\$3.80	NECESSARY	30.40	30.40
1	RH FRONT DOOR LOWER INNER MOULDING	NECESSARY	115.20	115.20
1	RH REAR DOOR	BUCKLED	1,950.80	1,950.80
1	RH REAR DOOR RUBBER BEADING	NECESSARY	250.10	250.10
1	RH REAR DOOR LOWER PROTECTOR	CUT	250.10	250.10
1	RH REAR DOOR LOWER INNER MOULDING	NECESSARY	115.20	115.20
1	RH REAR DOOR ARCH RUBBER MOULDING	NECESSARY	135.10	135.10
2	RH REAR DOOR HINGES @\$68.50	NOT NECESSARY	137.00	-
1	RH REAR DOOR LOCK MECHANISM	NOT NECESSARY	520.20	-
1	RH REAR DOOR FENDER	BUCKLED	3,250.80	3,250.80
1	RH REAR FENDER ARCH RUBBER MOULDING	TORN	135.20	135.20
1	RH REAR FENDER SPLASH SHIELD	CRACKED	280.10	280.10
14	RH REAR FENDER SPLASH SHIELD CLIPS @\$3.80	NECESSARY	53.20	53.20
2	REAR BUMPER RETAINERS @\$98.10	NECESSARY	196.20	196.20
1	RH REAR SPORT RIM	CUT	1,540.50	1,540.50
1	RH REAR TYRE	CUT	380.00	200.00
1	RH REAR KNUCKLE WITH BEARING ASSEMBLY	* CHECK	1,310.90	-
1	RH REAR LOWER ARM	NOT NECESSARY	952.10	-
1	RH REAR SHOCK ABSORBER	NOT NECESSARY	298.50	-
1	RH REAR UPPER ARM	NOT NECESSARY	598.50	-
2	BODY SEALANT @\$25.00	NECESSARY	50.00	50.00
1	REAR AXLE ASSEMBLY	NOT NECESSARY	3,350.20	-
1	ROCKER PANEL RUBBER (NPA)	NECESSARY	-	-
	LESS 10% DISCOUNT		-1,851.18	-1,116.44
			16,660.62	10,047.96

Report Ref No. CS/FCI18008015/Gtbe2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	TO KNOCK AND STRAIGHTEN RH CENTER PILLAR. CUT AND WELD DAMAGED PANEL. TO ADJUST AND REALIGN THE SAME.		1,600.00	1,000.00
	TO PUTTY AND SPRAY RH FRONT DOOR, RH CENTER PILLAR, RH ROCKER PANEL, RH REAR DOOR, RH FRONT, RH REAR DOOR PROTECTOR, RH REAR FENDER AND REAR BUMPER.		1,300.00	800.00
	TO REMOVE AND REFIT REAR SEAT, REAR SPORT RIM, ROOF LINING TO ASSIST WORKLOAD.		300.00	60.00
	TO REMOVE AND REFIT RH REAR FENDER 1/4 GLASS.		100.00	60.00
	TO REMOVE AND TRANSFER RH FRONT AND RH REAR DOOR FITTING AND FIXTURE. TO CONDUCT WATER SEEPAGE AND WINDOW NOISE TEST.		350.00	120.00
	TO RUST PROOF THE AFFECTED AREAS.		100.00	60.00
	TO DROP REAR EXHAUST, REAR AXLE AND SUSPENSION ASSEMBLY. TO REMOVE AND RENEW NECESSARY PARTS AND TO CONDUCT FINAL CHECKING AND TESTING.	NOT NECESSARY	480.00	-
	TO DROP PETROL TANK, PIPES, HOSES TO FACILITATE BODY WORK REPAIR. FINAL CHECKING AND TESTING.		180.00	60.00
	TO CHECK WIRING AND ALL LIGHTING.		80.00	30.00
			4,490.00	2,190.00
	GRAND TOTAL		21,150.62	12,237.96
	RECOMMENDED COST OF REPAIRS (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$1,179.81 NETT)			12,237.96

Report Ref No. CS/FCI18008015/Gtbe2

XING GUO QIANG

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.