

ASS. REC. BY:

REF: CS/CTL18008017/Asbnz

Special Instruction:

Surveyor

Adrian

ASSIGNMENT (Office)

From (Person):

Jowyn Tay

of

CTL

Date/Time:

02052018 5:01pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLD 1073U

Insured:

SLT 2650M

at Workshop m/s

Borneo Motor

Tel:

9847 6171

of

17 Ubi Rd 4

Policy No:

DM PCSN 3082951700

Claim No:

SNM18D01717C01

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A

01042018

CA / REV / REP. / REV 24 HRS wpi

22.05.2018 @ after 1030am

Date/Time:

02052018 5:24pm

Person Contacted:

Thomas

H.O.D. Endorsement:

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate Sam

SLD 1073U - CCU / AXA 16017369 / Kpa3g2

QA: 300316

SLT 2650M - x

(R 3,186.55 Red - 53%)

REF: CTI

ASSIGNMENT

From: Date: 22/5/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLD 10734

at Workshop m/s:

of

Borneo Motor
17 ubi Rd 4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

After 10.30am

Make of Veh:

Sam

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 04/8/3 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{1 wps}

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLD10734 Yr Regn: 206, Jne
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota ALTIS c.c. 1598

Colour: Black A/C: Insured / Std / NI / NA

Sp. Reading: 51717 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: MRO3REH104546547

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R16
R: 205/55R16BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal. 06 mm R/Bal. 06 mm

L/Bal. 06 mm L/Bal. 06 mm

D.O.A. D.O.I. 22/05/18

Survey held at Borneo Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP China

RECEIVED 18 JUL 2018

Date/Time: File Pass to?

18/07/18

1) Typist

Date/Time: File Return to?

2)

☐ : Preli. Report☒ : Final Report

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation

) \$ + RS. \$

) Photos

) Others

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$ 2,811.30 p/p)

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		02 May 2018 17:01 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TEO ZHI YUAN, KELVIN(ZHANG ZHIYUAN), ID: S8742923G			[Created by insurer]
Main Claimant:	TAN CHOA WEI LEONARD, ID: S8041120J			
Vehicle Reg. No.:	SLD1073U	Date of Loss:	01/04/2018 18:00 - :59	
Claim Type:	TP / SNM18D01717C02	Policy/Cover Note No.:	DMPCSN3082951700 (Comprehensive)	
Vehicle Reg. No. (Insured):	SLT2650M	Policy No. (Claimant):		
		Excess:	\$50.00	
Repairer:	Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road 4, 408611 Ubi - Tel: 6631 1868			
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 11/05/2018]			
Adj Asg. Remarks:	EST \$6417.70, CASE WITH SJE.			

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results.						Assigned By	Completed On	Created On	Done?

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	02/04/2018 13:27
Date Of Accident	01/04/2018 18:10
Exact Location Of Accident	JB - CIQ CUSTOM
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLD1073U
Insured/Policyholder	
Name Of Registered Owner	TAN CHOA WEI LEONARD
NRIC No	S8041120J
Email Address	TAN_LEONARD@HOTMAIL.COM
Mobile Phone No	(LOCAL) +65-92225900
Alternative Phone No	OFFICE-92225900
Vehicle Particulars	
Manufacturer	TOYOTA
Model	COROLLA ALTIS-1.6 (A)
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR
Insurance Company	
Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	VPA/P1778502
Cover Note Number	
Driver	
Name of Driver	TAN CHOA WEI LEONARD
NRIC No	S8041120J
Date Of Birth	27/12/1980
Occupation	INDOOR
Date Of Driving Pass	06/12/1999
Driving Experience	18 YEARS AND 3 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-92225900
Fax Number	
Contact Number	OFFICE-92225900
EEmail Address	TAN_LEONARD@HOTMAIL.COM

Address	BLK 57 TELOK BLANGAH HEIGHTS #02-143
Postcode	100057
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	RAINING
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	2

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

PLEASE REFER AS ATTACHED

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLT2650M
Vehicle Make/Model/Colour	TOYOTA/SENTA
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	TEO ZHI YUAN KELVIN
NRIC/Passport Number	S8742923G
Contact Number	97711712
Address	BLK 310C PUNGGOL WALK #06-606
Postcode	823310
Insurance Company Name	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	
No. Of Passenger (Including Driver)	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident


on 1st April 2018, on link bridge heading towards CIQ Customs Building located in Johor Bahru, Malaysia. We were queing on the link bridge to the customs.
My car is stationary with foot brake pedal 'on'. The 3rd party vehicle, SLT 2650m Toyota Sienta suddenly from behind hit hardly onto my rear bumper. Initial inspection is damaged rear bumper and inner boot plastic cover is not aligned. Bumper is misaligned. Sensor also slight damaged.


Time of Incident: 1810 H. (6:10pm)


Location : On the bridge towards CIQ Building (Malaysia)

Declaration

We declare the foregoing particulars are true in every respect.

 02/04/18 1110
Policyholder's Signature / Date & Time

 02/04/18 1110
Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

AXA INSURANCE PTE LTD
 8 Shenton Way, #24-01
 AXA Tower, Singapore 068811
 Customer Service Centre #B1-01
 Tel:(65)63387288 Fax:(65)63382522
 Website:www.axa.com.sg
 GST Registration Number: 199903512M
 customer.service@axa.com.sg



CERTIFICATE OF INSURANCE

■ Motor Vehicles (Third-Party Risks and Compensation) Act. (Chapter 189) ■ Motor Vehicles (Third-Party Risks and Compensation) Rules. 1960 ■ Road Transport Act. 1987 (Malaysia) ■ Motor Vehicles (Third-Party Risks) Rules. 1959 (Malaysia)

CERTIFICATE NO.	: VPA/P1778502	Account No. : 13950
Coverage	: Comprehensive	
Sum Insured	: Market Value At The Time Of Loss	
Name of Policy Holder	: TAN CHOA WEI LEONARD	
Vehicle Registration No.	: SLD1073U	
Period of Insurance	: From 01/06/2017 To 31/05/2018 (Both Dates Inclusive)	

PERSONS OR CLASSES OF PERSONS ENTITLED TO DRIVE*

- (a) The Policyholder
 The Policyholder may also drive a Motor Car not belonging to or not hired (under a hire purchase agreement or otherwise) to him or his employer or his partner
- (b) Any other person who is driving on the Policyholder's order or with his permission
 Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.

LIMITATIONS AS TO USE*

Use only for social, domestic and pleasure purposes and for the Policyholder's business
 The policy does not cover - use for hire or reward, racing, pace-making, reliability trial, speedtesting, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with motor trade; or when the Motor Car, whether stationary; in use or otherwise, is in or on, a racing track, circuit, route, course or any other roads by whatever name called that are typically used for racing, pace-making or such similar purposes.

(01)

Basic Own Damage Excess	: SGD 600.00
Voluntary Excess	: SGD 500.00
Final Basic Own Damage Excess	: SGD 1,100.00

An Additional Excess is applicable as follows:

S\$500.00 for Unnamed Authorized Driver &/or Declared Young & Inexperienced Driver.
 S\$5,000.00 for Undeclared Young and Inexperienced Driver.
 (Please refer to your policy on the terms & conditions)

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act, (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

I/We hereby certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act, (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

AXA INSURANCE PTE LTD

Authorized Signature

Issued by - SGIWONG2 on 19/05/2017

IMPORTANT :


Policyholders are warned that on the sale of a motor vehicle they must surrender the Certificate of Insurance and the Policy to the insurance company. If the Certificate of Insurance has been lost or destroyed a Statutory Declaration to the effect must be made. Failure to comply with this obligation is an offence under the Motor Vehicle (Third-Party Risks and Compensation Act (Cap. 189).

The Premium Warranty Clause requires the premium to be paid in full within a specific period failing which there would be no liability under the policy, renewal certificate, covernote and endorsement etc.

**SINGAPORE ARMED FORCES
IDENTITY CARD**

Name
**TAN CHOA WEI,
LEONARD**

NRIC No
S8041120J



This card is the property of the Singapore Armed Forces. Any person finding this card is requested to forward it without delay to Central Manpower Base or any Police Station.

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: **S8041120J**
Name
TAN CHOA WEI, LEONARD

Birth Date: **27 Dec 1980**
Issue Date: **08 Aug 2012**



002094618D



GENALTC090PV1049552A0411

00000000134578

NRIC No / Colour
S8041120J/ PINK

Race
CHINESE
Date Of Birth
27/12/1980
Service Status
REGULAR

Blood Group
O (+)
Country Of Birth
SINGAPORE
Military Rank Status
MILITARY EXPERT

Sex
M

Address
**ADDRESS: APT BLK 57 TELOK BLANGAH HEIGHTS #02-143
SINGAPORE 100057 DATE: 29.09.2015 S8041120J**



YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(ES)

EFFECTIVE DATE

Class 3 Motor Cars=< 3000kg with =<7 passengers, exclusive of the driver; and other motor vehicles =< 2500kg 06 Dec 1999

NP 428A





Ltk - Catherine

Borneo Motors (Singapore) Pte Ltd

Online Service Booking
www.toyotasingsapore.com.sgToyota Bodycare Centre
17 Ubi Road 4
Singapore 408611
Tel no.: 6631 1188Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 3 Anson Road #16-00 Springleaf Tower Singapore 079202 Attn: Motor Claims Dept	S1000003 / 10011	Mr Tan Choa Wei Leonard 57 Telok Blangah Heights #02-141 Singapore 100057 Mobile: 92325900
	Document No	
	Document Date	
	02/04/2018	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	CEXGHE	ST	01/04/2018	SLD1073U	39975	16266	7DS/SLD1073U/010411
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
MR053REH104546547	12BN351215	60	Sam San Jai	02/04/2018 17:00	--/--/----	0.00	

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	2	BP-SUNDRY SUNDRIES TP-DIRECT SETTLEMENT TP-SLT2650M ACC DATE:01/04/2018 DRIVE IN:02/04/2018 DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				✓ 30.00
2	3	BP-SUBLET DRILL HOLE & INSTALL REAR REVERSE SENSOR				✓ 154.00
3	3	BP-SUBLET CHECK LIGHTING & CONDUCT WATER LEAK TEST				✓ 150.00
4	3	BP-SUBLET REMOVE & INSTALL REAR BOOTLID CARPET, GAR NISH AND TRIMMING TO ASSIST REPAIR				✓ 209.00
5	3	BP-SUBLET REPLACE REAR BUMPER, REAR BUMPER REINFORC EMENT, ETC STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				616 184.00
6	3	BP-SUBLET RESPRAY JOB ON REAR ACCIDENT AFFECTED AR EAS				759 151.00
7	1	S52159-02004 COVER, RR BUMPER Defud	1.00	539.90		✓ 539.90
8	3	S52576-02140 RETAINER, RR BUMPER L } New	1.00	105.70		✓ 105.70
9	3	S52575-02140 RETAINER, RR BUMPER R } New	1.00	105.70		✓ 105.70
10	4	S52161-0K040 CLIPS ncc	10.00	39.00		✓ 390.00
11	5	S52023-02190 REINFORCEMENT, RR Not new	1.00	386.60		X 386.60
Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts Labour Materials Lubrication/Fluid Others	Less
			Amount Due

PLEASE TEAR ALONG PERFORATED LINE

3639551

TO SECURITY GUARD

3639551

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 02/04/2018
TIME 15:06

VEHICLE NO SLD1073U

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors



Borneo Motors (Singapore) Pte Ltd

Online Service Booking:

www.toyotasingsapore.com.sg

17 Ubi Road

Singapore 408611

Tel no: 6031 1188

Co Reg No : 196700086Z
GST Reg No : MR-8500000-9

ESTIMATE

Join Toyota ME @ http://toyotame.borneomotors.com.sg & earn points to redeem for attractive items!

Account Detail	Account No	Customer Detail
China Taiping Insurance (S) Pte Ltd 30 Anson Road #15-00 Springleaf Tower Singapore 079903 Attn: Motor Claims Dept	51005003 / 100011	Mr Tan Choe Wei Leonard 57 Telok Blangah Heights #02-113 Singapore 100957 Mobile: 92225900
	Document No	
	Document Date	

Year	Make	Model	Reg Date	Veh Reg No	Kilometers	WIP No	Order No/Remarks
15	GENGK2	SE	01/04/2016	SLD1073U	39875	16266	7DS/SLD1073U/01041
Chassis No	Engine No	TWC No	Terms	Service Engineer	Vehicle In	Collected On	
ML053REH104546547	13BX533211	00	24x24x24	02/04/2016 17:00	---	---	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	6	SP5307-02180 PANEL, LAMP LOWER	1.00	549.30		549.30
10	7	SP1061-11021 43 BACK SENSOR (21W) 310A	1.00	159.75		159.75
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices need to be confirmed Third party survey on a "Without Prejudice" basis No illegal modifications & alterations Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p> <p><i>Adrian Wong</i> 02/05/18 04 Days</p> <p>Borneo Motors is the only authorised workshop to maintain your Toyota. Service your Toyota every 6 months or 10,000 km (whichever comes first) to enjoy warranty benefits. Conditions apply.</p>						

For & on behalf of Borneo Motors	Customer's Signature	Change Summary	Total
	Please acknowledge receipt of vehicle	Parts 1,965.35 Labour 30.00 Materials 3,962.00 Lubrication/Fluid 0.00 Others 0.00	5,957.35
			Less 0.00
			Amount Due 6,417.70

PLEASE TEAR ALONG PERFORATED LINE

3639552

TO SECURITY GUARD

3639552

PLEASE ALLOW THE UNDERMENTIONED
VEHICLE TO LEAVE THE COMPANY PREMISES.DATE 02/04/2018
TIME 11:00

VEHICLE NO SLD1073U

CUSTOMER

SIGNATURE
FOR BORNEO MOTORS (SINGAPORE) PTE LTD

Borneo Motors

TAX INVOICE

Toyota Bodycare Centre
17 Ubi Road 4
Singapore 409611
Tel no.: 6631 1188

China Taiping Insurance (S) Pte Ltd
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909
Attn: Motor Claims Dept

S1000003 / ICCI1

39006719

08/06/2018

Mr Tan Choa Wei Leonard
57 Telok Blangah Heights
#02-143
Singapore 100057
Mobile: 92225900

15 GEXGKZ S2 ZRE171R 01/06/2016 SLD1073U 51717 16266 7DS/SLD1073U/01041

MR053REH104546547 1ZRX555215 60 Sam San Joi 02/04/2018 18.33 25/05/2018 14.49

1	Z	BP-SUNDRY	SUNDRIES	TP-DIRECT SETTLEMENT		30.00
		TP-SLT2650M		ACC DATE:01/04/2018		
		DRIVE IN:02/04/2018				
		DATE-IN:23/05/2018		DATE SURVEY:22/05/2018		
		NO OF REPAIR DAYS:4 DAYS				
		BY:ADRIAN(LKK)				
2	S	BP-SUBLET	DRILL HOLE & INSTALL REAR REVERSE SENSOR	A45		154.00
3	S	BP-SUBLET	CHECK LIGHTING & CONDUCT WATER LEAK TEST	A45		154.00
4	S	BP-SUBLET	REMOVE & INSTALL REAR BOOTLID CARPET,GAR	A45		308.00
		NISH AND TRIMMING TO ASSIST REPAIR				
5	S	BP-SUBLET	REPLACE REAR BUMPER	A45		616.00
		STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS				
6	S	BP-SUBLET	RESPRAY JOB ON REAR ACCIDENT AFFECTED AR	A45		759.00
		EAS				
7	1	S52159-02904	COVER,RR BUMPER		1.00	539.90
8	2	S52576-02140	RETAINER,RR BUMPER L		1.00	105.70
9	3	S52575-02140	RETAINER,RR BUMPER R		1.00	105.70
10	4	S52161-0K040	PIECE,RR BUMPER		10.00	39.00

2,811.30

790.30 GST 7.00%

196.79

30.00

0.00

1,991.00

0.00

0.00

3,008.09

PLEASE MAIL YOUR CHEQUE TO 33 LENG KEE ROAD, SINGAPORE 159102

08/06/2018
07:55

SLD1073U

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT118008017/ASBN2

Date: 19/07/2018

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3082951700
Claimant Vehicle No :	SLD1073U	Insured Vehicle No :	SLT2650M
Date of Loss:	01/04/2018	Nature of Claim:	TP
		Claim No:	SNM18D01717C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLD1073U	Engine No:	1ZR555215
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 (A)	Chassis No:	MR053REH104546547
Reg. Date:	01/06/2016 (Man. Year: 2015)	Odometer:	51717 km
Colour:	Black		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	2,015.85	820.30	1,195.55	59.31
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,982.00	1,991.00	1,991.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	5,997.85	2,811.30	3,186.55	53.13
+ GST 7.00/7.00% (\$\$)	419.85	196.79	223.06	53.13
Nett Amount (\$\$)	6,417.70	3,008.09	3,409.61	53.13

INSPECTION

Date of Assignment:	02/05/2018	Inspected At:	Borneo Motors (S) Pte Ltd (Ubi) 17 Ubi Road 4 Singapore 408611
Date Inspected:	22/05/2018		
Estimated Period of Repair:	4.0 days		

Adjuster: ADRIAN LING

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jul 2018)
Parts:	143	TOYOTA COROLLA ALTIS 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLD1073U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER RR BUMPER	Deformed	539.90 FS	*539.90 FS
2	1		*RETAINER RR BUMPER L	Necessary	105.70 FS	*105.70 FS
3	1		*RETAINER RR BUMPER R	Necessary	105.70 FS	*105.70 FS
4	10		*CLIPS	Necessary	39.00 FS	*39.00 FS
5	1		*REINFORCEMENT,RR	Not Necessary	386.60 FS	*- FS
6	1		*PANEL,LAMP LOWER	Repair	649.20 FS	*- FS
7	1		*BACK SENSOR (218) 310A	Not Necessary	159.75 FS	*- FS
8	1		*SUNDRIES	Necessary	30.00 FS	*30.00 FS
F=Franchise part. S=SpcNett.						
Total Parts (S\$)					2,015.85	820.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DRILL HOLE & INSTALL REAR REVERSE SENSOR	New	154.00	154.00
2	CHECK LIGHTING & CONDUCT WATER LEAK TEST	New	154.00	154.00
3	REMOVE & INSTALL REAR BOOTLID CARPET,GARNISH AND TRIMMING TO ASSIST REPAIR	New	308.00	308.00
4	REPLACE REAR BUMPER,REAR BUMPER REINFORCEMENT,ETC.STRAIGHTEN & ALIGN REAR ACCIDENT AFFECTED AREAS	New	1,848.00	616.00
5	RESPRAY JOB ON REAR ACCIDENT AFFECTED AREAS	New	1,518.00	759.00
Gross Labour Cost (S\$)			3,982.00	1,991.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >