

ASS. REC. BY:

REF: CS / msh18008023 / Svbn2 Special Instruction:

Surveyor

## ASSIGNMENT (Office)

From (Person):

Merimen Monica Chung

of

msth

Date/Time: 020518 4:10 pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKH 6858E

Insured:

SDZ 6188T

at Workshop m/s

Performance

Tel:

63190174

of

303 Alexandra Rd

Policy No:

17509560SMP

Claim No:

557175.

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

01052018

CA / REV / REP. / REV 24 HRS wpi

14052018

H.O.D. Endorsement:

Date/Time:

020518 4:32pm

Person Contacted:

Caroline

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate	Hum
	SKH 6858E - CS/RSC13004670 / Rq02	DUA: 080312
	SDZ 6188T - NBA/msh14007763 / CI	DUA: 171014
16/5/18	Send preli revised by merimen	
13/6/18	Final fig \$ 5191.35 confirmed by email (Ref 610.65, 1076)	

2017  
Bureau

REF: MS 19

# ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKH 6858E

Yr Regn: 4/1/2013

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 135I

C.C 2979

Colour: Black

A/C: Insured / Std / NI / NA

Sp. Reading: 19283

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: WISAUN72000VM 22858

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: N / S/Rim / STD A/Rim or

Tyre Size: F: 215/40R18

R: 295/35R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Bridgestone

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 1/5/18

D.O.I. 1/4/5/18

Survey held at Performance Motor

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*[Signature]*  
13/6/2018

RECEIVED 14 JUN 2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 14/6 - typist

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

meimen

Lump Sum / I.B.I. (\$

591.35

150  
10

160

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Monica Chung Pei Zhen

Date: 16 May 2018

**Preliminary Advice**

Insured Vehicle No	: SDZ6188T	Accident Date	: 01/05/2018
TP Vehicle No	: SKH6858E	Assignment Date	: 02/05/2018
Make	: BMW 135I	Est. Duration of Repair	: 3.00
Date of Inspection	: 14/05/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,802.00
Revised Amount	:S\$	4,642.10
Check Items (Estimated)	:S\$	1,159.90
Total	:S\$	5,802.00

Lump Sum Repair	:S\$	
-----------------	------	--

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

**Remarks**

( ) The vehicle is economical/not economical for repair.

( X ) The above survey was conducted on a 'without prejudice' basis.

## ...CLAIM SUBFOLDER...(New Assignment)

## CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	02 May 2018		02 May 2018 16:10 Assign				<b>New Assignment</b> Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

## CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	FOO CHIT YANG JUSTINA, ID: S1159251A		
Main Claimant:	FIONA MARY ELLA HENDERSON, ID: F2443057W		
Vehicle Reg. No.:	SKH6858E	Date of Loss:	01/05/2018 14:00 - :59 [63 Months and 27 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 557175	Policy/Cover Note No.:	27509560SMP (Comprehensive) Coverage: 29/09/2017 - 28/09/2018
Vehicle Reg. No. (Insured):	SDZ6188T	Policy No. (Claimant):	
		Excess:	
Repairst:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Monica Chung Pei Zhen - 6594 2552]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 03/05/2018]		
Driver/Custodian (Insured):	KEONG SOON WEI NICHOLAS (), NRIC: S8713732E, Tel: +6598399361		

## ASSOCIATED MAIL RECEIVED

View All

Compose Case Mail

There are no mail for this case.



## ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

**Veron Chen (LKKAUTO)**

---

**From:** Veron Chen (LKKAUTO)  
**Sent:** Wednesday, 13 June 2018 4:33 PM  
**To:** 'Han Kwan Yong'  
**Cc:** PBSP; SUR  
**Subject:** RE: FINAL REPORT / SKH6858E

Dear Han,

Noted with thanks.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Han Kwan Yong [mailto:han.kwan.yong@simedarby.com.sg]  
**Sent:** Wednesday, 13 June 2018 3:21 PM  
**To:** Veron Chen (LKKAUTO) <veronchen@lkkauto.com>  
**Cc:** PBSP <pml-pbsp@simedarby.com.sg>  
**Subject:** FW: FINAL REPORT / SKH6858E

Dear Veron,

Due to typo error cost of repair above \$3,000 actual sundries should be @ \$80.00.

We willing to accept the Sundries @ \$40.00 for this case only.

Thank you.

Regards,

Han K.Y.

---

**From:** Sebastian Yeang (LKK Auto) <SebastianYeang@lkkauto.com>  
**Sent:** Thursday, 7 June 2018 7:21 PM  
**To:** PBSP; SUR  
**Cc:** Veron Chen (LKKAUTO)  
**Subject:** RE: FINAL REPORT / SKH6858E

Dear Caroline

Please refer to attachment for the finalization.

\*Remark: Sundries is \$40 as agreed on the day of survey. The rest all no changes.

Thank You

CS/MSG18008023/Svb

Best Regards,

**Sebastian** | Automotive Assessor

**LKK Auto Consultants**

phone: 6256-3561 email: [sebastianyeang@lkkauto.com](mailto:sebastianyeang@lkkauto.com) fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	02/05/2018 10:16
Date Of Accident	01/05/2018 14:50
Exact Location Of Accident	HOLLAND VILLAGE CENTRE CARPARK
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKH6858E
<b>Insured/Policyholder</b>	
Name Of Registered Owner	FIONA MARY ELLA HENDERSON
Passport No/FIN	F2443057W
Email Address	FIONAHENDERSON100@GMAIL.COM
Mobile Phone No	(LOCAL) +65-93832324
Alternative Phone No	OFFICE-93832324

### Vehicle Particulars

Manufacturer	BMW
Model	135i
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	GA045240/1
Cover Note Number	

### Driver

Name of Driver	FIONA MARY ELLA HENDERSON
Passport No/FIN	F2443057W
Date Of Birth	23/09/1964
Occupation	INDOOR
Date Of Driving Pass	05/03/1996
Driving Experience	22 YEARS AND 1 MONTH
Gender	FEMALE
Mobile Number	(LOCAL) +65-93832324
Fax Number	
Contact Number	OFFICE-93832324
Email Address	FIONAHENDERSON100@GMAIL.COM

Address	249 HOLLAND RD
Postcode	278599
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OWNER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR- INDOOR CARPARK
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SDZ6188T
Vehicle Make/Model/Colour	116I SERIES BRONZE
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	KEONG SOON WEI NICHOLAS
NRIC/Passport Number	
Contact Number	98399361
Address	993 BT TIMAH RD #08-15
Postcode	589631
Insurance Company Name	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Nature Of Damage	REAR RIGHT
No. Of Passenger (Including Driver)	1



**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

**8. Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
Policyholder's Signature


Date & Time: 02.05.2018  
(9.05am)

\_\_\_\_\_  
Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

  
Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

# Sketch Plan Pg. 2

## SKETCH PLAN



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

MY CAR WAS PARKED IN THE UNDERGROUND CAR PARK AT HOLLAND VILLAGE SHOPPING CENTRE. LEFT WHEN I RETURNED THE REAR BUMPER + HEADLIGHT WAS SCRAPPED + DAMAGED.

A NOTE WAS PLACED ON MY WINDSCREEN WITH THE DRIVER'S DETAILS.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

*[Signature]*  
Policyholder's Signature

Date & Time: 2.5.18  
9am

*[Signature]*  
Driver's Signature  
(If driver is not the policyholder)

Date & Time: 02/05/18  
19.05 AM

*[Signature]*  
Reporting Centre Personnel's Signature

Name:  
NRIC/FIN No.:

Mon 14/05 @ 10am  
S.L.R.

SKH6858E  
3 days  
Sebastian 15/4/18  
- Part by part repair  
- Question Mark Item Photo  
- Photo ~~of~~ Before Paint  
LKK Auto Consultants hence notify the Repairer of the following:  
\* To resurvey before/after spray painting  
\* To display damaged part(s) during resurvey  
Prices are subject to confirmation  
No third party survey is on a "Without Prejudice" basis  
No quotation/estimation(s) is allowed  
Supplier/Repairer(s) must be resurveyed and is subject to final approval from Insurance Company  
Signature: \_\_\_\_\_  
Date: 02 MAY 2018

BMW Dealer **Performance Motors Limited**

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x  
303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770  
280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/536 (AfterSales)  
Fax. 64796604 (AfterSales)  
64796624 (AfterSales)

GST REG. NO : M2 - 0020081-x

**E S T I M A T E**

Estimate No. : b1 46792 Page No. : 1 of 1  
Date Estimated : 02/05/2018  
Prepared By : Han Kwan Yong

<b>- ESTIMATE REPAIR FOR -</b> Fiona Mary Ella Henderson 249 Holland Road  Singapore 278599	<b>- ACCOUNT -</b> 40000 Cash Sales - Service Singapore
---	---

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKH6858E	VM22858	04/01/2013	135i-C (A)	0

DESCRIPTION	VALUE
To replace front bumper & attachments including to realign front bumper	850.00
To respray front bumper	934.00
To replace left headlight including program and conduct tests for proper function.	451.00
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00
Sundries. nrc	40.00

Total Labour 1: 2,425.00

DESCRIPTION	QTY	PRIC	VALUE
# LH HEADLIGHT BRACKET ? nm	1	55.90	55.90
FRT BUMPER CARRIER ✓ nm	1	500.75	500.75
FRT BUMPER (M/HEADLAMP CLEANING) ? CRA	1	1,050.00	1,050.00
# FRT BUMPER LH NOZZLE ? nm	1	54.00	54.00
# LH BI XENON HEADLIGHT ✓ SCR	1	1,716.35	1,716.35

Total Parts : 3,377.00

5802

Claims OD / 3rd Party / Uninsured losses / Direct Settlement  
Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_  
Date & Time \_\_\_\_\_ Excess RS \_\_\_\_\_  
Surveyor's Name \_\_\_\_\_ Sign \_\_\_\_\_  
Surveyor's Tel \_\_\_\_\_ Authorized Yes / No \_\_\_\_\_  
Authorized Date \_\_\_\_\_ Time \_\_\_\_\_  
RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No  
Surveyor's E-mail \_\_\_\_\_  
No. of Working Days Recommended \_\_\_\_\_

Labour 1	:	2,425.00
Parts	:	3,377.00
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	406.14
Grand Total	:	6,208.14

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*  
\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 46792  
Date Estimated : 02/05/2018  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Fiona Mary Ella Henderson  
249 Holland Road

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

Singapore 278599

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE
SKH6858E	VM22858	04/01/2013	135i-C (A)	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
To replace front bumper and attachment include knocking out dents caused by the accident	850.00		850.00 ✓
To respray front bumper	934.00		934.00 ✓
To replace LH bi xenon headlight include programming and conducting tests for proper function	451.00		451.00 ✓
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00 ✓
Sundries.	80.00		80.00 40

DESCRIPTION	INIT PRICE	QTY	DISC. %	NETT
FRT BUMPER (M/HEADLAMP CLEANING) CRK	1,050.00	1.00		1,050.00
LH BI XENON HEADLIGHT SCR.	1,716.35	1.00		1,716.35

### # SUPPLEMENTARY ITEMS

Parts : \$ 2766.35  
Labour : \$ 2425.00

5191.35 @ 3 days

Total Labour :	2,465.00
Total Parts :	2,766.35
Total Labour & Parts :	5,231.35
Deduction for Excess :	
Total Repair Costs less Excess:	5,231.35
GST @7%:	366.19
Grand Total :	5,597.54

2425.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

Final Report SKH6858E Page 1  
Supplier's items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Finalised by: Caroline DID: 63190174 Fax: 64794601

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18008023/SVBN2

Date: 18/06/2018

## REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	27509560SMP
Claimant:	SKH6858E	Insured Vehicle No :	SDZ6188T
Vehicle No :		Nature of Claim:	TP
Date of Loss:	01/05/2018	Claim No:	557175

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SKH6858E	Engine No:	11348309N55B30A
Make & Model:	BMW 135i, 3.0 (A)	Chassis No:	WBAUN72000VM22858
Reg. Date:	04/01/2013 (Man. Year: 2012)	Odometer:	19283 km
Colour:	Black		
Engine Capacity:	2979 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	215/40R18	Rear Tyre Size:	245/35R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,417.00	2,806.35	610.65	17.87
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,385.00	2,385.00	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>5,802.00</b>	<b>5,191.35</b>	<b>610.65</b>	<b>10.52</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>406.14</b>	<b>363.39</b>	<b>42.75</b>	<b>10.53</b>
<b>Nett Amount (S\$)</b>	<b>6,208.14</b>	<b>5,554.74</b>	<b>653.40</b>	<b>10.52</b>

## INSPECTION

Date of Assignment: 02/05/2018

Date Inspected: 14/05/2018 Inspected At:

Performance Motors Limited  
(Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 3.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

### Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 18 Jun 2018)
<b>Parts:</b> M1-COUPE	BMW 135i 3.0 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SKH6858E)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b> Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH HEADLIGHT BRACKET	Not Necessary	55.90 FS	*- FS
2	1		*FRT BUMPER CARRIER	Not Necessary	500.75 FS	*- FS
3	1		*FRT BUMPER (M/HEADLAMP CLEANING)	Cracked	1,050.00 FS	*1,050.00 FS
4	1		*FRT BUMPER LH NOZZLE	Not Necessary	54.00 FS	*- FS
5	1		*LH BI XENON HEADLIGHT	Scratched	1,716.35 FS	*1,716.35 FS
6	1		*SUNDRIES	Necessary	40.00 FS	*40.00 FS
F=Franchise part. S=SpcNett.						
<b>Total Parts (S\$)</b>					<b>3,417.00</b>	<b>2,806.35</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER & ATTACHMENTS INCLUDING TO REALIGN FRONT BUMPER	New	850.00	850.00
2	TO RESPRAY FRONT BUMPER	New	934.00	934.00
3	TO REPLACE LEFT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	451.00	451.00
4	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS	New	150.00	150.00
Gross Labour Cost (S\$)			2,385.00	2,385.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >