

ASS. REC. BY

REF: CS/FCU8008029/Tltbnz Special Instruction:

Surveyor: ASSIGNMENT (Office)

From (Person): WS Sathara of FEL Date/Time: 02052018 307pm

Estimated Cost: Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SFS 2040A Insured: SHC 122X

at Workshop m/s Cycle & Carriage Tel: 9186 5112.

of 188 Pandan Loop

Policy No: Claim No: 018003053 MFSH

Sum Insured: Excess:

Make of Veh: D.O.A. 18042018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS' H.O.D. Endorsement:

Date/Time: 02052018 4:13pm Person Contacted: Alan Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SFS 2040A - X
	SHC 122X - MS/INC14016237/Hlabks DA: 240814
2/15-	revert via email preli advise
	Part by Part \$5898 +1 (Red: 2804.94 :32%)

MOTOR SURVEY ASSIGNMENT

Date	19-04-2018	Our Ref No. D18003053MFSH
Accident Date	18-04-2018	Claim Type. Third Party
Insured Vehicle	SHC0122X	Third Party Vehicle. SFS2040A
Survey Location	PANDAN LOOP SERVICE CENTER 188 PANDAN LOOP	
Contact Person.	ALAN QUEK	
Contact No.	67714377/ 91865112	Fax No. 68721272
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE INDUSTRIES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SITHARA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Denise Tay (LKKAuto)

From: Denise Tay (LKKAuto)
Sent: Tuesday, 22 May 2018 2:19 PM
To: Admin-D (LKKAuto); 'Claim Workflow System'; assignments
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003053MFSH/1
Attachments: PRELI ADVISED SFS 2040A.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle **SFS 2040A**

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 2 May 2018 4:14 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: SITHARA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003053MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Please be informed that vehicle currently not in the workshop, repairer will arrange.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Wednesday, 2 May, 2018 3:07 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; SITHARA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003053MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18003053MFSH

Date: 22/5/2018

Our Ref: CS/FCI18008029/T1tb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SFS 2040A.

Please be informed that we had conducted the inspection of the abovementioned vehicle 15/5/18 at the premises of M/s Cycle and Carriage and have the following to report: -

Workshop Estimate Amount	: S\$ <u>8,703.65</u>
Revised Estimate Amount	: S\$ <u>5,669.77</u>
"Check" Items Amount	: S\$ <u>1,822.19</u>
Market Value	: S\$ _____
LTA Reimbursement Value	: S\$ _____
Nett Value	: S\$ _____

Description of Damage:

The vehicle sustained damages at the rear portion.



Comments/ Present Status:

Damages Consistent.

Yours faithfully

Taufikh

Automotive Assessor

Driving License

REPUBLIC OF SINGAPORE

IDENTITY CARD NO. S12963001



Name

ONG KIAN HUAT KENNETH



Race

CHINESE

Date of Birth

22-08-1958

Country of Birth

SINGAPORE

Sex

M



Driving License



APT BLK 371 HOLLAND ROAD #14-01
SINGAPORE 278698

NRIC No: S12963001

Blood Group: O+
Date of issue: 26-07-1993

Date: 17/07/2011

No: 6761583

Driving License



Driving License


YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSIES)

PASS DATE

Class 3 Motor Cars and Motor Tractors the weight of
which unladen does not exceed 2500 kilograms

12 Apr 1979

NP 428A



Addendum Sheet Pg. 1



GENERAL INSURANCE ASSOCIATION OF SINGAPORE RECORDS MANAGEMENT CENTRE
6 Raffles Quay #15-00 Singapore 048580
Tel: (65) 6224 0020 Fax: (65) 6224 0030
Operating Hours: Monday to Friday, 09:00 - 17:00
UDN: 50055022/05 / GST Reg. No.: FA00017735

IMPORTANT NOTE: Please submit the completed Addendum form to the same Authorised Reporting Centre with whom you submitted the Original Report.

ADDENDUM

(A) PARTICULARS OF PERSON MAKING THE AMENDMENTS:

Original Report No : MBHH18051723 Vehicle Registration No: SFS2040A
Name (as shown in NRIC) : NRIC/FIN/Passport No : S12963001
(*Vehicle Driver / Vehicle Owner) (*) Please delete as appropriate
Address : Singapore ()
Contact (Tel) : Mobile No.: 97372328
Email Address : kcadlong@singnet.com.sg
Date of Accident : 18/04/2018 Time of Accident : 09:20
Place of Accident : ALONG BRAS BASAH ROAD
Insurance Company: Sampo Insurance Singapore Pte. Ltd.

(B) ADDITIONAL INFORMATION / AMENDMENTS:

I have made a report on the above mentioned accident and would like to include additional information or make the following amendments:

Was there any video captured by Car Camera? - NO
[Multiple blank lines for additional information]

Policyholder / Driver's Signature
Date:

Mayury
Reporting Centre Personnel's Signature
Name: Mayury
NRIC/FIN No.: A36220718
Date: 20/04/2018



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorized Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFS2040A

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 23259
Reg No/Reg Date SFS2040A / 14/01/2015
Date In/Mileage / 0
Chassis No WDD2120362B105087
Engine No 27492030300013
Make/Model MB/E 250 2.0 CGI SEDAN (W212)
Colour/Trim 027 792 Palladium S/ 042 211 Leather Ant

Table with columns: Account No, Terms, Date/Time Printed, CSE, Operator. Row 1: WF001862, Credit, 30/04/2018/ 14:28, AQ, 305 / Alan Quek Ai Lun

Main itemized list table with columns: Description of Goods / Services, Qty, Unit Price, Disc%, Amount. Includes items like POLICY NO/ACC DATE, BPILAB, BPIRES, REAR BUMPER, etc.

ESTIMATE TAX INVOICE (Large diagonal watermark)

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
Tel: 6771 4377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

LKK Auto Consultants hence notify the Repairer of the following:

- Confirmed & accepted by spray painting
To display damaged part(s) during resurvey
Parts prices are subject to confirmation
Third party survey is on a "Without Prejudice" basis
No illegal modification(s) is allowed

Authorized signatory and company stamp and signature to final approval from Insurance Company

Tarifika 97495749
wpr
15/5/18 Resurvey before paint.
6 days surp@wharfs.com
Nett 8,703.65
7% GST on 8703.65 609.26
Total Payable 9,312.91
10319.48

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced.



WE DRIVE FIRST CLASS

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

SUPPLEMENTARY

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

ESTIMATE FOR SFS2040A

MS FIRST CAPITAL INSURANCE LIMITED
MOTOR CLAIM DEPARTMENT
36 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Vehicle & Document Information

WIP No 23259
Reg No/Reg Date SFS2040A / 14/01/2015
Date In/Mileage 15/05/2018/ 38016
Chassis No WDD2120362B105087
Engine No 27492030300013
Make/Model MB/E 250 2.0 CGI SEDAN (W212)
Colour/Trim 027 792 Palladium S/ 042 211 Leather Ant

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	15/05/2018/ 17:13	AQ	305 / Alan Quek Ai Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPNSUN POLICY NO/ACC DATE :D18MTPV01001617 // 18-04-2018 DRIVE IN:30-04-2018 // TP CAR NO:SHCI22X (FIRST CAPITAL INSURANCE) DATE IN/DATE SURVEY:15-05-2018 // LKK TAUFIKH BY/AUTHORIZED ON :				
A BPILAB REPAIR REAR END PANEL				960.00
A BPIRES RESPRAY REAR END PANEL				600.00
X REAR BOTTOM UNDER CARRIAGE COVER	1.00	38.15	00.00	38.15
X RIVET	4.00	4.42	00.00	17.68

ESTIMATE

Tanjun 15/5/18
@1715
add + 3 days
23/5/18

SUPPLEMENTARY

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771 4577 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

	Nett	1,615.83
7% GST on	1615.83	113.11
	Total Payable	1,728.94

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



Mercedes-Benz

Cycle & Carriage Industries Pte Limited
Authorised Dealer
Company No. 190400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SFS2040A

MS FIRST CAPITAL INSURANCE LIMITED

MOTOR CLAIM DEPARTMENT
38 ROBINSON ROAD #16-01
CITY HOUSE
SINGAPORE 068877
65073848

Taufikh

WIP No 23259
Reg No/Reg Date SFS2040A / 14/01/2015
Date In/Mileage 15/05/2018/ 38016
Chassis No SWDD2120362B105087
Engine No 27492030300013
Make/Model MB/E 250 2.0 CGI SEDAN (W212)
Colour/Trim 027 792 Palladium S/ 042 211 Leather Ant

Vehicle & Document Information

Account No	Terms	Date/Time Printed	CSE	Operator
WF001862	Credit	20/06/2018/ 16:55	AQ	305 / Alan Quek A1 Lun

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M BPN5UN POLICY NO/ACC DATE :D18MTPV01001617/A 18-04-2018 DRIVE IN:30-04-2018 // TP-CAR NO:SHC122X (FIRST-CAPITAL INSURANCE) DATE IN/DATE SURVEY:15-05-2018 // LKK TAUFIKH BY/AUTHORIZED ON :SITHARA // 02-05-2018				
A BPILAB USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.NETT			0.10	380.00
A BPILAB REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.				960.00
A BPIRES RESPRAY REAR BUMPER				600.00
A BPILAB REPAIR REAR END PANEL				960.00
A BPIRES RESPRAY REAR END PANEL				600.00
X REAR BUMPER	1.00	1630.57	00.00	1630.57
X LH/R BUMPER GARNISH	1.00	128.17	00.00	128.17
X RH/R BUMPER GARNISH	1.00	128.17	00.00	128.17
X REAR BOTTOM PANEL	1.00	227.03	00.00	227.03
X LH/R BOTTOM BRACKET	1.00	17.36	00.00	17.36
X CT/R BASIC MOUNTING FOR BUMPER	1.00	211.58	00.00	211.58
X REAR BOTTOM UNDER CARRIAGE COVER	1.00	38.15	00.00	38.15
X RIVET	4.00	4.42	00.00	17.68

OFFICIAL TAX INVOICE

6 working Days

ESTIMATE

Alan Quek
Cycle & Carriage Industries Pte Ltd
Body Care & Repair Center
DID: 6771-8377 HP: 9186 5112 Fax: 6872 1272
Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett	5,898.71
7% GST on	5898.71
Total Payable	6,311.62

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for removal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



WE DRIVE FIRST CLASS

Mercedes-Benz - are registered trademarks of Daimler, Stuttgart, Germany

Pandan Loop Service Center
188 Pandan Loop
Singapore 126378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18008029/T1tbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 05-07-2018	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHC 122X	Veh. Inspected	SFS 2040A
Policy No.		Coverage (\$)	0.00
Claim No.	D18003053MFSH	Excess (\$)	0.00
Assign From	SITHARA	Assign Date	02/05/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E250	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WDD2120362B105087	Colour	SILVER
Odometer	38016	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/45 R17	MICHELIN	6 mm
L/H Front Tyre	245/45 R17	MICHELIN	6 mm
R/H Rear Tyre	245/45 R17	MICHELIN	6 mm
L/H Rear Tyre	245/45 R17	MICHELIN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	18/04/2018	Inspection Date	15/05/2018
Survey held at	CYCLE & CARRIAGE INDUSTRIES (1986) PL 188 PANDAN LOOP SINGAPORE 128378 (MERCEDES-BENZ)		
5a. Remarks			
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFS 2040A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BUMPER (SN)	DEFORMED	1,630.57	1,630.57
1	LH/R BUMPER GARNISH (SN)	NECESSARY	128.17	128.17
1	RH/R BUMPER GARNISH (SN)	NECESSARY	128.17	128.17
1	REAR BOTTOM PANEL (SN)	CUT	227.03	227.03
1	LH/R BOTTOM BRACKET (SN)	DEFORMED	17.36	17.36
1	RH/R BOTTOM BRACKET (SN)	NOT NECESSARY	17.36	-
4	CT/R PARKING SENSOR (SN)	NOT NECESSARY	688.28	-
4	CT/R PARKING SENSOR SEAL (SN)	NOT NECESSARY	25.68	-
1	LH/R BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	36.24	-
1	RH/R BASIC MOUNTING FOR BUMPER (SN)	NOT NECESSARY	36.24	-
1	CT/R BASIC MOUNTING FOR BUMPER (SN)	DEFORMED	211.58	211.58
1	LH/R EXHAUST MUFFLER (SN)	NOT NECESSARY	1,835.62	-
1	LH/R EXHAUST MUFFLER BRACKET (SN)	NOT NECESSARY	91.90	-
1	REAR CROSS MEMBER (SN)	NOT NECESSARY	789.45	-
1	REAR BOTTOM UNDER CARRIAGE COVER (ADDITIONAL) (SN)	CRACKED	38.15	38.15
4	RIVET (ADDITIONAL)(SN)	NECESSARY	17.68	17.68
			5,919.48	2,398.71
LABOUR				
USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO STANDARD SETTINGS.			380.00	380.00
REMOVE & INSTALL REAR EXHAUST SYSTEM.			300.00	-
REMOVE & REPLACE REAR BUMPER & REMOVE REAR SUPPORT ASSY COMPONENTS & REFINISH.			1,440.00	960.00
RESPRAY REAR BUMPER.			720.00	600.00
REPAIR REAR END PANEL (ADDITIONAL).			960.00	960.00
RESPRAY REAR END PANEL (ADDITIONAL).			600.00	600.00
			4,400.00	3,500.00
GRAND TOTAL			10,319.48	5,898.71
RECOMMENDED COST OF REPAIRS				5,898.71



Report Ref No. CS/FCI18008029/T1tbn2

MOHAMAD TAUFIKH
M.MATAI, AMSAE-A
Automotive Assessor

ADRIAN LING WAI PING
B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.